

**ESTEEM PERFORMANCE PTE LTD**

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

**Spare Parts**

Vehicle No. :

Make &amp; Model :

Chassis No. :

**SLN 4169 E**

TOYOTA PRIUS

JTDKB3FU203556663

Submit By :

Year Manufacture :

Engine No. :

**CARMEN LIM**

2017

**Cost / List****Supplementary**

| S/No. | Part Description                 | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|----------------------------------|-----|------------|-------|-------------------------|
| 1     | Taillamp panel LH                | 1   | \$189.60   |       | ✓                       |
| 2     | LH side skirt                    | 1   | \$721.50   |       | ✓                       |
| 3     | Fuel tank cover motor            | 1   | \$369.67   |       | ✓                       |
| 4     | Taillamp clip                    | 3   | \$13.50    |       | ✓                       |
| 5     | Taildoor stopper LH              | 1   | \$14.21    |       | ✓                       |
| 6     | Taillamp cover LH                | 1   | \$61.78    |       | ✓                       |
| 7     | Warning triangle box             | 1   | \$45.00    | S.N   | ✓                       |
| 8     | Support panel air guide LH upper | 1   | \$89.70    |       | ✓                       |
| 9     | Support panel air guide LH lower | 1   | \$89.70    |       | ✓                       |
| 10    | Headlamp ballast LH              | 1   | \$551.97   |       | ✓                       |
| 11    | Wiper garnish                    | 1   | \$561.70   |       | ✓                       |
| 12    | Wiper garnish cover LH           | 1   | \$75.80    |       | ✓                       |
| 13    | Rear brake caliber LH            | 1   | \$751.60   |       | ✓                       |
| 14    | Leveling sensor                  | 1   | \$588.60   |       | ✓                       |
| 15    | Rear disc roto LH                | 1   | \$321.70   |       | ✓                       |
| 16    | LH rear antiroll bar link        | 1   | \$161.70   |       | ✓                       |
| 17    | Coil spring stopper top          | 1   | \$59.80    |       | ✓                       |
| 18    | Coil spring stopper bottom       | 1   | \$61.37    |       | ✓                       |
| 19    | LH rear trailing arm             | 1   | \$303.70   |       | ✓                       |
| 20    | Floor panel LH                   | 1   | \$189.60   |       | ✓                       |
| 21    | Driver seat back rest rail       | 1   | \$669.40   |       | ✓                       |
| 22    | Passenger seat back rest rail    | 1   | \$669.40   |       | ✓                       |
| 23    | Taillamp socket assy LH          | 1   | \$75.90    |       | ✓                       |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

6591.90

**Spare Parts**

Vehicle No. : **SLN 4169 E**  
Make & Model : **TOYOTA PRIUS**  
Chassis No : **JTDKB3FU203556663**

Submit By : **CARMEN LIM**  
Year Manufacture : **2017**  
Engine No. :  
**Cost / List**

**Supplementary**

| S/No. | Part Description            | Qty | Unit Price | Price | Disposition by Surveyor |
|-------|-----------------------------|-----|------------|-------|-------------------------|
| 1     | Rear brake pad <i>1-1/2</i> | 1   | \$195.40   |       | <i>X</i>                |
| 2     |                             |     |            |       |                         |
| 3     |                             |     |            |       |                         |
| 4     |                             |     |            |       |                         |
| 5     |                             |     |            |       |                         |
| 6     |                             |     |            |       |                         |
| 7     |                             |     |            |       |                         |
| 8     |                             |     |            |       |                         |
| 9     |                             |     |            |       |                         |
| 10    |                             |     |            |       |                         |
| 11    |                             |     |            |       |                         |
| 12    |                             |     |            |       |                         |
| 13    |                             |     |            |       |                         |
| 14    |                             |     |            |       |                         |
| 15    |                             |     |            |       |                         |
| 16    |                             |     |            |       |                         |
| 17    |                             |     |            |       |                         |
| 18    |                             |     |            |       |                         |
| 19    |                             |     |            |       |                         |
| 20    |                             |     |            |       |                         |
| 21    |                             |     |            |       |                         |
| 22    |                             |     |            |       |                         |
| 23    |                             |     |            |       |                         |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

*6787-30*  
*4x (S.N)*