

ASS. REC. BY:

REF: CS/SMO18004047/Gvd3

Special Instruction:

Surveyor: CIO ASSIGNMENT (Office)From (Person): Grace Teo of SMO Date/Time: 2/3/18

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 1055E Insured: SLB 7728Kat Workshop m/s SMRT Tel: 6866 2672of 60 Woodlands Ind. Prk E4Policy No: Claim No: CMTD1800925/THE

Sum Insured: Excess:

Make of Veh: D.O.A. 28/02/2018
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1wp} H.O.D. Endorsement:Date/Time: 9.41am 2/3/18 Person Contacted: Shanti Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SHB 1055E - CC3 / AK17000212 / Klyg3q2</u> D.O.A. <u>30/12/16</u>
	<u>SLB 7728K - X</u>
<u>5/3/18</u>	<u>Email preli revised to Grace</u>
<u>14/3/18</u>	<u>LS \$3750 (Red 5013.74, 5790) confirmed by email</u>

X20

SMO

ASSIGNMENT

Estimate No. _____ Date 2/3/18

Estimated Cost _____

OD (TP) WS TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No. SHB 1055E

at Workcentre SMRT

at _____

Insured _____

Policy No. _____

Damage No. _____

Sum Insured _____ Excess _____

Chassis Record _____

Make of Vehicle _____

N/S		O/S	

Policy Condition _____

Remark: The veh had commenced its repair at the time of inspection.

Ball on Market Value _____

ICAC Accident Report _____ Consistent? : Yes or No _____

GIA / PR Seen _____ Consistent? : Yes or No _____

Est. Repairs 4 days Res. Yes or No _____

Lit. Sum 20 % 3 Val. Yes or No _____

CA / REV / RER / 24 HRS 1wp

Date _____ Person Contacted _____

Vehicle IN / OUT _____

SHB 1055E 06 Dec 2013

Type M/Cat M/Cycle B/Cycle V/Lorry (C) Prime No. _____

Track Trailers _____

Make Toyota Prius 1798

Colour Maroon

So Reading _____

Eng No _____

CNO JTDKN36U605711033

Gen Cond (C) Fair Poor Burnt

Steering (C) Locked Jammed Leaked Burnt

Brake (C) Locked Jammed Leaked Burnt

Mod N/A STD A/R _____

Tyre Size 155/65R15

BS / DUN / EXNOVA / GY / PS / LIZA / MIC / OHTSL / PR / SLM

TOYO / YOKO FALKEN

Front _____ Rear _____

R/Ba 6 mm L/Ba 6 mm

D/OA _____

Survey Ref: w/s

Des of Damages (C) O/S / N/S / U/O / Roof/hood

The U/O / Chassis frame / Body Structural affected due to collision

RECEIVED 14 MAR 2018

Cost/Time File Pass 1/2

☐ Prelim. Report

☐ Final Report

Days Of Repair 4

Resurvey No. of Trip 1

Survey Fee _____

Transport _____

14/3 - typist

Record Form No. TP

LS \$3750.00

Add Fee: ☐ Site Ins. \$ _____

☐ Inter. \$ _____

☐ Rep. \$ _____

☐ Test. \$ _____

Survey Department Check List (Case Handler)

Reference No.: CS SMO 1800 4047 / 6 vcl 3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Damaged Vehicle Photographs Uploaded	✓			

(3) Workshop Estimate/Assignment Form		Y-Date	N-Date	Y-Date	N-Date
N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)		Y-Date	N-Date	Y-Date	N-Date
C	Resurvey photo Uploaded	✓			

Check By: VERON 14/3/18
 Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO18004047/Gvd3		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 02-03-2018		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLB 7728K	Veh. Inspected	SHB 1055E	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1800925/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/02/2018	Inspection Date	02/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: CMTD1800925/THE

Our ref: CS/SMO18004047/Gvd3

Date: 5/3/2018

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SHB 1055E


We thank you for your instruction on 2/3/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/3/2018 at the premises of M/s SMRT AUTOMOTIVE SERVICES PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	8,622.08
Revised Estimate Amount	: S\$	3,830.88
"Check" Items Amount	: S\$	506.39
Market Value	: S\$	
LTA Reimbursement Value	: S\$	
Nett Value	: S\$	

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

XING GUO QIANG

M.MATAI, AMSAE-A

Automobile Assessor

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 14 March 2018 9:16 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); 'Ms Lee (Lee Sheng Auto)';
SUR
Subject: RE: SHB1055E

Dear Poh Suan,

Confirmed amount Lump Sum \$3,750 @ 4 working days

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 12 March 2018 6:57 PM
To: 'Ms Lee (Lee Sheng Auto)' <ekchen_lee@leeshengauto.com.sg>
Cc: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: FW: SHB1055E

Hi Ms Lee,

Please provide the check items and before paint photos.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Monday, 12 March 2018 5:40 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Guo Qiang (LKKAUTO)
Cc: SUR; CS A Team
Subject: RE: SHB1055E

Dear Poh Suan,

Kindly forward us check items and before paint photos.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) [mailto:YeoPohsuan@smrt.com.sg]
Sent: Monday, 12 March 2018 5:12 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB1055E

Hi Guo Qiang,

Attached herewith the repair estimate of SHB 1055E having Case No: TAX/02/18/2167.

There is no change to the approved amount of \$3,750 @ 4 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 12 March 2018 2:35 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 5 March 2018 2:34 PM
To: 'Teo, Grace'
Cc: 'Choo, Thelma'; 'Henry, Irene James'; SUR
Subject: RE: CMTD1800925/THE - SLB7728K(OD) / SHB1055E ACC ON 28.02.18
Attachments: SHB 1055E PRELI ADVISED.pdf

Dear Grace,

Enclosed preliminary revised of vehicle SHB 1055E
Date of survey: 2/3/2018
Number of days: 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Monday, 5 March 2018 12:15 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Choo, Thelma' <thelma.choo@sompo.com.sg>; 'Henry, Irene James' <irene.henry@sompo.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: CMTD1800925/THE - SLB7728K(OD) / SHB1055E ACC ON 28.02.18

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Monday, 5 March 2018 11:19 AM
To: peiying@smemotor.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma <thelma.choo@sompo.com.sg>; Henry, Irene James <irene.henry@sompo.com.sg>
Subject: CMTD1800925/THE - SLB7728K(OD) / SHB1055E ACC ON 28.02.18

Our Claim Reference : CMTD1800925/THE

Hi Pei Ying,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo is the handler of this case.

Please be informed that we have appointed **LKK AUTO** to conduct the survey.

Excess - WAIVED

Aside to **LKK AUTO**,

Please assist to conduct motor survey on Own Damage basis as repair estimate attached.

Please revert with your preliminary report upon completion of survey to my colleague Thelma.

Authorise if consistent.

Excess applicable – WAIVED

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: peiyang@smemotor.com.sg [<mailto:peiyang@smemotor.com.sg>]

Sent: Monday, March 05, 2018 10:41 AM

To: Claims - Motor Survey

Subject: OWN DAMAGE CLAIM FOR SLB7728K

Hi,

Pls note that the vehicle is already in workshop. Kindly arrange for survey.

Thanks

Regards,
Pei Ying

From: ptr2@smemotor.com.sg
Sent: Monday, March 5, 2018 9:23 AM
To: SME Motor-Chia Pei Ying
Subject: Attached Image

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 2 March 2018 9:36 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Henry, Irene James
Subject: CMTD1800925/THE - ACCIDENT INVLG SLB7728K & SHB1055E ON 28.02.18
Attachments: 2167 - 1055.pdf; SHB1055E.PDF

Our Claim Reference: CMTD1800925/THE

Dear LKK,

Please make arrangement to conduct the survey for SHB1055E.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teo, Grace

Sent: Thursday, March 01, 2018 1:09 PM

To: 'Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)'

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims); Choo, Thelma; Henry, Irene James

Subject: CMTD1800925/THE - ACCIDENT INVLG SLB7728K & SHB1055E ON 28.02.18

Our Claim Reference: CMTD1800925/THE

Your Reference: SHB1055E

Hi Shanti,

We acknowledged receipt of your claim documents.

Please be informed that Thelma Choo the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Shanti B Thaiyal Nayagi (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims) [<mailto:BThaiyalN@smrt.com.sg>]

Sent: Thursday, March 01, 2018 9:27 AM

To: 'motorsurvey@sompo.com.sg'

Cc: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Kok Tuck Foo (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Koo Yew Chung (Auto Svcs/Ext Biz Svcs/AR & SC); Phua Zhi Yang (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Grace Ng Siu Ching (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Kha Chiew (Auto Svcs/Ext Biz Svcs/AR & SC/ARC/AR); Lim Wei Siong (Auto Svcs/Ext Biz Svcs/Claims & IA/Taxis/Claims)

Subject: RE: SHB1055E- Survey (Sompo Insurance)

Dear Sir /Mdm

Kindly arrange to survey the vehicle **SHB1055E** within 48 hours according to GIA guide line, involving your insured **SLB7728K**

Vehicle in Woodlands Depot

Regards

Shanti

SMRT Automotive Services PTE LTD

Accident Reporting Center (Claims Dept)

6866 2671/2 | bthaiyaln@smrt.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	28/02/2018 15:25
Date Of Accident	28/02/2018 14:15
Exact Location Of Accident	SEBBAWANG ROAD TOWARD JALAN MATAR AYER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SHB1055E
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000
Vehicle Particulars	
Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	
Driver	
Name of Driver	JOHN NG TEO LONG
NRIC No	S1391311J
Date Of Birth	31/10/1959
Occupation	OUTDOOR
Date Of Driving Pass	14/05/1980
Driving Experience	37 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	298
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG SEMBAWANG TOWARDS JALAN MATA AYER AND I WAS TRAVELLING ON THE RIGHT LANE AS I WAS GOING TO TURN RIGHT. ALL THE VEHICLES WERE SLOW MOVING AND SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE SLB7728K HAD COLLIDED ONTO THE REAR OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB7728K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO SENG KEY
NRIC/Passport Number	S1480378E
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	JOHN NG TEO LONG
------	------------------

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SHB1055E

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

28/2/18


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB1055E
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5916485
Chassis No.:	JTDKN36U605711033
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	06 Dec 2013
First Registration Date:	06 Dec 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	05 Dec 2021
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	05 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$62,740.00
COE Rebate Amount:	\$29,409.00
Total Rebate Amount:	\$35,685.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 05 Mar 2018

OK

8-3-18 / 9:00

8-3-18 / 13:00 (ADV)

9-3-18 / 8:00

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates


5-3-18 / 8:00

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1055E
 Ref. No : TAX/02/18/2167
 Reg. Date : 06/12/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : JOHN NG TEO LONG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 28/02/2018 02:17:00 PM
 Accident Reported Date / Time : 28/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Guo Qiang
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094809
 Special Instruction to ARC, if any :

SLB7728K - SOMPO INSURANCE
 BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
 SURVEYOR guoqiang (LKK) & Email : guoqiang@lkkauto.com HP: 82880282
 LUMPSUM REPAIR

Prepared Date : 28/02/2018 03:48:00 PM



11:50

8.3.18 pass.

Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

Date 5-3-18

2nd witness

Date 8-3-18

288372

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

8-3-2018

Vehicle Return Time:

09:00 am

SMRT staff sign:

288310
 1 1 1 1
 1 1 3 1
 4 2 4 1

Supplementary

* Refer to the Supplementary part list

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U60-5711033

Mileage

: 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	300.00
Total Spray Painting Charges	: 1,116.00	500.00
Total Material Charges	: 2,401.65	2,287.46
Other Charges	: 1,236.88	676.88
TOTAL	: 5,768.53	3,764.34
Lum Sum Total	: 5,750.00	3,750.00
No. of Repair Days	: 6.00	4.00
Prepared / Adjusted By	:	GUOQIANG (LKK)
Arc / Surveyor Sign Off Date	: 01/03/2018 08:56:47 AM	02/03/2018 04:22:21 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/03/2018 08:56:47 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1803-0201

Invoice No :

Quotation Date : 10/3

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 300

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 100
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X NN
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 100
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X NN
TO WASH AND VACUUM	60.00	0.00 X NN
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 / NET.
Total Other Costs	1,236.88	0.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR <i>Re</i>	1	458.60	25.00	343.95	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR <i>BT</i>	1	205.70	25.00	154.27	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH <i>BT</i>	1	139.60	25.00	104.70	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH <i>BT</i>	1	139.60	25.00	104.70	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH <i>Mc</i>	1	94.80	25.00	71.10	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH <i>Mc</i>	1	94.80	25.00	71.10	Replace	Replace	No
76088-47020		6505617	BUMPER LIP COVER RR/LH <i>Mc</i>	1	72.20	25.00	54.15	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH <i>Mc</i>	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR <i>Re</i>	1	228.90	25.00	171.67	Replace	Replace	No
			PIXEL STICKER <i>Mc</i>	2	60.00 <i>120</i>	0.00	120.00	Replace	Replace	No
58307-47060		6505522	END PANEL <i>X Repair</i>	1	602.10	25.00	451.57	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX <i>X NN</i>	1	37.00	0.00	37.00	Replace	Replace	No
			SENSOR REVERSE <i>Mc</i>	1	180.00	0.00	180.00	Replace	Replace	No
67005-47241			TAILGATE ASY <i>BT</i>	1	1,007.90	25.00	755.92	Replace	Replace	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH <i>X NN</i>	1	504.90	25.00	378.67	Replace	Replace	No
69350-47030			TAILGATE DOOR LOCK <i>X NN</i>	1	444.10	25.00	333.07	Replace	Replace	No
67881-47022			TAILGATE DOOR WEATHER STRIP <i>Tw</i>	1	353.40	25.00	265.05	Replace	Replace	No
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1 <i>Mc</i>	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN <i>Mc</i>	1	37.00	0.00	37.00	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH <i>Mc</i>	1	29.40	25.00	22.05	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH <i>Mc</i>	1	29.40	25.00	22.05	Replace	Replace	No
	COMMON		SEALANT W/SCREEN <i>Mc</i>	2	37.00 <i>74</i>	0.00	74.00	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) <i>Mc</i>	1	51.90	25.00	38.92	Replace	Replace	No
75442-47030			NAME PLATE (PRIUS) <i>Mc</i>	1	60.80	25.00	45.60	Replace	Replace	No
75443-47030			NAME PLATE (TOYOTA) <i>Mc</i>	1	51.90	25.00	38.92	Replace	Replace	No
75310-47020		6505639	EMBLEM REAR <i>Mc</i>	1	60.30	25.00	45.22	Replace	Replace	No
	COMMON		STICKER DECAL 6555 8888 <i>Mc</i>	1	21.60	0.00	21.60	Replace	Replace	No
			STICKER DECAL SMRT <i>Mc</i>	1	7.80	0.00	7.80	Replace	Replace	No
TOTAL MATERIALS							5255.20	4,060.75	4,060.70	
TOTAL MATERIALS(Discounted)								3,189.70	3,254.80	

Number				Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace S	No /
TOTAL MATERIALS								3,002.09	2,859.34	
TOTAL MATERIALS(Discounted)								2,401.65	2,287.46	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
89997-30070		ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						141.66			

$$\begin{array}{r}
 2859.34 \\
 - 200 \\
 2287.46 \\
 + 300.00 \\
 + 1176.88 \\
 \hline
 3764.34 \\
 \text{US \$3750/-}
 \end{array}$$

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1055E
 Ref. No : TAX/02/18/2167
 Reg. Date : 06/12/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : JOHN NG TEO LONG
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 28/02/2018 02:17:00 PM
 Accident Reported Date / Time : 28/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094809
 Special Instruction to ARC, if any :
 SLB7728K - SOMPO INSURANCE
 Prepared Date : 28/02/2018 03:48:00 PM



4 Days.

Lumpsum repair

After repair photos.

Lim Qiang - 8288 0282

02/3/18.

[Signature]
5/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U60-5711033

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,116.00	0.00
Total Material Charges	: 3,189.70	3,254.80
Other Charges	: 1,236.88	0.00
TOTAL	: 6,556.58 <i>8655.08</i>	0.00
Lum Sum Total	: 6,550.00 <i>8763.74</i>	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 01/03/2018 08:56:47 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/03/2018 08:56:47 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	300.00
Total Labour	1,014.00	300.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY REAR PANEL	180.00	100.00
TO RESPRAY TAIL GATE	378.00	200.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00
Total Spray Painting & Panel Beating	1,116.00	500.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	100.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88
Total Other Costs	1,236.88	676.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	456.60	25.00	343.95	Replace	Replace	No ✓
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace S	No ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace S	No ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace S	No ✓
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Check	No X
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.58	Replace	Check	No X
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓
58307-47060		6505522	END PANEL	1	602.10	100.00	0.00	Replace	Repair	No 12
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No X
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No ✓
76801-47070-B0			TAILGATE OUTSIDE GARNISH	0	504.90	25.00	0.00	Replace	Not given	No X
39350-47030			TAILGATE DOOR LOCK	0	444.10	25.00	0.00	Replace	Not given	No X
37881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No ✓
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No ✓
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ✓
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No ✓
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No ✓
	COMMO N		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No ✓
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓
5442-7030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No ✓
5443-7030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No ✓
5310-7020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No ✓
	COMMO N		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No ✓

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18004047/Gvd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 16-03-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 7728K	Veh. Inspected	SHB 1055E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1800925/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U605711033	Colour	MAROON
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	28/02/2018	Inspection Date	02/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1055E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY,RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY,RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	TAILGATE ASY (DISC 25%)	BENT	1,007.90	755.92
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	TWISTED	353.40	265.05
1	MOULDING BACK WINDOW,LOWER NO 1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING,LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING,RH (DISC 25%)	NECESSARY	29.40	22.05
1	NAME PLATE (HYBRID)(DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (PRIUS)(DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA)(DISC 25%)	NECESSARY	51.90	38.92
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SENSOR REVERSE (SN)	DAMAGED	180.00	180.00
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
2	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	74.00	74.00
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	ADVERTISEMENT STICKER (SN)	NECESSARY	296.88	296.88
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER LIP COVER RR/RH	NOT NECESSARY	118.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
1	ANTENNA ELECTRICAL LOWER REAR (DISC 10%)	DAMAGED	157.40	141.66
			5,709.48	3,156.21

Report Ref No. CS/SMO18004047/Gvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING & BODY WORK.INCLUSIVE OF THE REPAIR OF END PANEL.		1,014.00	300.00
	SPRAY PAINT.		1,116.00	500.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		100.00	60.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO REMOVE AND REFIX REAR WINDSCREEN.		120.00	100.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO INSPECT RR LIGHTING,MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			3,070.00	1,180.00
	GRAND TOTAL		8,779.48	4,336.21

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,750.00
---	--	--	-----------------

Report Ref No. CS/SMO18004047/Gvd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.