

SMRT Accident Vehicle Repair Estimates

AIG

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4989K
Ref. No : TAX/02/18/2160
Reg. Date : 20/11/2015
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TOO KIM THOR
Type of Accident : OTHERS
Date / Time of Accident : 28/02/2018 09:25:00 AM
Accident Reported Date / Time : 28/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094799
Special Instruction to ARC, if any :
GBD1183D
Prepared Date : 28/02/2018 10:16:08 AM



Sebastian
28/2/18

- Part by part repair.
- Question Mark Item Photo
- Photo Before Paint.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U605767229

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 2,232.00	0.00
Total Material Charges	: 8,134.09	8,134.09
Other Charges	: 1,116.88	0.00
TOTAL	: 12,496.97	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	5 days
Arc / Surveyor Sign Off Date	: 28/02/2018 04:00:07 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/02/2018 04:00:07 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR LH	378.00	0.00 X
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 X
RESPRAY WHEEL CAP	180.00	0.00 X
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 7
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
Total Spray Painting & Panel Beating	2,232.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REMOVE AND REFIT TYRE	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 ✓
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
Total Other Costs	1,116.88	0.00

Part 4- Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7002-7070		6505529	DOOR FRT/LH	1	894.40	25.00	670.80	Replace	Replace X	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace X	No
3802-7050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace ✓ DT	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace ✓ N	No
3876-7030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace ✓	No
3852-7020			FENDER LINER PAD, FR WHEEL. LH	1	49.30	25.00	36.97	Replace	Replace ✓	No
2602-7060		6505676	CAP SUB-ASSY, WHEEL	1	174.10	25.00	130.57	Replace	Replace X	No
2611-7140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace X	No
		6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace X	No
2119-7930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace ✓	No Deform
2611-7080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace ?	No
2021-7023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace ?	No
7014-7030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace ?	No
7013-7030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace ?	No
2116-7040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace ?	No
1521-7050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace ?	No
1529-7060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace ?	No
1529-7040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace ?	No
1529-7040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace ✓	No
1170-7500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace ✓	No
3301-7060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace R	No
3201-7902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace ?	No
5852-7900			MOULDING BODY, LH	1	673.60	25.00	505.20	Replace	Replace R	No
TOTAL MATERIALS							7,628.92	7,628.89		
TOTAL MATERIALS(Discounted)							8,134.09	8,134.09		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									