

not Authorized
L/S B
To be phoned after
repair
Tel: 62583561
Express?

M/s Everdrive Enterprise Pte Ltd

Vehicle No: SLF 7107 G
Make/Model: Mazda 3

LIST ITEMS

1 pc	front bumper	dis/7.1
8 pcs	front bumper clip	new
2 pcs	front bumper bracket	
2 pcs	front bumper side retainer	but n/s
1 pc	R/H front bumper side cover	ground
2 pcs	headlamp	n/s one o/s bad?
1 pc	front grille	
1 pc	front grille logo	
1 pc	front grille chrome moulding	one?
2 pcs	front bumper lamp	11
2 pcs	front signal lamp lower garnish	n/s ground
1 pc	front windscreen glass	one
1 pc	front windscreen moulding	new
1 pc	front support panel	new
1 pc	L/H front fender	3.5 bad
1 pc	L/H front fender dust cover	7.1
10 pcs	L/H front fender dust cover clip	new
1 pc	L/H front fender inner panel	new
1 pc	L/H front fender inner top garnish	11
1 pc	L/H front door	3.5 bad
1 pc	L/H front door rubber	new
2 pcs	L/H front door hinge	7.1
1 pc	L/H front door wing mirror	3.5
1 pc	L/H front door wing mirror signal lamp	3.5
1 pc	L/H front door lock	7.1/3.5
1 pc	L/H front door regulator gear	but
1 pc	L/H front door regulator gear motor	3.5
1 pc	L/H front door glass channel	but
1 pc	L/H front door stricker	11
1 pc	L/H front door glass outer moulding	but
1 pc	L/H front door inner trimboard	de/one
1 pc	L/H front door pillar	3.5 bad
1 pc	L/H front door outer handle	
1 pc	L/H front door outer handle bracket	
1 pc	L/H rocker panel	3.5 bad
1 pc	L/H door centre pillar	complete
1 pc	L/H rear door	2.5 bad
1 pc	L/H rear door rubber	new
2 pcs	L/H rear door hinge	7.1
1 pc	L/H rear door lock	3.5
1 pc	L/H rear door regulator gear	11
1 pc	L/H rear door regulator gear motor	11
1 pc	L/H rear door glass channel	but
1 pc	L/H rear door stricker	11
1 pc	L/H rear door glass outer moulding	but

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before, after, or on painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Estimate modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$	852.40	✓
\$	19.20	✓
\$	159.60	?
\$	45.60	IPC
\$	42.00	?
\$	1,934.00	IPC
\$	447.60	?
\$	38.00	?
\$	165.10	?
\$	480.40	X
\$	224.60	IPC
\$	1,450.30	✓
\$	165.00	✓
\$	559.70	X
\$	612.50	✓
\$	158.00	✓
\$	20.00	✓
\$	725.10	X
\$	85.20	X
\$	1,150.80	✓
\$	143.50	✓
\$	186.00	✓
\$	626.70	✓
\$	189.60	✓
\$	329.10	✓
\$	247.60	✓
\$	358.40	✓
\$	65.10	✓
\$	75.00	X
\$	145.00	✓
\$	575.60	?
\$	684.10	✓
\$	177.00	✓
\$	65.20	✓
\$	642.00	✓
\$	664.50	X
\$	1,135.20	✓
\$	135.40	✓
\$	168.20	✓
\$	328.40	✓
\$	247.60	X
\$	358.40	X
\$	65.10	✓
\$	76.00	X
\$	105.00	✓
\$	17,128.80	

Balance c/f

		Balance b/d	\$ 17,128.80	
1 pc	L/H rear door outer handle <i>11</i>		\$ 178.00	X
1 pc	L/H rear door outer handle bracket <i>11</i>		\$ 65.20	X
1 pc	L/H rear door outer inner trimboard <i>De/cue</i>		\$ 525.10	/
1 pc	L/H front lower arm <i>buc</i>		\$ 428.10	/
1 pc	L/H front shock absorber <i>buc</i>		\$ 497.80	/
1 pc	L/H front knuckle arm <i>buc</i>		\$ 570.40	/
1 pc	L/H front knuckle arm bearing <i>ner</i>		\$ 256.70	/
1 pc	L/H front driveshaft		\$ 1,356.20	?
1 pc	front stabilizer bar		\$ 469.70	?
2 pcs	front stabilizer bar link <i>twl</i>		\$ 96.20	/
1 pc	steering rack assy <i>buc/gm</i>	<i>(20%)</i>	\$ 2,158.20	/
1 pc	steering cross member		\$ 985.10	
1 pc	L/H front brake disc <i>11</i>		\$ 386.00	X
<u>S/NETT ITEMS</u>				
1 pc	front windscreen sealant <i>ner</i>		\$ 80.00	405.N
1 pc	L/H front wheel rim <i>wp/buc</i>		\$ 800.00	4005.N
1 pc	L/H front tyre		\$ 400.00	?
Labour charges.			\$ 3,800.00	1500
Spray painting.			\$ 1,700.00	1300
To remove/refit aircon condenser & refill gas to facilitate repairs. <i>11</i>			\$ 140.00	X
To remove/refit radiator assy to facilitate repairs. <i>11</i>			\$ 100.00	X
To remove/renew L/H front & rear door.			\$ 200.00	100
To remove/refit passenger seat, carpet, roof lining to facilitate repairs.			\$ 200.00	150
To remove/refit dashboard to facilitate repairs.			\$ 450.00	? 260
To remove/renew front windscreen glass.			\$ 160.00	120
To remove/renew L/H front undercarriage.			\$ 400.00	300
To remove/refit engine to facilitate repairs. <i>11</i>			\$ 800.00	X
To wheel alignment.			\$ 150.00	60
Towing charges.			\$ 100.00	50
To check wirings.			\$ 60.00	20
Total			<u>\$ 34,839.50</u>	