

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3109K

DATE 1/3/2018 11:51

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>x repair</i>			\$ 562.30
	Front Bumper Bracket Top (LH) <i>?</i>			\$ 22.40
	Front Bumper Retainer Mounting <i>?</i>			\$ 9.20
	Headlamp (LH) <i>/</i>			\$ 1,388.00
	Front Fender (LH) <i>/</i>			\$ 619.00
	Front Fender Shield (LH) <i>X</i>			\$ 169.80
	Front Fender Retainer <i>X</i>			\$ 9.20
	Frt Wheel Hub Cap, LH <i>/</i>			\$ 150.70
	<i>Front Bumper (LH) x repair</i>			
	<i>Front Bumper (LH) x repair</i>			
	<i>Rock Panel Beating (LH) x repair</i>			
	SUB TOTAL			\$ 2,930.60
	LESS 20%			\$ 586.12
	DISCOUNTED TOTAL			\$ 2,344.48
	Labour Charge			
	Panel Beating			\$ 850.00 <i>400</i>
	Spray Painting Charge			\$ 600.00 <i>580</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Frt Wheel Alignment			\$ 80.00 <i>7</i>
	TOTAL LABOUR			\$ 1,630.00
	ESTIMATE TOTAL			\$ 3,974.48
	<i>Kate 10K res</i>			
	<i>1/3/18 14:35hs</i>			
	<i>2 Apr.</i>			
	<i>PIP</i>			
	<i>Before Paint p Lts</i>			
	LKK Auto Consultants hence notify the Repairer of the following: <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company 			
	Acknowledged by Repairer			
	Signature:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			