

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/ 62717433 FAX:62745715

Pgl

DOA: 28.2.2018

No	Description	Unit	Cost (\$)
1	FRONT RH DOOR	1	\$ b7- 520.00
2	FRONT RH DOOR HINGE	2	\$ Ry 50.00
3	FRONT RH DOOR LOCK	1	\$ X 120.00
4	FRONT RH DOOR STRIKER	1	\$ X 20.00
5	FRONT RH DOOR CHECKER	1	\$ X 25.00
6	FRONT RH DOOR OUTER HANDLE	1	\$? 100.00
7	FRONT RH DOOR RUBBER	1	\$ at- 60.00
8	FRONT RH DOOR PILLAR RUBBER	1	\$ na- 80.00
9	REAR RH DOOR	1	\$ bt- 500.00
10	REAR RH DOOR HINGE UPPER	1	\$ Ry 30.00
11	REAR RH DOOR HINGE LOWER	1	\$ Ry 25.00
12	REAR RH DOOR CHECKER	1	\$ Ry 25.00
13	REAR RH DOOR RUBBER	1	\$ na- 65.00
14	SIDE SKIRT RH	1	\$ de✓ 120.00
	Tanpin 97445719		
	Ex \$ 375		
	N.t Authorise		
	2/3/18 @ 12pm		
	Felays.		
	Please before print		
	sur@kluayto.com		
			Total (A) : \$ 1,740.00
			Cost + 5% \$ 87.00
			Total: \$ 1,827.00

BLOCK 1009 BUKIT MERAH LANE 3
#01-80 SINGAPORE 159723
TEL:62715133/ 62717433 FAX:62745715

Pg 2

DOA: 28.2.2018

[illegible]