

ASS. REC. BY:

REF:

CS/CTI18004054/TIVD3ⁿ²

Special Instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Angie Poo

of

CTI

Date/Time:

11/3/18 @ 4:38pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 8248L

Insured:

SJT 11164

at Workshop m/s

Vermogen Ase

Tel:

6358 3031

of

1 Bukit Putok Crescent #05-23 Weeja Plaza

Policy No:

Claim No:

SNM18D00110302/6

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

28/2/18

Insp at: 6 Benor sector

CA / REV / REP. / REV 24 HRS

(wup)

H.O.D. Endorsement:

Date/Time:

9:38am @ 2/3/18

Person Contacted:

Ezel

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLD 8248L - X

SJT 11164 - CC4/CTI 17011626/TIHb3q2

D.O.A: 26/5/17

23/5/18

LS \$6200 confirmed by email (Ref 8120-76, 577)

Signature

Tanglin

REF: --

CT1

ASSIGNMENT

From:

Date: 01032018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	X

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD 8248L Yr Regn: 2016 June

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

CC 1496

Colour:

white

A/C Insured / Std / NI / NA

Sp. Reading:

115016

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

R41117543

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

Rear:

R/Bal:

6

mm

R/Bal:

6

mm

L/Bal:

6

mm

L/Bal:

6

mm

D.O.A:

D.O.I:

2/3/18

Survey held at

Vernag in Berni

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 23 MAY 2018

Date/Time File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time File Return to?

2) 215- typist

Report Format:

meri men

Lump Sum / I.B.I: (\$

6000/2

Days Of Repair:

7

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

13-PS-51

Photo:

Other:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

226

Survey Department Check List (Case Handler)

Reference No. : CS/CTI/8004054/T1vd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 23/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/CTI18004054/T1vd3		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-03-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJT 1116U	Veh. Inspected	SLD 8248L	
Policy No.		Coverage (\$)	0.00	
Claim No.	SNM18D001103C02/6	Excess (\$)	0.00	
Assign From	ANGIE FOO	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/02/2016	Inspection Date		
Survey held at	6 BENOI SECTOR			
Repairer	VERMOGEN ACE PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Sent: Thursday, 1 March 2018 4:38 PM
To: assignments
Subject: FW: OUR REF: PRS/SNM18D01103C02/6 & YR REF: SLD8248L -TO CONDUCT PRE REPAIR SURVEY -SLD8248L

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]
Sent: Thursday, 1 March 2018 4:36 PM
To: ezelvermogenace@gmail.com
Cc: 'Eric Glorioso' <ericvermogenace@gmail.com>; edmondvermogenace@gmail.com; 'pila.vermogenace' <pila.vermogenace@gmail.com>; 'juan paulo baldoz' <paulovermogenace@gmail.com>; 'Minoko' <minokovermogenace@gmail.com>; Irene Tay <irene.tay@sg.cntaiping.com>; 'Luis Tan' <luis.vermogenace@gmail.com>; 'vmg.vermogenace' <vmg.vermogenace@gmail.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Subject: RE: OUR REF: PRS/SNM18D01103C02/6 & YR REF: SLD8248L -TO CONDUCT PRE REPAIR SURVEY -SLD8248L

WITHOUT PREJUDICE

Dear Ezel,

We refer to your email on even date.

We had appointed Marcus Chua M/S LKK Auto Consultants Pte Ltd to conduct survey on your client's vehicle.

Please ensure that your client's vehicle is available for survey within 2 working days.

REMARKS:
Dear Marcus,

Please conduct survey, and check consistency of the damages on without prejudice.

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00

Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ezelvermogenace@gmail.com [mailto:ezelvermogenace@gmail.com]
Sent: Thursday, 1 March, 2018 4:07 PM
To: Angie Foo
Cc: 'Eric Glorioso'; edmondvermogenace@gmail.com; 'pila.vermogenace'; 'juan paulo baldoz'; 'Minoko'; Irene Tay; 'Luis Tan'; 'vmg.vermogenace'; Claims Dept of CTI
Subject: RE: OUR REF: PRS/SNM18D01103C02/6 & YR REF: SLD8248L -TO CONDUCT PRE REPAIR SURVEY -SLD8248L

Dear Angie,

As spoken just now, please assign Marcus Chua (LKK) to conduct PRS.

Thanks & Regards,
Ezel Tejano

From: Angie Foo [mailto:angie.foo@sg.cntaiping.com]
Sent: Thursday, March 1, 2018 4:03 PM
To: ezelvermogenace@gmail.com
Cc: 'Eric Glorioso' <ericvermogenace@gmail.com>; edmondvermogenace@gmail.com; 'pila.vermogenace' <pila.vermogenace@gmail.com>; 'juan paulo baldoz' <paulovermogenace@gmail.com>; 'Minoko' <minokovermogenace@gmail.com>; Irene Tay <irene.tay@sg.cntaiping.com>; 'Luis Tan' <luis.vermogenace@gmail.com>; 'vmg.vermogenace' <vmg.vermogenace@gmail.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF: PRS/SNM18D01103C02/6 & YR REF: SLD8248L -TO CONDUCT PRE REPAIR SURVEY -SLD8248L

WITHOUT PREJUDICE

Dear Ezel,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
SAMUEL PHUN
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
DEREK OH SIONG WEE
KALVIN ANG
MARCUS CHUA
SIMON HO
LOW SAR HUEI
HONG FOOK CHOY

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Kindly let us hear from you.

REMARKS:

Kindly take note, the claim handler on this case is Irene Tay 6389 6192

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: ezelvermogenace@gmail.com [mailto:ezelvermogenace@gmail.com]

Sent: Wednesday, 28 February, 2018 6:32 PM

To: Claims Dept of CTI; Irene Tay

Cc: 'Eric Glorioso'; edmondvermogenace@gmail.com; 'pila.vermogenace'; 'juan paulo baldoz'; 'Minoko'; 'Luis Tan'; 'vmg.vermogenace'

Subject: Accident involving SLD8248L & SJT1116U on 28/02/2018 - PLEASE ARRANGE TP SURVEY

Dear Sir / Madam,

Kindly arrange our client's vehicle for pre-repair survey at Vermogen Ace Pte Ltd here at 6 Benoi Sector S(629904).

Please refer to attachment and revert to us soon.

VEHICLE IN WORKSHOP

Thank you.

Dear Officer In-charge,

Please let us know what is the liability?

Kindly check & revert to us as soon as possible.

Thank you.

Best Regards,
Ezel Tejano
Vermogen Ace Pte Ltd
1 Bukit Batok Crescent
#05-23 Wcega Plaza
Singapore 658064
Tel: 6358 3031
Fax: 6694 4929

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 23 May 2018 11:30 AM
To: 'Baldoz Juan Paulo Bongon'
Cc: Janice Lee (LKKAUTO); Asher Sng (LKKAUTO); Vic (LKKAUTO); Taufikh (LKKAUTO); Guo Qiang (LKKAUTO); Vmg admin; Glorioso Eric Paul Patambang; Tezano Exequiel Dawal; Minoko Chan; Edmond Lim; Lina Rosli; Luis Tan; Paul Tan; Pila Ng; SUR
Subject: RE: SLD8248L DOA: 17/02/2018 TO FINALISE (CHINA TAIPING TP)

Dear Paulo Baldoz,

Noted with thanks,

Final invoice and all supporting documents sent over to CHINA TAIPING INSURANCE

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [mailto:paulo.b@vermogen-group.com]
Sent: Wednesday, 23 May 2018 11:11 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>
Subject: Re: SLD8248L DOA: 17/02/2018 TO FINALISE (CHINA TAIPING TP)

Hi Veron,

Confirmed finalize \$6,200.00 (lump sum repair) 7 working day.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:
1 Bukit Batok Crescent #04-54
Wcega Plaza Singapore 658064

On Wed, May 23, 2018 at 10:14 AM, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Paulo Baldoz,

WITHOUT PREJUDICE

Offer Lump Sum \$6200 before GST @ 7 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Baldoz Juan Paulo Bongon [<mailto:paulo.b@vermogen-group.com>]

Sent: Tuesday, 22 May 2018 10:50 AM

To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Cc: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; Vmg admin <vmg@vermogen-group.com>; Glorioso Eric Paul Patambang <eric.g@vermogen-group.com>; Tezano Exequiel Dawal <ezel.t@vermogen-group.com>; Minoko Chan <minoko@vermogen-group.com>; Edmond Lim <edmond@vermogen-group.com>; Lina Rosli <linarosli@vermogen-group.com>; Luis Tan <luis@vermogen-group.com>; Paul Tan <paul@vermogen-group.com>; Pila Ng <pila@vermogen-group.com>

Subject: SLD8248L DOA: 17/02/2018 TO FINALISE (CHINA TAIPING TP)

Dear Taufikh,

Please check and confirm finalise COR @ **\$6,750** bef gst (lump sum) 7 working days.

Excluded: PRS, RS, WEEKENDS, PH.

Thank you

Best Regards,

Paulo Baldoz

Vermogen Ace Pte Ltd

Operation Address:

6 Benoi Sector Singapore 629904

Tel: 6358 3031

Fax: 6694 4929

Mailing Address:

1 Bukit Batok Crescent #04-54

Wcega Plaza Singapore 658064

 P1030703.JPG

 P1030704.JPG

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/02/2018 14:49
Date Of Accident	28/02/2018 06:45
Exact Location Of Accident	BKE TOWARDS KJE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD8248L
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRER
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995064
Cover Note Number	

Driver

Name of Driver	TAN KIM SIONG CHRISTOPHER (CHEN JINSONG CHRISTOPHE
NRIC No	S7500636E
Date Of Birth	10/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	26/11/1998
Driving Experience	19 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:




Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/PIN No.:


ROSA PTE LTD

BKE - Google Maps

2/28/2018

Google Maps BKE




Image capture: Jul 2015 © 2018 Google

Singapore

Google, Inc.

Street View - Jul 2015



SLD8248L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/17/2018

Vehicle Reg. No. : SLD8248L
Vehicle Reg. Date: 29-Jun-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037546
Chassis No. : RU11117543

COST OF CLAIMS

Parts Cost / List Items : \$ 12,244.70
Plus/Less 20% \$ 2,448.94
Total Cost / List : \$ 9,795.76
Special Nett Items : \$ 825.00
Total Parts Amount : \$ 10,620.76
Total Labour Amount : \$ 3,700.00
Gross Total : \$ 14,320.76
GST % : 7% \$ 1,002.45
Nett Amount : \$ 15,323.21

Surveyor Name and Company :

Taufan 97495749
Date of survey : 2/3/18 @ 5pm

Part by Part / Lump Sum : 7 days

Resurvey Before Paint / After Paint

Authorize/Not Authorize/Without Prejudice

Email : sur@lkhauto.com

Fax No : _____

HP No : _____

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8248L**

Vehicle Reg. Date: **6/29/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4037546**

Chassis No. : **RU11117543**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bt	\$ 1,860.00		
2	1	Tailgate outer garnish	X nn	\$ 285.00		
3	1 set	Tailgate outer garnish clips	X nn	\$ 40.00		
4	1	Tailgate logo	nn	\$ 52.00		
5	1	Tailgate emblem "VEZEL"	de	\$ 56.20		
6	1	Tailgate lamp RH	X	\$ 490.00		
7	1	Tailgate lamp clips	X	\$ 50.00		
8	1	Tailgate outer handle switch	X	\$ 180.00		
9	2	Tailgate damper LH/RH	X	\$ 424.00		
10	1	Tailgate wiper motor	X	\$ 250.00		
11	1	Tailgate wiper blade	X	\$ 75.00		
12	1	Tailgate buzzer	X	\$ 150.00		
13	1	Tailgate inner handle	X	\$ 74.00		
14	1	Tailgate inner lock	? bt	\$ 245.00	✓	
15	1	Tailgate lock sensor	? de	\$ 220.00	✓	
16	1	Tailgate striker	Rx	\$ 32.00		
17	1	Tailgate trimboard	? de	\$ 295.00	✓	
18	1 set	Tailgate trimboard clips	? nn	\$ 45.00	✓	
19	1	Tailgate weatherstrip	fw	\$ 145.00		
20	1 set	Tailgate windscreen moulding	nn	\$ 164.00		
21	1	Tail lamp RH	X nn	\$ 489.00		
22	1set	Tail lamp clips	X nn	\$ 18.00		
23	1	Rear bumper	de	\$ 950.00		
24	1set	Rear bumper clips	nn	\$ 50.00		
25	2	Rear bumper retainer LH/RH	nn	\$ 144.00		
26	2	Rear bumper bracket LH/RH	? de	\$ 116.00	X nn	
27	1	Rear bumper reflector RH	at	\$ 167.00		
28	1	Rear bumper cover RH	de	\$ 210.00		
29	1set	Rear bumper cover clips	nn	\$ 25.00		
30	2	Rear bumper cover retainer LH/RH	nn	\$ 84.00		
31	1	Rear end panel outer	bt	\$ 585.00		
32	1	Rear end panel inner	Rx	\$ 396.00		
33	1	Rear end panel top garnish	? de	\$ 184.00	✓	
34	1set	Rear end panel top garnish clips	? nn	\$ 25.00	✓	
35	1	Spare tyre panel	Rx	\$ 1,230.00		
36	1	Spare tyre panel insulator	nn	\$ 240.00		
37	1	Spare tyre panel top board	? de	\$ 420.00	✓	
38	1	Spare tyre tool tray	de	\$ 430.00		
39	1	Exhaust muffler	Rx	\$ 855.00		
40	1	Exhaust muffler mounting	X nn	\$ 79.50		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLD8248L**

Vehicle Reg. Date: **6/29/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4037546**

Chassis No. : **RU11117543**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust muffler heat shield	9 hr ✓	\$ 165.00	✓	
42	2	Rear plate lamp LH/RH	X nu	\$ 250.00		
43	1	Rear number plate with frame	X nu		\$ 45.00	
44	1	Tailgate windscreen sealant	nu ✓		\$ 80.00	
45	1	Tailgate windscreen inner seal	nu ✓		\$ 80.00	
46	1	Rear end panel sealant	nu ✓		\$ 80.00	
47	1	Reverse sensor	nu ✓	200	\$ 300.00	
48	1	Spare tyre panel sealant	X nu		\$ 80.00	
49	1	Spare tyre panel padding	X nu		\$ 100.00	
50	1	Sundries	nu ✓	30	\$ 60.00	
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Chassis No. : RU11117543

[illegible]



SLD8248L

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : CHINA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 2/17/2018

Vehicle Reg. No. : SLD8248L
Vehicle Reg. Date: 29-Jun-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037546
Chassis No. : RU11117543

COST OF CLAIMS

Parts Cost / List Items : \$ 12,244.70
Plus/Less 20% \$ 2,448.94
Total Cost / List : \$ 9,795.76
Special Nett Items : \$ 825.00
Total Parts Amount : \$ 10,620.76
Total Labour Amount : \$ 3,700.00
Gross Total : \$ 14,320.76
GST % : 7% \$ 1,002.45
Nett Amount : \$ 15,323.21

Surveyor Name and Company :

Tan Jia 97495749
Date of survey : 2/3/18 @ 5pm
Part by Part / Lump Sum : 7 days
Resurvey Before Paint / After Paint 0
Authorize/Not Authorize/Without Prejudice 0
Email : sur@khantow.com
Fax No : _____
HP No : _____

This claim is handled by : EZEL

L/S = 6750

$$\begin{aligned} P &= 6761.20 \\ &- 20\% \\ &= 5408.96 \\ SN &= 470 \\ L &= 2580 \\ &= 8458.96 \\ &- 20\% \\ &= 6767.17 \end{aligned}$$

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8248L
Vehicle Reg. Date: 6/29/2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037546
Chassis No. : RU11117543

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Tailgate	bt✓	\$ 1,860.00		
2	1	Tailgate outer garnish	X	\$ 285.00		
3	1	Tailgate outer garnish	X	\$ 40.00		
4	1 set	Tailgate outer garnish clips	no✓	\$ 52.00		
5	1	Tailgate logo	ial✓	\$ 56.20		
6	1	Tailgate emblem "VEZEL"	X	\$ 490.00		
7	1	Tailgate lamp RH	X	\$ 50.00		
8	1	Tailgate lamp clips	X	\$ 180.00		
9	1	Tailgate outer handle switch	X	\$ 424.00		
10	2	Tailgate damper LH/RH	X	\$ 250.00		
11	1	Tailgate wiper motor	X	\$ 75.00		
12	1	Tailgate wiper blade	X	\$ 150.00		
13	1	Tailgate buzzer	X	\$ 74.00		
14	1	Tailgate inner handle	?	\$ 245.00		
15	* 1	Tailgate inner lock	?	\$ 220.00		
16	* 1	Tailgate lock sensor	Rp	\$ 32.00		
17	1	Tailgate striker	?	\$ 295.00		
18	* 1	Tailgate trimboard	?	\$ 45.00		
19	1 set	Tailgate trimboard clips	trial	\$ 145.00		
20	1	Tailgate weatherstrip	ne✓	\$ 164.00		
21	1 set	Tailgate windscreen moulding	X	\$ 489.00		
22	1	Tail lamp RH	X	\$ 18.00		
23	1 set	Tail lamp clips	de✓	\$ 950.00		
24	1	Rear bumper	no✓	\$ 50.00		
25	1 set	Rear bumper clips	nee✓	\$ 144.00		
26	2	Rear bumper retainer LH/RH	bx	\$ 116.00		
27	2	Rear bumper bracket LH/RH	at✓	\$ 167.00		
28	1	Rear bumper reflector RH	de✓	\$ 210.00		
29	1	Rear bumper cover RH	ne✓	\$ 25.00		
30	1 set	Rear bumper cover clips	ne✓	\$ 84.00		
31	2	Rear bumper cover retainer LH/RH	bt✓	\$ 585.00		
32	1	Rear end panel outer	KY	\$ 396.00		
33	1	Rear end panel inner	?	\$ 184.00		
34	* 1	Rear end panel top garnish	?	\$ 25.00		
35	* 1 set	Rear end panel top garnish clips	1 ?	\$ 25.00		
36	1	Spare tyre panel	KY	\$ 1,230.00		
37	1	Spare tyre panel insulator	nee✓	\$ 240.00		
38	1	Spare tyre panel top board	q	\$ 420.00		
39	* 1	Spare tyre panel top board	de✓	\$ 430.00		
40	1	Spare tyre tool tray	KY	\$ 855.00		
41	1	Exhaust muffler	K	\$ 79.50		
42	1	Exhaust muffler mounting				

P=6596.20

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : SLD8248L
Vehicle Reg. Date: 6/29/2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4037546
Chassis No. : RU11117543

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	* 1	Exhaust muffler heat shield	✓	\$ 165.00		
42	2	Rear plate lamp LH/RH	✓	\$ 250.00		
43	1	Rear number plate with frame	X		\$ 45.00	
44	1	Tailgate windscreen sealant	new ✓		\$ 80.00	
45	1	Tailgate windscreen inner seal	new ✓		\$ 80.00	
46	1	Rear end panel sealant	new ✓		\$ 80.00	
47	1	Reverse sensor	new ✓	200	\$ 300.00	
48	1	Spare tyre panel sealant	X		\$ 80.00	
49	1	Spare tyre panel padding	X		\$ 100.00	
50	1	Sundries	new ✓	30	\$ 60.00	
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

P=105
SN=470

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. :	SLD8248L
Vehicle Reg. Date:	6/29/2016
Make / Model :	H. VEZEL 1.5X CVT
Engine No. :	L15B4037546
Chassis No. :	RU11117543

Estimates on Labour

[illegible]
$$L = 2580$$

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18004054/T1VD3N2

Date: 25/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN1540021702	
Claimant Vehicle No :	SLD8248L	Insured Vehicle No :	SJT1116U	
Date of Loss:	28/02/2018	Nature of Claim:	TP	Claim No: SNM18D01103C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD8248L	Engine No:	L15B4037546
Make & Model:	HONDA VEZEL, 1.5 (A)	Chassis No:	RU11117543
Reg. Date:	29/06/2016 (Man. Year: 2016)	Odometer:	115016 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,620.76	5,219.68	5,401.08	50.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,700.00	2,580.00	1,120.00	30.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,320.76	7,799.68	6,521.08	45.54
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	14,320.76	6,200.00	8,120.76	56.71
+ GST 7.00/7.00% (S\$)	1,002.45	434.00	568.45	56.71
Nett Amount (S\$)	15,323.21	6,634.00	8,689.21	56.71

INSPECTION

Date of Assignment:	07/03/2018	Inspected At:	Vermogen Ace Pte Ltd (HQ)
Date Inspected:	02/03/2018		Blk B, 44 Benoi Rd
			Singapore 629904

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 25 May 2018)	
Parts: M1-SUV	HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code: (Unsubmitted, no print-code for SLD8248L)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*TAILGATE	Bent	1,860.00 FL	*1,100.90 FL
2	1	*TAILGATE OUTER GARNISH	Not Necessary	285.00 FL	*- FL
3	1	*SET TAILGATE OUTER GARNISH CLIPS	Not Necessary	40.00 FL	*- FL
4	1	*TAILGATE LOGO	Necessary	52.00 FL	*52.00 FL
5	1	*TAILGATE EMBLEM VEZEL	Necessary	56.20 FL	*56.20 FL
6	1	*TAILGATE LAMP RH	Not Necessary	490.00 FL	*- FL
7	1	*TAILGATE LAMP CLIPS	Not Necessary	50.00 FL	*- FL
8	1	*TAILGATE OUTER HANDLE SWITCH	Not Necessary	180.00 FL	*- FL
9	2	*TAILGATE DAMPER LH/RH	Not Necessary	424.00 FL	*- FL
10	1	*TAILGATE WIPER MOTOR	Not Necessary	250.00 FL	*- FL
11	1	*TAILGATE WIPER BLADE	Not Necessary	75.00 FL	*- FL
12	1	*TAILGATE BUZZER	Not Necessary	150.00 FL	*- FL
13	1	*TAILGATE INNER HANDLE	Not Necessary	74.00 FL	*- FL
14	1	*TAILGATE INNER LOCK	Bent	245.00 FL	*245.00 FL
15	1	*TAILGATE LOCK SENSOR	Distorted	220.00 FL	*220.00 FL
16	1	*TAILGATE STRIKER	Repair	32.00 FL	*- FL
17	1	*TAILGATE TRIMBOARD	Deformed	295.00 FL	*295.00 FL
18	1	*SET TAILGATE TRIMBOARD CLIPS	Necessary	45.00 FL	*45.00 FL
19	1	*TAILGATE WEATHERSTRIP	Twisted	145.00 FL	*145.00 FL
20	1	*SET TAILGATE WINDSCREEN MOULDING	Necessary	164.00 FL	*164.00 FL
21	1	*TAIL LAMP RH	Not Necessary	489.00 FL	*- FL
22	1	*SET TAIL LAMP CLIPS	Not Necessary	18.00 FL	*- FL
23	1	*REAR BUMPER	Deformed	950.00 FL	*885.00 FL
24	1	*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
25	2	*REAR BUMPER RETAINER LH/RH	Necessary	144.00 FL	*144.00 FL
26	2	*REAR BUMPER BRACKET LH/RH	Not Necessary	116.00 FL	*- FL
27	1	*REAR BUMPER REFLECTOR RH	Cut	167.00 FL	*167.00 FL
28	1	*REAR BUMPER COVER RH	Deformed	210.00 FL	*210.00 FL
29	1	*SET REAR BUMPER COVER CLIPS	Necessary	25.00 FL	*25.00 FL
30	2	*REAR BUMPER COVER RETAINER LH/RH	Necessary	84.00 FL	*84.00 FL
31	1	*REAR END PANEL OUTER	Bent	585.00 FL	*585.00 FL
32	1	*REAR END PANEL INNER	Repair	396.00 FL	*- FL
33	1	*REAR END PANEL TOP GARNISH	Deformed	184.00 FL	*184.00 FL
34	1	*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	25.00 FL	*25.00 FL
35	1	*SPARE TYRE PANEL	Repair	1,230.00 FL	*- FL
36	1	*SPARE TYRE PANEL INSULATOR	Necessary	240.00 FL	*240.00 FL
37	1	*SPARE TYRE PANEL TOP BOARD	Deformed	420.00 FL	*420.00 FL
38	1	*SPARE TYRE TOOL TRAY	Deformed	430.00 FL	*430.00 FL
39	1	*EXHAUST MUFFLER	Repair	855.00 FL	*- FL
40	1	*EXHAUST MUFFLER MOUNTING	Not Necessary	79.50 FL	*- FL
41	1	*EXHAUST MUFFLER HEAT SHIELD	Bent	165.00 FL	*165.00 FL
42	2	*REAR PLATE LAMP LH/RH	Not Necessary	250.00 FL	*- FL
43	1	*REAR NUMBER PLATE WITH FRAME	Not Necessary	45.00 FS	*- FS
44	1	*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*80.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	80.00 FS	*80.00 FS
46	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*80.00 FS
47	1		*REVERSE SENSOR	Not Working	300.00 FS	*200.00 FS
48	1		*SPARE TYRE PANEL SEALANT	Not Necessary	80.00 FS	*- FS
49	1		*SPARE TYRE PANEL PADDING	Not Necessary	100.00 FS	*- FS
50	1		*SUNDRIES	Necessary	60.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	13,069.70	6,407.10
- List Item Discount on L Items 20.00/20.00% (S\$)	2,448.94	1,187.42	
	Total Parts (S\$)	10,620.76	5,219.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.REAR PORTION	New	1,500.00	1,200.00
2	TO PUTTY,RESPRAY PAINTING AND POLISH ACCIDENT AREA.REAR PORTION	New	1,200.00	1,000.00
3	TO REMOVE AND TRANSFER TAILGATE COMPONENTS	New	150.00	60.00
4	TO REMOVE AND REFIT TAILGATE WINDSCREEN	New	150.00	120.00
5	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	30.00
6	TO RUST PROOF AFFECTED AREAS	New	200.00	40.00
7	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT	New	100.00	30.00
8	TO REMOVE AND REFIT INTERIOR PARTS TO GIVE WAY THE REPAIR	New	150.00	40.00
9	TO REMOVE AND ALIGNED EXHAUST PIPE	New	150.00	60.00
Gross Labour Cost (S\$)			3,700.00	2,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >