

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJX2413J

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 23/02/2018

TP Veh Reg No: SLM3053S

Estimate No: ES1890209/YISHUN

Date: 01 Mar 2018

Policy No: MPC17A00344300

Veh Reg No: SJX2413J

Make/Model: TOYOTA VIOS G AUTO

Chassis No: MR053HY9305169446

Engine No: 1NZY103573

Reg. Date: 26/05/2010

Estimate Repair Cost to Vehicle No :SJX2413J

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	576.10	1 PC	576.10	✓
2 REAR BUMPER LH SIDE RETAINER	92.80	1 PC	92.80	✓
3 REAR BUMPER LH REFLECTOR	98.10	1 PC	98.10	✓
4 REAR BUMPER CLIPS	3.89	6 PCS	23.34	✓
5 LH TAILLAMP	501.80	1 PC	501.80	✓
6 REAR BOOT	845.90	1 PC	845.90	✓
7 REAR BOOT LOGO	54.10	1 PC	54.10	✓
8 REAR BOOT EMBLEM (VIOS)	69.10	1 PC	69.10	✓
9 REAR BOOT EMBLEM (G)	58.30	1 PC	58.30	✓
10 REAR BOOT INNER LOCK	360.40	1 PC	360.40	✓
11 REAR PANEL	602.10	1 PC	602.10	?
			3,282.04	
		Less 25%	820.51	2,461.53
Special Net				
12 REVERSE SENSOR	200.00	1 PC	200.00	✓
			200.00	200.00
Labour				
13 PANEL BEATING	750.00	1 LA	750.00	600
14 PUTTY & RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER, REAR LH FENDER	750.00	1 LA	750.00	600
			1,500.00	1,500.00
Total				S\$ 4,161.53
Add GST @ 7%				291.31
Total Amount Payable				S\$ 4,452.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Acknowledged by Repairer

Signature:

Date: