

MOTORIMAGE ENTERPRISES PTE. LTD..
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0085/2016
DATE : 18-MAR-2016

INDIA INTERNATIONAL INSURANCE PTE LTD
64 CECIL STREET
#05-00
IOB BUILDING S(049711)
TEL : 63476100
FAX : 62244174

OWNER'S NAME : AMAT JEFNI BIN MOHAMED (98366949 NORLIN) * OPC *
ADDRESS : BLK 667B JURONG WEST STREET 65
#08-163
S(642667)
TELEPHONE NO : 9686 2044

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MT/00164516/01
VEHICLE NO : SJB06062
MODEL CODE : GD5GK4J
MODEL/YEAR : IMPREZA 1.6I 4D AWD 5MT
ENGINE NO : EJ16D136435
CHASSIS NO : JF1GD5KJ37G072190
MILEAGE : 126185 KM
DATE IN : 18/03/2016
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : WONG GUO XIANG
ACCIDENT DATE : 21/11/2015

Print Date : 21/03/2016
Print Time : 08:53:08

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SJB0606Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	REPLACE & REPAIR REAR BUMPER, LHS QUARTER PANEL	1680.00	5601
2	ZZ/002	RESPRAY REAR BUMPER, LHS QUARTER PANEL	1680.00	8401
3	ZZ/003	LTA INSPECTION FOR OPC - NUMBER PLATE	120.00	✓
4	ZZ/004	CONDUCT REAR LIGHTING TEST	100.00	4d
5	ZZ/005	TO CONDUCT REAR PORTION ANTI-RUST COATING	na 350.00	X
6	ZZ/006	TO CONDUCT REAR PORTION PROTECTANT COATING	na 300.00	Y
7	ZZ/007	SUNDRIES	100.00	?
TOTAL LABOUR CHARGES			4330.00	

Not Authorized

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey B4 point

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SJB0606Z

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 REAR BUMPER	57704FE170	540.00	✓	
2 REAR BUMPER BRACKET LH CORNER	57717FE460	25.20	—	
3 REAR BUMPER UPPER SIDE BRACKET LH	57717FE650	46.80	?	
4 TAIL LAMP ASSY RLH	84201FE600	374.00	?	
SUB TOTAL		986.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		197.20	0.00	0.00
GRAND TOTAL		788.80	0.00	0.00
OVERALL TOTAL		788.80		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SJB0606Z

TOTAL LABOUR CHARGES	4330.00
TOTAL SPARE PARTS CHARGES	788.80

GRAND TOTAL	5118.80 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.