

REF: ASM (AXA)

00852

ASSIGNMENT

From:

Date:

27042018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

EE 808B

at Workshop m/s

Kah Motor

of

No. 255 Alexandra Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)


Make of Veh:

Amika

(Policy Condition)

1130am.

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

69K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

EE 808B

Yr Regn:

2012 / MAY

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Odyssey 2.4A c.c. 235X

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

1024699

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMRB3850CC200845

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/55R17

R:

1"

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/02/18

D.O.I.

27/04/18

Survey held at

Kah Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PIP \$ 5310.87 (Reel \$ 2354.85 / 31%).

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|---------------------------|---|
| AXA INSURANCE PTE LTD | | Ref : CC4/ASM18004066/pb3 | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 | | Date : 02-03-2018 |  |
| | | Code : ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SLG 9696D | Veh. Inspected | EE 808B |
| Policy No. | | Coverage (\$) | 0.00 |
| Claim No. | | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 02/03/2018 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | | c.c | 0 |
| Engine No. | HIDDEN | Year of Reg. | |
| Chassis No. | | Colour | |
| Odometer | - | Steering | |
| Brakes | | Modification | |
| General | | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | | | mm |
| L/H Front Tyre | | | mm |
| R/H Rear Tyre | | | mm |
| L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | |
| | | | |
| 5. General Information | | | |
| Accident Date | 27/02/2018 | Inspection Date | |
| Survey held at | KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : EE808B
Chassis No : JHMRB3850CC200845
Model : ODYSSEY 2.4 EXV AUTO 12YM
Owner's Name : ISS INTERNATIONAL SCHOOL (S)
Ins Policy No :
Date of Accident : 27/2/2018

Document No. : SQT18000898
Date : 2. Mar 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24Z21721035
Date | Time : 2. Mar 2018 10:11:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|--|-------|---------------------------|--------|-------------------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: CHAN CHING OI OWNER INSURER: AXA INSURANCE ACC DATE: 27/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SLG9696D | | | | | | |
| BOSUN | SUNDRIES | net 1 | 50.00 ³⁰ | | 50.00 ³⁰ | 3.50 | 53.50 |
| BOJSE | SEALANT FOR TAILGATE | net 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOJSE | SEALANT FOR TAILGATE WINDSCREEN | net 2 | 80.00 | | 160.00 | 11.20 | 171.20 |
| BOJSE | SEALANT FOR REAR END PANEL | net 1 | 80.00 ^{7.4117} | | 80.00 | 5.60 | 85.60 |
| BKRP02M | CUT OFF & RENEW RR PANEL. STRAIGHTEN | 1 | 2250.00 ¹¹⁶⁰ | 20 | 1800.00 ⁹²⁸ | 126.00 | 1926.00 |
| BML02I | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER | 1 | 80.00 ^{XNA} | 20 | 64.00 | 4.48 | 68.48 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & | 1 | 350.00 ²⁸⁰ | 20 | 280.00 ²²⁴ | 19.60 | 299.60 |
| BG02D | REMOVE & INSTALL RR. WINDSCREEN (N) | 1 | 280.00 | 20 | 224.00 ²²⁴ | 15.68 | 239.68 |
| BODAMKIT | WINDSCREEN DAM KIT. | net 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BKBU01R | REMOVE/REFIT TAILGATE CAMERA TO ASSIST REPAIR (N) | 1 | 280.00 | 20 | 224.00 | 15.68 | 239.68 |
| BMI02D | REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR (N) | 1 | 225.00 ¹⁴⁰ | 20 | 180.00 ¹⁰ | 12.60 | 192.60 |
| BA02R | REMOVE/REFIT RR BUMPER SENSORS TO ASSIST REPAIR (N) | 1 | 100.00 | 20 | 80.00 | 5.60 | 85.60 |
| BP06R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 2200.00 ¹³⁵⁰ | 20 | 1760.00 ¹⁰⁵⁰ | 123.20 | 1883.20 |
| Sum Labor | | | | | 5062.00 | 354.34 | 5,416.34 |
| RS-4CS | 4PCS CORNER SENSOR W DISPLAY | 1 | 272.00 ^{? ant} | | 272.00 ¹⁸⁰ | 19.04 | 291.04 |
| BO-NUM-COMP-L | NUMBER PLATE WITH CASING-L(N) | 1 | 45.00 ^{X sue} | | 45.00 | 3.15 | 48.15 |
| 66100-SLE-300ZZ | PANEL COMP RR | 1 | 484.40 ^{? X sue} | 35 | 314.86 | 22.04 | 336.90 |



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : EE808B
Chassis No : JHMRB3850CC200845
Model : ODYSSEY 2.4 EXV AUTO 12YM
Owner's Name : ISS INTERNATIONAL SCHOOL (S)
Ins Policy No. :
Date of Accident : 27/2/2018

Document No. : SQT18000898
Date : 2. Mar 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24Z21721035
Date | Time : 2. Mar 2018 10:11:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-----------------|---------------------------|-----|------------|--------|---------|---------------|------------------|
| 73225-SLE-000 | RUBBERWINDSHIELD DAM | 1 | 22.00 | 35 | 14.30 | 1.00 | 15.30 |
| 73226-SLE-000 | RUBBERWINDSHIELD DAM | 1 | 19.60 | 35 | 12.74 | 0.89 | 13.63 |
| 73227-SLE-000 | MOLDINGRR.WINDSHIELD | 2 | 18.40 | 35 | 23.92 | 1.67 | 25.59 |
| 73228-SLE-000 | MOLDINGR.RR.WINDSHIELD | 1 | 17.10 | 35 | 11.11 | 0.78 | 11.89 |
| 73229-SLE-000 | SEAL ARR.WINDSHIELD | 2 | 2.00 | 35 | 2.60 | 0.18 | 2.78 |
| 73230-SLE-000 | SEAL BRR.WINDSHIELD | 2 | 0.80 | 35 | 1.04 | 0.07 | 1.11 |
| 73278-SLE-000 | MOULDINGL.RR.WINDSHIELD | 1 | 17.10 | 35 | 11.11 | 0.78 | 11.89 |
| 68100-SLE-010ZZ | TAIL GATE COMP | 1 | 1010.30 | 35 | 656.69 | 45.97 | 702.66 |
| 74440-SLE-003 | WEATHERSTRIPTAILGATE | 1 | 122.30 | 35 | 79.49 | 5.56 | 85.05 |
| 74895-SLE-J51 | GARN ASSYRR LICE | 1 | 184.40 | 35 | 119.86 | 8.39 | 128.25 |
| 74896-SLE-J51ZA | GARNISH SETTAILGATE LOWER | 1 | 414.90 | 35 | 269.68 | 18.88 | 288.56 |
| 84640-SLE-U01ZC | LINING ASSYRR.PANEL | 1 | 191.80 | 35 | 124.67 | 8.73 | 133.40 |
| 75701-SLE-003 | EMBLEM(H) | 1 | 28.20 | 35 | 18.33 | 1.28 | 19.61 |
| 75722-SLE-003 | EMBLEM(ODYSSEY) | 1 | 31.80 | 35 | 20.67 | 1.45 | 22.12 |
| 04715-SLE-900ZZ | FACERR.BUMPER | 1 | 714.90 | 35 | 464.68 | 32.53 | 497.21 |
| 33505-SLE-003 | REFLECTORR.RR. | 1 | 42.70 | 35 | 27.75 | 1.94 | 29.69 |
| 33555-SLE-003 | REFLECTORL.RR. | 1 | 42.70 | 35 | 27.75 | 1.94 | 29.69 |
| 71504-SLE-900ZD | COVERRR.TOWING HOOK | 1 | 15.90 | 35 | 10.33 | 0.72 | 11.05 |
| 71591-SFE-000ZZ | BRKT L RR BPR BEAM | 1 | 66.20 | 35 | 43.03 | 3.01 | 46.04 |
| 71593-SLE-003 | SPACERR.RR.BUMPER | 1 | 20.80 | 35 | 13.52 | 0.95 | 14.47 |
| 71598-SLE-003 | SPACERL.RR.BUMPER | 1 | 20.80 | 35 | 13.52 | 0.95 | 14.47 |
| 91505-S9A-003 | CLIP ABUMPER | 2 | 3.90 | 35 | 5.07 | 0.35 | 5.42 |
| Sum Item | | | | | 2603.72 | 182.25 | 2,785.97 |

Survey By

RASUL - Hp 90010068

Date & Time

27/04/18 @ 1130

Excess

5 clays

Status

Signature

Resony b4 print

Total Amount 7,665.72 536.59 8,202.31

Total (Inclusive of GST) 8,202.31

8494.48

Printed on 2/3/2018 2:06:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

8627.61



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : EE808B

Chassis No : JHMRB3850CC200845

Model : ODYSSEY 2.4 EXV AUTO 12YM

Owner's Name : ISS INTERNATIONAL SCHOOL (S)

Ins Policy No. :

Date of Accident : 27/2/2018

Document No. : SQT18000898 **Page** 3

Date : 2. Mar 2018

Customer No. : WZA006

Svc Advisor : PATRICK MOK LIP KAY

Engine No : K24Z21721035

Date | Time : 2. Mar 2018 10:11:55 AM

Surveyor Name :

Survey Date :

Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST | Amount |
|------|-------------|-----|------------|--------|--------|--------|----------|
| | | | | | | Amount | incl GST |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/3/2018 2:06:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.


GST Amount is calculated from individual line(s)

Service Request Details

Claim

S8M009O8

Reference

None 

Loss Date

February 27, 2018

Request Date

March 2, 2018

Due Date

March 9, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Agree to perform service

Vehicle Information

Incident Vehicle Registration #

EE808B

Make

TPVD HONDA

02032018 @ 2:45pm
Patrick van not in

Service Address

...

Primary Contact/Insured

LIM KOK SOON

9A SENGKANG EAST AVENUE, #03-31, 544743, Singapore

96961657

DLHAIRBEAUTY@HOTMAIL.COM

Claim Handler

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 7 May 2018 8:52 AM
To: Anikka Lai
Cc: assignments; Admin A
Subject: RE: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY *LKK REF: CC4/ASM18004066/R1pb3

Without Prejudice

Dear Sirs/ Madam,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation is subject to insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [mailto:anikkalai@honda.com.sg]
Sent: Friday, 4 May 2018 7:17 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY

Dear Xiao Tong,

Pls advise the outcome.

Thank you.

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
255 Alexandra Road
Singapore 159937
DID : 65145481
Email: anikkalai@honda.com.sg

From: Anikka Lai
Sent: Thursday, 3 May, 2018 7:35 PM
To: 'Hsiao Tong (LKKAuto)' <chewht@lkkauto.com>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY

Dear Xiao Tong,

Survey has done last week, pls advise the liability of direct settlement.

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
255 Alexandra Road
Singapore 159937
DID : 65145481
Email: anikkalai@honda.com.sg

From: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Sent: Thursday, 26 April, 2018 3:58 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Cc: assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: RE: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY

WITHOUT PREJUDICE

Hi Anikka,

As spoken earlier, we will arrange survey as follows: -

Date: 27 April 2018 (Friday)
Time: Btw 10am – 3PM

We will advise liability after survey done.

By copy to Catherine,

As spoken, kindly assist to arrange survey on tomorrow.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]

Sent: Wednesday, 25 April 2018 4:05 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: FW: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY

Dear Xiao Tong,

I have taken over this case from Patrick Mok.

Pls advise the liability of direct settlement, as the accident happened on Feb.

Thank you.

Warmest Regards

Anikka Lai

Kah Motor Co. Sdn Bhd

255 Alexandra Road

Singapore 159937

DID : 65145481

Email: anikkalai@honda.com.sg

From: Anikka Lai

Sent: Thursday, 19 April, 2018 12:09 PM

To: 'motor.survey@axa.com.sg' <motor.survey@axa.com.sg>; 'cst@axa.com.sg' <cst@axa.com.sg>

Subject: EE808B vs SLG9696D DOA: 27/2/2018 - CHECK LIABILITY

Dear Sir / Madam,

Attached pls find the GIA report and estimate cost of repair. Kindly advise the liability of direct settlement.


Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
255 Alexandra Road
Singapore 159937
DID : 65145481
Email: anikkalai@honda.com.sg

From: Printer Service
Sent: Thursday, 19 April, 2018 11:25 AM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Hsiao Tong (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 8 June 2018 3:02 PM
To: 'Anikka Lai'; Hsiao Tong (LKKAuto)
Cc: Admin A; assignments
Subject: FW: EE808U - FINALIZATION
Attachments: 3261_001.pdf; Resurvey B4 Paint & Item _ EE 808 B

Dear Anikka,

Thank you for your email.

Dear Hsiao Tong,

FYNA. Our Ref: CC4/ASM18004066/R1pb3

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]

Sent: Friday, 8 June, 2018 2:58 PM

To: assignments <assignments@lkkauto.com>

Subject: EE808U - FINALIZATION

Dear Catherine,

We enclosed the total final repair costs for,

| | |
|---|------------------|
| Vehicle No. | EE808U |
| Final Repair Costs (exclude GST) | \$5461.09 |
| Repair Period* (Days) | 5 days |

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you

Warmest Regards

Anikka Lai

Kah Motor Co. Sdn Bhd

255 Alexandra Road

Singapore 159937

DID : 6514 5481 HP : 8288 6302

Email: anikkalai@honda.com.sg

From: Printer Service

Sent: Friday, 8 June, 2018 2:54 PM

To: Anikka Lai <anikkalai@honda.com.sg>

Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRB3850CC200845
License No: EE808B
Mileage: 127275
Engine No: K24Z21721035

Document No: SVO18030956
Printed By: ANIKKALAI
Order Date: 30. May 2018
Order Time: 11:32:50 AM
Service Advisor: ANIKKA LAI SWEE KAM

| ITEM | DESCRIPTION | QTY | UNIT | DISC % | AMOUNT | 7% GST Amount | Amount incl GST |
|-----------------|---|-----|----------|--------|-----------------|---------------|-----------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: CHAN CHING OI OWNER INSURER: AXA INSURANCE ACC DATE: 27/02/2018 SURVEYED BY: RASUL / LKK DATE: 27/04/2018 REF NO: TP INSURER: AXA INSURANCE TP VEH: SLG9696D | | | | | | |
| RS-4P | BUMPER SENSOR 4PCS | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| 73225-SLE-000 | RUBBERWINDSHIELD DAM | 1 | 22.00 | 25 | 16.50 | 1.16 | 17.66 |
| 73226-SLE-000 | RUBBERWINDSHIELD DAM | 1 | 19.60 | 25 | 14.70 | 1.03 | 15.73 |
| 73227-SLE-000 | MOLDINGRR.WINDSHIELD | 2 | 18.40 | 25 | 27.60 | 1.93 | 29.53 |
| 73228-SLE-000 | MOLDINGR.RR.WINDSHIELD | 1 | 17.10 | 25 | 12.82 | 0.90 | 13.72 |
| 73229-SLE-000 | SEAL ARR.WINDSHIELD | 2 | 2.00 | 25 | 3.00 | 0.21 | 3.21 |
| 73230-SLE-000 | SEAL BRR.WINDSHIELD | 2 | 0.80 | 25 | 1.20 | 0.08 | 1.28 |
| 73278-SLE-000 | MOULDINGL.RR.WINDSHIELD | 1 | 17.10 | 25 | 12.82 | 0.90 | 13.72 |
| 68100-SLE-010ZZ | TAIL GATE COMP | 1 | 1,010.30 | 25 | 757.72 | 53.04 | 810.76 |
| 74895-SLE-J51 | GARN ASSYRR LICE | 1 | 184.40 | 25 | 138.30 | 9.68 | 147.98 |
| 74896-SLE-J51ZD | GARNISH SETTAILGATE LOWER | 1 | 414.90 | 25 | 311.17 | 21.78 | 332.95 |
| 75701-SLE-003 | EMBLEM(H) | 1 | 28.20 | 25 | 21.15 | 1.48 | 22.63 |
| 75722-SLE-003 | EMBLEM(ODYSSEY) | 1 | 31.80 | 25 | 23.85 | 1.67 | 25.52 |
| 04715-SLE-900ZZ | FACERR.BUMPER | 1 | 714.90 | 25 | 536.17 | 37.53 | 573.70 |
| 71504-SLE-900ZC | COVERRR.TOWING HOOK | 1 | 15.90 | 25 | 11.92 | 0.83 | 12.75 |
| 71593-SLE-003 | SPACERR.RR.BUMPER | 1 | 20.80 | 25 | 15.60 | 1.09 | 16.69 |
| 71598-SLE-003 | SPACERL.RR.BUMPER | 1 | 20.80 | 25 | 15.60 | 1.09 | 16.69 |
| 91505-S9A-003 | CLIP ABUMPER | 2 | 3.90 | 25 | 5.85 | 0.41 | 6.26 |
| BO-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 S | | 120.00 | 8.40 | 128.40 |
| 76707-STK-000 | SEALA | 1 | 6.40 S | 25 | 4.80 | 0.34 | 5.14 |
| 76830-SKN-E01 | JOINT ASSY WASHER | 1 | 11.10 S | 25 | 8.32 | 0.58 | 8.90 |
| | SUM PARTS: | | | | 2,239.09 | 156.73 | 2,395.82 |
| BOSUN | SUNDRIES | 1 | 30.00 | | 30.00 | 2.10 | 32.10 |
| BOJSE | SEALANT FOR TAILGATE | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |
| BOJSE | SEALANT FOR TAILGATE WINDSCREEN | 1 | 80.00 | | 160.00 | 11.20 | 171.20 |
| BKRP02M | 1729 CUT OFF & RENEW RR PANEL STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS. | 1 | 1,160.00 | 20 | 928.00 | 64.96 | 992.96 |
| BKTG02R | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N) | 1 | 280.00 | 20 | 224.00 | 15.68 | 239.68 |
| BG02D | 1757 REMOVE & INSTALL RR. WINDSCREEN. (N) | 1 | 280.00 | 20 | 224.00 | 15.68 | 239.68 |
| BODAMKIT | WINDSCREEN DAM KIT. | 1 | 80.00 | | 80.00 | 5.60 | 85.60 |



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

| | | | |
|--------------------|------------------------|-------------------------|---------------------|
| Customer: | WZA006 / AXA INSURANCE | Document No: | SVO18030956 |
| Chassis No: | JHMRB3850CC200845 | Printed By: | ANIKKALAI |
| License No: | EE808B | Order Date: | 30. May 2018 |
| Mileage: | 127275 | Order Time: | 11:32:50 AM |
| Engine No: | K24Z21721035 | Service Advisor: | ANIKKA LAI SWEE KAM |

| | | | | | | | |
|---------|--|----------------------------|----------|----|-----------------|---------------|-----------------|
| BKBU01R | REMOVE/REFIT TAILGATE CAMERA TO ASSIST REPAIR (N) | 1 | 280.00 | 20 | 224.00 | 15.68 | 239.68 |
| BMI02D | REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR (N) | 1 | 140.00 | 20 | 112.00 | 7.84 | 119.84 |
| BA02R | REMOVE/REFIT RR BUMPER SENSORS TO ASSIST REPAIR (N) | 1 | 100.00 | 20 | 80.00 | 5.60 | 85.60 |
| BP06R | 1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P) | 1 | 1,350.00 | 20 | 1,080.00 | 75.60 | 1,155.60 |
| | | SUM LABOUR: | | | 3,222.00 | 225.54 | 3,447.54 |
| | | TOTAL SGD | | | 5,461.09 | 362.27 | 5,843.36 |
| | | Total Payable (SGD) | | | | | 5,843.36 |

GST Amount is calculated from individual line(s)



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

| | | | | | |
|------------------|--------------------------------|--------------------|--------------------------|------|---|
| Customer | : ISS INTERNATIONAL SCHOOL (S) | Document No. | : SQT18002387 | Page | 1 |
| | 21 PRESTON ROAD | Date | : 8. Jun 2018 | | |
| | INTERNATIONAL SCHOOL | Customer No. | : WI018 | | |
| | SINGAPORE 109355 | Svc Advisor | : | | |
| Registration No | : EE808B | Engine No | : K24Z21721035 | | |
| Chassis No | : JHMRB3850CC200845 | Date Time | : 8. Jun 2018 2:47:11 PM | | |
| Model | : ODYSSEY 2.4 EXV AUTO 12YM | Surveyor Name | : | | |
| Owner's Name | : ISS INTERNATIONAL SCHOOL (S) | Survey Date | : | | |
| Ins Policy No. | : | Authorisation Date | : | | |
| Date of Accident | : | | | | |

| Item | Description | Qty | Unit Price | Disc % | Amount | 7% GST Amount | Amount incld GST |
|---------------|------------------------|-----|------------|--------|--------|---------------|------------------|
| O-WS-SEALANT | WINDSCREEN SEALANT (N) | 2 | 60.00 | 12% | 60.00 | 4.20 | 64.20 |
| 76707-STK-000 | SEALA | 1 | 6.40 | 25 | 4.80 | 0.34 | 5.14 |
| 76830-SKN-E01 | JOINT ASSY WASHER | 1 | 11.10 | 25 | 8.32 | 0.58 | 8.90 |
| Sum Item | | | | | 73.12 | 5.12 | 78.24 |

Survey By

Date & Time

Excess

Status

Signature

Total Amount 73.12 5.12 78.24

Total (Inclusive of GST) 78.24

Printed on 8/6/2018 2:50:15 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 13 August 2018 5:02 PM
To: 'Anikka Lai'
Cc: Rasul (LKKAuto); Admin A
Subject: RE: EE808U - FINALIZATION *LKK REF: CC4/ASM18004066/R1pb3
Attachments: 3261_001.pdf; Resurvey B4 Paint & Item _ EE 808 B

Without Prejudice

Hi Anikka,

We refer to the above matter.

According to surveyor, the below items is not consistent to the accident: -

- Garn Assyrr Lice
- Coverrr. Towing Hook

For COR, recommended amount at P/P 5,310.87(before GST) with 5 repair days.

Kindly confirm.

** Kindly forward your LOD with all the relevant documents(ie: final repair bill, authorisation to act, rental receipt) to us (LKK) for our necessary action.

Please note that all the finalisation subject to insurer approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 8 June 2018 3:02 PM
To: 'Anikka Lai' <anikkalai@honda.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>
Subject: FW: EE808U - FINALIZATION

Dear Anikka,

Thank you for your email.

Hsiao Tong (LKKAUTO)

From: Desmond Toh <desmondtoh@honda.com.sg>
Sent: Saturday, 25 August 2018 11:31 AM
To: Hsiao Tong (LKKAUTO)
Cc: Jerome Tan; Winson Chow
Subject: FW: LOD Submission of TPDS - Accident Involving EE808B and SLG9696D on 27/04/2018
Attachments: 4284_001.pdf

Your Ref: CC4/ASM18004066/R1pb3

Our Ref: EE808B

M/s: AXA Insurance Singapore Pte Ltd
C/o: LKK Auto Consultants Pte Ltd
8 Shenton Way
#27-01 AXA Tower
Singapore 068811
Attn: **Hsiao Tong, Chew | Case Handler**

Dear Hsiao Tong,

Above is the attached document for third party direct settlement claim.

Kindly provide us your finalized settlement & payment as your soonest.

Best Regards

Desmond Toh

Kah Motor Co Sdn Bhd

Website : www.honda.com.sg



Visit our
Facebook page



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



<SEEK MANDATE> - S8M009O8 [ACCIDENT INVOLVING SLG 9696D(OI) & EE 808B (TP) ON 27/02/2018]

Type

🔗 Question

Message

Liability: 100%. Insured rear-ended third party. Inform OI about third party claim. Agreed to settle and aware NCD issue. We seek your mandate up to \$6,453.03(all-in). IA with mandate had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 25 Aug 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607195R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 25.08.2018

Survey Details:

| | |
|---------------------|----------------------|
| Date of loss | 27.02.2018 |
| Date of appointment | 02.03.2018 |
| Date of survey | 27.04.2018 |
| Location of survey | KAH MOTOR.CO.SDN.BHD |

Vehicle Details:

| | |
|----------------------|--------------------------------|
| Claim Type: | Third party |
| Vehicle number | EE 808B |
| Make and Model | Honda Odyssey Sunroof (2354cc) |
| Date of registration | 02.05.2012 |
| Excess | NIL |
| Market Value | \$ 69,000.00 |
| Parf/COE Rebate | \$ 57,022.00 |
| Nett Loss | \$ 11,978.00 |

Repair details:

| | |
|------------------|-------------|
| Initial Estimate | \$ 7,665.72 |
|------------------|-------------|

Proposed/Revised repair cost:

| | |
|--------------------------------|--------------------|
| Parts | \$ 2,088.87 |
| Check items (estimate) | NIL |
| Labour | \$ 3,222.00 |
| Supplementary | NIL |
| Total | \$ 5,310.87 |
| Lump Sum(if applicable) | NIL |

| | |
|---------------------------|----------|
| Number of days for repair | <u>5</u> |
|---------------------------|----------|



Auto
Consultants
Pte Ltd

Company Registration No. 199607196R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Date: 25.08.2018

Remarks:

| |
|--|
| |
|--|

Mandate:

| Liability(TP) | 100% | |
|------------------------------|--------------------|--------------------|
| | | |
| Proposed repair cost (w/GST) | \$ 5,682.63 | |
| Loss of use | NIL | |
| Loss of rental (w/GST) | \$ 770.40 | (6days x \$120.00) |
| Loss of income | NIL | |
| LTA/GIA search fees | NIL | |
| Others | NIL | |
| Proposed Total | \$ 6,453.03 | |



Re:<SEEK MANDATE> - S8M009O8 [ACCIDENT INVOLVING SLG 9696D(OI) & EE 808B (TP) ON 27/02/2018]

Type

🔗 Question

Message

pls proceed

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

| | | | |
|-------------------|----------------------|--------|---------------------|
| Vehicle No: | SLG 9696D (Insd veh) | Model: | HONDA ODYSSEY 2.4 A |
| | EE 808B (TP veh) | | |
| Date of Accident: | 27/02/2018 | | |

| | | | |
|-----------------------|---|------------------------------|--|
| Global Sum Settlement | : | <input type="checkbox"/> Yes | <input checked="" type="checkbox"/> No |
| Repair Estimate | : | \$ | 9,231.54 |
| Final Repair Cost | : | \$ | 5,682.63 |
| Loss of Use | : | \$ | days at \$0.00 per day |
| Rental (if any) | : | \$ | 770.40 6 days |
| LTA / GIA Search Fee | : | \$ | |

| | | | |
|---------|---|----|--|
| Others: | : | \$ | |
|---------|---|----|--|

| | | | |
|----------------------|---|----|----------|
| | : | \$ | |
| Final Settlement Sum | : | \$ | 6,453.03 |

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: 27

BOLA Liability: 100 (%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

| Payment Instruction: Payee's Breakdown | | | |
|--|-------------------------|---|-------------|
| 1) | KAH MOTOR CO..SDN. BHD. | : | \$ 6,453.03 |

NUR SHAQILAH BTE ABDOL
WAHAB

12/02/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18004066/R1pb3s2

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 12-02-2019



ATTN: RICHARD ANG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|--------------|-------------|----------------|------------|
| Insured Veh. | SLG 9696D | Veh. Inspected | EE 808B |
| Policy No. | GA257894/1 | Coverage (\$) | 0.00 |
| Claim No. | S8M00908 | Excess (\$) | 0.00 |
| Assign From | RICHARD ANG | Assign Date | 02/03/2018 |

2. Vehicle Particulars & Condition

| | | | |
|--------------|---------------------|--------------|------------|
| Make & Model | HONDA ODYSSEY 2.4 A | c.c | 2354 |
| Engine No. | HIDDEN | Year of Reg. | 2012 |
| Chassis No. | JHMRB3850CC200845 | Colour | GREY |
| Odometer | 124699 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | FAIR | | |

3. Conditions of Tyres

| | Size | Make | Balance |
|----------------|-----------|--------|---------|
| R/H Front Tyre | 215/55R17 | DUNLOP | 6 mm |
| L/H Front Tyre | 215/55R17 | DUNLOP | 6 mm |
| R/H Rear Tyre | 215/55R17 | DUNLOP | 6 mm |
| L/H Rear Tyre | 215/55R17 | DUNLOP | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|----------------|----------------------|-----------------|------------|
| Accident Date | 27/02/2018 | Inspection Date | 27/04/2018 |
| Survey held at | NO. 255 ALEXANDRA RD | | |
| Repairer | KAH MOTOR.CO.SDN.BHD | | |

5a. Remarks

| |
|---|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|---|

5b. Estimate Days of Repair

| | |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|----------------|



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EE 808B

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|--------------------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 4 | CORNER SENSOR W DISPLAY (SN) (CONSISTENT) | CUT | 272.00 | 180.00 |
| 1 | NUMBER PLATE WITH CASING - L (SN) (CONSISTENT) | SERVICEABLE | 45.00 | - |
| 1 | PANEL COMP RR (SN) (CONSISTENT) | SERVICEABLE | 314.86 | - |
| 1 | RUBBERWINDSHIELD DAM (SN) (CONSISTENT) | NECESSARY | 16.50 | 16.50 |
| 1 | RUBBERWINDSHIELD DAM (SN) (CONSISTENT) | NECESSARY | 14.70 | 14.70 |
| 2 | MOLDINGRR.WINDSHIELD (SN) (CONSISTENT) | NECESSARY | 27.60 | 27.60 |
| 1 | MOLDINGR.RR.WNDSHIELD (SN) (CONSISTENT) | NECESSARY | 12.82 | 12.82 |
| 2 | SEAL ARR.WINDSHIELD (SN) (CONSISTENT) | NECESSARY | 3.00 | 3.00 |
| 2 | SEAL BRR.WINDSHIELD (SN) (CONSISTENT) | NECESSARY | 1.20 | 1.20 |
| 1 | MOULDINGL.RR.WINDSHIELD (SN) (CONSISTENT) | NECESSARY | 12.82 | 12.82 |
| 1 | TAIL GATE COMP (SN) (CONSISTENT) | BENT | 757.72 | 757.72 |
| 1 | WEATHERSTRIPTAILGATE (SN) (CONSISTENT) | SERVICEABLE | 79.49 | - |
| 1 | GARN ASSYRR LICE (CRACKED) (SN) (CONSISTENT) | NOT CONSISTENT WITH THE IMPACT | 119.86 | - |
| 1 | GARNISH SETTAILGATE LOWER (SN) (CONSISTENT) | CUT | 311.17 | 311.17 |
| 1 | LINING ASSYRR.PANEL. (SN) (CONSISTENT) | SERVICEABLE | 124.67 | - |
| 1 | EMBLEM (H) (SN) (CONSISTENT) | NECESSARY | 21.15 | 21.15 |
| 1 | EMBLEM (ODYSSEY) (SN) (CONSISTENT) | NECESSARY | 23.85 | 23.85 |
| 1 | FACERR.BUMPER (SN) (CONSISTENT) | DEFORMED | 536.17 | 536.17 |
| 1 | REFLECTORRR.RR. (SN) (CONSISTENT) | SERVICEABLE | 27.75 | - |
| 1 | REFLECTORL.RR. (SN) (CONSISTENT) | SERVICEABLE | 27.75 | - |
| 1 | COVERRR.TOWING HOOK (MISSING) (SN) (CONSISTENT) | NOT CONSISTENT WITH THE IMPACT | 10.33 | - |
| 1 | BRKT L RR BPR BEAM (SN) (CONSISTENT) | SERVICEABLE | 43.03 | - |
| 1 | SPACERR.RR.BUMPER (SN) (CONSISTENT) | NECESSARY | 15.60 | 15.60 |
| 1 | SPACERL.RR.BUMPER (SN) (CONSISTENT) | NECESSARY | 15.60 | 15.60 |
| 2 | CLIP ABUMPER (SN) (CONSISTENT) | NECESSARY | 5.85 | 5.85 |
| 1 | SUNDRIES (SN) (CONSISTENT) | NECESSARY | 50.00 | 30.00 |
| 1 | SEALANT FOR TAILGATE (SN) (CONSISTENT) | NECESSARY | 80.00 | 80.00 |
| 2 | SEALANT FOR TAILGATE WINDSCREEN (SN) (CONSISTENT) | NOT NECESSARY | 160.00 | 160.00 |
| 1 | SEALANT FOR REAR END PANEL (SN) (CONSISTENT) | NECESSARY | 80.00 | - |

Report Ref No. CC4/ASM18004066/R1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| 1 | WINDSCREEN DAM KIT (SN) (CONSISTENT) | NECESSARY | 80.00 | 80.00 |
| 2 | WINDSCREEN SEALANT (SN) (CONSISTENT) (ADDITIONAL) | NECESSARY | 120.00 | 120.00 |
| 1 | SEALA (SN) (CONSISTENT) (ADDITIONAL) | NECESSARY | 4.80 | 4.80 |
| 1 | JOINT ASSY WASHER (SN) (CONSISTENT) (ADDITIONAL) | NECESSARY | 8.32 | 8.32 |
| | | | 3,423.61 | 2,438.87 |
| | LABOUR | | | |
| | CUT OFF & RENEW RR PANEL. STRAIGHTEN. | | 2,250.00 | 928.00 |
| | INSPECT RR LIGHTING MECHANISMS. PERFORM WATER. | NOT NECESSARY | 80.00 | - |
| | REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &. | | 350.00 | 224.00 |
| | REMOVE & INSTALL RR. WINDSCREEN. | | 280.00 | 224.00 |
| | REMOVE / REFIT TAILGATE CAMERA TO ASSIST REPAIR. | | 224.00 | 224.00 |
| | REMOVE / REFIT BOOT TRIMS TO ASSIST REPAIR. | | 180.00 | 112.00 |
| | REMOVE / REFIT RR BUMPER SENSORS TO ASSIST REPAIR. | | 80.00 | 80.00 |
| | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. | | 1,760.00 | 1,080.00 |
| | | | 5,204.00 | 2,872.00 |
| | GRAND TOTAL | | 8,627.61 | 5,310.87 |
| RECOMMENDED COST OF REPAIRS | | | | 5,310.87 |

Report Ref No. CC4/ASM18004066/R1pb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.