



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

Registration No : EE808B

Chassis No : JHMRB3850CC200845

Model : ODYSSEY 2.4 EXV AUTO 12YM

Owner's Name : ISS INTERNATIONAL SCHOOL (S)

Ins Policy No. : -----

Date of Accident : 27/2/2018

Document No. : SQT18000898 Page 1

Date : 2. Mar 2018

Customer No. : WZA006

Svc Advisor : PATRICK MOK LIP KAY

Engine No : K24Z21721035

Date | Time : 2. Mar 2018 10:11:55 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHAN CHING OI OWNER INSURER: AXA INSURANCE ACC DATE: 27/02/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SLG9696D						
BOSUN	SUNDRIES	1	50.00	30	50.00	3.50	53.50
BOJSE	SEALANT FOR TAILGATE	1	80.00		80.00	5.60	85.60
BOJSE	SEALANT FOR TAILGATE WINDSCREEN	2	80.00		160.00	11.20	171.20
BOJSE	SEALANT FOR REAR END PANEL	1	80.00	?	80.00	5.60	85.60
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2250.00	1160?	1800.00	126.00	1926.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00	X 20	64.00	4.48	68.48
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	350.00	280	280.00	19.60	299.60
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00	/ 20	224.00	15.68	239.68
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00	/	80.00	5.60	85.60
BKBU01R	REMOVE/REFIT TAILGATE CAMERA TO ASSIST REPAIR (N)	1	280.00	/ 20	224.00	15.68	239.68
BMI02D	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR (N)	1	225.00	140?	180.00	12.60	192.60
BA02R	REMOVE/REFIT RR BUMPER SENSORS TO ASSIST REPAIR (N)	1	100.00	/ 20	80.00	5.60	85.60
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	2200.00	1350	1760.00	123.20	1883.20
Sum Labor					5062.00	354.34	5,416.34
RS-4CS	4PCS CORNER SENSOR W DISPLAY	1	272.00	?	272.00	19.04	291.04
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00	X	45.00	3.15	48.15
66100-SLE-300ZZ	PANEL COMP RR	1	484.40	35	314.86	22.04	336.90



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : EE808B
Chassis No : JHMRB3850CC200845
Model : ODYSSEY 2.4 EXV AUTO 12YM
Owner's Name : ISS INTERNATIONAL SCHOOL (S)
Ins Policy No :
Date of Accident : 27/2/2018

Document No. : SQT18000898 Page 2
Date : 2. Mar 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24Z21721035
Date | Time : 2. Mar 2018 10:11:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
73225-SLE-000	RUBBERWINDSHIELD DAM	1	22.00	35	14.30	1.00	15.30
73226-SLE-000	RUBBERWINDSHIELD DAM	1	19.60	35	12.74	0.89	13.63
73227-SLE-000	MOLDINGRR.WINDSHIELD	2	18.40	35	23.92	1.67	25.59
73228-SLE-000	MOLDINGR.RR.WINDSHIELD	1	17.10	35	11.11	0.78	11.89
73229-SLE-000	SEAL ARR.WINDSHIELD	2	2.00	35	2.60	0.18	2.78
73230-SLE-000	SEAL BRR.WINDSHIELD	2	0.80	35	1.04	0.07	1.11
73278-SLE-000	MOULDINGL.RR.WINDSHIELD	1	17.10	35	11.11	0.78	11.89
68100-SLE-010ZZ	TAIL GATE COMP	1	1010.30	35	656.69	45.97	702.66
74440-SLE-003	WEATHERSTRIPTAILGATE	1	122.30	35	79.49	5.56	85.05
74895-SLE-J51	GARN ASSYRR LICE	1	184.40	35	119.86	8.39	128.25
74896-SLE-J51ZA	GARNISH SETTAILGATE LOWER	1	414.90	35	269.68	18.88	288.56
84640-SLE-U01ZC	LINING ASSYRR.PANEL.	1	191.80	35	124.67	8.73	133.40
75701-SLE-003	EMBLEM(H)	1	28.20	35	18.33	1.28	19.61
75722-SLE-003	EMBLEM(ODYSSEY)	1	31.80	35	20.67	1.45	22.12
04715-SLE-900ZZ	FACERR.BUMPER	1	714.90	35	464.68	32.53	497.21
33505-SLE-003	REFLECTORR.RR.	1	42.70	35	27.75	1.94	29.69
33555-SLE-003	REFLECTORL.RR.	1	42.70	35	27.75	1.94	29.69
71504-SLE-900ZD	COVERRR.TOWING HOOK	1	15.90	35	10.33	0.72	11.05
71591-SFE-000ZZ	BRKT L RR BPR BEAM	1	66.20	35	43.03	3.01	46.04
71593-SLE-003	SPACERR.RR.BUMPER	1	20.80	35	13.52	0.95	14.47
71598-SLE-003	SPACERL.RR.BUMPER	1	20.80	35	13.52	0.95	14.47
91505-S9A-003	CLIP ABUMPER	2	3.90	35	5.07	0.35	5.42
Sum Item					2603.72	182.25	2,785.97

Survey By RASUL - Hp 90010068

Date & Time 27/04/18 @ 1130

Excess

Status

Signature

Total Amount 7,665.72 536.59 8,202.31

Total (Inclusive of GST) 8,202.31

Printed on 2/3/2018 2:06:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : EE808B
Chassis No : JHMRB3850CC200845
Model : ODYSSEY 2.4 EXV AUTO 12YM
Owner's Name : ISS INTERNATIONAL SCHOOL (S)
Ins Policy No. :
Date of Accident : 27/2/2018

Document No. : SQT18000898 **Page** 3
Date : 2. Mar 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : K24Z21721035
Date | Time : 2. Mar 2018 10:11:55 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/3/2018 2:06:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)