


SMRT Accident Vehicle Repair Estimates

China Taiping 64117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5745X
 Ref. No : TAX/02/18/2153
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : CHANG HOON SAM
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 25/02/2018 04:10:00 PM
 Accident Reported Date / Time : 26/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094798
 Special Instruction to ARC, if any :
 TOS /GY7872P - CHINA TAIPING - LKK
 Prepared Date : 28/02/2018 09:12:30 AM



Plants hence notify
 the following:
 before/after spray painting
 damaged part(s) during resurvey
 are subject to confirmation
 survey is on a "Without Prejudice" basis
 confirmation(s) is allowed
 item(s) must be resurveyed and
 approval from Insurance Company

Sebastian
 28/2/18

- Part by part repair
- Question mark Item Photo
- Photo Before Paint

Plants hence notify
 the following:
 before/after spray painting
 damaged part(s) during resurvey
 are subject to confirmation
 survey is on a "Without Prejudice" basis
 confirmation(s) is allowed
 item(s) must be resurveyed and
 approval from Insurance Company

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU103575818

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	338.00	0.00
Total Spray Painting Charges :	378.00	0.00
Total Material Charges :	437.92	437.92
Other Charges :	160.00	0.00
TOTAL :	1,313.92	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	3.00	0.00
Prepared / Adjusted By :		2 days
Arc / Surveyor Sign Off Date :	28/02/2018 02:56:06 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 28/02/2018 02:56:06 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 280
Total Spray Painting & Panel Beating	378.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 ✕
Total Other Costs	160.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace <i>A</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <input checked="" type="checkbox"/>	No <i>AKC</i>
TOTAL MATERIALS							437.93	437.92		
TOTAL MATERIALS(Discounted)							437.92	437.92		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									