

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8704P

DATE 1/3/2018 10:34

AKC

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender (RH) <i>X repair</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>X</i>			\$ 164.40
	Rear Windscreen Moulding <i>X</i>			\$ 60.00
	Rear Door (RH) <i>X repair</i>			\$ 1,351.10
	Rocker Panel Outer Garnish (RH) <i>X repair</i>			\$ 483.60
	Rear Tyre Rim (RH) <i>X</i>			\$ 351.90
	Rear Wheel Hup-Cap (RH) <i>✓</i>			\$ 150.70
	<i>Rear Bumper X repair</i>			
	SUB TOTAL			\$ 4,581.80
	LESS 20%			\$ 916.36
	DISCOUNTED TOTAL			\$ 3,665.44
	Rear Fender Advertisement Logo (RH) <i>✓</i>			\$ 100.00 Nett
	Rear Windscreen Sealant <i>X</i>			\$ 46.00 Nett
	Rear Door Advertisement Logo (RH) <i>✓</i>			\$ 100.00 Nett
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>✓</i>			\$ 80.00 Nett
				\$ 326.00
	Labour Charge			<i>4.00</i>
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00 <i>540</i>
	Wiring Charge			\$ 50.00 <i>X</i>
	Tuff Kote			\$ 50.00 <i>X</i>
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 <i>50</i>
	Remove/Refix Rear Windscreen Glass			\$ 120.00 <i>X</i>
	Remove/Refix Reverse Sensor			\$ 120.00 <i>X</i>
	Transfer of Door			\$ 120.00 <i>X</i>
	Rear Wheel Alignment			\$ 80.00 <i>X</i>
				\$ 2,140.00
				\$ 6,131.44

Katilly
M 1/3/2018
201
PIP
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and approved by the insurance company

TOTAL LABOUR
ESTIMATE TOTAL

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.