

Survivor:

## ASSIGNMENT (Office)

From (Person): Abdul Rahman of SPF Date/Time: 02/03/2018

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SLT 8175D Insured: QX 5611

at Workshop m/s Tan Chong Tel: 9456 8832

of 911 Bukit Timah

Policy No: Claim No: AEMD/105/009/2018/021

Sum Insured: Excess:

Make of Veh: D.O.A. 26/12/2018

(Client's Record) 08/03/2018 @ 4pm owner writing

CA/REV/REP./REV 24 HRS 'wp' H.O.D. Endorsement:

Date/Time: 02/03/2018 3:45pm Person Contacted: Lawrence Vehicle: IN/OUT

| Date/Time | Action/Instruction (✓) Estimate |
|-----------|---------------------------------|
|           | SLT 8175D - x                   |
|           | QX 5611 - x                     |

9/4/18 @ 11:30am Lawrence said vehicle has not send in for repair, pending liability

9/4/18 Submit preli report - vehicle has not send in for repair.

21/2/19 Final fig \$ 2442.82 (Red 3563.78, 599), 3 days

22/2/19 To re-open and submit final report Celine 27/2/19.

Upper Range (2k - 4k), pls pass to typist

28/2/19 re-open ref only \* LA DOC 12/4/18 \* ↓

Signature: *[Signature]*

REF:

00460

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD: TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No: SLT 817SD

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS *up*

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time / Action / Instruction

Veh No:

SLT 817SD

Regn: 2017 / NOV

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NISSAN SYLPHY 1600 cc 1598

Colour

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

4177

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MNT BBA B17200 36970

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/60R16

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.I.

TAN CHONG

N/S FR

RECEIVED 03 APR 2018

Date/Time, File Pass to?

☒ : Protl. Report

☐ : Final Report

Date/Time, File Return to?

2) *typist*

Report Format:

Lump Sum / I.B.I. (\$) *up*

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invc (\$)

☐ : Weekend (\$)

\$ + RS. \$

Phone

Copies

TOTAL

280

## Veron Chen (LKKAUTO)

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Thursday, 21 February 2019 5:48 PM  
**To:** Norsipah  
**Cc:** SUR; Admin A; Hsiao Tong (LKKAUTO); Shu Pei (LKKAUTO)  
**Subject:** RE: Finalization: SLT8175D / QX561U DOA 26.01.2018

Dear Sipah,

For claims against Singapore Police Force, we have instruction not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Norsipah <norsipah@tanchong.com>  
**Sent:** Thursday, 21 February 2019 2:52 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Subject:** RE: Finalization: SLT8175D / QX561U DOA 26.01.2018

Best Regards,  
Sipah

---

**From:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Sent:** 21 February 2019 14:00  
**To:** Norsipah <norsipah@tanchong.com>  
**Subject:** RE: Finalization: SLT8175D / QX561U DOA 26.01.2018

Dear Sipah,

Can re-forward finalise.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

**From:** Norsipah <norsipah@tanchong.com>

**Sent:** Thursday, 21 February 2019 1:53 PM

**To:** Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Shu Pei (LKKAuto) <shupe@lkkauto.com>

**Subject:** RE: Finalization: SLT8175D / QX561U DOA 26.01.2018

**Importance:** High

Hi

Please finalize soonest.

Thank you.

Best Regards,

Sipah

Tan Chong Motor Sales Pte Ltd

913 Bukit Timah Road

Singapore 589622

E: [norsipah@tanchong.com](mailto:norsipah@tanchong.com) D:+6567038915

Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

---

**From:** Norsipah

**Sent:** 18 October 2018 14:50

**To:** LKK Admin ([admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)) <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; LKK Surveyor ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; Taufikh@lkkauto.com

**Subject:** RE: Finalization: SLT8175D / QX561U DOA 26.01.2018

**Importance:** High

Hi,

Can finalize?

Best Regards,

Sipah

---

**From:** Norsipah

**Sent:** 31 July 2018 10:30

**To:** LKK Admin ([admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)) <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; LKK Surveyor ([sur@lkkauto.com](mailto:sur@lkkauto.com)) <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; 'Taufikh@lkkauto.com' <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>

**Subject:** FW: Finalization: SLT8175D / QX561U DOA 26.01.2018

**Importance:** High

Hi,

Please assist.

Best Regards,

Sipah

**From:** Norsipah  
**Sent:** 05 June 2018 13:51  
**To:** [Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)  
**Subject:** Finalization: SLT8175D / QX561U DOA 26.01.2018

Hi Taufikh

For your finalization.

Best Regards,  
Sipah  
Tan Chong Motor Sales Pte Ltd  
913 Bukit Timah Road  
Singapore 589622  
E: [norsipah@tanchong.com](mailto:norsipah@tanchong.com) D:+6567038915  
Website: [www.tanchong.com](http://www.tanchong.com) :: [www.nissan.com.sg](http://www.nissan.com.sg)

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0085/2018  
DATE : 02-MAR-2018

SPP ACCIDENT CLAIMS SECTION  
POLICE LOGISTICS DEPARTMENT  
NO.1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY S(298333)  
TEL : 64784840  
FAX : 64784848  
MR QUEK SWEE CHOON

OWNER'S NAME : MS LIONG JIA ZHEN CINDY (LIANG JIAZHEN)  
ADDRESS : BLK 480 JURONG WEST STREET 41  
#10-306  
S(640480)  
TELEPHONE NO : 81286678

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-QX561U  
VEHICLE NO : SLT8175D  
MODEL CODE : 82TARCEB17EWA----K  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017  
ENGINE NO : HR16917416C  
CHASSIS NO : HNTBBD1720030970  
MILEAGE : 1 KM  
DATE IN : 02/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 26/01/2018

*RAAN 1432*  
*ATTN: ABDUL RAHMAN*  
*02/03/18*  
**DIRECT SETTLEMENT**

*#1000*  
**OWNER CLAIMING LOSS OF USE / RENTAL**

**CAR AT WORKSHOP / CAR NOT AT WORKSHOP**

**KINDLY REVERT TO ME ASAP**

**EMAIL : lawrenceteo@tanchong.com**

**H/P : 94568832**

**FAX : 64697472**

*Like*

*an*  
*man*  
*4/18*

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT8175D

| S/NO JOB CODE        | NATURE OF JOB                                                                         | ESTIMATED CHARGES      | SURVEYOR'S RECOMMENDATION |
|----------------------|---------------------------------------------------------------------------------------|------------------------|---------------------------|
| 1 FRI                | FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION | 48.00                  | ✓                         |
| 2 RPI                | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL S120/PANEL X 02                  | <del>250.00</del> 120  | ✓                         |
| 3 SEALT              | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA                    | 100.00                 | X                         |
| 4 22/001             | REPAIR LH FRONT FENDER, LH SUPPORT AND RENEW FRONT BUMPER                             | <del>1500.00</del> 780 | ✓                         |
| 5 22/002             | S/PAINT FRONT BUMPER, LH FRONT FENDER AND LH SUPPORT                                  | <del>1000.00</del> 625 | ✓                         |
| TOTAL LABOUR CHARGES |                                                                                       | 2888.00                |                           |

TAN CHONG MOTOR SALES PTE. LTD.  
BUKIT TIMAH W/SHOP  
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SL78175D

|                                                       |              | DAMAGED PARTS & PRICES |      |                      |
|-------------------------------------------------------|--------------|------------------------|------|----------------------|
| S/NO PARTS DESCRIPTION                                | PARTS NUMBER | NETT                   | LIST | 5/NETT REMARKS       |
| 1 SUNDRIES                                            | NPN          |                        |      | ? 100.00 X <i>nm</i> |
| 2 EMBLEM RAD GRIL                                     | 62890-1KA0A  | 59.70 ?                |      | } X <i>nm</i>        |
| 3 CLIP AIR GUIDE \$1.30 EA X 02                       | 01553-09321  | 2.60 ?                 |      |                      |
| 4 GUIDE-LH                                            | 62823-3RA0A  | 175.50 ?               |      |                      |
| 5 BRKT RAD RH                                         | 62396-3SB0A  | 20.50 ?                |      |                      |
| 6 BRKT RAD LH                                         | 62397-3SB0A  | 15.20 ?                |      |                      |
| 7 RAD GRILLE                                          | 62312-3SB0A  | 700.70 ?               |      |                      |
| 8 CLIP BUMPER \$1.20 EA X 02                          | 01553-10501  | 2.40 ?                 |      |                      |
| 9 BRKT APRON LOWER                                    | 62663-3ST0A  | 181.80 ?               |      |                      |
| 10 ENERGY ABSORBER                                    | 62090-3ST0A  | 206.30 ?               |      |                      |
| 11 REINFORCE-BUMPE                                    | F2032-3STWR  | 512.40 ?               |      |                      |
| 12 BRKT BUMPER LH                                     | 62225-3ST1A  | 21.10 <i>re</i> ✓      |      |                      |
| 13 CROWNET BUMPER \$1.20 EA X 02                      | 01281-01431  | 2.40 <i>re</i> ✓       |      |                      |
| 14 FINISHER FR BUMPER FOG LAMP                        | 62257-9A75A  |                        |      | 41.50 ? X <i>nm</i>  |
| 15 FASCIA FR BUMPER                                   | 62022-9A76H  |                        |      | 472.30 <i>DE</i> ✓   |
| 16 GRILLE A FRT BUMPER                                | 62254-9A75A  |                        |      | 39.70 ? X <i>nm</i>  |
| 17 FOG LAMP LH                                        | B61E0-3ST0A  |                        |      | 559.40 ? X <i>nm</i> |
| 18 COVER A BUMPER                                     | 622A0-9A75H  |                        |      | 6.50 ? X <i>nm</i>   |
| 19 LAMP ASSY-LH                                       | 26060-3SB1C  | 473.40 <i>CA</i> ✓     |      |                      |
| SUB TOTAL                                             |              | 2374.00                | 0.00 | 1219.40              |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, 5/NETT-.00%) |              | 474.80                 | 0.00 | 0.00                 |
| GRAND TOTAL                                           |              | 1899.20                | 0.00 | 1219.40              |
| OVERALL TOTAL                                         |              | 3118.60                |      |                      |

LEGEND: REMARKS( OK ) = APPROVED; REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TINAH W/SHOP  
 SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO BLS175D

|                           |           |
|---------------------------|-----------|
| TOTAL LABOUR CHARGES      | 2888.00   |
| TOTAL SPARE PARTS CHARGES | 3118.60   |
| GRAND TOTAL               | 6006.60 * |

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

|                 |                     |
|-----------------|---------------------|
| NAME            | RASUL - Hp 90010068 |
| SURVEYED DATE   | 08/03/18 @ 1600     |
| AUTHORIZED DATE |                     |
| EXCESS CLAUSE   | 0.00 3 days         |
| LIABILITY       | 0.00                |
| REMARKS         | Resurvey of part    |

12/3/18

PLEASE NOTE: This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comps

Acknowledged by Repairer

Signature:

Date:

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

FINALIZED : ACCIDENT/BODY REPAIRS  
WORKSHOP : BUKIT TIMAH  
CONTACT NO : 4694091  
REFERENCE : INS/IC/LAW/0085/2018  
DATE : 02-MAR-2018

SPF ACCIDENT CLAIMS SECTION  
POLICE LOGISTICS DEPARTMENT  
NO.1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY S(298333)  
TEL : 64784840  
FAX : 64784848  
MR QUEK SNEE CHOON

OWNER'S NAME : MS LEONG JIA ZHEN CINDY (LIANG JIAZHEN)  
ADDRESS : BLK 480 JURONG WEST STREET 41  
#10-306  
S(640480)  
TELEPHONE NO : 81286678

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : TP-QX561U  
VEHICLE NO : SLT8175D  
MODEL CODE : BDTARCZD17EWA----K  
MODEL/YEAR : NISSAN SYLPHY 1.6 (CVT) MY2017  
ENGINE NO : HR16917416C  
CHASSIS NO : MNTBBAB1780030970  
MILEAGE : 1 KM  
DATE IN : 02/03/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : LAWRENCE  
ACCIDENT DATE : 26/01/2018

215

LKK

2/2/2018

Went  
\$100/day x 23  
= \$200 + tax  
= \$321/-

TAN CHONG MOTOR SALES PTE. LTD.  
 BUKIT TIMAH W/SHOP  
 SERVICE DEPARTMENT

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT8175D  
 -----

| S/NO                 | JOB CODE | NATURE OF JOB                                                                         | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATION |
|----------------------|----------|---------------------------------------------------------------------------------------|-------------------|---------------------------|
| 1                    | FHI      | FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION | 48.00             | 48.00                     |
| 2                    | RPI      | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 02                 | 240.00            | 120.00                    |
| 3                    | SEALI    | APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA                    | 100.00            | .00                       |
| 4                    | ZZ/001   | REPAIR LH FRONT FENDER, LH SUPPORT AND RENEW FRONT BUMPER                             | 1500.00           | 780.00                    |
| 5                    | ZZ/002   | S/PAINT FRONT BUMPER, LH FRONT FENDER AND LH SUPPORT                                  | 1000.00           | 625.00                    |
| TOTAL LABOUR CHARGES |          |                                                                                       | 2888.00           | 1573.00                   |

## TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT8175D

| S/NO PARTS DESCRIPTION                                | PARTS NUMBER | DAMAGED PARTS & PRICES |      |        | REMARKS |
|-------------------------------------------------------|--------------|------------------------|------|--------|---------|
|                                                       |              | NETT                   | LIST | S/NETT |         |
| 1 SUNDRIES                                            | NPN          |                        |      | 100.00 | X       |
| 2 EMBLEM RAD GRIL                                     | 62890-1KA0A  | 59.70                  |      |        | X       |
| 3 CLIP AIR GUIDE \$1.30 EA X 02                       | 01553-09321  | 2.60                   |      |        | X       |
| 4 GUIDE-LH                                            | 62823-3RA0A  | 175.50                 |      |        | X       |
| 5 BRKT RAD RH                                         | 62396-3SB0A  | 20.50                  |      |        | X       |
| 6 BRKT RAD LH                                         | 62397-3SB0A  | 15.20                  |      |        | X       |
| 7 RAD GRILLE                                          | 62312-3SB0A  | 700.70                 |      |        | X       |
| 8 CLIP BUMPER \$1.20 EA X 02                          | 01553-10501  | 2.40                   |      |        | X       |
| 9 BRKT APRON LOWER                                    | 62663-3ST0A  | 181.80                 |      |        | X       |
| 10 ENERGY ABSORBER                                    | 62090-3ST0A  | 206.30                 |      |        | X       |
| 11 REINFORCE-BUMPE                                    | P2032-3STMH  | 512.40                 |      |        | X       |
| 12 BRKT BUMPER LH                                     | 62225-3ST1A  | 21.10                  |      |        | OK      |
| 13 GROMMET BUMPER \$1.20 EA X 02                      | 01281-01431  | 2.40                   |      |        | OK      |
| 14 FINISHER FR BUMPER POG LAMP                        | 62257-9A75A  |                        |      | 41.50  | X       |
| 15 FASCIA FR BUMPER                                   | 62022-9A76H  |                        |      | 472.30 | OK      |
| 16 GRILLE A FRT BUMPER                                | 62254-9A75A  |                        |      | 39.70  | X       |
| 17 POG LAMP LH                                        | B61E0-3ST0A  |                        |      | 559.40 | X       |
| 18 COVER A BUMPER                                     | 622A0-9A75H  |                        |      | 6.50   | X       |
| 19 LAMP ASSY-LH                                       | 26060-3SB1C  | 473.40                 |      |        | OK      |
| SUB TOTAL                                             |              | 496.90                 | 0.00 | 472.30 |         |
| LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%) |              | 99.38                  | 0.00 | 0.00   |         |
| GRAND TOTAL                                           |              | 397.52                 | 0.00 | 472.30 |         |
| OVERALL TOTAL                                         |              | 869.82                 |      |        |         |

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.  
911, BUKIT TIMAH ROAD  
SINGAPORE 589623

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLT8175D

|                           |         |
|---------------------------|---------|
| NETT ITEM                 | 496.90  |
| LESS 20.00%)              | -99.38  |
| NETT AMOUNT               | 397.52  |
| LIST ITEM                 | 0.00    |
| LESS 30.00%)              | 0.00    |
| LIST AMOUNT               | 0.00    |
| SPECIAL NETT ITEM         | 472.30  |
| LESS .00%)                | 0.00    |
| SPECIAL NETT AMOUNT       | 472.30  |
| TOTAL LABOUR CHARGES      | 1573.00 |
| TOTAL SPARE PARTS CHARGES | 869.82  |
| TOTAL CHARGES             | 2442.82 |
| ADD 7 % GST               | 171.00  |
| GRAND TOTAL               | 2613.82 |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGINEERING & MGT DIVISION

Ref : CS/SPF18004075/R1vbn2

ACCIDENT CLAIM SECTION  
(SINGAPORE POLICE FORCE)  
1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY SINGAPORE 298333

Date : 28-02-2019



Code : SPF

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                       |                |            |
|--------------|-----------------------|----------------|------------|
| Insured Veh. | QX 561U               | Veh. Inspected | SLT 8175D  |
| Policy No.   |                       | Coverage (\$)  | 0.00       |
| Claim No.    | AEMD/105/009/2018/021 | Excess (\$)    | 0.00       |
| Assign From  | ABDUL RAHMAN          | Assign Date    | 02/03/2018 |

## 2. Vehicle Particulars & Condition

|              |                       |              |            |
|--------------|-----------------------|--------------|------------|
| Make & Model | NISSAN SYLPHY 1.6 CVT | c.c          | 1598       |
| Engine No.   | HIDDEN                | Year of Reg. | 2017       |
| Chassis No.  | MNTBBAB17Z0030970     | Colour       | BLUE       |
| Odometer     | 4177                  | Steering     | IN ORDER   |
| Brakes       | IN ORDER              | Modification | SPORTS RIM |
| General      | FAIR                  |              |            |

## 3. Conditions of Tyres

|                | Size       | Make        | Balance |
|----------------|------------|-------------|---------|
| R/H Front Tyre | 195/60 R16 | BRIDGESTONE | 6 mm    |
| L/H Front Tyre | 195/60 R16 | BRIDGESTONE | 6 mm    |
| R/H Rear Tyre  | 195/60 R16 | BRIDGESTONE | 6 mm    |
| L/H Rear Tyre  | 195/60 R16 | BRIDGESTONE | 6 mm    |

## 4. Description of Damages

|                                                                                 |
|---------------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS. |
|---------------------------------------------------------------------------------|

## 5. General Information

|                |                                                                            |                 |            |
|----------------|----------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 26/01/2018                                                                 | Inspection Date | 08/03/2018 |
| Survey held at | TAN CHONG MOTOR SALES PTE LTD<br>911, BUKIT TIMAH RD,<br>SINGAPORE 589623. |                 |            |

## 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 3 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLT 8175D

| Qty                         | Description of Parts                                                                  | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|---------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                                       |               |                           |                   |
| 1                           | EMBLEM RAD GRIL (N)                                                                   | NOT NECESSARY | 59.70                     | -                 |
| 2                           | CLIP AIR GUIDE @\$1.30 (N)                                                            | NOT NECESSARY | 2.60                      | -                 |
| 1                           | GUIDE-LH (N)                                                                          | NOT NECESSARY | 175.50                    | -                 |
| 1                           | BRKT RAD RH (N)                                                                       | NOT NECESSARY | 20.50                     | -                 |
| 1                           | BRKT RAD LH (N)                                                                       | NOT NECESSARY | 15.20                     | -                 |
| 1                           | RAD GRILLE (N)                                                                        | NOT NECESSARY | 700.70                    | -                 |
| 2                           | CLIP BUMPER @\$1.20 (N)                                                               | NOT NECESSARY | 2.40                      | -                 |
| 1                           | BRKT APRON LOWER (N)                                                                  | NOT NECESSARY | 181.80                    | -                 |
| 1                           | ENERGY ABSORBER (N)                                                                   | NOT NECESSARY | 206.30                    | -                 |
| 1                           | REINFORCE-BUMPE (N)                                                                   | NOT NECESSARY | 512.40                    | -                 |
| 1                           | BRKT BUMPER LH (N)                                                                    | NECESSARY     | 21.10                     | 21.10             |
| 2                           | GROMMET BUMPER @\$1.20 (N)                                                            | NECESSARY     | 2.40                      | 2.40              |
| 1                           | LAMP ASSY-LH (N)                                                                      | CRACKED       | 473.40                    | 473.40            |
|                             | LESS 20% DISCOUNT                                                                     |               | -474.80                   | -99.38            |
|                             |                                                                                       |               | 1,899.20                  | 397.52            |
| <b>SPECIAL NETT ITEMS</b>   |                                                                                       |               |                           |                   |
| 1                           | SUNDRIES (SN)                                                                         | NOT NECESSARY | 100.00                    | -                 |
| 1                           | FINISHER FR BUMPER FOG LAMP (SN)                                                      | NOT NECESSARY | 41.50                     | -                 |
| 1                           | FASCIA FR BUMPER (SN)                                                                 | DEFORMED      | 472.30                    | 472.30            |
| 1                           | GRILLE A FRT BUMPER (SN)                                                              | NOT NECESSARY | 39.70                     | -                 |
| 1                           | FOG LAMP LH (SN)                                                                      | NOT NECESSARY | 559.40                    | -                 |
| 1                           | COVER A BUMPER (SN)                                                                   | NOT NECESSARY | 6.50                      | -                 |
|                             |                                                                                       |               | 1,219.40                  | 472.30            |
| <b>LABOUR</b>               |                                                                                       |               |                           |                   |
|                             | FOCUS & ADJUST H/LAMP,RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION. |               | 48.00                     | 48.00             |
|                             | PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.                                 |               | 240.00                    | 120.00            |
|                             | APPLY SEALANT TO ALL AFFECTED PANEL JOINT & RESEAL NECESSARY AREA.                    | NOT NECESSARY | 100.00                    | -                 |
|                             | REPAIR LH FRONT FENDER,LH SUPPORT AND RENEW F                                         |               | 1,500.00                  | 780.00            |

Report Ref No. CS/SPF18004075/R1vbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty                         | Description of Parts                                  | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------------------------|-----------|---------------------------|-------------------|
|                             | S/PAINT FRONT BUMPER, LH FRONT FENDER AND LH SUPPORT. |           | 1,000.00                  | 625.00            |
|                             |                                                       |           | 2,888.00                  | 1,573.00          |
| GRAND TOTAL                 |                                                       |           | 6,006.60                  | 2,442.82          |
| RECOMMENDED COST OF REPAIRS |                                                       |           |                           | 2,442.82          |

Report Ref No. CS/SPF18004075/R1vbn2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$4,000

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.