

15/05/00

INSURANCE CASE OWNER:

Sharon

CC6 / CTI18004076 / AK5332

LKK:

IDAC:

Surveyor:

ADRIAN

DOI:

01/02/18

Date / Time:

01/03/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJH 1912B

Claim No.:

SNM18D00825C02

Name of Insured:

SKYLINK AXO PTE LTD

Policy No.:

DMTPSN17SL741700

Insured Tel No.:

HP:

Make / Model:

HONDA CIVIC - 1.6 (A)

Excess Sec II :SS

D.O.A.:

09/02/18

Place of Accident:

PIE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: FONG KAH LENG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.: 899-81531

(V/L: YES / NO)

Insured Liability:

%

Final? Yes / No

SDG 955



INSRS:

WSP: 1st Answer/CS

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time	STAGE	DATE / PIC
SDG 955 - X	Non-Reporting ltr (1st):	
SJH 1912B - CS/CTI18002767/10/13 con 09/02/18	Non-Reporting ltr (2nd):	
J- NATENC18002761/14 con 09/02/18	Non-Reporting ltr (Final):	
# Pending Est & PA	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List: Handler	Typist
	Notification ltr (if non-pickup)	
07-03-18 4/1 IS LIABLE FOR 1st VEH, 3RD VEHICLE IS LIABLE TO 4/1 VEH IN LINE WITH BOLA SCENARIO.	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
3032018 Seek further information from CTI via email.	Final Repair Bill:	
	Car Rental Invoice:	
10042018 File pacs to work on to close.	Towing Invoice	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

SS

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

SS

LOR + LOU

SS

LOR + LOU

SS

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

18400.00

COPY SENT
09/04/18

RECEIVED 10 APR 2018

Reject Case

By (staff):

Sharon

Approved by:

Sharon

Date:

10-04-18

REF:

Suzuki

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: - % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SD6958 Yr Regn: 2017, Jan.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Astra

c.c 1399

Colour: Red.

A/C: Insured / Std / NI / NA

Sp. Reading: 24220

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

01/03/18

Survey held at:

1st Autowork.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Claim.

P/p 3.345.40

(Red: \$5938.60 / 64%)

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others:

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18004076/Aks3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 02-03-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJH 1912B		Veh. Inspected	SDG 95S
Policy No.	DMTPSN1754741700		Coverage (\$)	0.00
Claim No.	SNM18D00835C02		Excess (\$)	0.00
Assign From			Assign Date	02/03/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	09/02/2018		Inspection Date	01/03/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 1/3/2018

Reference: SDG95S
OPEL ASTRA
Make: HB 1.4 AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SDG95S
CHASSIS NO.:W0LBE6EC6HG002692
ENGINE NO.:B1162297GSGX0079

Name of insured :NG TIM PENG
Date of accident.: 09/02/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Front Bumper <i>Regrd</i>	\$ 1,600.00
2	1	RHF Fender <i>Dented</i>	\$ 426.00
3	1	RHF Headlamp <i>None</i>	\$ 1,200.00
4	1	RHF Bumper Bracket <i>None</i>	\$ 65.00
5	1	RH Wind Mirror Cover <i>Missing</i>	\$ 120.00
6	1	RH Wind Mirror Assy <i>Part</i>	\$ 360.00
7	1	RH Wind Mirror Glass <i>None</i>	\$ 208.00
8	1	RHF Bumper Guide <i>None</i>	\$ 65.00

906
815.40
Parts Total: \$ 4,044.00
Less 10%: \$ 404.40
Total : \$ 3,639.60

Labour

Labour Description

No.	Labour Description	Price (SGD)
<u>Front portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 3,250.00
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 2,200.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00
4	To refocus headlamp	\$ 80.00

2530
Labour Total : \$ 5,560.00

Others

Other Description

No.	Qty		Price (SGD)
Front portion			
1	10	Front bumper clip <i>Abel</i>	\$ 65.00
2	3	RHF Fender Liner Clip <i>Abel</i>	\$ 19.50

Other Total: \$ 84.50

GRAND TOTAL: \$ 9,284.10

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully


Suhaimi Ong

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian Lj
P/P 01/03/18

038mp

total 3345 40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shirley Hiew (LKK Auto)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Monday, 5 March 2018 11:03 AM
To: Shirley Hiew (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving SJH1912B (OI : CTI - SNM18D00835C02) AND SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

Hi Shirley,

As spoken, kindly refer to the above subject for your reference.

Regards,

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6181
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Monday, 5 March, 2018 11:01 AM
To: Lucas Lee
Subject: FW: Direct Settlement - Accident Involving SJH1912B (OI : CTI - TBA) AND SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

Dear Lucas,

Kindly Provide us your claim no.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)
Sent: Monday, 5 March 2018 10:04 AM
To: Sharon Tan <sharon.tan@directasia.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; 'claimsdept@sg.cntaiping.com' <claimsdept@sg.cntaiping.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>
Subject: FW: Direct Settlement - Accident Involving SJH1912B (OI : CTI - TBA) AND SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

Dear Sharon,

Thanks and noted.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Han [<mailto:sharon.han@sg.cntaiping.com>]

Sent: Monday, 5 March 2018 9:43 AM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>

Subject: RE: Direct Settlement - Accident Involving SJH1912B (OI : CTI - TBA) AND SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

Dear Shirley,

Our insured's report attached.

Thank you & regards

Sharon Han

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-02

Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6193

Fax: 6224 7175 / 6224 7478

Email: claimsdept@sg.cntaiping.com

sharon.han@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer : This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]

Sent: Monday, 5 March, 2018 8:59 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>

Subject: Direct Settlement - Accident Involving SJH1912B (OI : CTI - TBA) AND SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SDG 95S at M/s First Autoworks Pte Ltd – Kaki Bukit.

Enclosed for your perusal is:
TP GIA report

We will revert preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841 2132.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Zaini (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Friday, 23 March 2018 12:10 PM
To: Zaini (LKK Auto)
Cc: Hsiao Tong (LKKAuto); Admin A; Alfred Toh; Angie Foo; Sharon Han
Subject: RE: OUR REF: SNM18D00835C02/2/LKKDS & YR SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

WITHOUT PREJUDICE

Dear Zaini

Please proceed to reject the claim (refer BOLA scenario 15(a) and 28(d)).

Our insured is not liable to losses incurred by SDG95S.

Thank you.

Regards,

Adeline Chng

Executive
Claims Department (Motor Division)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 63896155
Fax: 62247478/62247175
Email: adeline.chng@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



Please consider the environment before printing this email

From: Zaini (LKK Auto) [mailto:Zaini@lkkauto.com]
Sent: Friday, 23 March, 2018 11:10 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>
Subject: RE: OUR REF: SNM18D00835C02/2/LKKDS & YR SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

WITHOUT PREJUDICE

Dear Sharon,

We refer to our email dated 13.03.2018.

Kindly let us have your approval/ instruction as third party (**1st Autoworks Pte Ltd**) is chasing for liability clearance.

Thank you.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Zaini (LKK Auto)

Sent: Tuesday, 13 March 2018 4:14 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Sharon Han <sharon.han@sg.cntaiping.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adeline Chng <adeline.chng@sg.cntaiping.com>; 'alfred.toh@sg.cntaiping.com' <alfred.toh@sg.cntaiping.com>; 'Angie Foo' <angie.foo@sg.cntaiping.com>

Subject: RE: OUR REF: SNM18D00835C02/2/LKKDS & YR SDG95S (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

WITHOUT PREJUDICE

Your Ref: SNM18D00835C02/2

Our Ref: CC6/CTI18004076/Aks3

Dear Sharon,

ACCIDENT INVOLVING VEHICLES SJH 1912B / SDG 95S / OTHERS ON 09/02/2018


We refer to the above matter.

TP reported that he was travelling on 2nd lane when OI vehicle cut into his lane and collided onto TP vehicle. Enclosed copy of TP CCTV footage for your further review.

OI reported that he was unable to stop in time and steered left immediately, resulting in a collision with TP vehicle. OI further stated that TP vehicle was driving from the left lane and the collision caused damages to his right main headlight, front right bumper and left side mirror. No CCTV footage provided by OI till date.

We had spoken to the OID where he confirmed that at the material time, he was travelling within his lane at the said location as reported when he suddenly change lane to avoid collision with the front vehicle. OID further mentioned that he was not fully aware if TP vehicle was travelling from the 2nd lane or 1st lane prior to the collision. However, OID informed that TP vehicle was positioned on his left immediately after the collision took place.

In view of the available evidences on hand, we opined that the above accident best fit the below BOLA SCENARIO as follows;

	SCENARIO	DESCRIPTION
28.		<p>Driver of the vehicle behind 100% liable for losses including vehicle immediately in front</p> <p>Reason: To avoid costly collision damages</p>

For your further instructions.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(406933)

From: Angie Foo [<mailto:angie.foo@sg.cntaiping.com>]

Sent: Thursday, 8 March 2018 4:01 PM

To: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>;

Sharon Han <sharon.han@sg.cntaiping.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Adeline Chng

<adeline.chng@sg.cntaiping.com>

Subject: OUR REF: SNM18D00835C02/2/LKKDS & YR SDG955 (TP : LKK REF - CC6/CTI18004076/Aks3) on 09/02/2018

Dear Shirley,

We refer to your email of 5th March 2018.

We attached our Insured's SAS Report and SKB9907J Third party report for your necessary action.

Please be advised that we are unable to issue LKK assignment letter to due motor-trade policy for this vehicle SJH1912B.

Kindly take note, the claim handler on this case is Sharon Han 63896193.

Thank you.

Regards,

Angie Foo

Executive

Motor Division

Claims Department

China Taiping Insurance (Singapore) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Co.Reg.No.200208384E

DID: 6389 6186

Fax: 6224 7478 /6224 7175

Email: angie.foo@sg.cntaiping.com

Email: claimsdept@sg.cntaiping.com

Website: www.sg.cntaiping.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18004076/Aka3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-04-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 1912B	Veh. Inspected	SDG 95S
Policy No.	DMTPSN1754741700	Coverage (\$)	0.00
Claim No.	SNM18D00835C02/2	Excess (\$)	0.00
Assign From		Assign Date	01/03/2018

2. Vehicle Particulars & Condition

Make & Model	OPEL ASTRA	c.c	1399
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	W0LBE6EC6HG002692	Colour	RED
Odometer	24220	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	MICHELIN	6 mm
L/H Front Tyre	225/45R17	MICHELIN	6 mm
R/H Rear Tyre	225/45R17	MICHELIN	6 mm
L/H Rear Tyre	225/45R17	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/02/2018	Inspection Date	01/03/2018
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING) SINGAPORE 415933		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDG 95S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	1,600.00	-
1	RHF FENDER	DENTED	426.00	426.00
1	RHF HEADLAMP	NOT NECESSARY	1,200.00	-
1	RHF BUMPER BRACKET	NOT NECESSARY	65.00	-
1	RH WIND MIRROR COVER	MISSING	120.00	120.00
1	RH WIND MIRROR ASSY	BENT	360.00	360.00
1	RH WIND MIRROR GLASS	NOT NECESSARY	208.00	-
1	RHF BUMPER GUIDE	NOT NECESSARY	65.00	-
	LESS 10% DISCOUNT		-404.40	-90.60
			3,639.60	815.40
	SPECIAL NETT ITEMS			
10	FRONT BUMPER CLIP (SN)	NOT NECESSARY	65.00	-
3	RHF FENDER LINER CLIP (SN)	NOT NECESSARY	19.50	-
			84.50	-
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		3,250.00	1,300.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA.		2,200.00	1,200.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REFOCUS HEADLAMP.	NOT NECESSARY	80.00	-
			-	-
			-	-
			-	-
			5,560.00	2,530.00
	GRAND TOTAL		9,284.10	3,345.40

Report Ref No. CC6/CTI18004076/Aka3s2



RECOMMENDED COST OF REPAIRS			3,345.40
-----------------------------	--	--	----------

Report Ref No. CC6/CT118004076/Aka3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.