

1st Autoworks Pte Ltd  
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 1/3/2018

Reference: SDG95S  
OPEL ASTRA  
Make: HB 1.4 AT

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SDG95S  
CHASSIS NO.:W0LBE6EC6HG002692  
ENGINE NO.:B1162297GSGX0079

Name of insured :NG TIM PENG  
Date of accident.: 09/02/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Front Bumper <i>Payu</i>	\$ 1,600.00 <i>+</i>
2	1	RHF Fender <i>Painted</i>	\$ 426.00 <i>✓</i>
3	1	RHF Headlamp <i>new</i>	\$ 1,200.00 <i>+</i>
4	1	RHF Bumper Bracket <i>new</i>	\$ 65.00 <i>+</i>
5	1	RH Wind Mirror Cover <i>Missing</i>	\$ 120.00 <i>✓</i>
6	1	RH Wind Mirror Assy <i>But</i>	\$ 360.00 <i>✓</i>
7	1	RH Wind Mirror Glass <i>new</i>	\$ 208.00 <i>+</i>
8	1	RHF Bumper Guide <i>new</i>	\$ 65.00 <i>+</i>

906  
815.40  
Parts Total: \$ 4,044.00  
Less 10%: \$ 404.40  
Total : \$ 3,639.60

Labour

No.	Labour Description	Price (SGD)
<u>Front portion</u>		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 per day)	\$ 3,250.00 <i>1300</i>
2	Carry out spray painting on accident affected area (\$550 per panel)	\$ 2,200.00 <i>1200</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00 <i>✓</i>
4	To refocus headlamp	\$ 80.00 <i>+</i>

2830  
Labour Total : \$ 5,560.00

Others

Other Description

<u>No.</u>	<u>Qty</u>		<u>Price (SGD)</u>
<u>Front portion</u>			
1	10	Front bumper clip <i>new</i>	\$ 65.00
2	3	RHF Fender Liner Clip <i>new</i>	\$ 19.50

Other Total: \$ 84.50

GRAND TOTAL: \$ 9,284.10

**NB:** THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

  
Suhaimi Ong

Service Executive  
Suhaimi Ong  
HP : 8298 8933 Fax:6844 5185

*Adrian Lj*  
*P/P 01/03/18*

*038mp.*

*total 3345.40*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: