

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD	Document No.	: SQT18000875	Page	1
	8 SHENTON WAY	Date	: 1. Mar 2018		
	#27-01 AXA TOWER	Customer No.	: WZA006		
	SINGAPORE 068811	Svc Advisor	: STEVEN CHUI FOOK SENG		
Registration No	: SKZ6716L	Engine No	: K24W31201279		
Chassis No	: MRHCR2630EP000060	Date Time	: 1. Mar 2018 8:52:23 AM		
Model	: ACCORD 2.4 AT 2014 (EURO 4)	Surveyor Name	:		
Owner's Name	: TUEA FAT HO	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 27/2/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:TUEA FAT HO						
	OWNER INSURER:TOKIO MARINE						
	ACC DATE:27/02/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:AXA INSURANCE						
	TP VEH:GBB2002Y						
BOSUN	SUNDRIES		100.00				
BOSUN	SUNDRIES	1	80.00	30	80.00	5.60	85.60
BOJSE	BODY JOINT SEALANT.	1	100.00	X NN	100.00	7.00	107.00
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00	/	80.00	5.60	85.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	180.00	?	180.00	12.60	192.60
BKBH12S	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE &	1	2800.00	1125	2800.00	196.00	2996.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	1500.00	1400	1500.00	105.00	1605.00
	Bonnet - BT				Sum Labor	4740.00	331.80
							5,071.80
33100-T2A-T51	HEADLIGHT ASSYR.WITH LED ?	1	2342.30	35	1522.49	106.57	1629.06
33150-T2A-T51	HEADLIGHT ASSY,L.WITH LED - SCR.	1	2342.90	35	1522.88	106.60	1629.48
80110-T2A-T01	CONDENSER COMP ?	1	575.30	35	373.94	26.18	400.12
71121-T2M-T21	BASEFR.GRILLE ?	1	149.50	35	97.17	6.80	103.97
71122-T2M-T01	MOULDINGFR.GRILLE / Cst.	1	233.90	35	152.03	10.64	162.67
71123-T2M-T01	BARR.FR.GRILLE MOLDING A ?	1	14.90	35	9.68	0.68	10.36
71124-T2M-T01	BARR.FR.GRILLE MOLDING B ?	1	23.00	35	14.95	1.05	16.00
71125-T2A-A00	STAYFR.GRILLE ?	1	9.90	35	6.43	0.45	6.88
71127-T2M-T01	BASEFR.GRILLE EMBLEM / HGT. / MCL.	1	8.80	35	5.72	0.40	6.12
71173-T2M-T01	BARL.FR.GRILLE MOLDING A ?	1	14.90	35	9.68	0.68	10.36
71174-T2M-T01	BARL.FR.GRILLE MOLDING B ?	1	23.00	35	14.95	1.05	16.00

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SKZ6716L
Chassis No : MRHCR2630EP000060
Model : ACCORD 2.4 AT 2014 (EURO 4)
Owner's Name : TUEA FAT HO
Ins Policy No. :
Date of Accident : 27/2/2018

Document No. : SQT18000875 Page 2
Date : 1. Mar 2018
Customer No. : WZA006
Svc Advisor : STEVEN CHUI FOOK SENG
Engine No : K24W31201279
Date | Time : 1. Mar 2018 8:52:23 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
75700-TA0-A00	EMBLEMFR. /	1	25.90	35	16.83	1.18	18.01
90301-ST0-003	NUTPUSH 3MM /	2	1.90	35	2.47	0.17	2.64
91501-TR0-003	CLIPINNER FENDER /	4	2.30	35	5.98	0.42	6.40
71101-T2M-T40ZZ	FACEFR.BUMPER /	1	620.50	35	403.32	28.23	431.55
71103-T2A-A00	GRILLEFR.BUMPER LOWER /	1	37.60	35	24.44	1.71	26.15
71112-T2A-A10	GARNISHL.FR.FOG LIGHT /	1	32.00	35	20.80	1.46	22.26
71130-T2M-T21ZZ	BEAM COMPFR.BUMPER /	1	406.50	35	264.22	18.50	282.72
71140-T2A-A01	BEAMR.FR.BUMPER UPPER /	1	28.60	35	18.59	1.30	19.89
71145-T2M-T00	BASEFR.LICENCE PLATE /	1	17.60	35	11.44	0.80	12.24
71150-T2F-A00	GARNISH ASSYFR.BUMPER LOWER /	1	76.90	35	49.98	3.50	53.48
71190-T2A-A01	BEAML.FR.BUMPER UPPER /	1	28.60	35	18.59	1.30	19.89
71193-T2A-A01	SPACERR.FR.BUMPER /	1	10.40	35	6.76	0.47	7.23
71198-T2A-A01	SPACERL.FR.BUMPER /	1	10.40	35	6.76	0.47	7.23
91505-TM8-003	CLIPBUMPER /	10	2.00	35	13.00	0.91	13.91
BO-NUM-COMPL	NUMBER PLATE WITH CASING-L(N) /	1	45.00		45.00	3.15	48.15
Sum Item					4638.10	324.67	4,962.77

Survey By

Date & Time

Excess

Status

Signature

Guo, Qiang - 82880282

13/3/18

Total Amount 9,378.10 656.47 10,034.57

Total (Inclusive of GST) 10,034.57

before paint photos.

5 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 2/3/2018 8:00:39 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)