



凱摩哆服務 KAI MOTOR TRADING

BLK 3007 UBI ROAD 1 #01-440, SINGAPORE 408701.
TEL: 6747 4006 FAX: 6743 7591 EMAIL: kaimotor@gmail.com
BUS. REG. NO: 44223100L GST NO: M90371531Y

專業服務：汽車意外保險賠償，拖車，汽車修理及維修服務，打嗎呷，噴漆。
Specialist in: Accidents Insurance Claim, Towing Service, Motor Vehicle Repairing, Panel Beating, Spray Painting.

Date : 27/02/2018

Attn: The Motor Claims Department
Your Insured veh no : SKQ 8879 J
AIG ASIA PACIFIC INSURANCE PTE LTD.
78 Shenton Way
07-16 Chartis Building
Singapore 079120

TPLEK
Xiao Tong

WITHOUT PREJUDICE

(By Email Only)

HP: 96893735 Adrian
MROS3REE104103549

Dear Sir / Madam

Estimate Cost repair Bill To Toyota Alits SJZ 8381 S & SKQ 8879 J on 13/02/2018

To Supply :-

1pc	Front door RH	Dented
1pc	Front door outer moulding RH	new
1pc	Front door protector RH	at
1pc	Front door protector moulding RH	at
1pc	Front door rubber RH	new
1pc	Front Door inner lock RH	new
1pc	Rear door RH	Dented
1pc	Rear door outer moulding RH	new
1pc	Rear door protector RH	at
1pc	Rear door moulding RH	at
1pc	Rear door rubber RH	new

2424.89
1818.66

\$1,350.00	1071.60
\$ 149.50	+
\$ 112.09	✓
\$ 152.30	35.10
\$ 198.20	+
\$ 545.50	+
\$1,210.30	1055.70
\$ 148.20	+
\$ 115.30	✓
\$ 35.10	✓
\$ 150.30	+
\$ 3,906.50	
\$ 976.63	
\$ 2,929.88	

less

25%

To dismantle & replace damage parts, panel beat where necessary.
To putty, apply primer & spray paint on the affected portion.

930
\$ 780.00 400
\$ 850.00 500
\$ 60.00 30
\$4,619.88

To check wiring functions.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian hury
1/s 28/02/18.
04 PAYS

total 2748.66
1/s 22K