

22/03/2018

ASS/REC.BY:

REF: CS/FCI18004092/84321

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

02/03/18 @ 3.46pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLQ 6871 G

Insured:

SHC 2308P

at Workshop m/s

Auto Insure

Tel:

91002998

of

G Marsiling Lane

Policy No:

Claim No:

D18001780MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/03/2018

CA / REV / REP. / REV 24 HRS

(wp)

05/03/18

H.O.D. Endorsement:

Date/Time:

4.42pm @ 2/3/18

Person Contacted:

Sam

Vehicle  IN  OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 6871 G - x
	SHC 2308P - x
	Part by Part 12,832.16. (Red: )

FCI

ASSIGNMENT


Date 05/03/18

SLQ 6871 G

19/7/17

Business Class: \_\_\_\_\_  
 Type:  M/Cycle Bus/Van/Lorry/Taxi/Tram/Motor Truck/Trailer/Other  
 Make: Mazda 3  
 Colour: Blue  
 Sp. Reading: 13610  
 Engine No: \_\_\_\_\_  
 VIN: JM6BN22A84016119Z  
 Gen. Cond: Good  Poor/Burnt  
 Steering:  Jammed/Leaked/Burnt/Other  
 Brake:  Jammed/Leaked/Burnt/Other  
 Mod:  SRM STD A/Rum/Other  
 Tyre Size: 205/60R16  
 = 11

Policy Condition: \_\_\_\_\_  
 Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GA - RR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res: Yes or No  
 LHM Sum: \_\_\_\_\_ % C/Va: Yes or No

BS/DUN/EXNOVA/G+RS/LZA/MIC/OHTS/LRR/SUM  
 YO/O/YOKO/Other  
 Front: \_\_\_\_\_ Fee: \_\_\_\_\_  
 R.Ba: 6 --- R.Ba: 6 ---  
 L.Ba: 6 --- L.Ba: 6 ---  
 D.O.A: 1/3/18 D.O: 5/3/18  
 Surveyed at: Auto Insure  
 Des. of Damages:            
 The U/C - Chassis/frame - Body Structure affected due to collision

CA / REV / REP. / 24 HRS (wp)  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Date	Time	Action / Instruction
12/3/18		
RECEIVED 14 AUG 2018		

Use Time File Pass of:  Prel. Report  
 Final Report  
 Typist: TP  
 Report Form: TP  
 LHM Sum: 12,832.16

Days Of Repair: 13  
 Resurvey No. of Trip: 2  
 Add Fee:            
 Survey Fee: 18x15=270  
 120+270  
 50  
 50+150  
 108  
 738  
 JSP  
 OSP  
 15/8/18



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004092/Std3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 02-03-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 2308P	Veh. Inspected	SLQ 6871G
Policy No.		Coverage (\$)	0.00
Claim No.	D18001780MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	02/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/03/2018	Inspection Date	
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**MOTOR SURVEY ASSIGNMENT****Date** 02-03-2018 **Our Ref No.** D18001780MFSH**Accident Date** 01-03-2018 **Claim Type.** Third Party**Insured Vehicle** SHC2308P **Third Party Vehicle.** SLQ6871G**Survey Location** 6 MARSILING LANE**Contact Person.** SAM GOH**Contact No.** 315712626/ 91002998 **Fax No.** 63680081**Survey Type** WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:**Appointed Surveyor** LKK AUTO CONSULTANTS PTE LTD**Contact Person** NA **Fax No.** 68416315**Contact Number.** NA**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST****Cc : Workshop** AUTO INSURE PTE LTD **Attention.** NIL**Cc : TP Solicitor** NA **TP Solicitor Fax No.** NA**Officer Incharge** EILEEN LEE**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

## Denise Tay (LKKAuto)

---

**From:** claims01@web-designers.com on behalf of AutoInsure (Claims) <claims01@autoinsure.com.sg>  
**Sent:** Saturday, 23 June 2018 12:41 PM  
**To:** Sebastian Yeang (LKK Auto)  
**Subject:** Re: SUPPLEMENTARY SLQ6871G

### **WITHOUT PREJUDICE**

Hi Sebastian,

We refer to the above matter.

Please be informed that we have yet to receive your finalization amount till to-date.

Kindly let us have your finalization amount soon.

Thanks.

***\*Kindly note that w.e.f 21st Mar 2017, we are relocated to:***

***6 Marsiling Lane S739145***

***tel: (65) 3157 2626***

***Please mail all future correspondence to stated address.\****

Regards

Sam Goh  
did: (65) 3157 2624 / 3157 2628  
mobile: (65) 9743 6363  
e: [claims01@autoinsure.com.sg](mailto:claims01@autoinsure.com.sg)

Auto Insure Pte. Ltd.  
201437380M  
6 Marsiling Lane S739145

t: (65) 3157 2626  
f: (65) 6368 0081  
w: [www.autoinsure.com.sg](http://www.autoinsure.com.sg)  
g.e: [claims@autoinsure.com.sg](mailto:claims@autoinsure.com.sg)

-- Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail.--

On Mon, Mar 5, 2018 at 12:20 PM, AutoInsure (Claims) <[claims01@autoinsure.com.sg](mailto:claims01@autoinsure.com.sg)> wrote:

Hi Sebastien,

Attachment for your attention.



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001780MFSH

Date: 12/3/2018

Our Ref: CS/FC118004092/Std3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLO 6871G**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 5/3/2018 at the premises of M/s Auto Insure, and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 18,251.84</u>
Revised Estimate Amount	: <u>S\$ 12,211.20</u>
"Check" Items Amount	: <u>S\$ 2,335.92</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$</u>
Nett Value	: <u>S\$</u>

**Description of Damage:**

The vehicle sustained damages at the front and rear.



**Comments/ Present Status:**

Damages Consistent.

Yours faithfully  
Sebastian  
Automotive Assessor

Job Sheet (/ClaimWS/Surveyor/JobSheet/235539)



PRI Documents



Close X

## PRI Header Details

<b>Claim No</b>	D18001780MFSH	<b>Policy No</b>	D-18088936MFSH	<b>Claimant S.No &amp; Name</b>	1 & AUTO INS
<b>Workshop Name</b>	AUTO INSURE PTE LTD (Contact Person : SAM GOH)	<b>Survey Location &amp; Contact Details</b>	6 MARSILING LANE <b>Mobile:</b> 91002998 , <b>Phone:</b> 315712626 , <b>Fax:</b> 6368001 <b>EmailId:</b> CLAIMS01@WEB-DEZIGNERS.COM		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM *		
<b>Insured Name</b>	COMFORT TRANSPORTATION PTE LTD	<b>Insured Vehicle No</b>	SHC2308P	<b>TP Vehicle No</b>	SLQ6871G
<b>PRI Recieved Date</b>	02-03-2018 05:00:55 PM	<b>Surveyor Appointed Date</b>	02-03-2018 03:45:02 PM	<b>Surveyor Accept Date</b>	02-03-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	02-03-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Denise Tay (LKKAuto)

---

**From:** Denise Tay (LKKAuto)  
**Sent:** Monday, 12 March 2018 11:26 AM  
**To:** Admin-D (LKKAuto); 'Claim Workflow System'; assignments  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18001780MFSH/1  
**Attachments:** PRELI ADVISED SLQ 6871G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLQ 6871G**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Friday, 2 March 2018 4:44 PM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>  
**Subject:** RE: SURVEY ASSESSMENT - D18001780MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Friday, 2 March 2018 3:45 PM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [EILEENLEE@MSFIRSTCAPITAL.COM.SG](mailto:EILEENLEE@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001780MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.  
Kindly submit your report via CWS within the next 14 days.

Best Regards,  
Admin Team  
Claim Workflow System  
Motor Claims Department

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/03/2018 15:43
Date Of Accident	01/03/2018 08:30
Exact Location Of Accident	AYE CITY AFTBUONA VISTA EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLQ6871G
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	REPORTING@AUTOINSURE.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-31572626

#### Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 SEDAN EU6 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

#### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999994993
Cover Note Number	

#### Driver

Name of Driver	LIM CHOONG PENG , DANNY
NRIC No	S8904324G
Date Of Birth	02/02/1989
Occupation	OUTDOOR
Date Of Driving Pass	23/07/2009
Driving Experience	8 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88212626
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 6 MARSILING LANE  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OTHER - HIRER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident CHAIN COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : NA  
 GENDER: : FEMALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name WOODLANDS WEST NPC  
 Police Station Address ROAD: 9 MARSILING LANE , POSTCODE: 739146 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO ATTACHMENT

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SHC2308P  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category TAXI  
 Name of Driver LAM KIN LEONG  
 NRIC/Passport Number  
 Contact Number 96227123  
 Address  
 Postcode

Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SHD8506P  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category TAXI  
Name of Driver WONG YIN CHON  
NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number SKE9291K  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver JASON CHUN CHUAN JIE  
NRIC/Passport Number  
Contact Number 98378706  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)





SINGAPORE  
POLICE FORCE



T/20180301/2051

2 of 3

Report No. T/20180301/2051

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

CONTINUATION OF REPORT

**Brief Details.**

On 01/03/2018 at about 0830hrs, I was driving my car V1) SLQ6871G along AYE towards CTE. As I was driving Uber, I had a passenger with me. I was on the right most lane of a 4-lane road. While driving, the traffic ahead was slowing down and in front of me, was a taxi V2)SHD8506P. As I was approaching closer to V2, I slowed down and came to a complete stop. Suddenly, I felt a hard impact from my rear and caused me to collided onto the rear of V2. When I got down from my car, discovered that it was a chain collision. A taxi V3) SHC2308P had collided onto my rear thus I collided onto V2 and V2 collided onto the rear of V4)SKE9291K. My car sustain minor dents on the front bumper, heavy damages on the rear and damages on both of the rear passenger doors. V3 sustain heavy damage on the front portion of the car and V2 sustain minor dents on the rear bumper.

There was a passenger in V2 and V3. Ambulance and Traffic Police was at scene. Passengers from my car, V2 and V3 was conveyed to hospital. No Government property was damaged.

Sketch Plan #3 Pg. 1



SINGAPORE  
POLICE FORCE



T/20180301/2051

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

3 of 3  
Report No. T/20180301/2051

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report: J/ Sgt 2 MOHAMED FAEZ BIN MOHAMED SAHID	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 01/03/2018 12:41
Officer In Charge Of Case: TP / GIT / SI MOHAMMED FADZLY BIN ABDUL AZIZ Contact No.: 65472078	Classification Of Case:

Authentication Stamp  
NP168

## Sketch Plan #4


### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

 _____ Policyholder's Signature Date & Time:	 _____ Driver's Signature (If driver is not the policyholder) Date & Time:	 _____ Reporting Centre Personnel's Signature Name: NRIC/FIN No.:
--	---	---

1/3/18 13:10 pm

Sketch Plan #5

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to police report  
T / 2018 0301 / 2051

DECLARATION

(We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:



Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

1/3/18 1310 pm

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

Sketch Plan #6 Pg. 1

REPUBLIC OF SINGAPORE DRIVING LICENCE

Identity Card No. S8904324G



LIM CHOONG PENG, DANNY

Issue Date: 02 Feb 1989  
Valid Until: 23 Jul 2009

001766245C

REPUBLIC OF SINGAPORE

IDENTITY CARD NO: S8904324G



Name  
LIM CHOONG PENG, DANNY

林峻平

Race  
CHINESE

Date of birth: 02-02-1989 Sex: M

Country of birth  
SINGAPORE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIFICATION

CLASS	DESCRIPTION	PASS DATE
Class 1B	Motorcycles up to 250 CC	07 Dec 2009
Class 2	Motor cars up to 2000 kg with not more than 7 passengers, exclusive of the driver; and motor tractors/vehicles up to 2000 kg	23 Jul 2009

S / No. 9000120659

S8904324G

Licence No: S8904324G

3449716



NRIC No S8904324G



Date of issue  
11-02-2004

Address  
APT BLK 308 BUKIT BATOK STREET 31  
#10-147  
SINGAPORE 650308

Doc Ref: SLQ6871G  
 Equip Ref: SMC2308P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
PARTS REPLACEMENT - LIST ITEMS				
1	1	REAR BUMPER ✓ CRK		\$ 1075.1365-00 ✓ CRK
2	2	REAR BUMPER SIDE RETAINERS LH/RH ✓ NEC		\$ 74.148-00 ✓ NEC
3	1	REAR REINFORCEMENT ✓ BT		\$ 539.580-00 ✓ BT
4	1	REAR END PANEL ✓ DT		\$ 505.884-00 ✓ DT
5	1	REAR END PANEL TOP GARNISH ?		\$ 425.00 X NN
6	1	BOOT ✓ DT		\$ 958.222-00 ✓ DT
7	2	REAR BOOT HINGE ?		\$ 220.00 X } NN
8	1	REAR FENDER TAIL LAMP LH		\$ 980.00 X }
9	1	REAR BOOT TAIL LAMP LH ✓ CRK		\$ 425.00 ✓ CRK
10	1	REAR TAIL LAMP PANEL LH ✓ DT		\$ 489.00 ✓ }
11	1	REAR TAIL LAMP LOWER PANEL RH ✓ DT		\$ 342.00 ✓ }
12	1	REAR FENDER TAIL LAMP LH ✓ CRK		\$ 980.00 ✓ CRK
13	1	REAR BOOT TAIL LAMP RH ?		\$ 425.00 X NN
14	2	REAR BUMPER REFLECTOR LH CRK ✓ RH X M		\$ 51.380-00 LH ✓ CRK
15	1	REAR FENDER RH R		\$ 1,174.20 R
16	1	REAR FENDER INNER SHIELD RH X		\$ 279.20 X NN
17	1	REAR FENDER LH ✓ DT		\$ 1,174.20 ✓ DT
18	1	REAR FENDER INNER SHIELD LH ✓ CRK		\$ 279.20 ✓ CRK
19	1	FRONT BUMPER ✓		\$ 826.120-50 ✓ CRK
20	1	FRONT BUMPER REINFORCEMENT ?		\$ 589.90 X }
21	1	FRONT BUMPER REINFORCEMENT COVER ?		\$ 280.00 X }
22	1	FRONT BUMPER TOP GARNISH ✓ DT		\$ 322.80 ✓ DT
23	1	CENTER GRILLE ✓ CRK		\$ 150.450-00 ✓ CRK
24	2	FRONT GRILLE CHROME RH/LH ✓ CRK		\$ 150.400-00 ✓ CRK
25	1	FRONT MAZDA LOGO ✓ NEC		\$ 54.112-00 ✓ NEC
SUB TOTAL				\$ 14,689.80
LESS 20%				\$ 2,937.96
TOTAL AMOUNT				\$ 11,751.84

10340.2  
 - 20%  
 -----  
 8272.16  
 + 420.0  
 + 3640.0 + 500  
 -----  
 13072.16 12832.16

Part by Part repair: \$ ~~13072.16~~ @ 13 days

Confirmed.

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR REVERSE SENSOR ✓ DMG		\$ <del>780.00</del> 200 ✓ DMG
2	1 SET	REAR BUMPER CLIPS ✓ N/C		\$ <del>60.00</del> 30 ✓ NEC
3	1	REAR LICENCE PLATE WITH HOLDER ✓ CUT		\$ <del>35.00</del> 45 ✓ CUT
4	1	FRONT LICENCE PLATE WITH HOLDER ✓ BT		\$ <del>35.00</del> 45 ✓ BT
5	1	REAR END PANEL SEALANT ✓ N/C		\$ <del>80.00</del> 40 ✓ NEC
6	1 SET	REAR FLOOR PANEL SOUND INSULATOR ?		\$ 120.00 X NN
7	2	REAR BUMPER TOW CAP ✓ MS		\$ <del>180.00</del> 60 ✓ MS
SUB TOTAL				\$ 870.00
TOTAL PARTS COST				\$ 12,621.84

Our Ref: SLQ6871G  
Your Ref: SHC2308P

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ <del>2,200.00</del> 1600
2	TOWING CHARGE	\$ -
3	TO CONDUCT HEADLAMP FOCUS	\$ -
4	TO REMOVE/REPAIR A/C CONDENSOR & REFILL AIRCON GAS	\$ -
5	TO REMOVE/INSTALL REAR WINDSCREEN	\$ <del>250.00</del> 120
6	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ <del>250.00</del> 100
7	TO REMOVE / REPAIR WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ <del>30.00</del> 30
8	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ <del>150.00</del> 50
9	TO REMOVE / REPAIR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS	\$ -
10	TO REMOVE / REPAIR REAR LUGGAGE COMPARTMENT	\$ <del>150.00</del> 50
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ <del>2,200.00</del> 1600
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ <del>150.00</del> 80
13	TO VACUUM, WAXING & CLEAN	\$ 100.00 X
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ <del>100.00</del> 30
TOTAL BEFORE GST		\$ 18,251.84
GST 7%		\$ 1,277.63
TOTAL (PARTS & LABOUR)		\$ 19,529.47

**Adjustments / Recommendations**

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$18,200.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director

28882-22



## Auto Insure Pte. Ltd.

6 Marsiling Lane  
 Singapore (739145)  
 E: claims@autoinsure.com.sg  
 W: www.autoinsure.com.sg  
 T: 3157 2626 F: 6368 0081  
 GST No.: 201437380M

# Supplementary Items

Our Ref: SLQ6871G

Your Ref: SHC2308P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<b><u>PARTS REPLACEMENT - LIST ITEMS</u></b>				
1	1	AIRCON CONDENSER		\$ <del>1,170.00</del> 987 ✓ DT
2	1	AIRCON COMPRESSOR		\$ 1,800.00 X NN
3	1	RADIATOR FAN MOTOR, BLADE, COWLING SET		\$ 960.00 ✓ DT
4	1	FRONT HEADLAMP RH		\$ 2,245.00 X } NN
5	1	FRONT HEADLAMP LH		\$ 2,245.00 X }
6	1	FRONT SUPPORT PANEL		\$ 580.60 X }
SUB TOTAL				\$ 9,000.60
LESS 20%				\$ 1,800.12
TOTAL				\$ 7,200.48



# Auto Insure Pte. Ltd.

6 Marsiling Lane  
Singapore (739145)  
E: claims@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 3157 2626 F: 6368 0081  
GST No.: 201437380M

## Supplementary Items

Our Ref: SLQ6871G

Your Ref: SHC2308P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	<u>PARTS REPLACEMENT - LIST ITEMS</u> FRONT DRIVER SEAT <i>ST</i>		\$ <del>4,288.00</del> <i>Local repair 500/r.</i>
			SUB TOTAL	\$ 4,288.00
			LESS 20%	\$ 857.60
			TOTAL	\$ 3,430.40



**Auto Insure Pte. Ltd.**

Blk 3, 391A Woodlands Road  
Yew Tee Industrial Estate  
Singapore (677964)  
E: claims@autoinsure.com.sg  
W: www.autoinsure.com.sg  
T: 6366 2788 F: 6368 0081  
GST No.: 201497380M

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SLQ6871G  
Your Ref: SHC2308P

Date: 5-Mar-18

BY EMAIL ONLY  
(claims@autoinsure.com.sg)

**ATTENTION: MOTOR CLAIMS DEPT**

email: motor\_claims@first-insurance.com.sg

First Capital Insurance Limited  
6 Raffles Quay #21-00  
Singapore 048580

Assessed Vehicle No : SLQ6871G  
Car Make and Model : MAZDA3  
Date of Accident : 1-Mar-18  
Date of Assessment : 5-Mar-18

We have carried out a physical assessment of SLN7693M at our workshop Auto Insure Pte Ltd sustained damages to the REAR AND FRONT portion of the vehicle.


**4. DESCRIPTION OF DAMAGE**

At the time of the inspection observed that this vehicle had sustained damages to the REAR AND FRONT portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount : P/P  
Adjusted Amount : \$ 18,200.00  
Est. Repair Days : 8



\*\* Considering that our vehicle is less than 6 months old,  
We will not agree to any repair of parts, only replacement will be done. \*\*

Pursuant to your instruction, we have **NOT AUTHORIZED** repair.  
The assessment was conducted on a **"WITHOUT PREJUDICE"** basis.  
If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

**Disclaimer**  
This report is intended for the exclusive use of the addressee solely in relation to the loss of occurrence in which the assessed vehicle is involved.  
No liability or responsibility whatsoever shall be held by  
**AUTO INSURE PTE LTD** For any reliance on this report by any third party.

Sebastian.  
5/3/18.  
- Part by part repair.  
- Question Mark Item  
Photo  
- Photo Before Paint.  
90036121  
sebastianyang@lkkauto.com.

13 days -  
**LKK Auto Consultants** hence notify the Repairer of the following:  
• To resurvey before/after spray painting  
• To display damaged part(s) during resurvey  
• Parts prices are subject to confirmation  
• Third party survey is on a "Without Prejudice" basis  
• No illegal modification(s) is allowed  
• Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company  
  
Acknowledged by Repairer  
Signature:  
Date:

Our Ref: SLQ6871G  
 Your Ref: SHC2308P

S/NO	QTY	DESCRIPTIONS	ASSESSED CONDITION	EST. BY WORKSHOP
<u>PARTS REPLACEMENT - LIST ITEMS</u>				
1	1	REAR BUMPER / CRK		\$ 1,365.50
2	2	REAR BUMPER SIDE RETAINERS LH/RH ✓ NEC		\$ 118.00
3	1	REAR REINFORCEMENT ✓ BT		\$ 589.90
4	1	REAR END PANEL ✓ DT		\$ 885.00
5	1	REAR END PANEL TOP GARNISH ?		\$ 425.00
6	1	BOOT ✓ DT		\$ 977.40
7	2	REAR BOOT HINGE ?		\$ 220.00
8	1	REAR FENDER TAIL LAMP LH		\$ 980.00
9	1	REAR BOOT TAILLAMP LH ✓ CRK		\$ 425.00
10	1	REAR TAIL LAMP PANEL RH LH ✓ DT		\$ 489.00
11	1	REAR TAIL LAMP LOWER PANEL RH ✓ DT		\$ 342.00
12	1	REAR FENDER TAIL LAMP RH LH ✓ CRK		\$ 980.00
13	1	REAR BOOT TAILLAMP RH ?		\$ 425.00
14	2	REAR BUMPER REFLECTOR LH CRK ✓ RH X		\$ 180.00
15	1	REAR FENDER RH R		\$ 1,174.20
16	1	REAR FENDER INNER SHIELD RH X		\$ 279.20
17	1	REAR FENDER LH ✓ DT		\$ 1,174.20
18	1	REAR FENDER INNER SHIELD LH ✓ CRK		\$ 279.20
19	1	FRONT BUMPER ✓		\$ 1,326.50
20	1	FRONT BUMPER REINFORCEMENT ?		\$ 589.90
21	1	FRONT BUMPER REINFORCEMENT COVER ?		\$ 280.00
22	1	FRONT BUMPER TOP GARNISH ✓ DT		\$ 322.80
23	1	CENTER GRILLE ✓ CRK		\$ 450.00
24	2	FRONT GRILLE CHROME RH/LH ✓ CRK		\$ 300.00
25	1	FRONT MAZDA LOGO ✓ NEC		\$ 112.00
			SUB TOTAL	\$ 14,689.80
			LESS 20%	\$ 2,937.96
			TOTAL AMOUNT	\$ 11,751.84

S/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	REAR REVERSE SENSOR ✓ DMG		\$ <del>280.00</del> 200
2	1 SET	REAR BUMPER CLIPS ✓ N/C		\$ <del>60.00</del> 30
3	1	REAR LICENCE PLATE WITH HOLDER ✓ CUT		\$ <del>75.00</del> 45
4	1	FRONT LICENCE PLATE WITH HOLDER ✓ 138		\$ <del>75.00</del> 45
5	1	REAR END PANEL SEALANT ✓ N/C		\$ <del>80.00</del> 40
6	1 SET	REAR FLOOR PANEL SOUND INSULATOR ?		\$ 120.00
7	2	REAR BUMPER TOW CAP ✓ MS		\$ <del>180.00</del> 60
SUB TOTAL				\$ 870.00
TOTAL PARTS COST				\$ 12,621.84

Our Ref: SLQ6871G

Your Ref: SHC2308P

S/NO	DESCRIPTION	EST. BY WORKSHOP
<b>LABOUR &amp; PAINTWORK</b>		
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS	\$ <del>2,200.00</del> 1600
2	TOWING CHARGE	
3	TO CONDUCT HEADLAMP FOCUS	\$ -
4	TO REMOVE/REFIX A/C CONDENSOR & REFILL AIRCON GAS	\$ -
5	TO REMOVE/INSTALL REAR WINDSCREEN	\$ <del>250.00</del> 120
6	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR	\$ <del>250.00</del> 100
7	TO REMOVE / REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS	\$ <del>80.00</del> 30
8	TO REMOVE / INSTALL REAR REVERSE SENSOR	\$ <del>150.00</del> 30
9	TO REMOVE / REFIX UPHOSTERY, GARNISH AND ATTACHMENT PARTS	\$ -
10	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT	\$ <del>150.00</del> 50
11	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED	\$ <del>2,200.00</del> 1600
12	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	\$ <del>150.00</del> 50
13	TO VACUUM, WAXING & CLEAN	\$ 100.00 X
14	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS	\$ <del>100.00</del> 30
TOTAL BEFORE GST		\$ 18,251.84
GST 7%		\$ 1,277.63
TOTAL (PARTS & LABOUR):		\$ 19,529.47

**Adjustments / Recommendations**

Our estimator have thoroughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

Our Workshop has agreed to undertake the job at a sum of \$18,200.00 for direct settlement with the third party insurance.

Yours Faithfully,

Jason Heng  
Claims Director



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18004092/Dtd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 15-08-2018	
		Code : FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 2308P	Veh. Inspected	SLQ 6871G
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18001780MFSH	Excess (\$)	0.00
Assign From	EILEEN LEE	Assign Date	02/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	MAZDA 3	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6BN22A8H0161192	Colour	BLUE
Odometer	13610	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
R/H Front Tyre	205/60 R16	TOYO	6 mm
L/H Front Tyre	205/60 R16	TOYO	6 mm
R/H Rear Tyre	205/60 R16	TOYO	6 mm
L/H Rear Tyre	205/60 R16	TOYO	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	01/03/2018	Inspection Date	05/03/2018
Survey held at	AUTO INSURE PTE LTD 6 MARSILING LANE S739145		
<b>5a. Remarks</b>			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>13 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 6871G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	1,365.50	1,075.00
2	REAR BUMPER SIDE RETAINERS LH / RH	NECESSARY	118.00	74.00
1	REAR REINFORCEMENT	BENT	589.90	538.00
1	REAR END PANEL	DENTED	885.00	505.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	425.00	-
1	BOOT	DENTED	977.40	958.00
2	REAR BOOT HINGE	NOT NECESSARY	220.00	-
1	REAR FENDER TAIL LAMP LH	NOT NECESSARY	980.00	-
1	REAR BOOT TAILLAMP LH	CRACKED	425.00	425.00
1	REAR TAIL LAMP PANEL LH	DENTED	489.00	489.00
1	REAR TAIL LAMP LOWER PANEL RH	DENTED	342.00	342.00
1	REAR FENDER TAIL LAMP LH	CRACKED	980.00	980.00
1	REAR BOOT TAILLAMP RH	NOT NECESSARY	425.00	-
2	REAR BUMPER REFLECTOR	N/S CRACKED / O/S NOT NECESSARY	180.00	51.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,174.20	-
1	REAR FENDER INNER SHIELD RH	NOT NECESSARY	279.20	-
1	REAR FENDER LH	DENTED	1,174.20	1,174.20
1	REAR FENDER INNER SHIELD LH	CRACKED	279.20	279.20
1	FRONT BUMPER	CRACKED	1,326.50	826.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	589.90	-
1	FRONT BUMPER REINFORCEMENT COVER	NOT NECESSARY	280.00	-
1	FRONT BUMPER TOP GARNISH	DENTED	322.80	322.80
1	CENTER GRILLE	CRACKED	450.00	150.00
2	FRONT GRILLE CHROME RH / LH	CRACKED	300.00	150.00
1	FRONT MAZDA LOGO	NECESSARY	112.00	54.00
1	AIRCON CONDENSER (ADDITIONAL)	DENTED	1,170.00	987.00
1	AIRCON COMPRESSOR (ADDITIONAL)	NOT NECESSARY	1,800.00	-
1	SET RADIATOR FAN MOTOR, BLADE, COWLING (ADDITIONAL)	DENTED	960.00	960.00
1	FRONT HEADLAMP RH (ADDITIONAL)	NOT NECESSARY	2,245.00	-

Report Ref No. CS/FCI18004092/Dtd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT HEADLAMP LH (ADDITIONAL)	NOT NECESSARY	2,245.00	-
1	FRONT SUPPORT PANEL (ADDITIONAL)	NOT NECESSARY	580.60	-
	LESS 20% DISCOUNT		-4,738.08	-2,068.04
			18,952.32	8,272.16
1	FRONT DRIVER SEAT (ADDITIONAL) (SN) (LOCAL REPAIR)	BENT	4,288.00	500.00
	LESS 20% DISCOUNT		-857.60	-
			3,430.40	500.00
	<b>SPECIAL NETT ITEMS</b>			
1	REAR REVERSE SENSOR (SN)	DAMAGED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	REAR LICENCE PLATE WITH HOLDER (SN)	CUT	75.00	45.00
1	FRONT LICENCE PLATE WITH HOLDER (SN)	BENT	75.00	45.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR FLOOR PANEL SOUND INSULATOR (SN)	NOT NECESSARY	120.00	-
2	REAR BUMPER TOW CAP (SN)	MISSING	180.00	60.00
			870.00	420.00
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS; PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACED THE DAMAGED PARTS AND COMPONENTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		2,200.00	1,600.00
	TOWING CHARGE. (NPA)		-	-
	TO CONDUCT HEADLAMP FOCUS. (NPA)		-	-
	TO REMOVE / REFIX A/C CONDENSOR & REFILL AIRCON GAS. (NPA)		-	-
	TO REMOVE / INSTALL REAR WINDSCREEN.		250.00	120.00
	TO DIAGNOSE ERASE FAULT MEMORY AFTER REPAIR.		250.00	100.00
	TO REMOVE/ REFIX WIRING SYSTEM AT ACCIDENT AND CHECK FOR PROPER FUNCTIONS.		80.00	30.00
	TO REMOVE / INSTALL REAR REVERSE SENSOR.		150.00	30.00
	TO REMOVE / REFIX UPHOLSTERY, GARNISH AND ATTCHMENT PARTS. (NPA)		-	-

Report Ref No. CS/FCI18004092/Dtd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIX REAR LUGGAGE COMPARTMENT.	NOT NECESSARY	150.00	50.00
	TO RESPRAY AND SUPPLY EXPANDABLE ITEMS & PUFFY ON PARTS REPLACED.		2,200.00	1,600.00
	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS.		150.00	80.00
	TO VACUUM, WAXING & CLEAN.		100.00	-
	TO PERFORM WATER SEEPAGE TEST ON REPAIRED PORTIONS.		100.00	30.00
			5,630.00	3,640.00
<b>GRAND TOTAL</b>			<b>28,882.72</b>	<b>12,832.16</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>12,832.16</b>

Report Ref No. CS/FCI18004092/Dtd3e2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.