

22/03/2002

ASS. REC. BY:

REF: CS/MSG/800.1095/KW3^{MSG}
Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Elaine Ngu of MSG Date/Time: 2/3/18 @ 11:18am

Estimated Cost: Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGK 1385 S Insured: FC60P

at Workshop m/s Cheng Hee Motor Tel: 6765 6142

of 38 woodlands Ind. Prk E1 # 05-04/05

Policy No: MSD/VMS/17-362559-CA Claim No: MSC/V/18-000309

Sum Insured: Excess:

Make of Veh: D.O.A. 27/02/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS lwp H.O.D. Endorsement:

Date/Time: 2:24pm @ 2/3/18 Person Contacted: June Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate

SGK 1385S - x

FC60P - x

13/3/18 Sand preli revised by merimen

3/5 L/Ly @ 32501 C, firmat E fcdp (Reel 16SH.13, 3470)

ASS. REC. BY:

REF: MSG-1Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGK 1385JYr Regn: 07, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: ToyotaColour: Dark BlueSp. Reading: 26501

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 2872118D.O.I. 12/3/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

13/3File pass to Catherine

RECEIVED 3 MAY 2018

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2) 3/5 - typistDays Of Repair: 6Resurvey No. of Trlp: 2Add Fee: ☐

: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

merimen325020010210

Survey Department Check List (Case Handler)

Reference No.: CS | MSG | 800 4095 | Kvd3
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 3/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/201



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18004095/Kvd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 02-03-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FC 60P	Veh. Inspected	SGK 1385S
Policy No.	MSD/VMS/17-362559-CA	Coverage (\$)	0.00
Claim No.	MSC/V/18-000309	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE NGU)	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	27/02/2018	Inspection Date
Survey held at	CHENG HOE MOTOR PL 38 WOODLANDS INDUSTRIAL PARK E1 #05-04/05 SINGAPORE 757700	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Elaine Ngu Siau Mei	Date: 13 Mar 2018
<u>Preliminary Advice</u>	

Insured Vehicle No	: FC60P	Accident Date	: 27/02/2018
TP Vehicle No	: SGK1385S	Assignment Date	: 02/03/2018
Make	: TOYOTA WISH	Est. Duration of Repair	: 6.00
Date of Inspection	: 12/03/2018		
Inspection At	: CHENG HOE MOTOR PTE LTD (WOODLANDS) 38 WOODLANDS INDUSTRIAL PARK E1, #05-04/05 SINGAPORE 757700		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,934.13
Revised Amount	:S\$	4,086.58
Check Items (Estimated)	:S\$	597.56
Total	:S\$	4,684.14
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	28 Feb 2018		02 Mar 2018 11:18 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MUHAMMAD SUKRI BIN MISADI, ID: S8922969C, Tel: +6581130663, Email: NOEMAIL		
Main Claimant:	KOR MEE YIN, ID: S1751563B		
Vehicle Reg. No.:	SGK1385S	Date of Loss:	27/02/2018 23:00 - :59
Claim Type:	TP / MSC/V/18-000309	Policy/Cover Note No.:	MSD/VMS/17-362559-CA (TP, Fire & Theft) Coverage: 17/03/2017 - 16/03/2018
Vehicle Reg. No. (Insured):	FC60P	Policy No. (Claimant):	
		Excess:	S\$300.00
Repairer:	Cheng Hoe Motor Pte Ltd (Woodlands) 38 Woodlands Industrial Park E1, #05-04/05, 757700 Woodlands - Tel: 6765 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/03/2018]		
Driver/Custodian (Insured):	MUHAMMAD SUKRI BIN MISADI (28 / Male), NRIC: S8922969C, Tel: +6581130663		
Adj Asg. Remarks:	REQUEST KENNETH KONG FOR SURVEY		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1563B
Vehicle Details	
Vehicle No.:	SGK13855
Vehicle to be Exported:	No
Intended De-registration Date:	28 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	WISH 1.8 A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	1ZZ2538599
Chassis No.:	ZNE100300515
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$19,663.00
Original Registration Date:	29 Jul 2006
First Registration Date:	29 Jul 2006
Transfer Count:	1
Actual ARF Paid:	\$21,630.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2026
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$48,479.00
COE Rebate Amount:	\$40,399.00
Total Rebate Amount:	\$40,399.00

The information contained herein is correct as at 28 Feb 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SGK1385S
TP/MSIG

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/WL

Claim Type: Third Party

Accident Date: 28/02/2018

TP Veh Reg No: FC60P

Estimate No: ES1890242/YISHUN
Date: 12 Mar 2018
Policy No: 5072922863-02
Veh Reg No: SGK1385S
Make/Model: TOYOTA WISH 1.8 A
Chassis No: ZNE100300515
Engine No: 1ZZ2538599
Reg. Date: 29/07/2006

Estimate Repair Cost to Vehicle No :SGK1385S

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	503.80	1 PC	503.80	✓
2 REAR BUMPER LH SIDE RETAINER	72.80	1 PC	72.80	✓
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
4 LH TAILLAMP	472.60	1 PC	472.60	✓
5 REAR TAILGATE	1,210.40	1 PC	1,210.40	✓
6 TAILGATE LOGO	50.20	1 PC	50.20	✓
7 TAILGATE INNER LOCK	443.50	1 PC	443.50	✓
8 TAILGATE LH DAMPER	224.63	1 PC	224.63	✓
9 REAR WINDSCREEN GLASS MOULDING	79.20	1 PC	79.20	✓
10 REAR PANEL OUTER	441.20	1 PC	441.20	✓
11 REAR PANEL INNER	99.51	1 PC	99.51	✓
			3,618.84	
		Less 25%	904.71	2,714.13
Special Net				
12 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
13 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
14 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
15 REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENT, REAR WIPER ASSY, THIRD BRAKE LIGHT, TO CUT, WELD & RENEW REAR END PANEL INNER & OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL, REAR LH FENDER & REALIGN THE SAME	800.00	1 LA	800.00	700
16 PUTTY & RESPRAY ON REAR LH FENDER, REAR FLOOR BOARD, REAR END PANELS, TAILGATE, REAR BUMPER & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	850
17 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,980.00	1,980.00

Total S\$ 4,934.13

Add GST @ 7% 345.39

Total Amount Payable S\$ 5,279.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18004095/KVD3N2

Date: 07/05/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-362559-CA
Claimant Vehicle No :	SGK1385S	Insured Vehicle No :	FC60P
Date of Loss:	27/02/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000309

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK1385S	Engine No:	1ZZ2538599
Make & Model:	TOYOTA WISH, 1.8 (A)	Chassis No:	ZNE100300515
Reg. Date:	29/07/2006 (Man. Year: 2006)	Odometer:	261501 km
Colour:	Metallic Dark Blue		
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,954.13	2,356.57	597.56	20.23
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,730.00	250.00	12.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,934.13	4,086.57	847.56	17.18
Approved Total (Overridden) (\$\$)		3,250.00		
(\$\$)	4,934.13	3,250.00	1,684.13	34.13
+ GST 7.00/7.00% (\$\$)	345.39	227.50	117.89	34.13
Nett Amount (\$\$)	5,279.52	3,477.50	1,802.02	34.13

INSPECTION

Date of Assignment:	02/03/2018	
Date Inspected:	12/03/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	M1-MPV	TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGK1385S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	503.80 FL	*503.80 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	72.80 FL	*72.80 FL
3	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
4	1		*LH TAILLAMP	Serviceable	472.60 FL	*- FL
5	1		*REAR TAILGATE	Bent	1,210.40 FL	*1,210.40 FL
6	1		*TAILGATE LOGO	Necessary	50.20 FL	*50.20 FL
7	1		*TAILGATE INNER LOCK	Dented	443.50 FL	*443.50 FL
8	1		*TAILGATE LH DAMPER	Serviceable	224.63 FL	*- FL
9	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	79.20 FL	*79.20 FL
10	1		*REAR PANEL OUTER	Bent	441.20 FL	*441.20 FL
11	1		*REAR PANEL INNER	Repair	99.51 FL	*- FL
12	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
13	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,858.84	3,062.10
- List Item Discount on L Items 25.00/25.00% (S\$)	904.71	705.53
Total Parts (S\$)	2,954.13	2,356.57

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY, TAILGATE & ATTACHMENT, REAR WIPER ASSY, THIRD BRAKE LIGHT, TO CUT, WELD & RENEW REAR END PANEL INNER & OUTER, KNOCK & REPAIR REAR FLOOR BOARD PANEL, REAR LH FENDER & REALIGN THE SAME	New	800.00	700.00
3	PUTTY & RESPRAY ON REAR LH FENDER, REAR FLOOR BOARD, REAR END PANELS, TAILGATE, REAR BUMPER & REAR AFFECTED AREAS	New	1,000.00	850.00
4	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			1,980.00	1,730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >