

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

02 MAR 2018

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Survey confirm by wife

Livita 68411972 12.00pm ~ 16.00pm

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLT6275L

Chassis No : MRHFC5650HT000405

Model : CIVIC 1.6 VTI YM2017

Owner's Name : ENG HOON CHAY

Ins Policy No. : 17-MU011386-R00

Date of Accident : 23/2/2018

Document No. : SQT18000863 Page 1

Date : 28. Feb 2018

Customer No. : WZA006

Svc Advisor : ARY CHUA WAI NGEE

Engine No : R16B22000767

Date | Time : 28. Feb 2018 10:52:52 AM

Surveyor Name : DID : +65 6846 5673
HP : +65 8100 6306

Survey Date : Email : arychua@honda.com.sg

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: 70044) OWNER: ENG HOON CHAY OWNER INSURER: TOKIO MARINE INSURANCE S'PORE LTD ACC DATE: 23/02/2018@22.25PM SURVEYED BY: 4~5 WORKING DAYS REF NO: TP INSURER: AXA INSURANCE S'PORE PTE LTD TP VEH: SLJ6866J						
					LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:		
71101-TEA-T00ZZ	FACEFR.BUMPER <i>20/02</i>	1	579.90	✓ 35	376.93	26.39	403.32
91505-TM8-003	CLIPBUMPER <i>neu</i>	14	2.00	✓ 35	18.20	1.27	19.47
71140-TEA-T00	BEAMR.FR.BUMPER UPPER <i>sel</i>	1	25.90	✓ 35	16.83	1.18	18.01
71193-TEA-T01	SPACERR.FR.BUMPER SIDE <i>sp</i>	1	10.40	✓ 35	6.76	0.47	7.23
71130-TEA-T00	BEAM COMPFR.BUMPER <i>11</i>	1	335.80	X 35	218.27	15.28	233.55
33100-TEC-Q01	HEADLIGHT ASSY,R.	1	568.70	? 35	369.65	25.88	395.53
34300-TET-H01	LIGHT ASSYR.SIDE TURN	1	32.20	? 35	20.93	1.47	22.40
60211-TBA-A00ZZ	PANELR.FENDER <i>2</i>	1	241.60	X 35	157.04	10.99	168.03
			Sum Item		1184.61	82.93	1,267.54
BOSUN	SUNDRIES	1 <i>neu</i>	10.00	✓	10.00	0.70	10.70
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	<i>fu</i>	100.00	7.00	107.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) <i>350</i>	1	1050.00	<i>700</i>	1050.00	73.50	1123.50
BKBH01S	STRAGHTEN ALIGN BULKHEAD & RENEW DAMAGE PARTS.	1	1800.00	<i>350</i>	1800.00	126.00	1926.00
			Sum Labor		2960.00	207.20	3,167.20

Survey By

Marcus Chah

Date & Time

2/3/18 @ 2pm

Excess

*Not Authorised**take photo before painting 3 dy.*

Total Amount 4,144.61 290.13 4,434.74

Total (Inclusive of GST) **4,434.74**