



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLF9544P

Chassis No : MRHFC5650GT000227

Model : CIVIC 1.6 VTI YM2016

Owner's Name : GAN CHOON AIK

Ins Policy No. :

Date of Accident : 26/2/2018

Document No. : SQT18000895 Page 1

Date : 2. Mar 2018

Customer No. : WZA006

Svc Advisor : PATRICK MOK LIP KAY

Engine No : R16B21600328

Date | Time : 2. Mar 2018 8:41:18 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

TP DIRECT SETTLEMENT (J/NO:)
OWNER: GAN CHOON AIK
OWNER INSURER: LIBERTY INSURANCE
ACC DATE: 26/02/2018
SURVEYED BY:
DATE:
REF NO:
TP INSURER: AXA INSURANCE
TP VEH: SLR1144A

BOSUN	SUNDRIES	1	50.00 20		50.00	3.50	53.50
BOJSE	SEALANT FOR BOOT COVER	1	80.00		80.00	5.60	85.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1800.00 120	20	1440.00	100.80	1540.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00 X	20	64.00	4.48	68.48
BKBU01K	REMOVE/REFIT BOOT COVER CAMERA TO ASSIST REPAIR (N)	1	180.00 160	20	144.00	10.08	154.08
BA02R	REMOVE/REFIT RR BUMPER SENSORS TO ASSIST REPAIR (N)	1	100.00	20	80.00	5.60	85.60
BMI02D	REMOVE/REFIT BOOT TRIMS TO ASSIST REPAIR (N)	1	225.00 X	20	180.00	12.60	192.60
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1100.00 900	20	880.00	61.60	941.60
Sum Labor					2918.00	204.26	3,122.26
RS-4CS	4PCS CORNER SENSOR W DISPLAY	1	272.00 X		272.00	19.04	291.04
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70 X	35	63.50	4.45	67.95
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10 X	35	306.86	21.48	328.34
74851-TEA-003	LOCK ASSYTRUNK	1	72.20 X	35	46.93	3.29	50.22
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00 X	35	45.50	3.19	48.69
75722-TBA-A00	EMBLEM SETRR.	1	11.50 X	35	7.47	0.52	7.99
75725-TEA-T01	EMBLEMRR.	1	10.60 X	35	6.89	0.48	7.37
04715-TEC-Q00ZZ	FACE ASSYRR.BUMPER	1	9999.99 X	35	6499.99	455.00	6954.99
					401.18	28.08	429.26

price?



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLF9544P
Chassis No : MRHFC5650GT000227
Model : CIVIC 1.6 VTI YM2016
Owner's Name : GAN CHOON AIK
Ins Policy No. :
Date of Accident : 26/2/2018

Document No. : SQT18000895 **Page** 2
Date : 2. Mar 2018
Customer No. : WZA006
Svc Advisor : PATRICK MOK LIP KAY
Engine No : R16B21600328
Date | Time : 2. Mar 2018 8:41:18 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71502-TEX-Y00	GARNISHRR.BUMPER LOWER	1	35.30 35.30	35	22.94	1.61	24.55
71503-TEA-T00	GARNISHR.RR.BUMPER SIDE	1	7.60 7.60	35	4.94	0.35	5.29
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE	1	2.20 2.20	35	1.43	0.10	1.53
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE	1	7.60 7.60	35	4.94	0.35	5.29
71530-TEA-T00ZZ	BEAM COMP RR.BUMPER	1	160.00 160.00	35	104.00	7.28	111.28
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE	1	2.20 2.20	35	1.43	0.10	1.53
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50 11.50	35	7.47	0.52	7.99
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50 11.50	35	7.47	0.52	7.99
91505-TM8-003	CLIPBUMPER	7	2.00 2.00	35	9.10	0.64	9.74
Sum Item					7412.86	518.92	7,931.78

Survey By ZARU - Hp 90010068

Date & Time 07/05/18 @ 1550

Excess 4 days

Status _____

Signature [Signature]

Resurvey by paint

Total Amount 10,330.86 723.18 11,054.04
Total (Inclusive of GST) 11,054.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 2/3/2018 9:58:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)