

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 047/IC/TCAC/CCR/2018
DATE : 01-MAR-2018

AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : MR THNG HENG GUAN
ADDRESS : 31 ALEXANDRA ROAD
#03-02
S(159967)
TELEPHONE NO : 96853063

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 10727584
VEHICLE NO : SLB2514T
MODEL CODE : TDWAREZE12VDAY406Z
MODEL/YEAR : NISSAN NOTE 1.2 SUPER CHARGE
ENGINE NO : HR12173528B
CHASSIS NO : JN1TBAE12Z0982402
MILEAGE : 28977 KM
DATE IN : 01/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 28/02/2018

6 days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sebastian .

5/3/18.

- Part by part repair .
- Question Mark Item Photo .
- Photo Before Paint .

90036121

sebastianyang@lkkauto.com .

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB2514T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	X
2	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	X
3	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	✓
4	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	120
5	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	✓
6	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	100
7	WHI	CHECK & INSPECT WIRE HARNESS FOR DAMAGE & OPEN/ SHORT CIRCUIT, REPAIR WHEN NECESSARY	240.00	X
8	ZZ/001	RENEW REAR BUMPER, BRACKETS, ENERGY ABSORBER, UPPER PANEL, STAYS, TAILGATE, WEATHERSTRIP, LUGGAGE PLATE		
9	ZZ/002	ETC PANELS & REPAIR <i>250/day</i>	2000.00	1000
10	ZZ/003	REMOVE & INSTALL REAR CARPETING TO FACILITATE REPAIR	120.00	✓
11	ZZ/004	REPLACE TAILGATE GLASS TO FACILITATE REPAIR	150.00	✓
12	ZZ/005	INSTALL SOLAR FILM ON TAILGATE GLASS	144.00	✓
13	ZZ/006	RESPRAY REAR BUMPER, TAILGATE, UPPER PANEL ETC <i>200/panel</i>	1000.00	600
14	ZZ/007	QC, RETUNE & CONSULT CHECK		
15	ZZ/008	WASH & VACUUM, POLISH & WAX, SHINE ALL TYRES	120.00	X
TOTAL LABOUR CHARGES			4789.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2514T

		DAMAGED PARTS & PRICES		
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMARKS
1	REAR W/SCREEN SEALANT ✓ NEC	SEALANT - 4		? 80.00
2	REVERSE SENSOR { ✓ DMG	SENSOR-TE5140		✓ 180.00
3	DIGI-S EMBLEM neg ✓ NEC	90893-3VU0A	✓ 51.20	
4	NOTE EMBLEM ✓ NEC	90892-3VA0A	73.60	
5	NISSAN EMBLEM ✓ NEC	90890-3VA0A	59.70	
6	TAILGATE HANDLE ?	90606-3VA0A	215.30	
7	ACTUATOR ?	90550-1HMOA	156.90	
8	LOCK ?	90502-1HM1A	116.70	
9	STRIKER ?	90570-1HMOB	31.70	
10	LUGGAGE PLATE ?	84992-3VA0A	63.50	
11	WEATHERSTRIP ?	90830-3VA0A	64.80	
12	TAILGATE CENTRE PANEL ?	90810-3VA5C	243.90	
13	TAILGATE GLASS ✓ NEC	90300-3VA0A	1240.00	
14	TAILGATE ✓ DT	K010M-3VAMA	976.40	
15	RIGHT BUMPER BRACKET ?	85220-3VA0C	44.00	
16	LEFT BUMPER BRACKET ?	85221-3VA0C	44.00	
17	BUMPER STAY (\$86.60 EA X 2) ✓ NEC	H5212-1HMMA	173.20	
18	ENERGY ABSORBER ?	85090-3VA0A	111.90	
19	CLIP (\$1.20 EA X 3) ✓ NEC	01553-10501	3.60	
20	REAR BUMPER ✓ Deform	85022-3VA0H	414.00	
21	REAR UPPER PANEL (End panel) ?	79100-3VA0A	552.80	
22	LEFT CLOSING PLATE ?	78819-3VA0A	45.00	
23	RIGHT CLOSING PLATE ?	78818-3VA0A	45.00	
24	FUEL LID X	78830-3VA0A	74.60	
25	RIGHT TAIL LAMP ?	26550-3VA5B	293.70	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB2514T

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
26	LEFT TAIL LAMP ?	26555-3VA5B	293.70			
27	LICENSE PLATE LAMP ASSY (\$62.10 EA X 2) ?	26510-8991B	124.20			
SUB TOTAL			5513.40	0.00	260.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			1102.68	0.00	0.00	
GRAND TOTAL			4410.72	0.00	260.00	
OVERALL TOTAL			4670.72			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB2514T

TOTAL LABOUR CHARGES	4789.00
TOTAL SPARE PARTS CHARGES	4670.72

GRAND TOTAL	9459.72 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.