

Surveyor

REF: CS/LAW 18004110 / mlqpn2

Special Instruction:

4s: \$ 10050-00

ASSIGNMENT (Office)

From (Person): Irene Lim of M Keelumuran Date/Time: 06022018

Estimated Cost: _____ Bill to: _____

Third Parties:

Claimant:

Surveyor: Auto Performance & Formteam

Workshop: T & S Motor.

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SJL 2382C Insured: SJC 4230S
at Workshop m/s: T & S Motor Tel: 9756 7923 (Malacca)

of Blok 5035 AMK Ind Park 2 # 01-357

Policy No: CLS-2016-213667 AXA Claim No: MN-7(1.T2-1611032A

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01072016

(Client's Record)

05-03-2018 (Monday) @ 2pm


SJE

H.O.D. Enforcement/Date: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time: 17/4/18 Confirmed with ly Final Fig _____, _____ days (Red \$ _____ / _____ %; Original 10 days)

Date/Time: 17/4/18 Submit Final Fig 6200, 7 days (Red \$ 3850, 38 %; Original 10 days)

Date/Time	Action/Instruction
	<u>Disregard the repair costs and repair period for the Frontal damages, owner no longer claiming for frontal damages only for its rear damages.</u>
	<u>SJL 2382C - CS/INC/16022499 / mlqpn2</u>
	<u>SJC 4230S - CS/AXA/30000008 / ml</u>
	<u>DA: 24/11/16</u>
	<u>DA: 28/12/12</u>
	
	<u>9/4/2018.</u>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

RECEIVED 12 APR 2018

Para(3) : Nett Value

Market Value : _____

Salvage Value : _____

Nett Value : _____

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1000

1) Date/Time 17/4/18 File Pass to myat

3) Date/Time _____ File Pass to _____

5) Date/Time _____ File Pass to _____

2) Date/Time _____ File Return to _____

4) Date/Time _____ File Return to _____

6) Date/Time _____ File Return to _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

M NEDUMARAN & CO*

Ref : CS/LAW18004110/M1qb

No. 11 SIN MING ROAD
#B2-09 (UNIT 2), THOMSON V TWO
SINGAPORE 575629

Date : 03-03-2018



Code : L134

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SJC 4230S	Veh. Inspected	SJL 2382C
Policy No.	CLS.2016.213667.AXA	Coverage (\$)	0.00
Claim No.	MN.IG.T2.1611032A	Excess (\$)	0.00
Assign From	IGENE LIM	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	09/07/2016	Inspection Date	05/03/2018
Survey held at	T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 SINGAPORE 569538		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Catherine Chong (LKK Auto)

From: Igene Lim <igene.lim@mneduco.com.sg>
Sent: Tuesday, 6 February, 2018 5:12 PM
To: Catherine Chong (LKK Auto); Celine Fong (LKKAuto); 'SUR'
Cc: Chua Li Suan
Subject: APPOINTMENT OF MA CHIN FOOK AS A SINGLE JOINT EXPERT
Attachments: 06022018163834.pdf; 06022018163954.pdf; 06022018163824.pdf

WITHOUT PREJUDICE

Our Ref : MN.IG.T2.1611032A

Dear Catherine,

Please find attached a copy of our letter with regard the appointment of Mr Ma Chin Fook as a Single Joint Expert in this matter.

Please let us hear from you soonest possible.

With thanks & regards,

IGENE LIM (MS)

(For and on behalf of Mr Nedumaran Muthukrishnan)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

Catherine Chong (LKK Auto)

From: Chua Li Suan <cls@comlaw.com.sg>
Sent: Thursday, 8 February, 2018 2:39 PM
To: Igene Lim; Catherine Chong (LKK Auto); Celine Fong (LKKAuto); 'SUR'
Subject: RE: APPOINTMENT OF MA CHIN FOOK AS A SINGLE JOINT EXPERT
Attachments: ACCIDENT STATEMENT OF SJC 4230S.PDF; PRI.PDF; SJL 2382C - PRS.PDF; SURVEY REPORT.PDF; Photo - SJL 2382C RI.PDF

Dear Mr Ma Chin Fook

1. Further to Igene's email of 6 Feb 2018 and its attachments, please also consider the attached documents:

- (a) Accident Statement of the driver of SJC 4230S
- (b) PRI report of Form Team with photos (PRI on 11 July 2016) (accident on 9 July 2016)
- (c) Re-survey report of Form Team with photos (re-survey on 9 September 2016)

2. Please also disregard the repair costs and repair period for the FRONTAL damages to SJL 2382C when putting up your report, as its owner is no longer claiming for its frontal damages but only for its rear damages.

Warm regards
Ms Chua Li Suan
DID: 6506 9132

ComLaw LLC
64 Cecil St #06-01
IOB Building
Singapore 049711

From: Igene Lim [<mailto:igene.lim@mneduco.com.sg>]
Sent: Tuesday, 6 February, 2018 5:12 PM
To: Catherine Chong (LKK Auto); Celine Fong (LKKAuto); 'SUR'
Cc: Chua Li Suan
Subject: APPOINTMENT OF MA CHIN FOOK AS A SINGLE JOINT EXPERT

WITHOUT PREJUDICE

Our Ref : MN.IG.T2.1611032A

Dear Catherine,

Please find attached a copy of our letter with regard the appointment of Mr Ma Chin Fook as a Single Joint Expert in this matter.

Please let us hear from you soonest possible.

With thanks & regards,
IGENE LIM (MS)
(For and on behalf of Mr Nedumaran Muthukrishnan)

M NEDUMARAN & CO
Advocates & Solicitors
Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : igene.lim@mneduco.com.sg

IMPORTANT NOTE: This electronic mail transmission (including any attachments) is private and confidential and may contain legally privileged information. If you are not the intended recipient, you may not use, copy or disseminate the information contained herein. Please delete this message and its attachments immediately and contact us at (65) 6509-8480 if you have received this message in error. Thank you.

Nivitha (LKK Auto)

From: Igene Lim <igene.lim@mneduco.com.sg>
Sent: Thursday, 22 February 2018 3:04 PM
To: Catherine Chong (LKK Auto); Celine Fong (LKKAuto); 'SUR'
Cc: Chua Li Suan
Subject: APPOINTMENT OF MA CHIN FOOK AS A SINGLE JOINT EXPERT // COMLAW'S
REF : CLS.2016.213667.AXA // MC SUIT NO. 20017/2016

WITHOUT PREJUDICE

Our Ref : MN.IG.T2.1611032A

Hi Catherine,

We have made an arrangement for our client's vehicle **SJL 2382C** to be available for re-inspection by the appointed Single Joint Expert, Mr Ma Chin Fook as follows:

Date : 5/3/2018 (Monday)
Time : 2.00 p.m.
Venue : T & S Motor Service
Block 5035 Ang Mo Kio Industrial Park 2
#01-357
Singapore 569538
Contact : Mei Hua @ 9756-7923

Kindly ensure that your surveyor attends to the above without fail.

Please also let us have your written confirmation on the above arrangement soon.

With thanks & regards,

Igene Lim

(For and on behalf of Mr Nedumaran Muthukrishnan)

M NEDUMARAN & CO

Advocates & Solicitors

Commissioner for Oaths

Branch Office :

No. 11 Sin Ming Road

#B2-09 (Unit 2), Thomson V Two

Singapore 575629

Tel : 6509-8480 / 6509-8481

Fax : 6509-8482

Email : igene.lim@mneduco.com.sg

1.03pm @ 22/2/18
vehicle Not In

M NEDUMARAN & CO

Advocates & Solicitors
Commissioner for Oaths

UEN NO. 53181067D

Please reply to our Branch Office for this matter

Nedumaran Muthukrishnan
LLM (hons) [Buckingham]
Barrister at Law (Lincoln's Inn)

Branch Office: No. 11 Sin Ming Road
#B2-09 (Unit 2), Thomson V Two
Singapore 575629
Tel : 6509-8480 / 6509-8481
Fax : 6509-8482
Email : lgene.lim@mneduco.com.sg

Our Ref : MN.IG.T2.1611032A

URGENT

6 February 2018

BY FAX 6256-4315 & POST

LKK AUTO CONSULTANTS PTE LTD
51 Paya Uni Industrial Park
Ubi Avenue 1, #02-25
Singapore 408933
Attention : Mr Ma Chin Fook

Dear Sir,

- SINGLE JOINT EXPERT FOR MOTOR VEHICLE NO. SJL 2382C
- MC SUIT NO. 20017 OF 2016
- ROAD TRAFFIC ACCIDENT ON 09/07/2016 INVOLVING VEHICLE NOS. SJL 2382C AND SJC 4230S

We refer to the above-captioned matter.

We act for the Plaintiff (motor vehicle no. SJL 2382C) and M/s ComLaw LLC acts for the Defendant (motor vehicle no. SJC 4230S) in the abovementioned suit arising out of a road traffic accident on 9th July 2016.

Please be informed that by consent of all parties, **MA CHIN FOOK** is appointed as a Single Joint Expert ("hereinafter referred to as SJE") for this action to provide an independent assessment in respect of the costs of repairs for vehicle no. SJL 2382C. Mr Ma Chin Fook is to determine the issue on quantum and to draw up an Affidavit of Evidence in Chief (AEIC) annexing a copy of the re-inspection report on the Plaintiff's vehicle SJL 2382C.

Kindly note that as a Single Joint Expert appointed by the Court, your primary duty is to the Court and you are required to give a fair and reasonable assessment of costs for the Plaintiff's motor vehicle SJL 2382C.

Our Ref : MN.G.T2.1611032A

We enclose herewith relevant document as follows:

- (1) The Plaintiff's GIA & Police reports;
- (2) The Defendant's GIA report;
- (3) Final repair bill from the Plaintiff's motor workshop;
- (4) Surveyor's report from the Plaintiff's appointed surveyor, Auto Performance Appraisal;
- (5) 94 coloured photos depicting damage to the Plaintiff's vehicle; and
- (6) Re-inspection report from FORMTEAM Consultancy Pte Ltd.

We would be grateful if your surveyor Mr Ma Chin Fook could let us know whether you will be available to conduct a re-inspection on the Plaintiff's motor vehicle SJL 2382C.

Thereafter, you are required to produce your re-surveyed report, inter alia, the estimated cost of repairs and number of days for repairs to the Plaintiff's motor vehicle, as well as the reason for the same.

Meanwhile, please also let us know the fees/costs chargeable for the re-inspection, preparation of the re-inspection report and affirmation of the Affidavit of Evidence in Chief with regard to the Plaintiff's motor vehicle SJL 2382C. We would also like to know the fees chargeable for the surveyor's attendance in Court should this matter proceed for a half day hearing.

Should you require further clarification on the above, please do not hesitate to call our Ms Igene Lim at 66509-8480.

Yours faithfully,

M NEDUMARAN & CO

NEDUMARAN MUTHUKRISHNAN
(Branch Office)

Encls

- c.c. 1) M/s ComLaw LLC – By fax 6538-7890 only
 Your Ref : CLS/2016/213667.svc
- 2) Client (SJL 2382C) (By fax 6481-5828 only)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 11/07/2016 13:08
Date Of Accident 09/07/2016 15:50
Exact Location Of Accident KJE TOWARDS BRICKLAND RD EXIT
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJL2382C
Insured/Policyholder
Name Of Registered Owner THIO TZE YUAN DESMOND
NRIC No S8125873B
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-92950090
Alternative Phone No Office-92950090
Vehicle Particulars
Manufacturer TOYOTA
Model VIOS-1.5 E (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? No
If No, Please state action to be taken Third Party
Vehicle Category Private Car
Insurance Company
Name of Insurance Company NTUC Income Insurance Co-operative Ltd
Type Of Coverage Comprehensive
Fleet Policy No
Policy Number 5052070439-04 (CLASSIC)
Cover Note Number
Driver
Name of Driver THIO TZE YUAN DESMOND
NRIC No S8125873B
Date Of Birth 29/08/1981
Occupation Outdoor
Date Of Driving Pass 02/10/2008
Driving Experience 7 Years And 9 Months
Gender Male
Mobile Number (Local) +65-92950090
Fax Number
Contact Number Office-92950090
Email Address NOEMAIL

Address: 488 ADMIRALTY LINK
#09-117
Postcode: S750488
Was driver an employee of the Insured's Company No
If No, Relationship of the Driver with the Insured Owner
Vehicle Registration Number of Driver's Own Vehicle
Vehicle
Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident Unknown - REFER TO POLICE REPORT
Weather Conditions Clear
Road Surface Dry

Other Information

Was any foreign vehicle involved in this accident? No
Was any body injured in the Accident? No
Was any other material or property damaged? Yes
Was there any video captured by Car Camera? No
Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? Yes
If Yes, Please state which Police Station

Police Station Name Ang Mo Kio South Neighbourhood Police Centre
Police Station Address ROAD: 81 Ang Mo Kio Ave 3, POSTCODE: 569929, COUNTRY: Singapore
Police Station Contact TEL NO: 1800-4519999 - FAX NO: 65535679
Was notice of intended Prosecution given? No
If Yes, against whom?

Circumstances of Accident

PLEASE SEE ATTACHED POLICE REPORT. ATTENDED BY: SUSAN

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJC4230S
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SBG8333B
Vehicle Make/Model/Colour
Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Authorised Driver.

3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the judgement of this report to the Insurers, you hereby consent in the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) my insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form(s) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law firms/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/postal packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law firms/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law firms/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

of the above Purpose.
IDAG BUKIT BATOK (VAC)
 511 Bukit Batok St 23
 Singapore 869545
 Tel: 6567 8427 / 6580 3312
 Fax: 6569 0722
 Email: wach@idag.com.sg
 Witnessed by Reporting Centre
 Personnel

0 Lamp Post No
225 36

9868332

Describe Circumstances of the Accident

Report

Refer to Police No : 1/20160710/20EP

Declaration

We declare the foregoing particulars are true in every respect.

11 JUL 2016

IDAC BUKIT BATOK (VAC)
 511 Bukit Batok St 23
 Singapore 659545
 Tel: 6567 9427 / 6560 3312
 Fax: 6569 0722
 Email: vacbb@singnet.com.sg

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



SINGAPORE POLICE FORCE



T/20160710/2044

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

1 of 4

Report No. T/20160710/2044

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 10/07/2016 12:20	Vide Report No.:	Station Diary No.: 55
--	------------------	--------------------------

Name of Informant: THIO TZE YUAN, DESMOND		Address: APT BLK 488 ADMIRALTY LINK #09-117 SINGAPORE 750488	
ID Type / ID No.: NRIC NO / S8125873B		Contact No.: Home/Office: Mobile: 92950090	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 34	Date of Birth: 29/08/1981	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SENIOR PROJECT MANAGER		Driving Licence Information: Class: Date of Expiry:	

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 09/07/2016 15:50	Type of Location: Gradient
Location: Along Road 1 KRANJI EXPRESSWAY Brickland Road EXIT Lamp Post Number: 225S8				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Vehicle No.	Vehicle Type	Make	Model	Color	Damage	Count
SBG8333B	Car				Slightly Damaged	0
SJC4230S	Car				Slightly Damaged	0
SJL2382C	Car	TOYOTA	VIOS E AUTO	Silver	Slightly Damaged	1



**SINGAPORE
POLICE FORCE**



T/20160710/2044

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

2 of 4

Report No. T/20160710/2044

CONTINUATION OF REPORT

SJL2382C	NTUC Income Insurance Co-Operative Limited	5052070439-04	20/11/2015	19/11/2016
----------	--	---------------	------------	------------

Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	KENNY ANG	ID No.	NIL
Related Vehicle	SJC4230S (Car)	Contact No.	81121707
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Name	THIO TZE YUAN, DESMOND	ID No.	S8125873B
Related Vehicle	SJL2382C (Car)	Contact No.	92950090
Hospital/Clinic	KHOO TECK PUAT HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	09/07/2016	Date Discharge	09/07/2016
No. of Days granted Medical Leave	04	Degree of Injury	Slight
Name	CHONG CHOY FOONG	ID No.	S8070314G
Related Vehicle	SJL2382C (Car)	Contact No.	97703917
Hospital/Clinic	KK WOMEN'S AND CHILDREN'S HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	09/07/2016	Date Discharge	09/07/2016
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight



**SINGAPORE
POLICE FORCE**



T/20160710/2044

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

3 of 4

Report No. T/20160710/2044

CONTINUATION OF REPORT

Brief Details.

ON THE ABOVE DATE AND TIME, I WAS DRIVING ALONG KJE AND EXITED AT BRICKLAND ROAD. AFTER I ENTER THE SLIP ROAD, I SAW THE CAR INFRONT BEARING PLATE NUMBER: SGB8333B MADE AN EMERGENCY BRAKE. I MANAGE TO BRAKE ON TIME BEHIND THE CAR.

AFTER A FEW SECONDS, THE CAR BEHIND BEARING PLATE NUMBER: SJC4230S COULD NOT BREAK ON TIME THUS HIT ONTO THE REAR OF MY CAR. THERES WERE DENTS AND SCRATCHES AT THE REAR BUMPER.

NO AMBULANCE AND POLICE CAME TO THE LOCATION. I MAKE MY WAY TO THE WORKSHOP IMMEDIATELY AFTER I HAVE SETTLE THE MATTER WITH THE DRIVERS.
I WENT TO THE HOSPITAL THEREAFTER AS ME AND MY PREGNANT WIFE FELT PAIN ON OUR NECK AND BACK.



**SINGAPORE
POLICE FORCE**



T/20160710/2044

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

4 of 4

Report No. T/20160710/2044

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MEGAT INDRA PUTRA BIN MOHD SAHARI	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 10/07/2016 12:20
Officer In Charge Of Case: TP / AEIT / SSI 2 JUREMAH BINTE AHMAD Contact No.: 65476190	Classification Of Case: SN 005
Authentication Stamp NP168	Signature:

Singapore Police Force

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	11/07/2016 15:50
Date Of Accident	09/07/2016 16:00
Exact Location Of Accident	KJE SLIP ROAD EXIT TO BRICKLANDS ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC4230S
Insured/Policyholder	
Name Of Registered Owner	KAREN CHAN @ NG BEE TIN
NRIC No	S7404138H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81282115
Alternative Phone No	Others-81121707

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC IMA A
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
If No, Please state action to be taken	
Vehicle Category	Private Car

Insurance Company

Name of Insurance Company	AXA Insurance Singapore Pte Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA087978/1
Cover Note Number	

Driver

Name of Driver	ANG SWEE BENG, KENNY (HONG RUIMING, KENNY)
NRIC No	S8403195Z
Date Of Birth	20/08/1984
Occupation	Indoor
Date Of Driving Pass	28/11/2002
Driving Experience	13 Years And 7 Months
Gender	Male
Mobile Number	(Local) +65-81121707
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	18 PAVILION CIRCLE
Postcode	658488
Was driver an employee of the Insured's Company	No
If No, Relationship of the Driver with the Insured	Friend
Vehicle Registration Number of Driver's Own Vehicle	SGJ535M
	-
	-
Insurance Company of Driver's Own Vehicle	NTUC Income Insurance Co-operative Ltd
	-
	-

General Information of the Accident

Type Of Accident	Collision- Head to Rear (Insured Hit TP)
Weather Conditions	Clear
Road Surface	Dry

Other Information

Was any foreign vehicle involved in this accident?	No
Was any body injured in the Accident?	No
Was any other material or property damaged?	Yes
Was there any video captured by Car Camera?	No
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	No
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	No
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN.

Are accident photos available for attachment?	Yes
---	-----

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJL2382C
Vehicle Make/Model/Colour	TOYOTA VIOS E AUTO
Details Of Properties	
Name of Driver	DESMOND THIO
NRIC/Passport Number	
Contact Number	92950090
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel



Sketch Plan

Bricklands Road

KJE Sup Road

Exit to Bricklands Road

Vehicle A: 8JC4230S

Largest
225SG

Vehicle B: 8JL2382C



Witness

KJE

Sketch Plan #2

Describe Circumstances of the Accident

I was Vehicle A was travelling ESE Slip Road towards
Bricklands Road. All of a sudden a few vehicles started to jam
brake. I jammed brake too but my vehicle skidded & collided
into vehicle B.

I got down & driver in front of vehicle B told us
the front vehicle in front of him jammed brake hence he did so.
Within few minutes, a tow truck suddenly appeared and asked
if we wanted to bring our vehicles to his workshop.


Vehicle A: SSC 4230S

Vehicle B: SJR 0382C

Witness: Lian Huiat 9656 3188.

Declaration


We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time



Driver's Signature (if driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel



Insurance Co. _____	
Vehicle NO. _____	Date Of Accident _____ / _____ / _____
<input type="checkbox"/> Reporting Only <input type="checkbox"/> Own Damage Claim <input type="checkbox"/> Third Party Claim	

AUTO PERFORMANCE APPRAISAL

APA

TAX INVOICE

Thio Tze Yuan Desmond
C/O T & S Motor Service
Blk 5035 Ang Mo Kio Industrial Park 2
#01-357
Singapore 569538

INVOICE NO : APA16001038

DATE : 22/07/2016

VEHICLE NO : SJL2382C
JOB REFERENCE NO : 16/001129
ACCIDENT DATE : 09/07/2016
SURVEY DATE : 12/07/2016

<u>DESCRIPTION</u>	<u>AMOUNT</u>
Survey Fees Inclusive Of	\$540.00
Transportation	
Photographs (\$1) Per Copies : 94	\$94.00

TOTAL AMOUNT : \$634.00

Notes :

All cheque payment should be "Crossed" and made payable to "Auto Performance Appraisal"

Auto Performance Appraisal



AUTO PERFORMANCE APPRAISAL

APA

VEHICLE SURVEY REPORTS																																
Thio Tze Yuan Desmond C/O T & S Motor Service Blk 5035 Ang Mo Kio Industrial Park 2 #01-357 Singapore 569538																																
1	Reference Job Reference No : 16/001129 Claim No : - Claim Type : Third Party Accident Date : 09/07/2016 Survey Date : 12/07/2016 Survey Report Date : 22/07/2016																															
2	Particulars Of Vehicle Vehicle Registration No : SJL2382C Make & Model : Toyota Vios 1.5E Auto Vehicle Registration Date : 20/11/2008 Chassis No : MR053HY9305080454 Engine No : Blocked Colour : Silver																															
3	Condition Of Vehicle And Tyres <table border="1"> <thead> <tr> <th><u>Mileage (KM)</u></th> <th><u>Brakes</u></th> <th><u>Steering</u></th> <th><u>Modification</u></th> </tr> </thead> <tbody> <tr> <td>274169</td> <td>Serviceable</td> <td>Serviceable</td> <td>None</td> </tr> <tr> <th><u>Tyres</u></th> <th><u>Make</u></th> <th><u>Size</u></th> <th><u>Balance (MM)</u></th> </tr> <tr> <td>Front RHS</td> <td>Crucero</td> <td>195/55R15</td> <td>5</td> </tr> <tr> <td>Front LHS</td> <td>Crucero</td> <td>195/55R15</td> <td>5</td> </tr> <tr> <td>Rear RHS</td> <td>Crucero</td> <td>195/55R15</td> <td>6</td> </tr> <tr> <td>Rear LHS</td> <td>Crucero</td> <td>195/55R15</td> <td>6</td> </tr> </tbody> </table>				<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>	274169	Serviceable	Serviceable	None	<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>	Front RHS	Crucero	195/55R15	5	Front LHS	Crucero	195/55R15	5	Rear RHS	Crucero	195/55R15	6	Rear LHS	Crucero	195/55R15	6
<u>Mileage (KM)</u>	<u>Brakes</u>	<u>Steering</u>	<u>Modification</u>																													
274169	Serviceable	Serviceable	None																													
<u>Tyres</u>	<u>Make</u>	<u>Size</u>	<u>Balance (MM)</u>																													
Front RHS	Crucero	195/55R15	5																													
Front LHS	Crucero	195/55R15	5																													
Rear RHS	Crucero	195/55R15	6																													
Rear LHS	Crucero	195/55R15	6																													
4	Description Of Damages The vehicle sustained damages at frontal and rear portion. (For information of damages please refer to Parts/Labour/Photographs attached)																															
5	Instruction This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.																															

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

Ref No : 16/001129

Damage And Repair Cost Adjustment

<u>S/No</u>	<u>Qty</u>	<u>Parts Description</u>	<u>Comments/condition</u>	<u>Workshop Estimate (\$)</u>	<u>Our Assessment (\$)</u>
			<u>List Items</u>		
1	1	Front bumper	Deformed/broken	447.25	✓ 447.25
2	2	Front bumper fog lamp cover	Reuse	130.00	-
3	1	Front bumper "TOYOTA" logo	Necessary	47.67	✓ 47.67
4	2	Front bumper side retainer	Broken	107.80	✓ 107.80
5	1	Front bumper reinforcement	Buckled	361.00	✓ 361.00
6	1	Front bumper inner top garnish	Deformed	169.70	✓ 169.70
7	1 set	Front bumper clips	Broken/necessary	30.00	✓ 30.00
8	1	Front bonnet	To repair	488.20	-
9	1	Front support panel assy	To repair	883.40	-
10	2	Front headlamp	Broken/cut	767.00	✓ 767.00
11	1	Rear bumper	Deformed/torn	451.60	✓ 451.60
12	2	Rear bumper reflector	Broken/cut	185.80	✓ 185.80
13	2	Rear bumper side bracket	Bent	112.60	✓ 112.60
14	2	Rear bumper side retainer	Broken	171.20	✓ 171.20
15	1 set	Rear bumper clips	Broken	30.00	✓ 30.00
16	1	Rear boot lid	Bent/dented	589.10	✓ 589.10
17	1	Rear boot outer handle garnish	Deformed	175.00	✓ 175.00
18	1	Rear boot centre "TOYOTA" logo	Necessary	48.10	✓ 48.10
19	1	Rear boot "VIOS" emblem	Necessary	55.60	✓ 55.60
20	1	Rear boot "E" emblem	Necessary	45.30	✓ 45.30
21	2	Rear boot hinge	Bent	128.00	128.00 X nn
22	1	Rear boot top lock	Bent/jammed	121.35	✓ 121.35
23	1	Rear boot lower lock catch	Bent	41.40	✓ 41.40
24	1	Rear boot weatherstrip	Cut	176.80	✓ 176.80
25	2	Rear taillamp panel	Buckled	257.00	257.00 X nn
26	2	Rear taillamp	Broken/cracked	665.20	✓ 665.20
27	1	Rear end panel	Buckled	575.00	✓ 575.00
28	1	Rear end panel top garnish	Deformed	211.40	✓ 211.40
29	1	Rear spare tyre top board	Deformed/cut	139.50	✓ 139.50
30	1	Rear spare tyre compartment	Buckled	682.50	✓ 682.50
31	2	Rear floor side panel	To repair	272.00	-
32	1	Rear compartment centre sponge tray	Dented/cut	167.50	✓ 167.50
33	1	Rear compartment RH sponge tray	Dented/cut	192.36	✓ 192.36
34	1	Rear compartment LH sponge tray	Dented/cut	154.35	✓ 154.35
35	2	Rear fender	RH dented/LH repair	1,391.50	695.75 X nn
36	2	Rear fender inner side trim	Deformed/cut	451.00	✓ 451.00
37	1 set	Rear fender inner side trim clips	Necessary	50.00	✓ 50.00
38	2	Rear fender under shield	Deformed	112.00	112.00 X nn

AUTO PERFORMANCE APPRAISAL

Annex A

Vehicle Assessment Reports

39	1 set	Rear fender under shield clips	Necessary	30.00	30.00 ✓
40	1	Rear windscreen moulding	Necessary	102.00	102.00 X nn
41	1	Rear RH chassis member	To repair	568.50	-
42	1	Rear exhaust silencer	Bent	811.30	811.30 2205/14
43	3	Rear exhaust silencer mounting	Deformed/cut	111.00	111.00 X nn

Less discount 25%

	12,707.98	9,670.13
	3,177.00	2,417.53
Total :	9,530.99	7,252.60

Special Nett Items

44	1	Front number plate	Bent/cut	45.00	45.00 X nn
45	1	Rear number plate	Bent/cut	45.00	45.00 /
46	1 set	Reverse sensors	Broken	250.00 500	250.00 220
47	1	Rear windscreen sealant	Necessary	50.00 40	50.00 /
48	1	Rear end panel/floor panel sealant	Necessary	50.00	50.00 /

Total :	440.00	440.00
---------	--------	--------

Total Spare Parts :	9,970.99	7,692.60
---------------------	----------	----------

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Annex B

Ref No : 16/001129

Damage And Repair Cost Adjustment

<u>Items</u>	<u>Job Description</u>	<u>Workshop Estimate (\$)</u>	<u>Adjusted Costs (\$)</u>
1	To tow vehicle to workshop.	60.00	60.00 ✓
2	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	2,200.00	1,800.00 1400
3	To putty and respray painting on affected areas.	2,500.00	2,000.00 1200
4	To remove, refix aircon condenser, pipes, drier vacuum and recharge gas.	150.00	120.00 X
5	To remove, refix rear windscreen glass.	150.00	120.00 X
6	To rewire check lightings for front and rear portion.	100.00	60.00 30
7	To remove, refix reverse sensor.	80.00	50.00 ✓
8	To remove, refix rear upholstery, garnish and attachments.	120.00	80.00 60
9	To remove, refix roof linings, rear seats, carpet and trims.	200.00	150.00 80
10	To remove, refix rear boot fittings to facilitate repair.	80.00	50.00 X
11	To remove, refix rear exhaust silencer.	80.00	50.00 ✓
12	To check, adjust, align chassis alignment back into its original specifications.	300.00	250.00 X
13	To apply undersealing.	120.00	90.00 ✓

Total Labour : 6,140.00 4,880.00

Total Spare Parts : 9,970.99 7,692.60

Total Labour : 6,140.00 4,880.00

Total Repair Costs : 16,110.99 12,572.60

AUTO PERFORMANCE APPRAISAL

Annex B

Vehicle Assessment Reports

Assessor's Recommendation

Repairer Estimate : 16,110.99

Our Adjustment : 12,572.60

Remarks

The repairer has agreed to undertake the repair of \$10,050.00, with a repair period of 10 working days.

Surveyed By:



Lek Boon Hwee
Automobile Appraiser

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

M NEDUMARAN & CO*

Ref : CS/LAW18004110/M1qbn2

No. 11 SIN MING ROAD
#B2-09 (UNIT 2), THOMSON V TWO
SINGAPORE 575629

Date : 12-04-2018



Code : L134

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SJC 4230S	Veh. Inspected	SJL 2382C
Policy No.	CLS.2016.213667.AXA	Coverage (\$)	0.00
Claim No.	MN.IG.T2.1611032A	Excess (\$)	0.00
Assign From	IGENE LIM	Assign Date	06/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053HY9305080454	Colour	SILVER
Odometer	315137	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	MICHELIN	7 mm
L/H Front Tyre	195/55 R15	MICHELIN	7 mm
R/H Rear Tyre	195/55 R15	MICHELIN	7 mm
L/H Rear Tyre	195/55 R15	MICHELIN	7 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.
REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	09/07/2016	Inspection Date	05/03/2018
Survey held at	T & S MOTOR SERVICE BLK 5035 ANG MO KIO INDUSTRIAL PARK 2 #01-357 . SINGAPORE 569538		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJL 2382C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	NOT NECESSARY	447.25	-
2	FRONT BUMPER FOG LAMP COVER	NOT NECESSARY	130.00	-
1	FRONT BUMPER "TOYOTA" LOGO	NOT NECESSARY	47.67	-
2	FRONT BUMPER SIDE RETAINER	NOT NECESSARY	107.80	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	361.00	-
1	FRONT BUMPER INNER TOP GARNISH	NOT NECESSARY	169.70	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	30.00	-
1	FRONT BONNET	NOT NECESSARY	488.20	-
1	FRONT SUPPORT PANEL ASSY	NOT NECESSARY	883.40	-
2	FROTN HEADLAMP	NOT NECESSARY	767.00	-
1	REAR BUMPER	REPLACED	451.60	451.60
2	REAR BUMPER REFLECTOR	REPLACED	185.80	185.80
2	REAR BUMPER SIDE BRACKET	REPLACED	112.60	112.60
2	REAR BUMPER SIDE RETAINER	REPLACED	171.20	171.20
1	SET REAR BUMPER CLIPS	REPLACED	30.00	30.00
1	REAR BOOT LID	REPLACED	589.10	589.10
1	REAR BOOT OUTER HANDLE GARNISH	REPLACED	175.00	175.00
1	REAR BOOT CENTRE "TOYOTA" LOGO	REPLACED	48.10	48.10
1	REAR BOOT "VIOS" EMBLEM	REPLACED	55.60	55.60
1	REAR BOOT "E" EMBLEM	REPLACED	45.30	45.30
2	REAR BOOT HINGE	NOT NECESSARY	128.00	-
1	REAR BOOT TOP LOCK	REPLACED	121.35	121.35
1	REAR BOOT LOWER LOCK CATCH	REPLACED	41.40	41.40
1	REAR BOOT WEATHERSTRIP	REPLACED	176.80	176.80
2	REAR TAILLAMP PANEL	NOT NECESSARY	257.00	-
2	REAR TAILLAMP	REPLACED	665.20	665.20
1	REAR END PANEL	REPLACED	575.00	575.00
1	REAR END PANEL TOP GARNISH	REPLACED	211.40	211.40
1	REAR SPARE TYRE TOP BOARD	REPLACED	139.50	139.50
1	REAR SPARE TYRE COMPARTMENT	REPLACED	682.50	682.50

Report Ref No. CS/LAW18004110/M1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FLOOR SIDE PANEL	REPAIRED SEE LABOUR	272.00	-
1	REAR COMPARTMENT CENTRE SPONGE TRAY	REPLACED	167.50	167.50
1	REAR COMPARTMENT RH SPONGE TRAY	REPLACED	192.36	192.36
1	REAR COMPARTMENT LH SPONGE TRAY	REPLACED	154.35	154.35
2	REAR FENDER	NOT NECESSARY	1,391.50	-
2	REAR FENDER INNER SIDE TRIM	REPLACED	451.00	451.00
1	SET REAR FENDER INNER SIDE TRIM CLIPS	REPLACED	50.00	50.00
2	REAR FENDER UNDER SHIELD	NOT NECESSARY	112.00	-
1	SET REAR FENDER UNDER SHIELD CLIPS	REPLACED	30.00	30.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	102.00	-
1	REAR RH CHASSIS MEMBER	REPAIRED SEE LABOUR	568.50	-
3	REAR EXHAUST SILENCER MOUNTING	NOT NECESSARY	111.00	-
	LESS 25% DISCOUNT		-2,974.17	-1,380.67
			8,922.51	4,141.99
1	REAR EXHAUST SILENCER (SN)	REPLACED	811.30	220.00
	LESS 25% DISCOUNT		-202.82	-
			608.48	220.00
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	REAR NUMBER PLATE (SN)	REPLACED	45.00	45.00
1	SET REVERSE SENSORS (SN)	REPLACED	250.00	220.00
1	REAR WINDSCREEN SEALANT (SN)	REPLACED	50.00	50.00
1	REAR END PANEL/FLOOR PANEL SEALANT (SN)	REPLACED	50.00	50.00
			440.00	365.00
	<u>LABOUR</u>			
	TO TOW VEHICLE TO WORKSHOP.		60.00	60.00
	TO REMOVE,CUT OUT DAMAGE PORTION,JACK OUT,STRAIGHTEN,PANEL BEATING,WELDING,ALIGN AND RENEW REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR SIDE PANEL AND REAR RH CHASSIS MEMBER.		2,200.00	1,400.00

Report Ref No. CS/LAW18004110/M1qbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		2,500.00	1,200.00
	TO REMOVE,REFIX AIRCON CONDENSER,PIPES,DRIER VACUUM AND RECHARGE GAS.	NOT NECESSARY	150.00	-
	TO REMOVE,REFIX REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO REWIRE CHECK LIGHTINGS FOR FRONT AND REAR PORTION.		100.00	30.00
	TO REMOVE,REFIX REVERSE SENSOR.		80.00	50.00
	TO REMOVE,REFIX REAR UPHOLSTERY,GARNISH AND ATTACHMENTS.		120.00	60.00
	TO REMOVE,REFIX ROOF LININGS,REAR SEATS,CARPET AND TRIMS.		200.00	80.00
	TO REMOVE,REFIX REAR BOOT FITTINGS TO FACILITATE REPAIR.	NOT NECESSARY	80.00	-
	TO REMOVE,REFIX REAR EXHAUST SILENCER.		80.00	50.00
	TO CHECK,ADJUST,ALIGN CHASSIS ALIGNMENT BACK INTO ITS ORIGINAL SPECIFICATIONS.	NOT NECESSARY	300.00	-
	TO APPLY UNDERSEALING.		120.00	90.00
			6,140.00	3,020.00
GRAND TOTAL			16,110.99	7,746.99
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,200.00

Report Ref No. CS/LAW18004110/M1qbn2

MA CHIN FOOK

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.