



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving

1 2009 VOLKSWAGEN TIGUAN 2.0 (SJU6263P)

Date of Loss

28 February 2018

Time of Loss

2.00

Loss Description

SJU 6263P (INSD) HIT VEHICLE SLP5913G (TP)

Comment

Workshop Details

Total Rebate Amount

17227

Nett Loss Amount

\$13,773.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (OD)

Target Date of Completion *

09/05/2018



Days of work completion *

21



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SJU6263P

Purchase Date

dd/mm/yyyy



Registration State

SINGAPORE

Registration Date *

18/12/2009



Mileage

146453

Age of Vehicle

8

CATEGORY

Manufacturing Year

POLICY INFORMAT... 2009

ASSESSMENT INFO...

2009

Driver Details

CATEGORY

Driver Name

FNOL INFORMATI...

ANDREW MOK

POST SURVEY INF...

CATEGORY Make

POLICY INFORMAT... VOLKSWAGEN

ASSESSMENT INFO... VOLKSWAGEN

CATEGORY Model

POLICY INFORMAT... TIGUAN 2.0

ASSESSMENT INFO... TIGUAN 2.0T AUTO 5N12T3 4WD

CATEGORY Type

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Type of Paint

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Chassis No

POLICY INFORMAT... WVGZZZ5NZAW043602

CATEGORY Date of Birth

FNOL INFORMATI... 20 November 1975

POST SURVEY INF... dd/mm/yyyy



CATEGORY Age

FNOL INFORMATI... 42

POST SURVEY INF...

CATEGORY Occupation

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Education Qualification

FNOL INFORMATI... Other

POST SURVEY INF...

CATEGORY Driving Experience

ASSESSMENT INFO...

CATEGORY Engine No

POLICY INFORMAT... CAW075520

ASSESSMENT INFO...

CATEGORY Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

CATEGORY Sum Insured

POLICY INFORMAT... 0

ASSESSMENT INFO...

CATEGORY Market Value

POLICY INFORMAT... 0

ASSESSMENT INFO...

FNOL INFORMATI... 1

POST SURVEY INF...

CATEGORY Driver License #

FNOL INFORMATI... S7538259F

POST SURVEY INF...

CATEGORY License Type

FNOL INFORMATI... 3

POST SURVEY INF...

CATEGORY License Issue Date

FNOL INFORMATI... 10 October 2016

POST SURVEY INF...

CATEGORY License Expiration Date

FNOL INFORMATI... 10 October 2026

POST SURVEY INF...

CATEGORY Address

FNOL INFORMATI... Singapore

POST SURVEY INF...

CATEGORY Address type

FNOL INFORMATI... Personal Correspondence

POST SURVEY INF...

CATEGORY Gender

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Marital status

FNOL INFORMATI... Unknown

POST SURVEY INF...

CATEGORY Identification #

FNOL INFORMATI... S7538259F

POST SURVEY INF...



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/03/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/Unnamed Driver Excess

0

Other Excess

Age of Tyres

Front Tyre Size

235/50R18

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

-- none --



Tyre Condition

Spare wheel

Rear Tyre Size

235/50R18

Front left side

HANKOOK8mm

Front right side

HANKOOK8mm

Rear left side

BRIDGESTONE3mm

Rear right side

BRIDGESTONE3mm



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes

No

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

Add

Approve

Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		1	1			HEADLAMP LH			Cracked	285				285	Reviewing
		2	1			HEADLAMP BRACKET LH (NPA)			Repair	0	0	0	0	0	Deny
		3	1			FRONT FENDER LH			Buckled	240				240	Reviewing
		4	1			FRONT FENDER SHIELD LH			Damaged	58				58	Reviewing
		5	10			FRONT FENDER SHIELD CLIPS			Necessary	1.5				15	Reviewing
		6	1			FRONT FENDER LOWER GARNISH LH (NPA)			Serviceable	0	0	0	0	0	Deny
		7	1			FRONT BUMPER			Buckled	430				430	Reviewing
		8	10			FRONT BUMPER CLIPS			Necessary	1.5				15	Reviewing
		9	1			FRONT BUMPER SIDE RETAINER LH			Damaged	15				15	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		10	1			FRONT BUMPER SIDE RETAINER RH			Serviceable	0	0	0	0	0	Deny
		11	1			FRONT BUMPER LOWER LIP / GARNISH			Serviceable	0	0	0	0	0	Deny
		12	1			FRONT BUMPER FOG LAMP LH			Serviceable	0	0	0	0	0	Deny
		13	1			FRONT WHEEL ARCH LH			Cracked	170				170	Reviewing
		14	1			FRONT WHEEL RIM			Repair	0	0	0	0	0	Deny
		15	1			FRONT LOWER ARM LH			Serviceable	0	0	0	0	0	Deny
		16	1			FRONT STABILIZER LINK LH			Serviceable	0	0	0	0	0	Deny
		17	1			FRONT ABSORBER LH			Serviceable	0	0	0	0	0	Deny
		18	1			FRONT ABSORBER STOPPER LH			Serviceable	0	0	0	0	0	Deny
		19	1			FRONT ABSORBER MOUNTING LH			Serviceable	0	0	0	0	0	Deny
		20	1			FRONT KNUCKLE ARM LH			Bent	260				260	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/J BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)
		21	1			FRONT KNUCKLE ARM BEARING LH			Necessary	195				195	Reviewing
		22	1			FRONT TIE ROD LH			Bent	45				45	Reviewing
		23	1			FRONT TIE ROD END LH			Bent	55				55	Reviewing
		24	1			FRONT DOOR LH			Repair	0	0	0	0	0	Deny
		25	1			FRONT DOOR UPPER HINGE LH			Repair	0	0	0	0	0	Deny
		26	1			FRONT DOOR LOWER HINGE LH			Serviceable	0	0	0	0	0	Deny
		27	1			FRONT ABS SENSOR LH				0				0	Reviewing
		28	1			FRONT GRILLE WITH MOULDING CHROME			Serviceable	0	0	0	0	0	Deny
		29	1			FRONT GRILLE EMBLEM			Serviceable	0	0	0	0	0	Deny

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
------	-------	-------------------------	-----------	------------	---------------	-------	-----------------	---------	--------

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
		1		PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS.	400	0	0	Reviewing		
		2		PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	500	0	0	Reviewing		
		3		PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	20	0	0	Reviewing		
		4		PROVIDE SKILL LABOUR TO REMOVE AND REPLACE/ REFIT FRONT LEFT UNDERCARRIAGE	200	0	0	Reviewing		
		5		PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	60	0	0	Reviewing		
		6		PROVIDE SKILL LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT E.G. ABS, SRS, ECU MEMORY ETC	0	0	0	Deny		
		7		DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR / FACILITATE REPAIR	0	0	0	Deny		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Add

Approve

Deny

	EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
		1	HANKOK 235/50R18 97V	Deny	0	SERVICEABLE	
		2	DAYS OF REPAIR : 5 DAYS	Reviewing			
		3	PROVIDE SKILL LABOUR TO REMOVE AND REPLACE, BALANCING WHEEL RIM AND FRONT TYRE	Reviewing	20	SUPPLEMENTARY	

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Claim Amount \$2,983.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$1,180.00	\$1,180.00
Spare Parts	\$1,783.00	\$1,783.00
Miscellaneous	\$20.00	\$20.00

Submit for Review