

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SLF 3756 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	//
2	To remove and renew air cond condenser, radiator, check fan, control unit, pressurise cooling system, vacuum and regas.	S/N \$ 1,200.00	//
3	To remove frontal fittings, dismantle front bumper, bonnet, rhs front fender, cut out and reweld, rhs fender support, rhs chassis console bracket. Dismantle and renew lock carrier, carrier bracket. Renew front bumper, bracket and carrier. Renew rhs front fender, bonnet, hinges headlamps and re-organise crash management components. Realign panels, re-install all parts removed. Repair rhs A pillar.	\$ 6,000.00	4000 <del>4000</del> 3000
4	To remove and reinstall both front door inner trim to facilitate renewal of both top chrome mouldin, removal and reinstallation of both wing mirror assy for respray.	S/N \$ 600.00	//
5	To respray front bumper, bonnet, lhs/rhs front fender, lhs/rhs front door and fender support.	\$ 5,400.00	3850
6	To carry out diagnostic.	S/N \$ 280.00	//
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 13,840.00</b>	