

XMR

REF: ALH

CC3/ALH18004129/Gibber

ASSIGNMENT

From: Date: 03032018

Estimated Cost:

OD / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

~~SLF 3756J~~ SLF 3756J

at Workshop no:

Premium

of

55 Ubi Rd 1

Insured

Policy No: 2100479661

Claims No: 073597415256

Sum Insured

Excess:

600 06/3/18

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Est. or Market Value:

\$138K

IDAC Accident Rpt:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

11

days

Rep:

Yes or No

Cum Sum:

%

3 Val:

Yes or No

GA / REV / REP. / 24 HRS

Date

Person Contacted:

Vehicle IN / OUT

Veh No:

SLF 3756J

Page 24 Aug 2016

Type: M / C / Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Audi A4

1395

Colour

Black

R/C

Insured / Std / NI / NA

Se Reading

2834

T Radio

Insured / Std / NI / NA

Eng No:

Ch No:

WAU888 F85 HA 009484

Gen Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size

F:

225/50R17

R:

"

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

6

mm

R/Bal

6

mm

L/Bal

6

mm

L/Bal

6

mm

D/OA

D/OI

02-03-18

Survey held at

w/s

11:30 AM

Des. of Damages

Fr

Rear / O/S / N/S / U/C / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collect

Date Time Action Instruction

SLF 3756J-X

05/3/18 @ 2:52pm Victor to Victor via messenger.

05/3/18 @ 5:04pm Victor informed CFA via messenger.

06/3/18 @ 11:46am Informed Tony CFA & ex: \$600 by email.

25/4/18 @ 2:15pm confirmed with Mr Bob final pay \$27248.70, 1 days.

(Paid \$11919.80, 30%)

RECEIVED 16 MAY 2018

Case Time File Passes?



Prel. Report

u/s driver



Final Report

Case Time File Return?

Days Of Repair:

11

Resurvey No. of Trip:

1

Survey Fee

200

Transaction

Add Fee:



One hour

\$



Intermittent

\$



Technician

\$



Vehicle

\$

Report Format:

UIC-OP

Lump Sum / B/L:

27248.70

10

240



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18004129/Gqb

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 05-03-2018



Code : AIG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SLF 3756J
Policy No. 2100479661	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date 27/02/2018	Inspection Date 02/03/2018
Survey held at PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 SINGAPORE 408699	

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 25 April 2018 2:15 PM
To: Boo seng yak; Guo Qiang (LKKAuto); SUR; Carrine Leong; Nora Khai
Subject: RE: FINAL REVISION SLF3756J - OD AIG - SURVEYED 2 FEB 18

Dear Mr Boo,

Confirm final fig \$27,248.20 before excess \$600.00 & GST and 11 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak [mailto:boojohnny@gmail.com]
Sent: Wednesday, 18 April 2018 6:52 PM
To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; Nora Khai <nora.khai@premiumauto.com.sg>
Subject: FINAL REVISION SLF3756J - OD AIG - SURVEYED 2 FEB 18

Hi Guo Qiang and all,

Revised estimate and photographs of check items is attached.

Please confirm repair cost of \$27,248.20 @ 11 days of repairs.

Your early closure is well appreciated.

Best regards - jb

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 6 March 2018 11:46 AM
To: Claims; SUR
Subject: RE: SLF 3756 J Own Damage Claims (VEHICLE IN)

Dear Tony,

As instructed by our client AIG, please proceed to repair the insured vehicle **SLF 3756J (excess \$600/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims [<mailto:claims@premiumauto.com.sg>]
Sent: Monday, 5 March 2018 7:20 PM
To: SUR <sur@lkkauto.com>
Cc: claims@premiumauto.com.sg
Subject: RE: SLF 3756 J Own Damage Claims (VEHICLE IN)

Dear all,

Owner just complain to us. He have contact AIG and the repair is approved and why we still cannot start repair.

Kindly advise.

Thank you.

Best Regards,

Tony Foong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199903271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	27 Feb 2018 17:25	Cim Veh Model Changed		[] Merimen Administrator
2	27 Feb 2018 17:25	Cim Created	Reg No: SLF3756J. Policy No: 2100479661-01. Acct Date: 2018/02/27. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MPA118028083	[I] Merimen Administrator
3	05 Mar 2018 11:15	Cim Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	05 Mar 2018 11:15	Adj Cim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	05 Mar 2018 11:15	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	05 Mar 2018 11:15	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/14	[A] CATHERINE CHONG KAI LING
7	05 Mar 2018 11:15	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	05 Mar 2018 11:15	Cim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	05 Mar 2018 11:15	Cim Veh Model Changed	(204616) AUDI A4 1.4 TFSI S TRONIC (A).	[A] CATHERINE CHONG KAI LING
10	05 Mar 2018 11:15	Adj Adjuster Assigned	[None] -> XING GUO QIANG	[A] CATHERINE CHONG KAI LING
11	05 Mar 2018 14:22	Adj Rpt Initiated		[A] SHIAU CHAN
12	05 Mar 2018 14:22	Cim Details Notified		[A] SHIAU CHAN
13	05 Mar 2018 14:47	Cim Registration Modified	Init.Est.:>5,000 - 6,000. Excess: -> 600.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Dally Amri, Mimi Zarina
14	05 Mar 2018 14:47	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
15	05 Mar 2018 14:51	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/14	[A] SHIAU CHAN
16	05 Mar 2018 14:52	Adj Mandate Request	Cur.Req:34502.00:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
17	05 Mar 2018 17:04	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/14. Mandate Remarks: Why is the labour 8 days for replacing Front support, Bonnet, RH front fender, Reinforcement, kindly re-adjust on the labour. Re-inspection to be done for damage check and supplementary items / lab	[I] Koh, Victor-CK
18	05 Mar 2018 17:04	Adj Mandate Set	Approved:28126.00:Why is the labour 8 days for replacing Front support, Bonnet, RH front fender, Reinforcement, kindly re-adjust on the labour. Re-inspection to be done for damage check and supplementary items / labour. Reinsp:Yes.	[I] Koh, Victor-CK

ACTIVITY

No record

labour 8 Days for replacing Front Support, Bonnet, Fenders, Reinforce ment, Head lamp, knocking RH fender bumper support panel

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1739177	05/03/2018 14:22	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLF3756J		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Syed-Yusoff, Saliha

Date: 05 Mar 2018

Preliminary Advice

Vehicle No	: SLF3756J	Accident Date	: 27/02/2018
Make	: AUDI A4	Policy No.	: 2100479661-01
Assignment Date	: 05/03/2018	Excess	: S\$0.00
Date of Inspection	: 02/03/2018	Est. Duration of Repair	: 13.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	38,168.00
Revised Amount	:S\$	28,126.00
Check Items (Estimated)	:S\$	6,376.00
Total	:S\$	34,502.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	68,160.00
Salvage Value	:S\$	
Margin for Repair	:S\$	69,840.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2423A
Vehicle Details	
Vehicle No.:	SLF3756J
Vehicle to be Exported:	No
Intended De-registration Date:	02 Mar 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CVN015319
Chassis No.:	WAUZZZF45HA009484
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,178.00
Original Registration Date:	24 Aug 2016
First Registration Date:	24 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$27,050.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2026
PARF Rebate Amount:	\$20,287.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$47,873.00
Total Rebate Amount:	\$68,160.00

The information contained herein is correct as at 02 Mar 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2423A
Vehicle Details	
Vehicle No.:	SLF3756J
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	CVN015319
Chassis No.:	WAUZZZF45HA009484
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,178.00
Original Registration Date:	24 Aug 2016
First Registration Date:	24 Aug 2016
Transfer Count:	0
Actual ARF Paid:	\$27,050.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2026
PARF Rebate Amount:	\$20,287.00
Intended COE Rebate Details	
COE Expiry Date:	23 Aug 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,500.00
COE Rebate Amount:	\$47,827.00
Total Rebate Amount:	\$68,114.00

The information contained herein is correct as at 05 Mar 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 16:55
Date Of Accident	27/02/2018 11:55
Exact Location Of Accident	AYE TOWARDS CITY BEF CLEMENTI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLF3756J
Insured/Policyholder	
Name Of Registered Owner	LIM TUCK LEONG
NRIC No	S6932423A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97694299
Alternative Phone No	OTHERS-97694299

Vehicle Particulars

Manufacturer	AUDI
Model	A4 SEDAN 1.4 TFSI S
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100479661-01
Cover Note Number	

Driver

Name of Driver	LIM TUCK LEONG
NRIC No	S6932423A
Date Of Birth	21/09/1969
Occupation	INDOOR
Date Of Driving Pass	06/06/1994
Driving Experience	23 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97694299
Fax Number	
Contact Number	OTHERS-97694299
EMail Address	NOEMAIL

Address	BLK 392 YISHUN AVENUE 6 #08-1008
Postcode	760392
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : KOH BOON HENG GENDER: : MALE
Passenger 2	NAME: : TOMMY HIL GENDER: : MALE
Passenger 3	NAME: : ANNE LEE GENDER: : FEMALE
Passenger 4	NAME: : JAMES KIM GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

TRAVELLING ALONG AYE TOWARDS CITY, BEFORE CLEMENTI EXIT, VEHICLE SLK9906C, SUDDENLY STOP WHICH CAUSED VEHICLE SJA7240D TO JAM BRAKE BUT IT CANNOT STOP IN TIME, CAUSING SJA7240, TO HIT THE VEHICLE SLK9906C. MY VEHICLE, SLF3756J, WAS TRAVELLING BEHIND SJA7240D AT ABOUT 85KM/H, CANNOT BRAKE ON TIME WHICH HIT SJA7240D, ON ITS REAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJA7240D
Vehicle Make/Model/Colour	

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLK9908C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 27/2/2019
1607h/s

Driver's Signature


(if driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature

Name: Lany Fongy
NRIC/IN No.: G201422

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

TRAVELLING ALONG AYE TOWARDS CITY, BEFORE CLEMENTI
EXIT, VEHICLE SLK9906C SUDDENLY STOP WHICH CAUSED
VEHICLE SJA7240D TO JAM BRAKE BUT IT CANNOT STOP IN
TIME CAUSING SJA7240D TO HIT THE VEHICLE SLK9906C
MY VEHICLE #SLF3756J WAS TRAVELLING BEHIND SJA7240D
AT ABOUT 85KM/H CANNOT BRAKE ON TIME WHEN HIT SJA7240D
ON ITS REAR

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 27/2/2018
1600 hrs

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____



Reporting Centre Personnel's Signature
Name: Tony Fong
NRC/ITN No.: 17204047X

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S6932423A**

Name: **LIM TUCK LEONG**

Birth Date: **21 Sep 1969**

Issue Date: **03 May 2003**

1006453298A



REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S6932423A**

Name: **LIM TUCK LEONG**

林德隆

Race: **CHINESE**

Date of Birth: **21-09-1969**

Country of Birth: **SINGAPORE**

Sex: **M**




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES!

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE: **06 Jun 1994**

NP 428A

Licence No: **S6932423A**



1270845

S6932423A

12-09-1993

APT BLK 392 YISHUN AVENUE 6 #08-1008
SINGAPORE 760392

NRIC No: **S6932423A**

Date: **02-12-2001**

No: **4137257**






CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Tuck Leong
 Period of Insurance : 24 Aug 2017 To 23 Aug 2018
 Engine No. : CVN015319
 Chassis No. : WAUZZZF45HA009484

Vehicle No. : SLF3756J
 Policy No. : 2100479661-01
 Endorsement No. :
 Issued Date : 14 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
 Engine Capacity/Tonnage : 1,395.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2016
 Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if you are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be insured under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Tuck Leong - \$500 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55, 56 Road 1 Singapore 408699 63062323

For other Approved Reporting Centres/Audited Repairers, please contact our 24-hour accident emergency hotline at +65 6338 8205. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
 SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

J. M. L. K.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

ESP/PAI

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/258/2018/GW
Date	:	01-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Lim Tuck Leong
Address	:	Blk 392 Yishun Ave6 #08-1008 Singapore 760392
Telephone	:	HP +65 97694299
Type of Claim	:	Own Damage Claim
Policy No.	:	2100479661-01
Vehicle No	:	SLF 3756 J
Model Code	:	Audi A4 Sedan 1.4 TFSI S
Model / Year	:	Feb-16
Engine No	:	CVN 015319
Chassis No	:	WAUZZZF45HA009484
Mileage	:	28334 KM
Date In	:	24-Aug-16
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	27-Feb-18
Place of Accident	:	Aye Towards City Bef Clementi Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gno Qiang - 8288 0282
Surveyed Date : 02/3/18
Authorised Date :
Excess Cost : Not Authorised.
Liability :
Remarks : before paint photos.
1) 13 Pags

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 3756 J.

S/N	Nature of Jobs	Estimate Charge
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360
2	To remove and renew air cond condenser, radiator, check fan, control unit, pressurise cooling system, vacuum and regas.	S/N \$ 1,200
3	To remove frontal fittings, dismantle front bumper, bonnet, rhs front fender, cut out and reweld, rhs fender support, rhs chassis console bracket. Dismantle and renew lock carrier, carrier bracket. Renew front bumper, bracket and carrier. Renew rhs front fender, bonnet, hinges headlamps and re-organise crash management components. Realign panels, re-install all parts removed. Repair rhs A pillar.	\$ 6,00
4	To remove and reinstall both front door inner trim to facilitate renewal of both top chrome mouldin, removal and reinstallation of both wing mirror assy for respray.	S/N \$ 6
5	To respray front bumper, bonnet, lhs/rhs front fender, lhs/rhs front door and fender support.	\$ 5,
6	To carry out diagnostic.	S/N \$
TOTAL LABOUR CHARGES		: \$ 13,

23/4

SLF 3756

1,479.2+
186.++
87.84+
143.6+
57.84+
2.5.2+
1,219.2+
551.6+
85.2+
96.++
38.24+
87.2+
156.++
25.36+
12.++
187.2+
1,730.4+
1.++

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / <i>le</i>	\$ 1,849.00	1479.20
2	FRONT BUMPER FIXING PARTS / <i>see</i>	\$ 245.00	196
3	FRONT BUMPER SECURING STRIP / <i>see</i>	2 \$ 60.00	47.80
4	FRONT BUMPER GRILLE <i>X</i> <i>NN</i>	\$ 171.00	<i>X</i>
5	FRONT BUMPER CLOSING ELEMENT / <i>BR</i>	\$ 180.00	143.60
6	FRONT BUMPER AIR GUIDE-RH / <i>see</i>	\$ 73.00	57.84
7	FRONT BUMPER AIR GUIDE GRILLE-RH / <i>see</i>	\$ 118.00	255.70 <i>5</i>
8	RADIATOR GRILLE / <i>CRA</i>	\$ 972.00	1219.20 <i>5</i>
9	FRONT BUMPER CARRIER / <i>CRA</i>	\$ 702.00	561.60
10	FOAM FILLER PIECE / <i>le</i>	\$ 107.00	85.20
11	FRONT BUMPER LOCK CARRIER BRACKET <i>R</i> / <i>see</i>	\$ 118.00	94 ✓
12	FRONT BUMPER SUPPORT-LH/RH / <i>MC</i>	2 \$ 48.00	38.24
13	FRONT BUMPER COVER / <i>cut</i>	\$ 109.00	87.20
14	FRONT BUMPER BRACKET-LH/RH <i>X</i> / <i>BT</i>	2 \$ 390.00	156 ✓
16	FRONT BUMPER GUIDE SECTION-RH / <i>MC</i>	\$ 32.00	25.36
17	FOAM FILLER PIECE-RH / <i>CRA</i>	\$ 15.00	12
18	HEADLIGHT LIFT CYLINDER-RH / <i>cut</i>	\$ 184.00	147.20
19	HEADLIGHT WASHER TUBE <i>X</i>	\$ 33.00	<i>X</i>
20	HEADLIGHT CORRUGATED PIPE <i>X</i> <i>NN</i>	\$ 79.00	<i>X</i>
SUB- TOTAL SPARE PARTS :		\$ 5,485.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

526A 110

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	Damage Pa	
		S/NETT	RE
21	BONENT / <i>huc</i>	\$ 2,163.00	1730.40
22	BONNET ATTACHMENT PART <i>X NN</i>	\$ 105.00	<i>X</i>
23	BONNET IMPACT PROTECTION-CENTER <i>- } huc</i>	\$ 24.00	18.88
24	BONNET IMPACT PROTECTION-LH <i>- }</i>	\$ 24.00	18.88
25	BONNET IMPACT PROTECTION-RH <i>- }</i>	\$ 24.00	18.88
26	FRONT FENDER TOP COVER-OUTER <i>X / ANN</i>	\$ 53.00	42.32
27	FRONT FENDER TOP COVER-INNER <i>X ✓ huc</i>	\$ 27.00	21.60
28	HEADLIGHT TOP COVER <i>/ huc</i>	\$ 20.00	15.36
29	BONNET HOOD STRUCT CYLINDER <i>X NN</i>	2 \$ 209.00	<i>X</i>
30	BONNET STRIKER LH/RH <i>X / BT</i>	2 \$ 88.00	69.92 ✓
31	BONNET LID LOCK <i>/ BT</i>	2 \$ 376.00	300.80
32	BONNET BOWDEN CABLE <i>X / NN</i>	2 \$ 100.00	<i>X</i>
33	BONNET LID LOCK CABLE <i>X / NN</i>	\$ 64.00	<i>X</i>
34	BONNET LID HINGE <i>/ BT</i>	2 \$ 532.00	424.80
35	FRONT FENDER-RH <i>/ huc</i>	\$ 665.00	532
36	FRONT FENDER ATTACHEMENT PART-RH <i>= { huc</i>	\$ 45.00	42.32
37	FRONT FENDER CLOSING ELEMENT-RH <i>= { huc</i>	\$ 44.00	34.56
38	FRONT FENDER BRACKET-RH <i>- }</i>	\$ 31.00	24.16
39	FRONT FENDER BRACKET DEFORMATION ELEMENT-RH <i>/ huc</i>	\$ 43.00	34.16
40	FRONT FENDER REAR BRACKET-RH <i>/ huc</i>	\$ 27.00	21.60
SUB-TOTAL SPARE PARTS		\$ 4,664.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description		Damage Pa	
			S/NETT	RE
41	FRONT FENDER UPPER BRACKET-RH	/	TBC	
42	FRONT FENDER BRACE-RH	/	\$ 103.00	82.40
43	FRONT FENDER FILLER PANEL-RH	/	\$ 29.00	22.72
44	FRONT WHEEL HOUSING LINER-RH	/	\$ 209.00	167.20
45	WHEEL HOUSING LINER ATTACHMENT PARTS	/	\$ 78.00	62
46	FRONT WHEEL SPOILER-RH	X	\$ 63.00	
47	FRONT STONE CHIP GUARD-RH	/	\$ 44.00	34.56
48	FRONT FENDER LINER EXTENSION BRACKET-RH	/	\$ 31.00	
50	FRONT FENDER FILLER-RH	X	\$ 543.00	
51	NOISE INSULATION PLATE-RH	X	\$ 22.00	
52	FRONT FENDER RAIL BRACKET-RH	X	\$ 54.00	
53	LED HEADLIGHT-RH	/	\$ 6,973.00	5578.40
54	FRONT GUDIE SECTION-RH	X	\$ 32.00	
55	HEADLIGHT POWER MODULE-RH	X	\$ 695.00	
56	HEADLIGHT CONTROL UNIT-RH	X	\$ 657.00	
57	COOLANT RADIATOR LOCK CARRIER	/	\$ 891.00	717.80
58	A/C CONDENSER	X	\$ 540.00	432
59	RADIATOR	X	\$ 585.00	468
60	INTERCOOLER RADIATOR	X	\$ 455.00	
SUB-TOTAL SPARE PARTS			\$ 12,004.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	Damage Pa	
		S/NETT	RE
61	AIR CLEANER ASSY <i>X photo / CRA</i>	\$ 338.00	270 ✓
62	AIR INTAKE DUCT <i>X / MCL.</i>	\$ 31.00	24.64 ✓
63	ENGINE AIR INTAKE HOSE <i>X { NN</i>	\$ 18.00	X
64	AIR DUCT INTAKE HOSE <i>X { LH X NN</i>	\$ 80.00	X
65	WINDOW SLOT SEAL-LH/RH <i>< RH - MCL.</i>	2 \$ 530.00	212
66	RADIATOR AIR GUIDE-RH <i>X / RE.</i>	\$ 23.00	18.40
67	RADIATOR INNER DUCT-RH <i>X NN</i>	\$ 10.00	X
68	FRONT NO. PLATE <i>- Cat</i>	S/N \$ 25.00	/
69	ACRYLIC SEALER <i>- { MCL.</i>	S/N \$ 180.00	/
70	CAVITY WAX <i>-</i>	S/N \$ 140.00	/
71	SUNDRIES <i>X / MCL</i>	\$ 800.00	71.76
TOTAL SPARE PARTS		: \$ 24,328.00	24712.40
TOTAL LABOUR CHARGES		: \$ 13,840.00	
GRAND TOTAL		: \$ 38,168.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

39552.40

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/258/2018/GW 14-Mar-18 Jeffery Tan 1 SLF 3756 J Audi A4 Sedan 1.4 TFSI S
Quantity	Description	Unit Price	Amount
LABORS			
1	To repair and respray RHS A-pillar.	S 1,000.00	509
	TOTAL	S 1,000.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/258/2018/GW
Date : 1-Mar-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Hi Guo Qiang
We took 11 days of repairs -
ib 16 Apr 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Lim Tuck Leong
Address : Blk 392 Yishun Ave6
#08-1008
Singapore 760392
Telephone : HP +65 97694299
Type of Claim : Own Damage Claim
Policy No. : 2100479661-01
Vehicle No : **SLF 3756 J**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Feb-16
Engine No : CVN 015319
Chassis No : WAUZZZF45HA009484
Mileage : 28334 KM
Date In : 24-Aug-16
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 27-Feb-18
Place of Accident : Aye Towards City Bef Clementi Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLF 3756 J.

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$ 360.00
2	To remove and renew air cond condenser, radiator, check fan, control unit, pressurise cooling system, vacuum and regas.	S/N \$	1,200.00	\$ 1,200.00
3	To remove frontal fittings, diamantle front bumper, bonnet, rhs front fender, cut out and reweld, rhs fender support, rhs chassis console bracket. Dismantle and renew lock carrier, carrier bracket. Renew front bumper, bracket and carrier. Renew rhs front fender, bonnet, hinges headlamps and re-organise crash management components. Realign panels, re-install all parts removed. Repair rhs A pillar.	\$	6,000.00	\$ 4,000.00
4	To remove and reinstall both front door inner trim to facilitate renewal of both top chrome mouldin, removal and reinstallation of both wing mirror assy for respray.	S/N \$	600.00	\$ 600.00
5	To respray front bumper, bonnet, lhs/rhs front fender, lhs/rhs front door and fender support.	\$	5,400.00	\$ 3,850.00
6	Added labour charges	\$	1,000.00	\$ 500.00
7	To carry out diagnostic.	S/N \$	280.00	\$ 280.00
TOTAL LABOUR CHARGES		:	\$ 14,840.00	\$ 10,790.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,849.00	\$ 1,479.20
2	FRONT BUMPER FIXING PARTS	\$ 245.00	\$ 196.00
3	FRONT BUMPER SECURING STRIP	2 \$ 60.00	\$ 47.84
4	FRONT BUMPER GRILLE	\$ 171.00	
5	FRONT BUMPER CLOSING ELEMENT	\$ 180.00	\$ 143.60
6	FRONT BUMPER AIR GUIDE-RH	\$ 73.00	\$ 57.84
7	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 118.00	\$ 255.20
8	RADIATOR GRILLE	\$ 972.00	\$ 1,219.20
9	FRONT BUMPER CARRIER	\$ 702.00	\$ 561.60
10	FOAM FILLER PIECE	\$ 107.00	\$ 85.20
11	FRONT BUMPER LOCK CARRIER BRACKET (Photo)	\$ 118.00	\$ 94.00
12	FRONT BUMPER SUPPORT-LH/RH	2 \$ 48.00	\$ 38.24
13	FRONT BUMPER COVER	\$ 109.00	\$ 87.20
14	FRONT BUMPER BRACEKT-LH/RH (Photos)	2 \$ 390.00	\$ 156.00
16	FRONT BUMPER GUIDE SECTION-RH	\$ 32.00	\$ 25.36
17	FOAM FILLER PIECE-RH	\$ 15.00	\$ 12.00
18	HEADLIGHT LIFT CYLINDER-RH	\$ 184.00	\$ 147.20
19	HEADLIGHT WASHER TUBE	\$ 33.00	
20	HEADLIGHT CORRUGATED PIPE	\$ 79.00	
SUB- TOTAL SPARE PARTS		\$ 5,485.00	\$ 4,605.68

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	c/f	Damage Parts & Prices	
			S/NETT	REMARKS
				\$ 4,605.68
21	BONENT		\$ 2,163.00	\$ 1,730.40
22	BONNET ATTACHMENT PART		\$ 105.00	
23	BONNET IMPACT PROTECTION-CENTER		\$ 24.00	\$ 18.88
24	BONNET IMPACT PROTECTION-LH		\$ 24.00	\$ 18.88
25	BONNET IMPACT PROTECTION-RH		\$ 24.00	\$ 18.88
26	FRONT FENDER TOP COVER-OUTER		\$ 53.00	\$ 42.32
27	FRONT FENDER TOP COVER-INNER		\$ 27.00	\$ 21.60
28	HEADLIGHT TOP COVER		\$ 20.00	\$ 15.36
29	BONNET HOOD STRUCT CYLINDER	2	\$ 209.00	
30	BONNET STRIKER LH/RH (Photos)	2	\$ 88.00	\$ 69.92
31	BONNET LID LOCK	2	\$ 376.00	\$ 300.80
32	BONNET BOWDEN CABLE	2	\$ 100.00	
33	BONNET LID LOCK CABLE		\$ 64.00	
34	BONNET LID HINGE	2	\$ 532.00	\$ 424.80
35	FRONT FENDER-RH		\$ 665.00	\$ 532.00
36	FRONT FENDER ATTACHEMENT PART-RH		\$ 45.00	\$ 42.32
37	FRONT FENDER CLOSING ELEMENT-RH		\$ 44.00	\$ 34.56
38	FRONT FENDER BRACKET-RH		\$ 31.00	\$ 24.16
39	FRONT FENDER BRACKET DEFORMATION ELEMENT-RH		\$ 43.00	\$ 34.16
40	FRONT FENDER REAR BRACKET-RH		\$ 27.00	\$ 21.60
SUB-TOTAL SPARE PARTS			\$ 4,664.00	\$ 7,956.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

		<u>Damage Parts & Prices</u>		
S/N	Parts Description	S/NETT	REMARKS	
		c/f	\$	7,956.32
41	FRONT FENDER UPPER BRACKET-RH	TBC		
42	FRONT FENDER BRACE-RH	\$	103.00	\$ 82.40
43	FRONT FENDER FILLER PANEL-RH	\$	29.00	\$ 22.72
44	FRONT WHEEL HOUSING LINER-RH	\$	209.00	\$ 167.20
45	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	78.00	\$ 62.00
46	FRONT WHEEL SPOILER-RH	\$	63.00	
47	FRONT STONE CHIP GUARD-RH	\$	44.00	\$ 34.56
48	FRONT FENDER LINER EXTENSION BRACKET-RH	\$	31.00	
50	FRONT FENDER FILLER-RH	\$	543.00	
51	NOISE INSULATION PLATE-RH	\$	22.00	
52	FRONT FENDER RAIL BRACKET-RH	\$	54.00	
53	LED HEADLIGHT-RH	\$	6,973.00	\$ 5,578.40
54	FRONT GUDIE SECTION-RH	\$	32.00	
55	HEADLIGHT POWER MODULE-RH	\$	695.00	
56	HEADLIGHT CONTROL UNIT-RH	\$	657.00	
57	COOLANT RADIATOR LOCK CARRIER	\$	891.00	\$ 712.80
58	A/C CONDENSER (Photos)	\$	540.00	\$ 432.00
59	RADIATOR (Photos)	\$	585.00	\$ 468.00
60	INTERCOOLER RADIATOR	\$	455.00	
SUB-TOTAL SPARE PARTS		\$	12,004.00	\$ 15,516.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLF 3756 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
			\$ 15,516.40
61	AIR CLEANER ASSY (Photo)	\$ 338.00	\$ 270.00
62	AIR INTAKE DUCT (Photo)	\$ 31.00	\$ 24.64
63	ENGINE AIR INTAKE HOSE	\$ 18.00	
64	AIR DUCT INTAKE HOSE	\$ 80.00	
65	WINDOW SLOT SEAL-LH/RH	2 \$ 530.00	\$ 212.00
66	RADIATOR AIR GUIDE-RH	\$ 23.00	\$ 18.40
67	RADIATOR INNER DUCT-RH	\$ 10.00	
68	FRONT NO. PLATE	S/N \$ 25.00	\$ 25.00
69	ACRYLIC SEALER	S/N \$ 180.00	\$ 180.00
70	CAVITY WAX	S/N \$ 140.00	\$ 140.00
72	SUNDRIES	\$ 800.00	\$ 71.76
TOTAL SPARE PARTS		\$ 24,328.00	\$ 16,458.20
TOTAL LABOUR CHARGES		\$ 14,840.00	\$ 10,790.00
GRAND TOTAL		\$ 39,168.00	\$ 27,248.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.	PA/OD/258/2018/GW
Date	14-Mar-18
Service Advisor	Jeffrey Tan
Pages	1
Regn No	SLF3756 J
Model No	Audi A4 1.4 TFSI

Quantity	Description	Unit Price	
<u>LABORS</u>			
1	To repair and respray RHS A pillar	\$ 1,000.00	\$ 500.00
TOTAL		\$ 1,000.00	\$ 500.00

For Premium Automobiles Pte Ltd

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLF 3756 J

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0258/2018/MAS

15 May 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLF 3756 J, Audi A4 Sedan 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLH 3756 J**, claimant, **Mr. Lim Tuck Leong**, please find the related document per attached.

1. A copy of the Original invoice no. 85012471 – S\$28,513.57
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLF 3756 J

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159098
Main Telephone: 6836 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159098
Telephone: 6388 2223
Telefax: 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408052
Telephone: 6385 2223
Telefax: 6475 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2223
9828 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 1 15:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012471 Date : 10/05/2018 Order : SLF3756J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF3756J (V 30040) Regn Date: 24/08/2016 Mileage: 28334 WIP No.: 57113

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45HA009404 Engine: CVN 015319 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	360.00	1.00	360.00
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE.	25.00	1.00	25.00
Q	EXC	M: 8888 Insurance Excess/Liability	-600.00	1.00	-600.00
S	BODYWORK	M: TO REMOVE AND RENEW AIR COND CONDENSER, RADIATOR, CHECK FAN, CONTROL UNIT, PRESSURISE COOLING SYSTEM CAVULUM AND REGAS.	1200.00	1.00	1,200.00
S	BODYWORK	M: TO REMOVE FRONTAL FITTINGS, DISMANTLE FRONT BUMPER BONNET, RHS FRONT FENDER, CUT OUT AND REWELD, RHS FENDER SUPPORT, RHS CHASSIS CONSOLE BRACKET, DISMANTLE AND RENEW LOCK CARRIER, CARRIER BRACKET, RENEW RHS FRONT FENDER, BONNET, HINGES, HEADLAMPS	4000.00	1.00	4,000.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Adi Centre Singapore
281 Alexandra Road
Singapore 159038
Main Telephone: 6386 2223
Main Telefax: 6471 3133

Alexandra Service Centre
281 Alexandra Road
Singapore 159038
Telephone: 6386 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6386 2223
Telefax: 6471 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2323
6628 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 2 15:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012471 Date : 10/05/2018 Order : SLF3756J Term : 30	Account: A0005 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF3756J (V 30840) Regn Dates: 24/06/2016 Mileage: 28334 WIP No.: 57113

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45H0009484 Engine: CVN 015319 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	AND RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REALI M: TO REMOVE AND REINSTALL BOTH FRONT DOOR INNER TRIM TO FACILITATE RENEWAL OF BOTH TOP CHROME MOULDING, REMOVAL AND REINSTALLATION OF BOTH WING MIRROR ASS FOR RESPRAY.	600.00	1.00	600.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER, BONNET, BOTH FRONT FENDER BOTH FRONT DOORS AND FENDER SUPPORT.	3850.00	1.00	3,850.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK.	280.00	1.00	280.00
S	BODYWORK	M: TO SUPPLY ACRYLIC SEALER AND CAVITY WAX.	320.00	1.00	320.00
S	BODYWORK	M: TO REPAIR AND RESPRAY RHS A-PILLAR.	500.00	1.00	500.00
X	ABW0133837	AIRCLENER	1.00	337.50	270.00
X	ABW0853651ABRN4	GRILLE	1.00	1524.00	1,219.20
X	ABW0941774A	HEADLIGHT	1.00	6973.00	5,578.40

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119998
Main Telephone: 6386 2223
Main Telefax: 6471 3133

Alexandra Service Centre
281 Alexandra Road
Singapore 119998
Telephone: 6386 2223
Telefax: 6471 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408723
Telephone: 6386 2223
Telefax: 6471 1033

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg

6386 2223
6471 3133

Page 3 15:37

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012471 Date : 10/05/2018 Order : SLF3756J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF3756J (V 30840) Regn Date: 24/08/2016 Mileage: 28334 WIP No.: 57113

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF45HA009484 Engine: CVN 015319 Dept: U

USB No.:

You have been assisted by :- UB-Carrine (33)

		Details	Qty	Unit Price	Amount	
X	ABW0821172A	WHEEL HOUS	Less 020%	1.00	209.00	167.20
X	ABW0863825	SOUND ABSORBER	Less 020%	1.00	296.00	236.80
X	ABW0821106A	FENDER	Less 020%	1.00	565.00	532.00
X	ABW0807081	COVER	Less 020%	1.00	109.00	87.20
X	ABW0807611	PLATE	Less 020%	1.00	179.50	143.60
X	ABW0121251K	RADIATOR	Less 020%	1.00	585.00	468.00
X	ABW0816421H	CONDENSER	Less 020%	1.00	540.00	432.00
X	ABW0805594	CARRIER	Less 020%	1.00	891.00	712.80
X	ABW0807550A	FOAM INSER	Less 020%	1.00	106.50	85.20
X	ABW0807113	BRACKET	Less 020%	1.00	702.00	561.60
X	ABW0823029A	HOOD	Less 020%	1.00	2163.00	1,730.40
X	ABW0807065C GRU	COVER	Less 020%	1.00	1849.00	1,479.20
X	ABW098629	ATT. PARTS	Less 020%	1.00	77.50	62.00
X	ABW0807334	SUPPORT	Less 020%	1.00	23.90	19.12
X	ABW0807333	SUPPORT	Less 020%	1.00	23.90	19.12
X	ABW0821471	BRACKET	Less 020%	1.00	27.00	21.60
X	ABW0821468	BRACKET	Less 020%	1.00	30.20	24.16
X	ABW0807284	GUIDE	Less 020%	1.00	31.70	25.36

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6886 2222
Main Telefax: 6471 3333

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6886 2222
Telefax: 6471 3333

Ubi Service Centre
55 Ubi Road 1
Singapore 408722
Telephone: 6886 2222
Telefax: 6471 3333

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 2323
6428 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Page 4 15:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012471 Date : 10/05/2018 Order : SLF3756J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF3756J (V 30040) Regn Date: 24/08/2015 Mileage: 28334 WIP No.: 57113

Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4SH0009484 Engine: CVN 015319 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (33)

		Details		Qty	Unit Price	Amount
X	ABW0821092	PLATE	Less 020%	1.00	43.20	34.56
X	ABW0823185B	CATCH	Less 020%	1.00	43.70	34.96
X	ABW0823186B	CATCH	Less 020%	1.00	43.70	34.96
X	ABW0821132B	SUPPORT	Less 020%	1.00	103.00	82.40
X	ABW0807134	BRACKET	Less 020%	1.00	195.00	156.00
X	ABW0823301D	HINGE	Less 020%	1.00	265.50	212.40
X	ABW0823302D	HINGE	Less 020%	1.00	265.50	212.40
X	ABW0129618	AIR DUCT	Less 020%	1.00	30.80	24.64
X	ABW0121764	AIR DUCT	Less 020%	1.00	72.30	57.84
X	ABW0820536	BRACKET	Less 020%	1.00	15.60	12.48
X	ABW0821434B	BRACKET	Less 020%	1.00	14.70	11.76
X	ABW0823746	COVER	Less 020%	1.00	19.20	15.36
X	ABW0807277	STRIP	Less 020%	2.00	29.90	47.84
X	ABW0821470	BRACKET	Less 020%	1.00	42.70	34.16
X	ABW0823125	PROTECTION	Less 020%	1.00	23.60	18.88
X	ABW0823126	PROTECTION	Less 020%	1.00	23.60	18.88
X	A4E0260749A	WASHER	Less 020%	2.00	3.20	5.12
X	A3D0260749C	WASHER	Less 020%	2.00	3.00	6.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 2133

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408722

Customer Service
Service Appointment
Hour Breakdown Service
Email: customers.care@premiumauto.com.sg

6386 2523
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 5 15:37

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85012471 Date : 10/05/2016 Order : SLF3756J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLF3756J (V 30840) Regn Date: 24/08/2016 Mileage: 28334 WIP No.: 57113
Model: A4 SEDAN 1.4 TFSI S tronic Chassis: WAUZZZF4SH0009484 Engine: CVM 015319 Dept: U
VSB No.:
You have been assisted by :- UB-Carrine (33)

		Details		Qty	Unit Price	Amount
X	ABW0823509	LATCH	Less 020%	2.00	188.00	300.00
X	ABW0853824A 989	STONEGUARD	Less 020%	1.00	43.20	34.56
X	ABW0807682R RN4	GRILL	Less 020%	1.00	319.00	255.20
X	ABW0821112	PLATE	Less 020%	1.00	28.40	22.72
X	ABW0821170C	COVER	Less 020%	1.00	52.90	42.32
X	A311601361	RUBBER VFL	Less 020%	10.00	2.80	22.40
X	ABW0955102A	CYLINDER	Less 020%	1.00	184.00	147.20
X	ABW0010515A	STICKER	Less 020%	1.00	6.10	4.88
X	ABW0010520A	PLATE	Less 020%	1.00	11.60	9.28
X	ABW0121284AL	AIR DUCT	Less 020%	1.00	23.00	18.40
X	ABW0807771	BRACKET	Less 020%	1.00	117.50	94.00
X	AN 0161857	POP-RIVET	Less 020%	12.00	2.90	27.84
X	AN 0385012	RIVET	Less 020%	4.00	1.50	4.80
X	AN 10583501989	RIVET	Less 020%	2.00	1.40	2.24
X	ABW0853284B 222	WINDOW SLO	Less 020%	1.00	265.00	212.00
X	ABW0823124	PROTECTION	Less 020%	1.00	23.60	18.88

Parts 16,113.20
Labour 0.00
Sublet 11,135.00
Menus 0.00
Lubricant 0.00

Sub-Total 26,648.20

7% GST 1,865.37

Grand Total 28,513.57



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLF 3756 J

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0258/2018/TF
20 March 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A4 SEDAN 1.4 TFSI S tronic
Vehicle Chassis No. : WAUZZZF4GHA164531
Vehicle Regn No. : SLF 3756 J
Vehicle Mileage : 28334KM
Vehicle Owner : Mr. Lim Tuck Leong
Certificate No : 2100479661-01
Policy Excess : S\$642.00 (inclusive 7% GST)
Accident Date : 27th February 2018
Place : AYE Towards City Bef Clementi Exit
Repair Cost : \$ 28,513.57
WIP No. : 57113
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time :
Date : 20/3/18

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number **S6932423A**

Name **LIM TUCK LEONG**

Birth Date **21 Sep 1969**

Issue Date **03 May 2000**



000457258A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6932423A



LIM TUCK LEONG

林德隆

Race
CHINESE

Date of Birth
21-09-1969

Country of Birth
SINGAPORE

Sex
M



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE
06 Jun 1994

Licence No: S6932423A

NP 428A



1270945

NRIC No: S6932423A



Blood Group
O+

Date of issue
12-09-1993

APT 814 302 MCHIN AVENUE 6
SINGAPORE 760302

NRIC No: S6932423A

Date: 02-12-2001 No: 4137257

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lim Tuck Leong
 Period of Insurance : 24 Aug 2017 To 23 Aug 2018
 Engine No. : CVN015319
 Chassis No. : WAUZZZF45HA009484

Vehicle No. : SLF3756J
 Policy No. : 2100479681-01
 Endorsement No. :
 Issued Date : 14 Aug 2017

ABOUT THE COVER

Make/Model : AUDI A4 1.4 TFSI S tronic
 Engine Capacity/Tonnage : 1,395.00 CC
 Driver Restriction : NA
 Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2016
 Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 169) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lim Tuck Leong - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406009 63962329

For other Approved Reporting Centres/AUG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 169), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125200

PREMIUM LEASING - AP

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

M. Anik

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

REP/AC

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Mar 2018		05 Mar 2018 11:15 Edit Adj Rpt	\$527,248.20 Edit Estimates	\$527,248.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LIM TUCK LEONG, ID: S6932423A, Tel: +6597694299, Email: NOEMAIL								
Vehicle Reg. No.:	SLF3756J	Date of Loss:	27/02/2018 11:00 - :59 [18 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 0739974152SG	Policy/Cover Note No.:	2100479661-01 (Comprehensive)						
		Excess:	\$5600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689628/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina.DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 14/03/2018]								
Driver/Custodian:	LIM TUCK LEONG (48 / Male), NRIC: S6932423A, Tel: +6597694299								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (05/03/2018): Alert - Adj Mandate Approved (\$528126.00) - SLF3756J - Claim Handler: Dally Amri... - AIG_SG (05/03/2018): SLF3756J / OD / 27/02/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLF3756J (0739974152SG)
OD
Feb 27 2018 11:55AM
[LIM TUCK LEONG]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Assessment Reports			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	05/03/18 14:51	Adjuster Immediate Advice		Thumbnail Print Load HTM
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	05/03/18 14:20	General View		Load JPG ☒
2	05/03/18 14:20	General View		Load JPG ☒
3	05/03/18 14:20	General View		Load JPG ☒
4	05/03/18 14:20	General View		Load JPG ☒
5	05/03/18 14:20	General View		Load JPG ☒
6	05/03/18 14:20	General View		Load JPG ☒
7	05/03/18 14:20	General View		Load JPG ☒
8	05/03/18 14:20	General View		Load JPG ☒
9	05/03/18 14:20	General View		Load JPG ☒
10	05/03/18 14:20	General View		Load JPG ☒
11	05/03/18 14:20	General View		Load JPG ☒
12	05/03/18 14:20	General View		Load JPG ☒
13	05/03/18 14:20	General View		Load JPG ☒
14	05/03/18 14:20	General View		Load JPG ☒
15	05/03/18 14:20	General View		Load JPG ☒
16	05/03/18 14:20	General View		Load JPG ☒
17	05/03/18 14:20	General View		Load JPG ☒
18	05/03/18 14:20	General View		Load JPG ☒
19	05/03/18 14:20	General View		Load JPG ☒
20	05/03/18 14:20	General View		Load JPG ☒
21	05/03/18 14:20	General View		Load JPG ☒
22	05/03/18 14:20	General View		Load JPG ☒
23	05/03/18 14:20	General View		Load JPG ☒
24	05/03/18 14:20	General View		Load JPG ☒
25	05/03/18 14:20	General View		Load JPG ☒
26	05/03/18 14:20	General View		Load JPG ☒
27	05/03/18 14:20	General View		Load JPG ☒
28	05/03/18 14:20	General View		Load JPG ☒
29	05/03/18 14:20	General View		Load JPG ☒
30	05/03/18 14:20	General View		Load JPG ☒
31	05/03/18 14:20	General View		Load JPG ☒
32	05/03/18 14:20	General View		Load JPG ☒
33	05/03/18 14:20	General View		Load JPG ☒
34	05/03/18 14:20	Odometer Reading		Load JPG ☒
35	05/03/18 14:20	General View		Load JPG ☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	05/03/18 14:20	General View		☒
37	05/03/18 14:20	General View		☒
38	05/03/18 14:20	General View		☒
39	05/03/18 14:20	General View		☒
40	19/04/18 18:09	Reinspection Photo		☒
41	19/04/18 18:09	Reinspection Photo		☒
42	19/04/18 18:09	Reinspection Photo		☒
43	19/04/18 18:09	Reinspection Photo		☒
44	19/04/18 18:09	Reinspection Photo		☒
45	19/04/18 18:09	Reinspection Photo		☒
46	19/04/18 18:09	Reinspection Photo		☒
47	19/04/18 18:09	Reinspection Photo		☒
48	19/04/18 18:09	Reinspection Photo		☒
49	19/04/18 18:09	Reinspection Photo		☒
50	19/04/18 18:09	Reinspection Photo		☒
51	24/04/18 10:19	Reinspection Photo		☒
52	24/04/18 10:19	Reinspection Photo		☒
53	24/04/18 10:19	Reinspection Photo		☒
54	24/04/18 10:19	Reinspection Photo		☒
55	24/04/18 10:19	Reinspection Photo		☒
56	24/04/18 10:19	Reinspection Photo		☒
57	24/04/18 10:19	Reinspection Photo		☒
58	24/04/18 10:19	Reinspection Photo		☒
59	24/04/18 10:19	Reinspection Photo		☒
60	24/04/18 10:19	Reinspection Photo		☒
61	24/04/18 10:19	Reinspection Photo		☒
62	24/04/18 10:19	Reinspection Photo		☒
63	24/04/18 10:19	Reinspection Photo		☒
64	24/04/18 10:19	Reinspection Photo		☒
65	24/04/18 10:19	Reinspection Photo		☒
66	24/04/18 10:19	Reinspection Photo		☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/03/18 14:20	Singapore Accident Statement		☐
2	05/03/18 14:20	Certificate of Insurance		☐
3	05/03/18 14:20	Driver's Driving License		☐
4	05/03/18 14:20	WORKSHOP ESTIMATE		☐
5	18/05/18 10:53	Workshop Invoice		☐
6	18/05/18 10:53	Discharge Voucher		☐
7	18/05/18 11:35	Supplementary		☐

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/02/18 17:25	Accident Statement		☐

Photos/Images			3 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/02/18 17:20	Accident Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
2	27/02/18 17:20	Accident Photo	 Load JPG	☒
3	27/02/18 17:20	Accident Photo	 Load JPG	☒
4	27/02/18 17:20	Accident Photo	 Load JPG	☒
5	27/02/18 17:20	Accident Photo	 Load JPG	☒
6	27/02/18 17:20	Accident Photo	 Load JPG	☒
7	27/02/18 17:20	Accident Photo	 Load JPG	☒
8	27/02/18 17:20	Accident Photo	 Load JPG	☒
9	27/02/18 17:20	Accident Photo	 Load JPG	☒
10	27/02/18 17:20	Accident Photo	 Load JPG	☒
11	27/02/18 17:20	Accident Photo	 Load JPG	☒
12	27/02/18 17:20	Accident Photo	 Load JPG	☒
13	27/02/18 17:20	ACCIDENT SCENE PHOTOS	 Load JPG	☒
14	27/02/18 17:20	ACCIDENT SCENE PHOTOS	 Load JPG	☒
15	27/02/18 17:20	ACCIDENT SCENE PHOTOS	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	27/02/18 17:15	Sketch Plan	 Load JPG	☒
2	27/02/18 17:15	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18004129/GQBE2

Date: 18/05/2018

REFERENCE

Insured/Claimant:	LIM TUCK LEONG	Policy No:	2100479661-01	
Date of Loss:	27/02/2018	Nature of Claim:	OD	Claim No: 0739974152SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF3756J		
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Engine No:	CVN015319
Reg. Date:	24/08/2016 (Man. Year: 2016)	Chassis No:	WAUZZZF45HA009484
Colour:	Black	Odometer:	28334 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$138,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,712.40	16,458.20	8,254.20	33.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,840.00	10,790.00	4,050.00	27.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,552.40	27,248.20	12,304.20	31.11
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	38,952.40	26,648.20	12,304.20	31.59
+ GST 7.00/7.00% (S\$)	2,726.67	1,865.37	861.30	31.59
Nett Amount (S\$)	41,679.07	28,513.57	13,165.50	31.59

INSPECTION

Date of Assignment:	05/03/2018		
Date Inspected:	02/03/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	11.0 days		

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Necessary	245.00 FS	*196.00 FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	60.00 FS	*47.84 FS
4	1		*FRONT BUMPER GRILLE	Not Necessary	171.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT	Broken	180.00 FS	*143.60 FS
6	1		*FRONT BUMPER AIR GUIDE - RH	Deformed	73.00 FS	*57.84 FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Deformed	255.20 FS	*255.20 FS
8	1		*RADIATOR GRILLE	Cracked	1,219.20 FS	*1,219.20 FS
9	1		*FRONT BUMPER CARRIER	Cracked	702.00 FS	*561.60 FS
10	1		*FOAM FILLER PIECE	Deformed	107.00 FS	*85.20 FS
11	1		*FRONT BUMPER LOCK CARRIER BRACKET	Necessary	118.00 FS	*94.00 FS
12	2		*FRONT BUMPER SUPPORT - LH/RH	Necessary	48.00 FS	*38.24 FS
13	1		*FRONT BUMPER COVER	Cut	109.00 FS	*87.20 FS
14	2		*FRONT BUMPER BRACKET LH / RH	Bent	390.00 FS	*156.00 FS
15	1		*FRONT BUMPER GUIDE SECTION - RH	Necessary	32.00 FS	*25.36 FS
16	1		*FOAM FILLER PIECE - RH	Cracked	15.00 FS	*12.00 FS
17	1		*HEADLIGHT LIFT CYLINDER - RH	Cut	184.00 FS	*147.20 FS
18	1		*HEADLIGHT WASHER TUBE	Not Necessary	33.00 FS	*- FS
19	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	79.00 FS	*- FS
20	1		*BONNET	Buckled	2,163.00 FS	*1,730.40 FS
21	1		*BONNET ATTACHMENT PART	Not Necessary	105.00 FS	*- FS
22	1		*BONNET IMPACT PROTECTION - CENTER	Necessary	24.00 FS	*18.88 FS
23	1		*BONNET IMPACT PROTECTION - LH	Necessary	24.00 FS	*18.88 FS
24	1		*BONNET IMPACT PROTECTION - RH	Necessary	24.00 FS	*18.88 FS
25	1		*FRONT FENDER TOP COVER - OUTER	Necessary	53.00 FS	*42.32 FS
26	1		*FRONT FENDER TOP COVER - INNER	Necessary	27.00 FS	*21.60 FS
27	1		*HEADLIGHT TOP COVER	Cut	20.00 FS	*15.36 FS
28	2		*BONNET HOOD STRUCT CYLINDER	Not Necessary	209.00 FS	*- FS
29	2		*BONNET STRIKER LH / RH	Bent	88.00 FS	*69.92 FS
30	2		*BONNET LID LOCK	Bent	376.00 FS	*300.80 FS
31	2		*BONNET BOWDEN CABLE	Not Necessary	100.00 FS	*- FS
32	1		*BONNET LID LOCK CABLE	Not Necessary	64.00 FS	*- FS
33	2		*BONNET LID HINGE	Bent	532.00 FS	*424.80 FS
34	1		*FRONT FENDER - RH	Buckled	665.00 FS	*532.00 FS
35	1		*FRONT FENDER ATTACHEMENT PART - RH	Necessary	45.00 FS	*42.32 FS
36	1		*FRONT FENDER CLOSING ELEMENT - RH	Necessary	44.00 FS	*34.56 FS
37	1		*FRONT FENDER BRACKET - RH	Necessary	31.00 FS	*24.16 FS
38	1		*FRONT FENDER BRACKET DEFORMATION ELEMENT - RH	Necessary	43.00 FS	*34.16 FS
39	1		*FRONT FENDER REAR BRACKET - RH	Necessary	27.00 FS	*21.60 FS
40	1		*FRONT FENDER UPPER BRACKET - RH (NPA)	Necessary	0.00 FS	*- FS
41	1		*FRONT FENDER BRACE - RH	Necessary	103.00 FS	*82.40 FS
42	1		*FRONT FENDER FILLER PANEL - RH	Necessary	29.00 FS	*22.72 FS
43	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	209.00 FS	*167.20 FS
44	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Necessary	78.00 FS	*62.00 FS
45	1		*FRONT WHEEL SPOILER - RH	Not Necessary	63.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FRONT STONE CHIP GUARD - RH	Necessary	44.00 FS	*34.56 FS
47	1		*FRONT FENDER INNER EXTENSION BRACKET - RH	Not Necessary	31.00 FS	*- FS
48	2		*FRONT FENDER FILLER - RH	Not Necessary	543.00 FS	*- FS
49	1		*NOISE INSULATION PLATE - RH	Not Necessary	22.00 FS	*- FS
50	1		*FRONT FENDER RAIL BRACKET - RH	Not Necessary	54.00 FS	*- FS
51	1		*LED HEADLIGHT - RH	Cracked	6,973.00 FS	*5,578.40 FS
52	1		*FRONT GUIDE SECTION - RH	Not Necessary	32.00 FS	*- FS
53	1		*HEADLIGHT POWER MODULE - RH	Not Necessary	695.00 FS	*- FS
54	1		*HEADLIGHT CONTROL UNIT - RH	Not Necessary	657.00 FS	*- FS
55	1		*COOLANT RADIATOR LOCK CARRIER	Broken	891.00 FS	*712.80 FS
56	1		*A/C CONDENSER	Bent	540.00 FS	*432.00 FS
57	1		*RADIATOR	Bent	585.00 FS	*468.00 FS
58	1		*INTERCOOLER RADIATOR	Not Necessary	455.00 FS	*- FS
59	1		*AIR CLEANER ASSY	Cracked	338.00 FS	*270.00 FS
60	1		*AIR INTAKE DUCT	Necessary	31.00 FS	*24.64 FS
61	1		*ENGINE AIR INTAKE HOSE	Not Necessary	18.00 FS	*- FS
62	1		*AIR DUCT INTAKE HOSE	Not Necessary	80.00 FS	*- FS
63	1		*WINDOW SLOT SEAL - LH / RH	N/S NotNecessary/O/S Necessary	530.00 FS	*212.00 FS
64	1		*RADIATOR AIR GUIDE - RH	Deformed	23.00 FS	*18.40 FS
65	1		*RADIATOR INNER DUCT - RH	Not Necessary	10.00 FS	*- FS
66	1		*FRONT NO. PLATE	Cut	25.00 FS	*25.00 FS
67	1		*ACRYLIC SEALER	Necessary	180.00 FS	*180.00 FS
68	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
69	1		*SUNDRIES	Necessary	800.00 FS	*71.76 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 24,712.40 16,458.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIR COND CONDENSER, RADIATOR, CHECK FAN, CONTROL UNIT, PRESSURISE COOLING SYSTEM, VACUUM AND REGAS	New	1,200.00	1,200.00
3	TO REMOVE FRONTAL FITTINGS, DISMANTLE FRONT BUMPER, BONNET, RHS FRONT FENDER, CUT OUT AND REWELD, RHS FENDER SUPPORT, RHS CHASSIS CONSOLE BRACKET. DISMANTLE AND RENEW LOCK CARRIER, CARRIER BRACKET. RENEW FRONT BUMPER, BRACKET AND CARRIER. RENEW RHS FRONT FENDER, BONNET, HINGES HEADLAMPS AND RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REALIGN PANELS, RE-INSTALL ALL PARTS REMOVED. REPAIR RHS A PILLAR	New	6,000.00	4,000.00
4	TO REMOVE AND REINSTALL BOTH FRONT DOOR INNER TRIM TO FACILITATE RENEWAL OF BOTH TOP CHROME MOULDING, REMOVAL AND REINSTALLATION OF BOTH WING MIRROR ASSY FOR RESPRAY	New	600.00	600.00
5	TO RESPRAY FRONT BUMPER, BONNET, LHS/RHS FRONT FENDER, LHS/RHS FRONT DOOR AND FENDER SUPPORT	New	5,400.00	3,850.00
6	TO CARRY OUT DIAGNOSTIC	New	280.00	280.00
7	TO REPAIR AND RESPRAY RHS A-PILLAR	New	1,000.00	500.00
Gross Labour Cost (S\$)			14,840.00	10,790.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >