

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0259/2018/GW
Date	:	01-Mar-18

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no. SLW 2448 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Tan Wei Nian
Address	:	7 Sengkang Avenue #02-24 Singapore
Telephone	:	(HP) 98246532
Type of Claim	:	Own Damage Claims
Policy No.	:	1800008874
Vehicle No	:	SLW 2448 R
Model Code	:	Audi A3 Sedan 1.0 TFSI 8v
Model / Year	:	Feb-18
Engine No	:	CHZ 637020
Chassis No	:	WAUZZZ8V7J1041266
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	28-Feb-18
Place of Accident	:	Before KPE Tunnel

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2448 R.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	/
2	To remove and transfer Aircon condenser, radiator, charged air cooler, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,200.00	/
3	To remove front fittings, dismantle and renew front bumper, bonnet, radiator grille. Renew both headlights and re-organise frontal crash management component. Reinstall all parts removed.	\$ 2,400.00	1500.
4	To respray paint on front bumper, bonnet.	\$ 1,800.00	1100
TOTAL LABOUR CHARGES - FRONT		: \$ 5,760.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2448 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER / BE CRA	\$	1,739.00
2	FRONT BUMPER GRILLE / BR	\$	140.00
3	FRONT BUMPER CLOSING ELEMENT ?	\$	460.00
4	FRONT BUMPER COVER TRIM-LH/RH R / KCL 2	\$	280.00
5	FRONT BUMPER AIR GUIDE GRILLE-LH ?	\$	164.00
6	RADIATOR GRILLE / CRA	\$	1,239.00
7	RADIATOR GRILLE CLOSING ELEMENT ?	\$	167.00
8	FOAM FILLER PIECE ?	\$	162.00
9	FOAM COVER ?	\$	105.00
10	BONNET ?	\$	2,755.00
11	BONNET ATTACHMENT PARTS ?	\$	141.00
12	EDGE PROTECTION ?	\$	24.00
13	BONNET STRIKER ?	\$	96.00
14	BONNET LID LOCK WITH MICRO ?	\$	177.00
15	LED HEADLIGHT-RH ?	2 \$	9,776.00
16	FRONT BUMPER SIDE REINFORCEMENT / BT	\$	633.00
17	A/C CONDENSER / Gaf	\$	500.00
18	FRONT NO. PALTE / BT	S/N \$	25.00
19	SUNDRIES ?	\$	300.00
TOTAL SPARE PARTS CHARGES - FRONT		:	\$ 18,883.00
TOTAL LABOUR CHARGES - FRONT			\$ 5,760.00
GRAND TOTAL - FRONT			<u>\$ 24,643.00</u>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2448 R.

S/N	Nature of Jobs		Estimated Charges	
1	To remove, check and transfer rear parking aid assy.	S/N	\$ 280.00	/
2	To remove and transfer rear lid wire harness, and lock system.	S/N	\$ 280.00	/
3	To remove and renew rear bumper, rear lid and transfer old fittings. Reinstall all parts removed.		\$ 1,600.00	1600
4	To respray paint rear lid, rear bumper.		\$ 1,800.00	1800 1150
5	To remove and renew rear silencer, align mid exhaust.	S/N	\$ 360.00	/
6	To carry out diagnostic.	S/N	\$ 192.00	/
SUB-TOTAL LABOUR CHARGES - (REAR)			: \$ 4,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SLW 2448 R.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER / Re	\$	1,697.00
2	REAR BUMPER SPOILER / TN	\$	206.00
3	REAR BUMPER SIDE REINFORCEMENT / BT	\$	501.00
4	REAR BUMPER SENSOR ?	4 \$	842.00
5	REAR LIGHT REFLECTOR -LH/RH ?	2 \$	70.00
6	REAR LID / BT	\$	2,310.00
7	ADHESIVE PACKING /	\$	15.00
8	AUDI EMBLEM /	\$	108.00
9	INSCRIPTION "A3" /	\$	83.00
10	INSCRIPTION "TFSI" /	\$	83.00
11	LETTERING "ULTRA" X	\$	83.00
11	REAR SILENCER ? photo.	\$	643.00
12	REAR SILENCER DUAL CLIP ?	\$	53.00
13	EXHAUST SYSTEM RETAINER ?	\$	36.00
14	REAR SILENCER HEAT SHIELD ?	\$	146.00
15	SUNDRIES ?	\$	280.00
TOTAL SPARE PARTS - frt/rear		:	\$ 26,039.00
TOTAL LABOUR CHARGES - frt/rear		:	\$ 10,272.00
GRAND TOTAL -		:	\$ 36,311.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Gno Qicry - 82880282
Surveyed Date : 02/3/18.
Authorised Date :
Excess Cost : Not Authorised.
Liability :
Remarks : before paint photos.
11 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant