

ASS. REC. BY:

REF: CS/SPF18004141/Svbez

Special Instruction:

SURVEYOR:

ASSIGNMENT (Office)From (Person): Lim Wei Yea of SPF Date/Time: 02032018 3:56pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: QX 499S Insured: _____at Workshop m/s SMRT Tel: _____of 60 Woodlands Ind Park EllPolicy No: _____ Claim No: HOMSPFETQ 17300218

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. _____
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	<u>QX 499S - CS SPF18012354 Sub</u> <u>SPF 22032018</u>
<u>7/3/18</u>	<u>Email to Wei Yea</u>
<u>19/3/18</u>	<u>@ 117am Wei Yea said we can submit our report</u>
	<u>Parts \$ - Man HR- (G.S)</u>

REF:

Summary

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

3X 4775

Yr Regn:

1

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Police Car

Make:

Toyota Alfis

C.C.

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

128965

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Door Locked

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NR / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Falken

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

1/5/18

Survey held at

28 Sg Kadut Dr

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt / Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time / Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 193- typist

Report Format :

Lump Sum / I.B.I. (\$) :

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Foo:

☐

: Site Insp (\$

) S + RS. SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

) TOTAL

TOTAL

200

200



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18004141/Svb		
ACCIDENT CLAIM SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 05-03-2018		
		Code : SPF		
1. Policy Particulars - OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 499S	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	LIM WEI YEA	Assign Date	02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	Inspection Date		05/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 19 March 2018 3:09 PM
To: 'Wei Yea LIM (SPF)'; Denise Tay (LKKAuto)
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Dear Wei Yea,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]
Sent: Monday, 19 March 2018 2:21 PM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Hi Veron,

As spoken, please use the following claim number for these two vehicles:

- HOMSPFETQ17300218

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
• TRANSFORMATION 2025 •
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Wednesday, 7 March 2018 16:06

To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Dear Wei Yea,

Please refer attached for QX 499S

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Friday, 2 March 2018 3:56 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 499S
- QX 1021E

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Registration No. QX 499S

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	CRACKED			
1.2	Front Bumper Retainers (Left & Right)	2	NECESSARY			
1.3	Radiator Grill	1	TORN			
1.4	Front Bumper Lower Grill	1	MISSING			
1.5	Fog Lamp Cover (Left & Right)	2	MISSING			
1.6	Front Number Plate	1	CUT			
1.7	RHS Fender	1	BENT			
1.8	RHS Fender Panel	1	BENT			
1.9	Front Bonnet Cover	1	BENT			
1.10	Bonnet Hinge	2	BENT			
1.11	RHS Head Lamp	1	CRACKED			
1.12	RHS Support Panel	1	BENT			
1.13	Wiper Tank	1	DEFORMED			
1.14	Wiper Tank Motor	1	UNCONFIRM			
1.15	Radiator Spare Tank	1	DEFORMED			
1.16	RHS Engine Under Cover	1	DEFORMED			
1.17	Centre Engine Under Cover	1	UNCONFIRM			
1.18	LHS Engine Under Cover	1	UNCONFIRM			
1.19	RHS Fender Lining	1	MISSING			
1.20	LHS Fender Lining	1	MISSING			
1.21	Front Bumper Clips	1	NECESSARY			
1.22	Radiator Grill Clips	1	NECESSARY			

1.23	RHS Side Skirting	1	REPAIR			
1.24	Bonnet Stand	1	MISSING			
1.25	Bonnet Stand Stopper	1	NECESSARY			
1.26	Bonnet Stand Holder	1	MISSING			
1.27	Air-Condenser	1	BENT			
1.28	Air-Condenser Piping	1	BENT			
1.29	ABS Pump	1	UNCONFIRM			
1.30	Front Emblem	1	NECESSARY			
1.31	RHS Upper & Lower Arm	2	BENT			
1.32	RHS Knuckle Arm	1	BENT			
1.33	Front Absorber	2	BENT			
1.34	RHS Knuckle Bearing	1	DAMAGED			
2	LABOUR DESCRIPTION					
1.1	Front Bumper:					6
	Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers (Left & Right)					
	Remove & Replace Radiator Grill					
	Replace Front Bumper Lower Grill					
	Replace Both Side Fog Lamp Cover (Left & Right)					
	Remove & Replace Front Number Plate					
	Putty & Spray Paint for Front Complete Bumper (3 colours)					
1.2	RHS Fender:					4
	Remove & Replace RHS Fender					
	Remove & Replace RHS Fender Panel					
	Putty & Spray Paint for RHS Fender (2 colours)					
1.3	Wiper Tank:					1

	Remove & Replace Wiper Tank						
	Remove & Replace Wiper Tank Motor						
1.4	Radiator Sprare Tank:						1
	Remove & Replace Radiator Sprare Tank						
1.5	RHS Support Panel & RHS Head Lamp:						4
	Remove & Replace RHS Support Panel						
	Remove & Replace RHS Head Lamp						
	Wiring for RHS Head Lamp						
1.6	Front Bonnet:						6
	Remove & Replace Front Bonnet						
	Remove & Replace Front Bonnet Hinges						
	Remove & Replace Bonnet Stand						
	Replace Bonnet Stand Stopper						
	Replace Bonnet Stand Holder						
	Re-align Front Bonnet						
	Putty & Spray Paint for Front Complete Bonnet (2 colours)						
	Install "POLICE" Wordings on new Front Bonnet						
1.7	RHS Side Skirting:						1
	Remove & Replace RHS Side Skirting						
	Putty & Spray Paint for RHS Side Skirting						
1.8	Engine Under Covers & Fender Lining:						1.5
	Replace RHS, Centre & LHS Engine Under Covers						
	Replace RHS & LHS Fender Lining						
1.9	Air-Con Condenser:						12
	Remove & Replace Air-Con Condenser						
	Remove & Replace Air-Con Condenser Piping						
	Top Up Air-Con Gas						
1.10	ABS Pump:					UNCONFIRM	16

[illegible]

Veron Chen (LKKAUTO)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Wednesday, 7 March 2018 5:33 PM
To: Veron Chen (LKKAUTO)
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); Shiau Chan (LKKAUTO); SUR; assignments
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Hi Veron,

Thanks.

Will review the appraisal report and check back with you if there is any query.

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



HOME TEAM
•TRANSFORMATION 2025•
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Wednesday, 7 March 2018 16:06
To: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; assignments <assignments@lkkauto.com>
Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Dear Wei Yea,

Please refer attached for QX 499S

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wei Yea LIM (SPF) [mailto:LIM_Wei_Yea@spf.gov.sg]

Sent: Friday, 2 March 2018 3:56 PM

To: assignments <assignments@lkkauto.com>

Cc: Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Perry HE (SPF) <Perry_HE@spf.gov.sg>; Bernard SEAH (SPF) <Bernard_SEAH@spf.gov.sg>; Peng Seng NG (SPF) <NG_Peng_Seng@spf.gov.sg>; Rashid ABU HASAN (SPF) <Rashid_Abu_Hasan@spf.gov.sg>; Ai Phing (LKKAuto) <aiphing@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>

Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 499S
- QX 1021E

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM

Contract Management

AEMD, Police Logistics Department

Singapore Police Force

DID: (65) 6478 4844



HOME TEAM
• TRANSFORMATION 2025 •
One Home, One Team
Building Our Future Together

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

Catherine Chong (LKK Auto)

From: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>
Sent: Friday, 2 March, 2018 3:56 PM
To: assignments
Cc: Kim Pang CHAY (SPF); Kwee Huat TAN (SPF); Perry HE (SPF); Bernard SEAH (SPF); Peng Seng NG (SPF); Rashid ABU HASAN (SPF); 'Ai Phing (LKKAuto)'; 'Shiau Chan (LKKAuto)'
Subject: RE: Appraisal Services for SPF vehicles at SMRT Automotive Services (QX499S & QX1021E)
Attachments: QX1021E.xlsx; QX499S.xlsx

Hi Catherine,

Please provide Appraisal Services for the following SPF vehicles at SMRT Automotive Services:

- QX 499S
- QX 1021E

In attached, please find the recommended Parts and Labour required for the repair of these vehicles.

Kindly contact the following SMRT personnel for viewing of the damaged vehicle:

- Mr Kong Sew Kui
- Mr Jason Yeo

Thank you and best regards,

WeiYea LIM
Contract Management
AEMD, Police Logistics Department
Singapore Police Force
DID: (65) 6478 4844



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."



Scope Of Work
Home Team Agency

SCOPE OF WORK

1 To provide labour, materials, transportation, tools and parts and others deemed necessary to carry out the following repairs:

CONTRACTOR :	SMRT	VEH TYPE :	FRC	UNIT :	SPF	Reference No. 0499/SPF/4W/18/02/33
VEH NO :	QX499S		REPAIR TYPE:		ACCIDENT	
VEH MAKE/MODEL:	TOYOTA ALTIS		ODOMETER :		128965	

S/N	PARTS DESCRIPTION	PART COST (\$)	QTY	Mark Up Rate	Parts Cost Per Unit After Mark Up (\$)	Total Parts Cost Per Unit After Mark Up (\$)
1	Scope Of Repairs					
1.1	Front Bumper ✓ CRK		1		0.00	0.00
1.2	Front Bumper Retainers (Left & Right) ✓ NEC		2		0.00	0.00
1.3	Radiator Grill ✓ TW		1		0.00	0.00
1.4	Front Bumper Lower Grill ✓ MS		1		0.00	0.00
1.5	Fog Lamp Cover (Left & Right) ✓ MS		2		0.00	0.00
1.6	Front Number Plate ✓ Cut		1		0.00	0.00
1.7	RHS Fender ✓ DT		1		0.00	0.00
1.8	RHS Fender Panel ✓ DT		1		0.00	0.00
1.9	Front Bonnet Cover ✓ DT		1		0.00	0.00
1.10	Bonnet Hinge ✓ BT		2		0.00	0.00
1.11	RHS Head Lamp ✓ CRK		1		0.00	0.00
1.12	RHS Support Panel ✓ BT		1		0.00	0.00
1.13	Wiper Tank ✓ Deform		1		0.00	0.00
1.14	Wiper Tank Motor ?		1		0.00	0.00
1.15	Radiator Spare Tank ✓ Deform		1		0.00	0.00
1.16	RHS Engine Under Cover ✓ Deform		1		0.00	0.00
1.17	Centre Engine Under Cover ?		1		0.00	0.00
1.18	LHS Engine Under Cover ?		1		0.00	0.00
1.19	RHS Fender Lining ✓ MS		1		0.00	0.00
1.20	LHS Fender Lining ✓ MS		1		0.00	0.00
1.21	Front Bumper Clips ✓ NEC		1		0.00	0.00
1.22	Radiator Grill Clips ✓ NEC		1		0.00	0.00
1.23	RHS Side Skirting R		1		0.00	0.00
1.24	Bonnet Stand ✓ MS		1		0.00	0.00
1.25	Bonnet Stand Stopper ✓ NEC		1		0.00	0.00
1.26	Bonnet Stand Holder ✓ MS		1		0.00	0.00
1.27	Air-Condenser ✓ DT		1		0.00	0.00
1.28	Air-Condenser Piping ✓ BT		1		0.00	0.00
1.29	ABS Pump ?		1		0.00	0.00
1.30	Front Emblem ✓ NEC		1		0.00	0.00
1.31	RHS Upper & Lower Arm ✓ BT		1		0.00	0.00
1.32	RHS Knuckle Arm ✓ DT		1		0.00	0.00
1.33	Front Absorber ✓ BT		2		0.00	0.00
1.34	RHS Knuckle Bearing ✓ DMS		1		0.00	0.00
2	Additional Services					
2.1	NA			0%	0.00	0.00
Remarks:					Parts Total:	\$

S/N	LABOUR DESCRIPTION	Man-Hour Rate (\$)	Man-Hour Qty	Total Man-Hour Cost (\$)
1	Scope Of Repairs			
1.1	Front Bumper:	6	✓	0.00
	Replace Front Bumper			
	Remove & Replace Both Side Front Bumper Retainers (Left & Right)			
	Remove & Replace Radiator Grill			
	Replace Front Bumper Lower Grill			
	Replace Both Side Fog Lamp Cover (Left & Right)			
	Remove & Replace Front Number Plate			
	Putty & Spray Paint for Front Complete Bumper (3 colours)			
1.2	RHS Fender:	4	✓	0.00
	Remove & Replace RHS Fender			
	Remove & Replace RHS Fender Panel			
	Putty & Spray Paint for RHS Fender (2 colours)			
1.3	Wiper Tank:	1	✓	0.00
	Remove & Replace Wiper Tank			
	Remove & Replace Wiper Tank Motor			
1.4	Radiator Sprare Tank:		1 ✓	0.00
	Remove & Replace Radiator Sprare Tank			
1.5	RHS Support Panel & RHS Head Lamp:	4	✓	0.00
	Remove & Replace RHS Support Panel			
	Remove & Replace RHS Head Lamp			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18004141/Svbe2		
CONTRACT MANAGEMENT SECTION (SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 23-03-2018		
Code : SPF3				
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		QX 499S	
Policy No.	Coverage (\$)		0.00	
Claim No. HOMSPFETQ17300218	Excess (\$)		0.00	
Assign From LIM WEI YEA	Assign Date		02/03/2018	
2. Vehicle Particulars & Condition				
Make & Model TOYOTA ALTIS	c.c		1598	
Engine No. HIDDEN	Year of Reg.		2010	
Chassis No. MR053ZEE106169226	Colour		WHITE	
Odometer 128965	Steering		IN ORDER	
Brakes IN ORDER	Modification		NIL	
General FAIR				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	Inspection Date		06/03/2018	
Survey held at	2B SUNGEI KADUT DR			
Repairer	SMRT AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Registration No. QX 499S

S/N	ITEM DESCRIPTION	PARTS				MAN-HOUR QTY
		PARTS QTY	Condition	PARTS COST PER UNIT (\$) AFTER MARK UP	TOTAL PARTS COST (\$) AFTER MARK UP	
1	MATERIALS					
1.1	Front Bumper	1	CRACKED			
1.2	Front Bumper Retainers (Left & Right)	2	NECESSARY			
1.3	Radiator Grill	1	TORN			
1.4	Front Bumper Lower Grill	1	MISSING			
1.5	Fog Lamp Cover (Left & Right)	2	MISSING			
1.6	Front Number Plate	1	CUT			
1.7	RHS Fender	1	BENT			
1.8	RHS Fender Panel	1	BENT			
1.9	Front Bonnet Cover	1	BENT			
1.10	Bonnet Hinge	2	BENT			
1.11	RHS Head Lamp	1	CRACKED			
1.12	RHS Support Panel	1	BENT			
1.13	Wiper Tank	1	DEFORMED			
1.14	Wiper Tank Motor	1	UNCONFIRM			
1.15	Radiator Spare Tank	1	DEFORMED			
1.16	RHS Engine Under Cover	1	DEFORMED			
1.17	Centre Engine Under Cover	1	UNCONFIRM			
1.18	LHS Engine Under Cover	1	UNCONFIRM			
1.19	RHS Fender Lining	1	MISSING			
1.20	LHS Fender Lining	1	MISSING			
1.21	Front Bumper Clips	1	NECESSARY			
1.22	Radiator Grill Clips	1	NECESSARY			
1.23	RHS Side Skirting	1	REPAIR			
1.24	Bonnet Stand	1	MISSING			
1.25	Bonnet Stand Stopper	1	NECESSARY			
1.26	Bonnet Stand Holder	1	MISSING			
1.27	Air-Condenser	1	BENT			

1.28	Air-Condenser Piping	1	BENT			
1.29	ABS Pump	1	UNCONFIRM			
1.30	Front Emblem	1	NECESSARY			
1.31	RHS Upper & Lower Arm	2	BENT			
1.32	RHS Knuckle Arm	1	BENT			
1.33	Front Absorber	2	BENT			
1.34	RHS Knuckle Bearing	1	DAMAGED			
2	LABOUR DESCRIPTION					
1.1	Front Bumper:					6
	Replace Front Bumper					
	Remove & Replace Both Side Front Bumper Retainers (Left & Right)					
	Remove & Replace Radiator Grill					
	Replace Front Bumper Lower Grill					
	Replace Both Side Fog Lamp Cover (Left & Right)					
	Remove & Replace Front Number Plate					
	Putty & Spray Paint for Front Complete Bumper (3 colours)					
1.2	RHS Fender:					4
	Remove & Replace RHS Fender					
	Remove & Replace RHS Fender Panel					
	Putty & Spray Paint for RHS Fender (2 colours)					
1.3	Wiper Tank:					1
	Remove & Replace Wiper Tank					
	Remove & Replace Wiper Tank Motor					
1.4	Radiator Sprare Tank:					1
	Remove & Replace Radiator Sprare Tank					
1.5	RHS Support Panel & RHS Head Lamp:					4
	Remove & Replace RHS Support Panel					
	Remove & Replace RHS Head Lamp					
	Wiring for RHS Head Lamp					
1.6	Front Bonnet:					6
	Remove & Replace Front Bonnet					
	Remove & Replace Front Bonnet Hinges					
	Remove & Replace Bonnet Stand					
	Replace Bonnet Stand Stopper					
	Replace Bonnet Stand Holder					
	Re-align Front Bonnet					

	Putty & Spray Paint for Front Complete Bonnet (2 colours)					
	Install "POLICE" Wordings on new Front Bonnet					
1.7	RHS Side Skirting:					1
	Remove & Replace RHS Side Skirting					
	Putty & Spray Paint for RHS Side Skirting					
1.8	Engine Under Covers & Fender Lining:					1.5
	Replace RHS, Centre & LHS Engine Under Covers					
	Replace RHS & LHS Fender Lining					
1.9	Air-Con Condenser:					12
	Remove & Replace Air-Con Condenser					
	Remove & Replace Air-Con Condenser Piping					
	Top Up Air-Con Gas					
1.10	ABS Pump:		UNCONFIRM			16
	Remove & Replace ABS Pump					
1.11	RHS Under Carriage:					8
	Remove & Replace Both Side Front Absorber					
	Remove & Replace RHS Lower Arm					
	Remove & Replace RHS Knuckle Arm					
	Remove & Replace RHS Knuckle Bearing					
	Remove & Re-fix back RHS Front Wheel to facilitate repairs					
1.12	Wheel Alignment					2
COSTING		TOTAL PARTS COST			\$0.00	
		TOTAL MAN-HOUR				62.5

Registration No. QX 499S

Registration No. QX 499S

Vehicle Inspected By

YEANG WAI KEEN
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.