

ASS. REC. BY:

REF:

CS / ALG18004144 / Kgbnz

Special Instruction:

Surveyor: Kenneth  
Mehmen

ASSIGNMENT (Office)

From (Person): Nox Muresa

of ALG

Date/Time: 21/02/2018 10:21Am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKX 9472E

Insured:

SKX 5197B

at Workshop m/s

Massive Trading

Tel:

9108 2728

of

Blk 5038 AMK Ind Park 2 #01-405

Policy No:

2100442581

Claim No:

429231282256

Sum Insured:

Excess:

Make of Veh:

D.O.A

18022018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Up'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Anthony

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKX 9472E - X
	SKX 5197B - X
	Kenneth confirmed LS \$2250, 3 days.
	(Paid \$1124, 33%)

ASS. REC. BY:

REF: AIG /

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: PK X94725 Yr Regn: 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 6 c.c. 1998

Colour: M. Black A/C: Insured / Std / NI / NA

Sp. Reading: 28347 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM8GT1072G0222904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. \_\_\_\_\_

Rear

R/Bal. 4 mm

L/Bal. 4 mm

D.O.I. 21/2/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S 151

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/2 GIA & Est not ready

RECEIVED 22 MAR 2010

Date/Time, File Pass to?

: Prel. Report

: Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation: \$ 250

S + RS, SI \$ 0

Photos

Others

TOTAL

250

Report Format: MER-TP

Lump Sum / I.B.I. (\$) 2750

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

250
0
270



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CS/AIG18004144/Kqb

78 SHENTON WAY #08-16  
CHARTIS BUILDING  
SINGAPORE 079120

Date : 05-03-2018



Code : AIG

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh. SKX 5197B	Veh. Inspected SKX 9472E
Policy No.	Coverage (\$) 0.00
Claim No.	Excess (\$) 0.00
Assign From NOOR MARIESA	Assign Date 21/02/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c 0
Engine No. HIDDEN	Year of Reg.
Chassis No.	Colour
Odometer -	Steering
Brakes	Modification
General	

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date 18/02/2018	Inspection Date 05/03/2018
Survey held at BLK 5038 AMK IND PARK 2 #01-405	
Repairer MASSIVE TRADING & AUTO	

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>  
**Sent:** Wednesday, 21 February, 2018 10:21 AM  
**To:** 'assignments@lkkauto.com'; 'admin-a@lkkauto.com'  
**Cc:** Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Chin, Lee-Ying  
**Subject:** aigencrypt - Pre repair inspection request - SKX9472E VS SKX5197B (OI) DOA: 18/02/18  
**Attachments:** Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKX51... (62.0 KB); 20180220154403021.pdf

Hi,

Please refer to the enclosed request from **Teo Keng Siang LLC**

Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

*Kindly assist to assign Mr Kenneth Kong as Single Joint Expert as requested.*

Thank you.

Best Regards,

Mariesa Abu Kassim (Mariesa)

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto

Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012202 | Fax +6 03 2685 5898

[NoorMariesa.AbuKassim@aig.com](mailto:NoorMariesa.AbuKassim@aig.com) | [www.aig.com](http://www.aig.com)

### IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/02/2018 12:48
Date Of Accident	18/02/2018 16:40
Exact Location Of Accident	TUAS CAUSEWAY TWDS SINGAPORE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKX9472E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM CHOON KUAN
NRIC No	S1698296B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94743191
Alternative Phone No	OTHERS-94743191

### Vehicle Particulars

Manufacturer	MAZDA
Model	6-2.0 SP (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100446050-02
Cover Note Number	

### Driver

Name of Driver	LIM CHOON KUAN
NRIC No	S1698296B
Date Of Birth	25/02/1965
Occupation	INDOOR
Date Of Driving Pass	24/06/1985
Driving Experience	32 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94743191
Fax Number	
Contact Number	OTHERS-94743191
E-Mail Address	NOEMAIL

Address BLK 469 CHUA CHU KANG  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - CHANGE/CROSS LANE  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 4  
 Passenger 1 NAME: : KWEK YEN PING  
 GENDER: : FEMALE  
 Passenger 2 NAME: : LIM SHI EN  
 GENDER: : FEMALE  
 Passenger 3 NAME: : LIM KAH JUN  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BUKIT BATOK NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 21 BUKIT BATOK EAST AVE 4 , POSTCODE: 659840 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-6659999 - FAX NO: 66655793  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

refer to attached statement

**Attachment(s)**

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SKX5197B  
 Vehicle Make/Model/Colour  
 Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



CONFIDENTIAL

Annex E

NOTICE OF REPORTING

This is to confirm that Lim Choon Kuan *Li*,  
NRIC/FIN S1698296B, has reported to the Police a non-injury traffic accident which  
occurred along Causeway Link from Malaysia towards Tuas Checkpoint  
on 18/02/2018 at 1644hrs involving the following vehicles:

- 1) SKX9472E, a black Mazda 6 driven by Complainant, HP: 94743191
- 2) SKXS197B, a white Mazda 6

2 If this accident was reported to the Police within 24 hours of its occurrence, then  
he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer: Sgt Yap Oi Long

*W*  
BUKIT BATOK NPC  
NO. 21 BUKIT BATOK EAST AVP  
SINGAPORE 659840  
TEL: 66659999

Date: 18/02/2018 Time: 1910hrs

S/D Ref: 54

Police Post/Unit: Jurong Division/Bukit Batok NPC

Original - to be issued to informant  
Duplicate - to be submitted to Traffic Police

CONFIDENTIAL

Hg

# Massive Trading & Auto

Mailing address : Blk 225 #07-579 Ang Mo Kio Ave 1 Singapore 560225  
H/p 91082728

Fax : 64816131

Lim Choon Kuan  
Blk 469 Chua Chu Kang  
#13-97  
Singapore 680469

*Not Authorized  
L1 by @ 2250h  
Resurvey After Paint  
3 days*

Vehicle No : SKX 9472 E  
Make : Mazda 6  
Year : 2016

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

### Estimate Cost Of Repair

1 pc	Front n/s headlamp assy ? <i>refer photo</i>	<i>ntjm</i> \$977.60 ✓
1 pc	Front bumper <i>delivered</i>	<i>Bull wt</i> \$1,096.40 ✓
1 pc	Front n/s bumper side retainer <i>re-ute</i>	<i>sm</i> \$75.10 ✓
1 pc	Front n/s fender <i>delivered</i>	<i>sm</i> \$385.70 ✓
1 pc	Front n/s fender innershield <i>re-ute</i>	<i>sm</i> \$145.20 ✗
		\$2,680.00
		Less 25% <i>20%</i> <del>\$536.00</del>
		\$2,144.00

### Labour Charges

Remove/renew the above parts including knocking, welding etc.	\$500.00	<i>400</i>
To putty & spray paint front & rear accident affected portion.	\$600.00	<i>400</i>
Check/reconnect wiring.	\$30.00	<i>20</i>
To spray anti rust on accident affected portion.	\$100.00	<i>30</i>
<b>Total</b>	<b>\$3,374.00</b>	

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CSAIG18004144/KQBN2  
**Date:** 23/03/2018

**REFERENCE**

**Handling Insurer:** AIG Asia Pacific Insurance Pte. Ltd. **Policy No:** 2100442581  
**Claimant Vehicle No :** SKX9472E **Insured Vehicle No :** SKX5197B  
**Date of Loss:** 18/02/2018 **Nature of Claim:** TP **Claim No:** 4292312822SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

**Reg No:** SKX9472E **Engine No:** PE20705925  
**Make & Model:** MAZDA 6, 2.0 V (A) **Chassis No:** JM6GJ1072G0222904  
**Reg. Date:** 31/12/2015 (Man. Year: 2015) **Odometer:** 28347 km  
**Colour:** Metallic Black  
**Engine Capacity:** 1998 cc  
**Market Value/New Car Price:** N/A  
**Sum Insured (S\$):** Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

**General Condition:** **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes  
**Handbrake (Serviceable):** Yes **Engine Modification:** No **Pre-accident Condition:** Yes

**CONDITION OF TYRES**

**Front Tyre Size:** 225/55R17 **Rear Tyre Size:** 225/55R17  
**Front Left Side:** Bridgestone 4 mm **Rear Left Side:** Bridgestone 4 mm  
**Front Right Side:** Bridgestone 4 mm **Rear Right Side:** Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

**COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,144.00	1,967.76	176.24	8.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	850.00	380.00	30.89
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,374.00</b>	<b>2,817.76</b>	<b>556.24</b>	<b>16.49</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,250.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,374.00</b>	<b>2,250.00</b>	<b>1,124.00</b>	<b>33.31</b>

**INSPECTION**

**Date of Assignment:** 21/02/2018  
**Date Inspected:** 21/02/2018 **Inspected At:** Massive Trading & Auto  
Blk 5038 #01-405, Ang Mo Kio Industrial Pk 2  
Singapore 569541

**Estimated Period of Repair:** 3.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FRONT N/S HEADLAMP ASSY	Mtg Cracked	977.60 FL	*977.60 FL	
2	1		*FRONT BUMPER	Buckled/Cut	1,096.40 FL	*1,096.40 FL	
3	1		*FRONT N/S BUMPER SIDE RETAINER	Serviceable	75.10 FL	*- FL	
4	1		*FRONT N/S FENDER	Bent	385.70 FL	*385.70 FL	
5	1		*FRONT N/S FENDER INNERSHIELD	Serviceable	145.20 FL	*- FL	
					<b>Sub Total (S\$)</b>	<b>2,680.00</b>	<b>2,459.70</b>
					- List Item Discount on L Items 20.00/20.00% (S\$)	536.00	491.94
					<b>Total Parts (S\$)</b>	<b>2,144.00</b>	<b>1,967.76</b>

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE/RENEW THE ABOVE PARTS INCLUDING KNOCKING,WELDING ETC	New	500.00	400.00
2	TO PUTTY & SPRAY PAINT FRONT & REAR ACCIDENT AFFECTED PORTION	New	600.00	400.00
3	CHECK/RECONNECT WIRING	New	30.00	20.00
4	TO SPRAY ANTI RUST ON ACCIDENT AFFECTED PORTION	New	100.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,230.00</b>	<b>850.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >