

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

*Not Affected
 ok
 1/58
 6 day
 5/3/18
 The ph. Atherage*

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04/05,
 IOB Building
 Singapore 049711

TEL: 63476100

FAX: 62244174

ATTN: Motor Claim Department

Your Ref No: 18/III/TP-048 (03)

Claim Type: Third Party

Accident Date: 01/03/2018

TP Veh Reg No: SHA3905U

Estimate No: EST0003989

Date: 02 Mar 2018

Policy No: 5091274471

Veh Reg No: **SJL6378P**

Make/Model: KIA SPORTAGE

Chasis No: KNAJE552397610965

Engine No: G4GC8H787576

Reg. Date: 05/12/2008

Estimate Repair Cost to Vehicle No :SJL6378P

Description	Quantity	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1 REAR GATE 'SPORTAGE' PLATE	1 PC	45.50	—
2 REAR GATE 'CVVT' PLATE	1 PC	52.50	—
3 REAR GATE '2.0' PLATE	1 PC	42.25	—
4 REAR BUMPER	1 PC	385.85	—
5 REAR BUMPER INNER SPONGE	1 PC	115.00	?
6 REAR BUMPER REINFORCEMENT	1 PC	255.30	?
7 REAR BUMPER TOP PAD	1 PC	68.50	—
8 REAR END PANEL	1 PC	326.50	?
9 REAR FENDER LH	1 PC	845.20	—
10 REAR FENDER INNER COWLING LH	1 PC	58.20	—
11 INNER COWLING CLIP	10 PC	55.00	—
12 TAIL LAMP LH	1 PC	338.00	?
13 REAR EXHAUST BOX LH	1 PC	785.20	?
14 REAR EXHAUST CHROME FINISHER LH	1 PC	150.00	—
15 REAR EXHAUST RUBBER HOLDER	2 PC	77.00	?
16 REAR SHOCK ABSORBER LH	1 PC	258.30	?
17 REAR KNUCKLE ARM LH	1 PC	458.20	?
18 REAR KNUCKLE BEARING LH	1 PC	285.00	?
19 REAR LOWER ARM LH	1 PC	320.00	?
20 REAR UPPER ARM LH	1 PC	295.00	?
21 REAR TRAILING ARM LH	1 PC	195.20	?
22 REAR ANTI ROLL BAR LINK LH	1 PC	85.85	?
23 REAR SPORT RIM LH (ORI)	1 PC	785.00	—
24 REAR FENDER GLASS MOULDING LH	1 PC	850.00	—

7,132.55

Less 10% 713.26 6,419.31

Special Net

25 REVERSE SENSOR	1 PC	250.00	200
26 REAR FENDER GLASS GUM	1 PC	45.00	X
27 REAR TYRE LH	1 PC	325.00	80% 120
		620.00	620.00

Labour

28 WIRE CHECKING	1 UNIT	30.00	20
29 REMOVE & REFIX REAR FENDER GLASS	1 UNIT	65.00	X
30 REMOVE & REFIX CUSHION AND SEATS	1 UNIT	180.00	80
31 REMOVE & REFIX EXHAUST BOX	1 UNIT	150.00	60

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street #04/05,
IOB Building
Singapore 049711

TEL: 63476100

FAX: 62244174

ATTN: Motor Claim Department

Your Ref No: 18/III/TP-048 (03)

Claim Type: Third Party

Accident Date: 01/03/2018

TP Veh Reg No: SHA3905U

Estimate No: EST0003989

Date: 02 Mar 2018

Policy No: 5091274471

Veh Reg No: **SJL6378P**

Make/Model: KIA SPORTAGE

Chasis No: KNAJE552397610965

Engine No: G4GC8H787576

Reg. Date: 05/12/2008

Estimate Repair Cost to Vehicle No :SJL6378P

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
32 REMOVE & REFIX REAR UNDERCARRIAGE	1 UNIT	250.00	?
33 4 WHEEL ALIGNMENT	1 UNIT	100.00	60
34 LABOUR CHARGE	1 UNIT	1,500.00	800
35 SPRAY PAINTING	1 UNIT	1,200.00	900
		3,475.00	3,475.00
Total			S\$ 10,514.31
Add GST @ 7%			736.00
Total Amount Payable			<u>S\$ 11,250.31</u>

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND TWO HUNDRED FIFTY AND CENTS THIRTY ONE ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: