

Singer

Khl.

REF:

INC

NS/INC18004156/Grber

## ASSIGNMENT

From:

Date:

Veh No:

SHC4004C

Regn:

30 Oct 2013

Estimated Cost:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Truck / Prime Mover /OD TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

Make:

Toyota Prius

cc 1798

at Workshop m/s

SMRT

Colour:

Maroon

A/C: Insured / Std / NI / NA

of

Sp Reading

419385

T/Radio: Insured / Std / NI / NA

Insured:

GU 9556K

Eng/No:

Policy No.

0083708293 - 13

010417 - 310318

C/No:

JTDKN36U505695634

Claims No.

MT/0984196-002

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

(Client's Record)

Steering: In order / Jammed / Leaked / Burnt or

Make of Veh:

Brake: In order / Jammed / Leaked / Burnt or

(Policy Condition)

Modi: Nil / S/Rim / STD A/Rim or

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Tyre Size:

F: 195 / 65R15

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

FALKEN

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt.:

Consistent? : Yes or No

R/Bal.

45 mm

R/Bal.

45 mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

45 mm

L/Bal.

45 mm

Est. Repairs:

5

days

Res.: Yes or No

D.O.A.

D.O.I.

02-03-18

Lum Sum:

20

%

3 Val.: Yes or No

Survey held at

w/s

4:30pm

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

SHC4004C - NJM/INC09024768/TJY  
GU 9556K - X

Dnt: 31.10.2009

Confirm \$3750.00. 5 days  
Red: \$7027.84, 65%.

RECEIVED 09 APR 2010

Date/Time, File Pass to?



Preli. Report

Days Of Repair:

5

1)

typist



Final Report

Resurvey No. of Trip:

1

Survey Fee:

160

Date/Time, File Return to?

Transportation:

2)

Add Fee:



Site Insp (\$

) \$ + RS. \$



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

TP

Lump Sum / Rpt. (\$

3750

TOTAL

195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004156/Grb				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 05-03-2018	
Code: INC4				
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GU 9556K	Veh. Inspected	SHC 4004C	
Policy No.	0083708293-13	Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/03/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	01/03/2018	Inspection Date	02/03/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

eBaoTech

General/Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	0083708293-13	MPH DISTRIBUTORS (S) PTE LTD	197601254G	GCV	Third Party, Fire & Theft	GU9556K	GU9556K	01/04/2017	31/03/2018

TP Claims against NTUC Income: Follow-Through Survey

Date : 04/04/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Estimate	Tentative repair cost
1	MT/0984098-002	SMRT TAXIS PTE LTD	SHB 5366G	SKA 7181D	28/02/2018	\$ 7,797.23	\$ 2,550.00
2	MT/0988982-001	SMRT TAXIS PTE LTD	SHC 4926S	SLK 1772Y	19/03/2018	\$ 2,842.70	\$ 550.00
3	MT/09889428-002	COMFORTDELGRO	SHA 4969D	SCE 4477U	02/04/2018	\$ 1,303.30	\$ 480.00
4	MT/0988889-002	COMFORTDELGRO	SH 6484E	SIG 4840K	31/03/2018	\$ 2,381.58	\$ 1,050.00
5	MT/0984196-002	SMRT TAXIS PTE LTD	SHC 4004C	GU 9556K	01/03/2018	\$ 10,777.84	\$ 3,750.00
6	MT/0987457-002	SMRT TAXIS PTE LTD	SHB 5197C	SLK 4501U	16/03/2018	\$ 5,230.50	\$ 920.00
7	MT/0981513-002	SMRT BUS	SMB 5057P	SLU 2644B	06/02/2018	\$ 1,540.00	\$ 700.00
8	MT/0981716-002	SMRT BUS	SG 5494M	SIG 6853K	08/02/2018	\$ 1,927.00	\$ 1,590.00
9	MT/0985967-002	SMRT TAXIS PTE LTD	SHF 7E	SJM 542R	13/03/2018	\$ 12,384.10	\$ 4,284.50

Claim received from LKK Auto

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	01/03/2018 10:23
Date Of Accident	01/03/2018 08:30
Exact Location Of Accident	KALLANG SECTOR TOWARDS PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4004C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	CHUA KOON YONG
NRIC No	S7040804Z
Date Of Birth	11/11/1970
Occupation	OUTDOOR
Date Of Driving Pass	05/05/1997
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	10-13
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : MTR TOH GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

I WAS TRAVELLING ALONG KALLANG SECTOR TOWARDS PIE WITH ONE PASSENGER (MALE CHINESE) ON BOARD. I SLOWED DOWN AND SIGNALLLED TO TURN RIGHT. I PROCEEDED WHEN THE TRAFFIC WAS CLEAR. SUDDENLY A VAN GU9556K WHICH WAS BEHIND MY TAXI, OVERTOOK MY TAXI AGAINST THE FLOW OF DIRECTION AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI. AFTER WHICH THIRD PARTY DROVE AWAY WITHOUT STOPPING. I WENT AFTER THIRD PARTY AND MANAGED TO STOP HIM A DISTANCE WAY.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FIEL TOO BIG
Was there any audio recorded?	NO

#### Details of Witness 1

Name	MR TOH
Phone Number	
Email Address	


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU9556K
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MOHAMED ASROY BIN ABDUL HALIM

NRIC/Passport Number  
Contact Number  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF INJURED PERSON 1

Name	CHUA KOON YONG
Approximate Age	
Injuries Sustain	THUMB SWOLLEN
Injured person in which vehicle?	GU9556K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

This image shows a single sheet of white paper with horizontal ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

### DECLARATION.

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



SKETCH PLANIMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature  
 Date & Time:

  
 Driver's Signature  
 (If Driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHC4004C
Vehicle to be Exported:	No
Intended De-registration Date:	05 Mar 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2013
Engine No.:	2ZR5890430
Chassis No.:	JTDKN36U505695634
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$33,120.00
Original Registration Date:	30 Oct 2013
First Registration Date:	30 Oct 2013
Transfer Count:	0
Actual ARF Paid:	\$8,368.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Oct 2021
PARF Rebate Amount:	\$6,276.00
Intended COE Rebate Details	
COE Expiry Date:	29 Oct 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	8
PQP Paid:	\$61,324.00
COE Rebate Amount:	\$27,962.00
<b>Total Rebate Amount:</b>	<b>\$34,238.00</b>
Message	

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Mar 2018

OK

## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4004C  
 Ref. No : TAX/03/18/2002  
 Reg. Date : 30/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : CHUA KOON YONG  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 01/03/2018 08:30:00 AM  
 Accident Reported Date / Time : 01/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094836  
 Special Instruction to ARC, if any :  
 GU9556K  
 Prepared Date : 01/03/2018 10:57:56 AM



5 Days.

Lump Sum Repair

After repair photos.

Gu. Qiang - 82880282

02/3/18.

*Signature* 6/3/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U50-5695634

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,854.00	0.00
Total Material Charges	: 3,280.80 7329.84	4,605.90
Other Charges	: 580.00	0.00
<b>TOTAL</b>	<b>: 6,728.80 10777.84</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 6,750.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 02/03/2018 09:27:14 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/03/2018 09:26:28 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	0.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b> 300/

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200/
TO REPSRAY FRONT HOOD	378.00	0.00 X
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 X 4 NN
TO RESPRAY FRONT FENDER RH	378.00	0.00 200/
TO RESPRAY APRON PANEL RH	180.00	0.00 X NN
TO RESPRAY VIEW MIRROR	180.00	0.00 100/
TO RESPRAY RIM	180.00	0.00 X NN
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,854.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30/
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 60/
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60/
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X NN
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>580.00</b>	<b>0.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT <i>Cut</i>	1	482.00	25.00	361.50 /	Replace	Replace	No
81511-47050			LENS & BODY, FR TURN RH <i>scr</i>	1	511.80	10.00	460.62 /	Replace	Replace	No
52115-47040		6505515	BUMPER SUPPORT F/RH <i>MC</i>	1	76.40	25.00	57.30 /	Replace	Replace	No
53301-47060		6505555	HOOD PANEL <i>X NN</i>	1	748.10	25.00	561.08 X	Repair	Replace	No
53420-47070			HOOD HINGE LH <i>X NN</i>	1	55.90	25.00	41.92 X	Replace	Replace	No
53410-47070			HOOD HINGE RH <i>X NN</i>	1	55.90	25.00	41.92 X	Replace	Replace	No
53201-47902			SUPPORT SUB-ASSY <i>X NN</i>	1	1,460.40	25.00	1,095.30 X	Repair	Replace	No
81130-47500		6505437	HEAD LAMP RH <i>scr</i>	1	945.20	10.00	850.68 /	Replace	Replace	No
53801-47050		6505557	FENDER FRT/RH <i>buc</i>	1	723.40	25.00	542.55 /	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) <i>MC</i>	1	51.90	25.00	38.92 /	Replace	Replace	No
53875-47030		6505553	FENDER LINER FRT/RH <i>TV</i>	1	171.70	25.00	128.77 /	Replace	Replace	No
53851-47040			FENDER LINER PAD, FR WHEEL RH <i>X</i>	1	49.30	25.00	36.97 X	Replace	Replace	No
53825-47010			FENDER PROTECTOR FRT/RH UPPER <i>NTV</i>	1	46.10	25.00	34.57 X	Replace	Replace	No
53710-12030			FENDER APRON FRT/RH <i>X</i>	1	168.10	25.00	126.07 X	Replace	Replace	No
		6503707	TYRE <i>scr (50%)</i>	1	126.74	0.00	126.74 /	Replace	Replace	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT <i>Cut</i>	1	1,484.20	25.00	1,113.15 /	Replace	Replace	No
81730-52090		6505466	MIRROR LAMP RH <i>scr</i>	1	65.30	10.00	58.77 /	Replace	Replace	No
879157-4010		6505598	COVER, OUTER MIRROR, RH <i>scr Repair X</i>	1	107.40	25.00	80.55 X	Replace	Replace	No
<b>TOTAL MATERIALS</b>								<b>4,101.04</b>	<b>5,757.38</b>	
<b>TOTAL MATERIALS(Discounted)</b>							<b>3,280.80</b>	<b>4,605.90</b>		

**Added Spare Parts / Material Usage After Surveyor Signed off**


Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
<b>TOTAL SUPPLEMENTARY MATERIALS</b>									

# SMRT Accident Vehicle Repair Estimates

5-3-18 / 8:00

## Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4004C  
 Ref. No : TAX/03/18/2002  
 Reg. Date : 30/10/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : CHUA KOON YONG  
 Type of Accident : SIDE SWIPE  
 Date / Time of Accident : 01/03/2018 08:30:00 AM  
 Accident Reported Date / Time : 01/03/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by : Guo Qiang  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024094836  
 Special Instruction to ARC, if any :  
 GU9556K - NTUC IDAC  
 BEFORE PAINT PHOTO AND AFTER REPAIR PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR guoqiang (LKK) & Email : guoqiang@lkkauto.com HP:82880282  
 LUMPSUM REPAIR  
 TYRE = 50%  
 Prepared Date : 01/03/2018 10:57:56 AM



QC 9/3/18 16.44 Pass

Recording Camera ☒ ☐  
 Radio Antenna ☒ ☐  
 1st witness ☒ Date 5-3-18  
 2nd witness ☐ Date

1/2  
 KM 419383

Vehicle to Wagon Date In: 5/3 To: 11/3  
 Time In: 1504 Driver: HWR  
 Wagon Job No: 08/0170  
 Vehicle sent to SMRT Date In: 9-3-18 To: 11-3-18  
 Time In: 11:10 Driver: YS  
 Received by (SMRT):

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U50-5695634

Mileage


: 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	300.00
Total Spray Painting Charges	: 1,854.00	500.00
Total Material Charges	: 3,936.62	3,739.00
Other Charges	: 580.00	-789.00
<b>TOTAL</b>	<b>: 7,384.62</b>	<b>3,750.00</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	5.00
Prepared / Adjusted By	:	GUOQIANG (LKK)
Arc / Surveyor Sign Off Date	: 02/03/2018 09:27:14 AM	02/03/2018 04:31:32 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 02/03/2018 09:26:28 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : QN-1803-0227

Invoice No :

Quotation Date : 12/3

Invoice Date :

Invoice Amount :

Prepared Date :



**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	300.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>300.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO REPSRAY FRONT HOOD	378.00	0.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
TO RESPRAY FRONT FENDER RH	378.00	200.00
TO RESPRAY APRON PANEL RH	180.00	0.00
TO RESPRAY VIEW MIRROR	180.00	100.00
TO RESPRAY RIM	180.00	0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,854.00</b>	<b>500.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	60.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-939.00
<b>Total Other Costs</b>	<b>580.00</b>	<b>-789.00</b>

10777.84

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT <i>cut</i>	1	482.00	25.00	361.50	Replace	Replace	No <i>/</i>
81511-47050			LENS & BODY, FR TURN RH <i>SCR</i>	1	511.80	10.00	460.62	Replace	Replace	No <i>/</i>
52115-47040		8505515	BUMPER SUPPORT F/RH <i>1 nec</i>	1	76.40	25.00	57.30	Replace	Replace	No <i>/</i>
53301-47060		6505555	HOOD PANEL <i>Xnn</i>	0	748.10	25.00	0.00	Repair	Not given	No <i>X</i>
53420-47070			HOOD HINGE LH <i>Xnn</i>	0	55.90	25.00	0.00	Replace	Not given	No <i>X</i>
53410-47070			HOOD HINGE RH <i>Xnn</i>	0	55.90	25.00	0.00	Replace	Not given	No <i>X</i>
53201-47902			SUPPORT SUB-ASSY <i>nn</i>	0	1,460.40	25.00	0.00	Repair	Not given	No <i>X</i>
81130-47500		6505437	HEAD LAMP RH <i>SCR</i>	1	945.20	10.00	850.68	Replace	Replace	No <i>/</i>
53801-47050		6505557	FENDER FRT/RH <i>br</i>	1	723.40	25.00	542.55	Replace	Replace	No <i>/</i>
75374-47051			NAME PLATE (HYBRID) <i>neu</i>	1	51.90	25.00	38.92	Replace	Replace	No <i>/</i>
53875-47030		6505553	FENDER LINER FRT/RH <i>nn</i>	1	171.70	25.00	128.77	Replace	Replace	No <i>/</i>
53851-47040			FENDER LINER PAD, FR WHEEL RH <i>Xnn</i>	1	49.30	25.00	36.98	Replace	Check	No <i>X</i>
53825-47010			FENDER PROTECTOR FRT/RH UPPER <i>Xnn</i>	1	46.10	25.00	34.58	Replace	Check	No <i>X</i>
53710-12030			FENDER APRON FRT/RH <i>Xnn</i>	1	168.10	25.00	126.08	Replace	Check	No <i>X</i>
		6503707	TYRE <i>SCR</i>	1	126.74	0.00	126.74	Replace	Replace	No <i>/</i>
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT <i>cut</i>	1	1,484.20	25.00	1,113.15	Replace	Replace	No <i>/</i>
81730-52090		6505466	MIRROR LAMP RH <i>SCR</i>	1	65.30	10.00	58.77	Replace	Replace	No <i>/</i>
879157-4010		6505598	COVER, OUTER MIRROR, RH <i>LR</i>	1	107.40	100.00	0.00	Replace	Repair	No <i>LR</i>
TOTAL MATERIALS							3,936.64	3,739.00		
TOTAL MATERIALS(Discounted)							3,936.62	3,739.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

3739.00  
+ 300.00  
+ 650.00  


---

4689.00  
- 20%  


---

3751.20

L/S \$ 3750/-

**Janice Lee (LKKAuto)**

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>  
**Sent:** Monday, March 12, 2018 5:21 PM  
**To:** Guo Qiang (LKKAuto)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** SHC4004C  
**Attachments:** img-312143451-0001.pdf

Hi Guo Qiang,

Attached herewith the repair estimate of SHC 4004C having Case No: TAX/03/18/2002.

There is no change to the approved amount of \$3,750 @ 5 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Sent: Monday, 12 March 2018 2:35 PM  
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)  
Subject: Scan Data from FX-D421D6



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Thatcham escribe

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004156/Grbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 13-04-2018



Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GU 9556K	Veh. Inspected	SHC 4004C
Policy No.	0083708293-13	Coverage (\$)	0.00
Claim No.	MT/0984196-002	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U505695634	Colour	MAROON
Odometer	419385	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	01/03/2018	Inspection Date	02/03/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4004C**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	BUMPER FRT (DISC 25%)	CUT	482.00	361.50
1	BUMPER SUPPORT F/RH (DISC 25%)	NECESSARY	76.40	57.30
1	FENDER FRT / RH (DISC 25%)	BUCKLED	723.40	542.55
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	WHEEL.DISC.FRONT (DISC 25%)	CUT	1,484.20	1,113.15
1	FENDER LINER FRT / RH (DISC 25%)	TORN	171.70	128.77
1	LENS & BODY, FR TURN RH (DISC 10%)	SCRATCHED	511.80	460.62
1	HEAD LAMP RH (DISC 10%)	SCRATCHED	945.20	850.68
1	MIRROR LAMP RH (DISC 10%)	SCRATCHED	65.30	58.77
1	TYRE (SN)	SCRATCHED	126.74	126.74
1	HOOD PANEL	NOT NECESSARY	748.10	-
1	HOOD HINGE LH	NOT NECESSARY	55.90	-
1	HOOD HINGE RH	NOT NECESSARY	55.90	-
1	SUPPORT SUB-ASSY	NOT NECESSARY	1,460.40	-
1	FENDER LINER PAD, FR WHEEL RH	NOT NECESSARY	49.30	-
1	FENDER PROTECTOR FRT / RH UPPER	NOT NECESSARY	46.10	-
1	FENDER APRON FRT / RH	NOT NECESSARY	168.10	-
1	COVER, OUTER MIRROR, RH	TO REPAIR	107.40	-
			7,329.84	3,739.00
<b><u>LABOUR</u></b>				
THATCHAM STANDARD REPAIR TIME ON BODY WORKS.			1,434.00	450.00
THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.			1,854.00	500.00
TO REPLACE SUNDRY PARTS.			100.00	-
TO WASH AND VACUUM.			60.00	-
			3,448.00	950.00
<b>GRAND TOTAL</b>			<b>10,777.84</b>	<b>4,689.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>3,750.00</b>

Report Ref No. NS/INC18004156/Grbe2

Report Ref No. NS/INC18004156/Grbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.