

来發 (明记) 啤 LAI HUAT (MENG KEE)

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 S
RCB No: 199407.

ESTIMAT

No EST0018694
Lim Hai

Pag
You
Job
Our
Payl
Date

No.

Reser

R/S - \$3000

le No SGH 2857G
le Model : Toyota Vios
ent on : 1/3/2018

Qty	Unit	Description
Supply of Parts		
00	Pc	✓ Front bumper
00	Pc	✓ Rear bumper
00	Pc	✓ Rear bumper side holder RH
00	Pc	✓ Rear end panel
00	Pc	Rear tail lamp RH
00	Pc	✓ Rear tail lamp gasket RH
00	Pc	✗ Rear tail lamp panel RH
00	Pc	✓ Rear boot lid weatherstrip
00	Pc	✓ Rear boot lid lock
Special nett item:		
00	Pc	Front number plate
00	Set	Rear reversing sensor with installation
Labour & Misc.		
00		Towing fee

0. 0

238.49 +
245.9 +
15.2 +
720.1 +
189. +
24.36 +
91.84 +
48.44 +
22.8 =
1,596.13 *

1,596.13 x
75. %
1,197.0975 *
35. +
200. =
235. *

135K Lonpac

50. +
60. +
1,000. +
800. =
1,910. *

Amount

1,197.1 +
235. +
1,910. =
3,342.1 *
0. 0
3,342.1 x
90. %
3,007.89 *

178.87 ✓
184.43 ✓
11.40 ✓
540.08 ✓
141.75 ✓
18.27 ✓
68.88 ✓
36.33 ✓
17.10 ✓
197.11

0. 0

35.00 ✓
200.00 ✓

235

50.00

50.00 ✓

有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
有先进的 SAICO Deluxe 喷漆烘炉。
ervices include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support
system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO
oven heater for re-spraying all motor vehicles."