



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2005711
INV Date 19/08/2020
Reference CC4/LPC18004157/Kds3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SGH 2857G
Insured Veh. SJN 7535K
Claim No. 18/18/18/VP05/020445
Policy No. Z18VP05017598
Accident Date 01/03/2018
Inspection Date 05/03/2018

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC18004157/Kds3n2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 19-08-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJN 7535K	Veh. Inspected	SGH 2857G	
Policy No.	Z18VP05017598	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020445	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA VIOS (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	MR053HY4204189348	Colour	METALLIC GREY	
Odometer	179039	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	LING LONG	8 mm	
L/H Front Tyre	175/65 R14	LING LONG	8 mm	
R/H Rear Tyre	175/65 R14	YOKOHAMA	7 mm	
L/H Rear Tyre	175/65 R14	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S AND FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2018	Inspection Date	05/03/2018	
Survey held at	LAI HUAT (MENG KEE) MOTOR PTE LTD 160 SIN MING DRIVE #04-01/02 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 2857G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	MTG CRACKED	238.49	238.49
1	REAR BUMPER	BENT	245.90	245.90
1	REAR BUMPER SIDE HOLDER RH	DISTORTED	15.20	15.20
1	REAR END PANEL	BENT	720.10	720.10
1	REAR TAIL LAMP RH	MTG DISTORTED	189.00	189.00
1	REAR TAIL LAMP GASKET RH	NECESSARY	24.36	24.36
1	REAR TAIL LAMP PANEL RH	BENT	91.84	91.84
1	REAR BOOT LID WEATHERSTRIP	DISTORTED / DENTED	48.44	48.44
1	REAR BOOT LID LOCK	DENTED	22.80	22.80
	LESS 25% DISCOUNT		-399.03	-399.03
			1,197.10	1,197.10
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	NECESSARY	35.00	35.00
1	SET REAR REVERSING SENSOR WITH INSTALLATION (SN)	DENTED	200.00	200.00
			235.00	235.00
	<u>LABOUR</u>			
	TOWING FEE.		50.00	50.00
	TO REMOVE +REPAIR EXHAUST PIPE.		100.00	60.00
	TO STRAIGHTEN REAR BODY INCLUDING CUTTING AND WELDING ,TO KNOCK DENTS ON REAR LUGGAGE PANEL AND RENEW OF PARTS.		1,200.00	1,000.00
	TO SPRAY PAINT.		900.00	800.00
	-		-	-
	-		-	-
	-		-	-
			2,250.00	1,910.00
	GRAND TOTAL		3,682.10	3,342.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,000.00

Report Ref No. CC4/LPC18004157/Kds3n2



Report Ref No. CC4/LPC18004157/Kds3n2

A handwritten signature in black ink, appearing to be 'KSC', on a light blue rectangular background.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 2857G

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 2857G

RE-INSPECTION

