

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No: EST0018694
Tan Kim Hai

Page: 1 of 2
Your ref.: TP-SJN 7535K Lonpac
Job No.: 69287
Our ref.: 18.03.02
Payment
Date: 2/3/2018

Attn

Vehicle No: SGH 2857G
Vehicle Model: Toyota Vios
Accident on: 1/3/2018

Not Authorized
L1 Sur 87
Resurvey After Pamy 7 days

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Front bumper	238.49	25.00	<i>Pa</i> 178.87 ✓
1.00	Pc	Rear bumper	245.90	25.00	<i>Pa</i> 184.43 ✓
1.00	Pc	Rear bumper side holder RH	15.20	25.00	<i>Pa</i> 11.40 ✓
1.00	Pc	Rear end panel	720.10	25.00	<i>Pa</i> 540.08 ✓
1.00	Pc	Rear tail lamp RH	<i>my Di</i> 189.00	25.00	141.75 ✓
1.00	Pc	Rear tail lamp gasket RH	24.36	25.00	<i>Mc</i> 18.27 ✓
1.00	Pc	Rear tail lamp panel RH	91.84	25.00	<i>Pa</i> 68.88 ✓
1.00	Pc	Rear boot lid weatherstrip	<i>D. J. J. J.</i> 48.44	25.00	36.33 ✓
1.00	Pc	Rear boot lid lock	22.80	25.00	<i>Net</i> 17.10 ✓
Special nett item:					
1.00	Pc	Front number plate	35.00		<i>3</i> 35.00 ✓
1.00	Set	Rear reversing sensor with installation	200.00		<i>Net</i> 200.00 ✓
Labour & Misc:					
1.00		Towing fee			50.00 ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018694
Tan Kim Hai

Page 2 of 2
Your ref. TP-SJN 7535K Lonpac
Job No. 69287
Our ref. 18.03.02
Payment
Date 2/3/2018

Attn

Vehicle No SGH 2857G
Vehicle Model : Toyota Vios
Accident on ... 1/3/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To remove + repair exhaust pipe	100.00		100.00
1.00		To straighten rear body including cutting and welding, to knock dents on rear luggage panel and renew of parts	1,200.00		1,200.00
1.00		To spray paint	900.00		900.00

Sub-Total 3,682.11
GST 7.00% 257.75
Total S\$ 3,939.86

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."