

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5781K -**AAD1803-001***Not Authorized
11 Sep 860501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5781K - CANDY**VF1ABL15AUC280907****RENAULT****LATITUDE****28.02.2018****CHINA TAIPING**

		PART		LIST	
1	1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46	} X
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84	
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i> 44.99	
9	1	ROCKER PANEL OUTER RH	\$	<i>R</i> 987.49	} X
10	1	SILL PANEL OUTER RH	\$	<i>R</i> 3,663.62	
11	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
12	1	FENDER PANEL INNER TRIM REAR	\$	<i>Sn</i> 671.45	
13	1	WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
14	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
15	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
16	1	EXHAUST REAR	\$	<i>R</i> 7,489.05	
17	1	EXHAUST CAP REAR	\$	<i>R</i> 230.49	} X
18	1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66	
19	1	DOOR GUIDE REAR RH	\$	<i>Sn</i> 176.82	
20	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50	
21	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55	
22	1	DOOR CHECK REAR RH	\$	<i>Sn</i> 203.06	
23	1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75	
24	1	DOOR GRAB HANDLE REAR RH	\$	<i>Sn</i> 210.96	
25	1	DOOR HANDLE OUTER REAR RH	\$	<i>Sn</i> 126.49	} X
26	1	DOOR HANDLE CAP REAR RH	\$	<i>Sn</i> 35.52	
27	1	DOOR HANDLE SEAL REAR RH	\$	<i>Sn</i> 7.89	
28	1	DOOR HANDLE COVER REAR RH	\$	<i>Sn</i> 13.22	
29	1	DOOR HANDLE MODULE REAR RH	\$	<i>Sn</i> 133.60	
30	1	DOOR REGULATOR REAR RH	\$	<i>R</i> 1,135.10	
31	1	DOOR REGUALTOR MOTOR REAR RH	\$	<i>Sn</i> 893.75	
32	1	DOOR FINISHER REAR RH	\$	<i>Sn</i> 423.10	
33	1	DOOR WHEATHESTRIIP REAR RH	\$	<i>Sn</i> 410.66	} X
34	1	DOOR SEAL REAR RH	\$	<i>Sn</i> 162.02	

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-001

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5781K -

35	1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sn</i> 334.69 X
36	1	DOOR MOULDING REAR RH	\$	<i>Sn</i> 176.82 X
37	1	DOOR PANEL FRT RH	\$	<i>N</i> 2,844.66 X

TOTAL	\$	32,437.07
10%	\$	3,243.71
	\$	29,193.37

Special Nett

1	1SET	PARKING AID	\$	<i>Sn</i> 700.00	}	X
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i> 66.00		
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 33.00		
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 10.00		
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	<i>nn</i> 20.00		
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 22.00		
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 66.00		
8	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	}	X
9	1	TAILLAMP CLIP RH	\$	<i>nn</i> 5.00		
10	1SET	WHEELARCH CLIP RR RH	\$	<i>nn</i> 66.00		
11	2	REAR WINDSCREEN SELANT	\$	<i>nn</i> 80.00 <i>40sm</i>	}	—
12	1	WINDSCREEN MOULDING	\$	<i>nn</i> 100.00		
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>nn</i> 100.00 <i>30sm</i>		
14	1	CAP HUB RH RR	\$	<i>Sn</i> 35.00 X	}	X
15	1	RIM RH RR	\$	<i>Sn</i> 385.00 X		
16	1	TYRE RH RR	\$	<i>Sn</i> 330.00 X		
17	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i> 80.00 X	}	X
18	1	DOOR STICKER "Classic"	\$	<i>nn</i> 30.00 X		
19	1	DOOR STICKER "6555-3333"	\$	<i>nn</i> 80.00 <i>60sm</i>		

TOTAL	\$	2,225.82
TOTAL PARTS	\$	31,419.19

Putty And Spray Painting Of The Affected Portion.

\$ 4,500.00 *6601*

To reinstall rear bumper parking sensor.

\$ *nn* 170.00 X

To Rust-Proofing Of The Affected Areas.

\$ 170.00 *601*Panel Beating, Knocking And Straightening
The Necessary Portion, Remove And Renewal
Of Parts, Adjust And Realign The Same\$ 4,200.00 *8001*

TRANS-CAB AUTO SERVICES PTE LTD

AAD1803-001

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5781K -

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>nn</i> 170.00 X
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 X
Towing Fees	\$	<i>nn</i> 120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 <i>100</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 <i>120</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 <i>60</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00 X

TOTAL	\$	10,610.00
Over All Total	\$	42,029.19

(PARTS BY PARTS)

Repair Days

~~15 Days~~*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: