

(08/11/13) wef

REF:

ASS. REC. BY: *Marcus*

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Mme
d/s 3100 (Red 4438.70 : 58%)

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1) *2613 TYPIST*☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

TP

3100/-

150
50
50
50
80
380

RECEIVED 27 MAR 2018

Ref. No	: CS/TP/8004163/UT6n2	Res. Date:	6/3/18	Date Received:	
Veh. No	: SLM 581/H	SP:		WKSP:	Rhant
C/No	:				
Action/Instruction:					
1.File	2.Submit Photo?	YES	/ NO		
3.Indicate Res. Date On Photo Page?	YES	/ NO	Message:		
If No, due to	a) No authorisation	b) Days of repair			
others:					
Final Re-inspection or Progress Photos				Inspected By:	

MSR116028765 / SMART Automotive Services Pte Ltd - Woodlands
ENTRY DATE & TIME: 02/03/2018 15:50
SUBMITTED BY: Alex Lim Wei Siong

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy abilly.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 02/03/2018 15:50
Date Of Accident 01/03/2018 17:35
Exact Location Of Accident TAMPINES STREET 92
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM5811H
Insured/Policyholder
Name Of Registered Owner WONG HEE LAP
NRIC No S2701278G
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-97472826
Alternative Phone No OTHERS-97472826
Vehicle Particulars
Manufacturer MAZDA
Model MAZDA5 5-DOOR WAGON 2.0L SP,6EAT SUNROOF
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number DMPCSN1725601700
Cover Note Number
Driver
Name of Driver WONG HEE LAP
NRIC No S2701278G
Date Of Birth 01/03/1962
Occupation INDOOR
Date Of Driving Pass 10/10/1998
Driving Experience 19 YEARS AND 4 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97472826
Fax Number OTHERS-97472826
Contact Number NOEMAIL
Email Address

Address 647 WOODLANDS RING ROAD
02-72
Postcode 730647
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : UNKNOWN

GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of Intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

My car was stationary when suddenly car B which was behind me hit the rear of car.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SBF1388C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver MOHD AMIN BIN AB RAHMAN

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was stationary when suddenly car B which was behind me hit the rear of car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 2/3/18, 1030am

Driver's Signature

(If driver is not the policyholder)

Date & Time: 2/3/18, 1030am

Reporting Centre Personnel's Signature

Name:

NRIC/IN No.:

CIATRAAC SketchPlanForm_V3

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1278G
Vehicle Details	
Vehicle No.:	SLM5811H
Vehicle to be Exported:	No
Intended De-registration Date:	06 Mar 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	PE10437414
Chassis No.:	JM6CW1071G0125131
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$19,442.00
Original Registration Date:	31 Mar 2017
First Registration Date:	31 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$19,442.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Mar 2027
PARF Rebate Amount:	\$14,581.00
Intended COE Rebate Details	
COE Expiry Date:	30 Mar 2027
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$53,001.00
COE Rebate Amount:	\$48,042.00
Total Rebate Amount:	\$62,623.00

The information contained herein is correct as at 06 Mar 2018



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
(Unit C) #01-51/53/55 Singapore 417883
Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
Co. Reg. No.: 200704951N
GST Reg. No.: 200704951N

Not April
2/5 \$3100
4/5

S/LM S-811H

	Tailgate	R	1559.00	X
	Tailgate 'S' emblem	MR	42.50	/
	Tailgate 'moxda' emblem	MR	43.10	/
	Tailgate Skyactiv emblem	MR	76.10	/
	Tailgate weatherstrip	1W1	169.00	/
	Tail lamp old	Daye/cne	485.60	/
	Rear bumper	20/re	915.40	/
2pi	Rear bumper side retainers @ 45-30	MR	90.60	/
2pi	Rear bumper reflectors @ 50-40	MR	100.80	X
	Rear bumper reinforcement	R	148.00	X
	Rear bumper splash shield OS	1W1	82.50	/
1set	Rear bumper splash shield clips 25	MR	25.00	/
	Rear end panel	R	491.10	X
		(20%)	4228.70	1928.8

1set	S. Net f			
	Rear bumper reverse sensor	shut	280.00	200
	Rear bumper top chrome moulding	20/1W1	680.00	600
	Rear end panel sealant	MR	50.00	X

	To check wiring	80.00	20
	To dismantle & ref. x seat cushion upholstery	180.00	80
	To dismantle & replace reverse sensor	80.00	50
	To spray rust proofing	80.00	30
	labour for panel beating & replacing parts	800.00	600
	To putty & spray painting	1080.00	780
	TOTAL	7538.70	/

As a condition of the repair, the repairer must notify the Insurer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD		Ref : CS/TP18004163/Utbn2		
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883		Date : 28-03-2018		
ON BEHALF OF WONG HEE LAP		Code : TP149		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SLM 5811H	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		05/03/2018	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071G0125131	Colour	GREY	
Odometer	16716	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/03/2018	Inspection Date	05/03/2018	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 5811H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	TO REPAIR SEE LABOUR	1,559.00	-
1	TAILGATE "5" EMBLEM	NECESSARY	42.50	42.50
1	TAILGATE "MAZDA" EMBLEM	NECESSARY	43.10	43.10
1	TAILGATE SKYACTIV EMBLEM	NECESSARY	76.10	76.10
1	TAILGATE WEATHERSTRIP	TWISTED	169.00	169.00
1	TAILLAMP O/S	DAMAGED / CRACKED	485.60	485.60
1	REAR BUMPER	DENTED / DEFORMED	915.40	915.40
2	REAR BUMPER SIDE RETAINERS @\$45.30	NECESSARY	90.60	90.60
2	REAR BUMPER REFLECTORS @\$50.40	NOT NECESSARY	100.80	-
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	148.00	-
1	REAR BUMPER SPLASH SHIELD O/S	TORN	82.50	82.50
1	SET REAR BUMPER SPLASH SHIELD CLIPS O/S	NECESSARY	25.00	25.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	491.10	-
	LESS 20% DISCOUNT		-	-385.96
			4,228.70	1,543.84
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR BUMPER TOP CHROME MOULDING (SN)	DENTED / TWISTED	680.00	600.00
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			1,010.00	800.00
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	20.00
	TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTERY.		180.00	80.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF TAILGATE,REAR BUMPER REINFORCEMENT AND REAR END PANEL.		800.00	600.00
	TO PUTTY & SPRAY PAINTING.		1,080.00	780.00
			2,300.00	1,560.00

Report Ref No. CS/TP18004163/Utnb2



GRAND TOTAL		7,538.70	3,903.84
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS/TP18004163/Utn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.