



Vfix Auto Service Pte Ltd
60 Kaki Bukit Ave 6
Ark@KB Singapore 417892
Email: vfixauto@gmail.com
Tel: 64489268 Fax: 64452368

M/S AIG ASIA PACIFIC INS PTE LTD
CHARTIS BUILDING
78 SHENTON WAY #08-16
SINGAPORE 079120

ESTIMATE

DATE : 01/03/2018
ACCT DATE : 31/12/2017
REF NO. : TP20180437
POLICY NO :

Attention: Motor Claim Department

RE : VEHICLE NO. SLM2562X NISSAN PULSAR

DESCRIPTION	AMOUNT S\$
1 1 REAR FENDER LH	957.00
2 1 REAR BUMPER	688.60
3 2 REAR BUMPER RETAINER	98.00
4 1 SHOCK ABSORBER REAR LH	543.20
5 1 REAR WHEEL KNUCKLE	412.30
6 1 REAR WHEEL BEARING	202.00
	\$ 2,901.10
Less 30%	870.33
	\$ 2,030.77

Handwritten notes: 130300, 200000, MS44, 11, 11, 11, 16946, 1186.22

DESCRIPTION	AMOUNT S\$
<u>SPECIAL NETT ITEMS</u>	
1 8 REAR BUMPER CLIP	40.00
2 1 QUATOR GLASS MOULDING	89.00
3 1 QUATOR GLASS SEALANT	90.00
4 1 SPORT RIM 17"	550.00
	\$ 769.00

Handwritten notes: 5.00, 305.00, 350.00

LABOUR & MISCELLANEOUS:	AMOUNT S\$
1 To remove damaged body panels with all necessary components/attachments apply hot-works where necessary straighten panel repair/reshape dented panels in accordance with factory specifications, replace new parts refit align into position refit all necessary components/attachments	1,400.00
2 To spray paint replaced/repaired body panels inclusive of preparatory works and painting materials	1,200.00
3 To remove, refit rear quator glass and water test	150.00
4 To remove, replace shock absorber, knuckle, wheel bearing	250.00
5 To remove, refit roof lining, upholstery interior garnishes	150.00
	\$ 3,150.00
	\$ 5,949.77

Handwritten notes: 600, 600, 60, 60, 80, 3095.22

SINGAPORE DOLLARS : FIVE THOUSAND NINE HUNDRED FORTY NINE AND CENTS SEVENTY SEVEN ONLY

Vfix Auto Service Pte Ltd



LKK Auto Consultants hereby **GRAND TOTAL**
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes: Not Attached, 2450/-