

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

2-Mar-18

ESTIMATE REPAIR BILL FOR HYUNDAI I30(A) WAGON REGN NO: SHB 8008 X

1 pc	Emblem I30 ✓	\$	27.80
1 pc	Emblem CRDI ✓	\$	29.40
1 pc	Emblem Hyundai X	\$	29.40
1 pc	Rear bumper ✓	\$	811.11
1 pc	Rear bumper o/s reflector ✓	\$	107.50
1 pc	Rear bumper sponge X	\$	79.20
1 pc	Rear bumper reinforcement X	\$	815.64
1 pc	Rear bumper reinforcement centre X	\$	79.20
2 pcs	Rear bumper n/s & o/s side bracket @ \$52.20 X	\$	104.40

	\$	2,083.65
Less 20%	\$	416.73
	\$	1,666.92

S/NETT

1 set	Rear bumper clips X	\$	48.00
1 set	Reverse sensor ✓	\$	280.00
1 set	Tailgate sticker X	\$	100.00 50
	Sundry	\$	50.00 20
	To dismantle and replace reverse sensor and test system	\$	80.00 20
	To labour charge for dismantle and renew the accident damaged parts. Including to knock-out, straighten, repair, reshape of the end panel, bootlid, bootlid lower garnish, etc	\$	750.00 300
	To putty and spray painting on the rear bumper, tailgate lower garnish, tailgate, end panel X	\$	800.00 360
	To apply rustproofing on the repaired and replaced panels X	\$	150.00 X
Total		\$	3,924.92

(ALL THE REPAIR COSTS ARE SUBJECT TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify

ALL COSTS ARE SUBJECT TO GST

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Kalvin (LKK)
7/3/18 0945h
2 Days
PIP
Before Part p hd