

22/03/2001

ASS. REC. BY:

REF: CS/EGT/18004182/ Kpd3k

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Yee Pei

of EGT

Date/Time: 5/3/18 @ 9.04am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFB 6222E

Insured: SJU 7534B

at Workshop m/s Motor Image

Tel: 9299 2643

of 19 Lorong 8 Ton Puyoh

Policy No:

Claim No: DSMpc/1800395

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26/02/18

(Client's Record)

CA / REV / REP. / REV 24 HRS 1wk

6/3/18 @ Morning

H.O.D. Endorsement:

Date/Time: 9.25am @ 5/3/18

Person Contacted:

Sayed

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SFB6222F - CD3/AIG09023518/M xx D.O.A: 17/10/2009
	SJU 7534B - x
07/3/18 @ 4.14p	revised to Rohaini by email.
12/9/18 @ 5.02p	confirmed with Saye final fig \$10294.28, 12 days by email.
	CRD \$ 9516.52, 48%



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18004182/Kqd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 05-03-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 7534B	Veh. Inspected	SFB 6222E
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800395	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/03/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/02/2018	Inspection Date	
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 . SINGAPORE 319255		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Monday, 5 March 2018 9:04 AM
To: 'admin-d@lkkauto.com'
Subject: OI : SJU7534B / TP : SFB6222E/LKK / DOA : 26/02/2018 (DSMPC1800395)
Attachments: SJU7534B - SAS.pdf; 2ND VEH SFB6222E - SAS.pdf; 1ST VEH SJS2096S - SAS.pdf; 2ND VEH SFB6222E - ESTIMATE.pdf; 2ND VEH SFB6222E - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MOTOR IMAGE ENTERPRISES PTE LTD**,

ADDRESS : 19 LORONG 8 TOA PAYOH
SINGAPORE 319255

PERSON TO CONTACT : OLIVER ZUBIRI @ 9090 3323

ERGO OFFICER-IN-CHARGE : ROHAINI

Note: To survey on DIRECT SETTLEMENT basis. Please inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and TP's SAS (**note: reports not to be released to any Third Party**).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 12 September 2018 5:02 PM
To: Sayedinah; Kenneth Kong (LKKAuto)
Cc: Mohamed Isman; Daniel Jude; Kuan Wei Loong; SUR
Subject: RE: SFB6222E-AIG-TP(SJU7534B)ERGO-FINALIZED

Dear Saye,

WITHOUT PREJUDISE

Confirm final fig \$10,294.28 before GST and 12 repair days.

Kindly send the relevant documents to ERGO insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Thursday, 6 September 2018 1:08 PM
To: Sayedinah <sayedinah@motorimage.net>; Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Shiau Chan (LKKAuto) <siewsc@lkkauto.com>
Cc: Mohamed Isman <isman@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>
Subject: RE: SFB6222E-AIG-TP(SJU7534B)ERGO-FINALIZED

Dear Sayed,

Thanks for your email

Dear Shiau Chan,
CS/EG18004182/Kqd3

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sayedinah <sayedinah@motorimage.net>
Sent: Thursday, 6 September 2018 1:05 PM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>
Cc: Mohamed Isman <isman@motorimage.net>; Daniel Jude <danieljude@motorimage.net>; Kuan Wei Loong <weiloong@motorimage.net>; Denise Tay (LKKAuto) <denisetay@lkkauto.com>

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 7 March 2018 4:14 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'; assignments; Rohaini Bte Hussain
Cc: SUR
Subject: RE: SJU7534B / TP : SFB6222E/LKK / DOA : 26/02/2018 (DSMPC1800395)
Attachments: CSEGI18004182Kqd3.pdf

Dear Rohaini,

Enclosed herewith preliminary advice of SFB 6222E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Monday, 5 March 2018 9:36 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJU7534B / TP : SFB6222E/LKK / DOA : 26/02/2018 (DSMPC1800395)

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Monday, 5 March 2018 9:04 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : SJU7534B / TP : SFB6222E/LKK / DOA : 26/02/2018 (DSMPC1800395)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **MOTOR IMAGE ENTERPRISES PTE LTD**,

ADDRESS : 19 LORONG 8 TOA PAYOH
SINGAPORE 319255



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1800395

Date: 07th March 2018

Our Ref: CS/EG118004182/Kqd3

Without Prejudice

The Motor Claims Department
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SFB 6222E


We thank you for the instruction on 05/03/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/03/2018 at the premises of M/s MOTOR IMAGE and have the following to report:-

Workshop Estimate Amount	: S\$ <u>19,402.28</u>
Revised Estimate Amount	: S\$ <u>8,220.16</u>
"Check" Items Amount	: S\$ <u>3,894.44</u>
Market Value	: S\$ <u>-</u>
Salvage Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s & front portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 12 days.

We have NOT authorise repair.

Yours faithfully

KENNETH KONG
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/02/2018 17:56
Date Of Accident	26/02/2018 17:15
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT BEFORE EXIT TO BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFB6222E
Insured/Policyholder	
Name Of Registered Owner	KOH WENG CHEONG, JEFFREY
NRIC No	S1401016E
Email Address	JEFFREY_KON@ITE.EDU.SG
Mobile Phone No	(LOCAL) +65-96640316
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	SUBARU
Model	XV-1.6 I-S AWD CVT (A)
Exact Purpose for which vehicle was being used at time of accident	LEISURE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100507011-00000
Cover Note Number	

Driver

Name of Driver	KOH WENG CHEONG, JEFFREY
NRIC No	S1401016E
Date Of Birth	18/03/1960
Occupation	INDOOR
Date Of Driving Pass	02/06/1981
Driving Experience	36 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96640316
Fax Number	
Contact Number	OFFICE-NOPHONE
E Mail Address	JEFFREY_KON@ITE.EDU.SG

Address	1
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TO BE ATTACHED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFR9367S
Vehicle Make/Model/Colour	TOYOTA/PICNIC
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG SEE WEE
NRIC/Passport Number	S7705231C
Contact Number	90678699
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJU7534B
-----------------------------	----------

Vehicle Make/Model/Colour	MITSUBISHI/LANCER
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MICHELLE KIM
NRIC/Passport Number	S9019768A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I, driver of SFB6222E, was driving ^{along} PIE ^{towards} ~~the~~
 change before the exit to BKE.
 I applied brake when car A stopped suddenly.
 Car C then hit ~~me~~ from my car from the
 rear. The impact caused car B to ~~be~~
 surge forward which then hit car A.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

x 
 Policyholder's Signature
 Date & Time: 27 Feb 2018
 10:15 AM

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

GA88/17 Sketch Plan Form, V2

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0653/2018
DATE : 27-FEB-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : KOH WENG CHEONG, JEFFREY
ADDRESS : APT BLK 255 KIM KEAT AVENUE
#08-144
S(310255)
TELEPHONE NO : 96640316

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100507011-00000
VEHICLE NO : SFB6222E
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y483993
CHASSIS NO : JF1GP3KC5HG201994
MILEAGE : 1 KM
DATE IN : 27/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 26/02/2018

Print Date : 01/03/2018
Print Time : 14:08:29

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM ERGO LOC:PIE TOWARS CHANGI AIRPORT BEFORE EXIT TO BKE DATE:26/02/2018 TIME:1715H		
3	ZZ/002	REMOVE/REPLACE FRT BUMPER,HOOD,FRT RH FENDER, FRT PANEL	2240.00	✓
4	ZZ/003	RESPRAY FRT BUMPER,HOOD,FRT RH FENDER,FRT PANEL	1680.00	1260.00 ✓
5	ZZ/004	REMOVE/REPLACE RR BUMPER,RR PANEL,RR RH FENDER	1680.00	840.00 ✓
6	ZZ/005	RESPRAY RR BUMPER,RR PANEL,RR RH FENDER	1260.00	1120.00 ✓
7	ZZ/006	DISMENTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	900.00	X ✓
8	ZZ/007	REMOVE & REFIX EXHAUST	150.00	✓
9	ZZ/008	TRANSFER(RR TAILGATE)MECHANISM	150.00	X
10	ZZ/009	TO CONDUCT WATER SEPAGE TEST	100.00	50.00 ✓
11	ZZ/011	REMOVE & INSTALL(REAR)WINDSCREEN	300.00	X
12	ZZ/012	TO CONDUCT (REAR)LIGHTING TEST	50.00	30.00 ✓
13	ZZ/013	TO SUPPLY AND INSTALL REVERSE SENSOR-2EYES	300.00	✓
14	ZZ/014	SUNDRIES 100		
15	ZZ/015	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS	550.00	280.00 ✓
16	ZZ/016	TO REMOVE & REPIX FUEL TANK	200.00	✓
17	ZZ/017	TO SUPPLY AND INSTALL(REAR)TINTED FILM	145.00	? X
18	ZZ/018	REMOVE &REFIX AIRCON CONDENSER&RADIATOR TO FACILITATE REPAIR	220.00	X
19	ZZ/10	WHEEL ALIGNMENT	200.00	? ✓
TOTAL LABOUR CHARGES			10125.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
		NETT	LIST	S/NETT		
1 EXH PIPE ASSY R	608C/N 44200FJ110	R 684.00	X			
2 MUFFLER AY	(SUPP) 44300FJ040	R 576.00	X			
3 PNL SD OUT QTR RP5RH	NEED 909400005 51439FJ0429P	R 864.00				
4 FLOOR PAN R	CKD-XV 52129FJ0009P	R 540.00	X			
5 SKIRT COMPL R 5D	52401FJ0209P	SVC 244.80	7 X			
6 PANEL COMPL-RADIATOR UPP	53029FJ0109P	R 54.00	X			
7 STAY HOOD COMPL	53029FJ0209P	R 72.00	X			
8 PANEL COMPLETE-RADIATOR UPPER RH	53029FJ0309P	SVC 100.80	7 X			
9 PANEL COMPL-RADIATOR UPP LH	53029FJ0409P	SVC 64.80	7 X			
10 PANEL COMPLETE-RADIATOR SIDE,RIGHT	53029FJ0509P	R 64.80	X			
11 PANEL COMPL-RADIATOR SIDE LH	53029FJ0609P	SVC 64.80	7 X			
12 FRAME COMPL-RADIATOR LWR PANEL	53029FJ0709P	SVC 68.40	7 X			
13 HOOD COMPLETE-FRONT	57229FJ0009P	R 540.00	X			
14 BUMPER FACE REAR XV	57704FJ041	R / CM 594.00				
15 BUMPER FACE F XUV	57704FJ070	CM 414.00				
16 ENR ABSORB FOAM XU	57705FJ010	SVC 79.20	7 X			
17 BRKT CORNER F RH	57707FJ001	S 43.20	X			
18 BRKT FLH BUMP CORN	57707FJ011	43.20	7 X			
19 BRKT RRH BUMP CORN	57707FJ080	28.80	7 X		} SVC	
20 BRKT RLH BUMP CORN	57707FJ090	28.80	7 X			
21 BRKT BUMP FRH	57707FJ141	7.20	7 X			
22 BRKT SD F XUV LH	57707FJ151	7.20	7 X			
23 BRKT RRH BUMP	57707FJ160	14.40	7 X			
24 BRKT RLH BUMP	57707FJ170	14.40	7 X			
25 BRKT BUMP R LWR	57707FJ201	14.40	7 X			

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES				S/LIST REMARKS
		NETT	LIST	S/NETT		
26 BEAM COMPL R EU	57711FJ0239P	R 187.20	7 X			
27 BACK BEAM COMPL-F	57711FJ0519P	R 259.20	7 X			
28 COVER-REAR BUMPER	57731FG010I6	Sm 14.40	X			
29 COVER FOG F XUV LH	57731FJ430	Sm 65.60	X			
30 COVER HOOK F	57731FJ460	Sm 4.70	X			
31 PANEL COMPL R GAT	60809FJ0509P	R 756.00	7 X			
32 GLASS ASSY R G	63019FJ040	Sm 1020.70	X			
33 LAT & ACT AY RG	63032FG111	SVC 176.40	7 X			
34 STRIKER R/G	63264AG100	R 21.60	X			
35 WEATHER STRIP-REAR GATE	63516FJ000	Sm 85.00	X			
36 GLASS-REAR QUARTER,RH	65209FJ000	ncc 504.00	7 ✓			
37 DAM RUBBER	65245FJ000	ncc 10.80	7 ✓			
38 DAM RUBBER R WIND	65245SC000	nn 21.60	7 X			
39 SEAL R QTR WIND	65277FJ000	ncc 4.70	7 ✓			
40 LAMP ASSY HEAD EHL LH	84001FJ630	ncc 853.20	✓			
41 REFLEX AY RH	84281FG000	Sm 21.60	X			
42 RELFLEX ASSY LH	84281FG010	Sm 21.60	X			
43 FOG DRL ASSY F	CBU-1.6 84503FJ000	Sm 425.00	X			
44 LENS & BODY COMPL	84912FJ361	SVC 355.40	7 X			
45 LENS & BODY COMPL (NEED CORD-84981FJ150)	84912FJ370	SVC 355.40	7 X			
46 LENS & BODY-FOG LIGHT,REAR	84913FG420	Sm 102.00	X			
47 GARNISH ASSY-REAR GATE,B	91111FJ190WU	SVC 238.00	7 X			
48 GRILLE F BASE PT	91122FJ060	SVC 180.00	7 X			
49 GRILLE F MLD RING6KA	91122FJ070	SVC 223.20	7 X			

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SPB6222E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
50	GRILLE F MLD WING6KA	91122FJ090	SVC 147.60	7 X		
51	BRKT-GRILLE FOR 1.6XV (DIFF TO 2.0XV)	91165FJ000	SVC 28.80	7 X		
52	SEAL	91171FJ010	SVC 19.80	7 X		
53	ORNAMENT F SIX	93013FJ040	na 67.10	X		
54	LETTER MARK-REAR	93079FJ060	na 68.00	X		
55	LETTER MARK-REAR	93079FJ100	na 40.80	X		
56	TRIM PNL R SKIRT	94026FJ000VH	na 90.00	X		
SUB TOTAL			11596.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			2319.32	0.00	0.00	0.00
GRAND TOTAL			9277.28	0.00	0.00	0.00
OVERALL TOTAL			9277.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFB6222E

TOTAL LABOUR CHARGES 10125.00
TOTAL SPARE PARTS CHARGES 9277.28

GRAND TOTAL 19402.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

*Not Authored
I.B.1
Resurvey B4 party
12 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

19810.20



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel: (65) 6703 8101/8102
 Fax: (65) 6253 5535
www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: ERC

Survey Date: _____

SUPPLEMENTARY PARTS FOR VEHICLE REGISTRATION NO SFB6222E

Surveyor: KENNETH LICK

	<u>DESCRIPTION</u>	<u>PART NO</u>	<u>AMOUNT</u>
1	REAR RH MUDGUARD <i>CM</i>	59122FJ001	\$64.80 <i>(M)</i>
2	GRILLE AIR UPNT ASSEMBLY <i>Ad</i>	7651FG000	\$89.60 <i>(M)</i>
3			
4	* AUTO ATTACHED		123.52
5			
6	GLASS REAR QUARTER <i>M</i>	65209FJ000	\$504.00 <i>(M)</i>
7	DAM RUBBER <i>M</i>	65245FJ000	\$10.80 <i>(M)</i>
8	SEAL R QTR WIND <i>M</i>	65277FJ000	\$4.70 <i>(M)</i>
9			
10			
11			
12			
13			
14			
15			
16			
17			
18			
19			
20			
21			
22			
23			
24			
25			



Motor Image Enterprises Pte Ltd
 19 Lorong 8 Toa Payoh
 Singapore 319255
 Tel: (65) 6703 8101/8102
 Fax: (65) 6253 5535
www.motorimage.net
 Co Reg No: 198702032R

Insurance Co: _____

Survey Date: _____

SUPPLEMENTARY LABOUR FOR VEHICLE REGISTRATION NO

SFB 6 222 E

Surveyor: KENNETH LICK

LABOUR DESCRIPTION

AMOUNT

1 REMOVE / REFIX RH REAR QUARTER GLASS

\$110.00

2 SUPPLY / INSTALL RH REAR QUARTER GLASS TINTED FILM

\$145.00

3

4

5

6

7

8

9

10



11

12

MOTOR IMAGE ENTERPRISES PTE LTD
19, LORONG 8, TOA PAYOH, SINGAPORE 319255
MAIN LINE : (65) 6703 8333
FAX : (65) 6252 5655
SERVICE CENTRE TEL : 6703 8101/02
WEBSITE : www.motorimage.net

Work Order: R000492
 Name 2: KOH WENG CHEONG, JEFFREY
 Company: APT BLK 255 KIM KEAT AVENUE
 License: SFB6222E
 Year: 16
 Technician: WAIFOONG
 Odometer: 1
 Date: 2.4.18 13:42

SUBARU XV 2015 / 2017
4-Wheel Total Alignment



MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0653/2018
DATE : 27-FEB-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : KOH WENG CHEONG, JEFFREY
ADDRESS : APT BLK 255 KIM KEAT AVENUE
#08-144
S(310255)
TELEPHONE NO : 96640316

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100507011-00000
VEHICLE NO : SFB6222E
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6I-S AWD CVT
ENGINE NO : FB16Y483993
CHASSIS NO : JF1GP3KC5HG201994
MILEAGE : 1 KM
DATE IN : 27/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 26/02/2018

Print Date : 01/03/2018
Print Time : 14:08:29

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, JA PAYOH
 SINGAPORE 319255

20/3 (GIC)

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM ERGO LOC:PIE TOWARS CHANGI AIRPO RT BEFORE EXIT TO BKE DATE:26/02/2018 TIME:1715H		
3	ZZ/002	REMOVE/REPLACE FRT BUMPER,HOOD,FRT RH FENDER, FRT PANEL	2240.00	✓
4	ZZ/003	RESPRAY FRT BUMPER,HOOD,FRT RH FENDER,FRT PANEL	1680.00	1260 ✓
5	ZZ/004	REMOVE/REPLACE RR BUMPER,RR PANEL,RR RH FENDER	1680.00	840 ✓
6	ZZ/005	RESPRAY RR BUMPER,RR PANEL,RR RH FENDER	1260.00	1128 ✓
7	ZZ/006	DISMANTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	900.00	X ←
8	ZZ/007	REMOVE & REFIX EXHAUST	150.00	7 ←
9	ZZ/008	TRANSFER(RR TAILGATE)MECHANISM	150.00	X ←
10	ZZ/009	TO CONDUCT WATER SEPAGE TEST	100.00	50 ✓
11	ZZ/011	REMOVE & INSTALL(REAR)WINDSCREEN	300.00	X ←
12	ZZ/012	TO CONDUCT (REAR)LIGHTING TEST	50.00	30 ✓
13	ZZ/013	TO SUPPLY AND INSTALL REVERSE SENSOR-2EYES	300.00	✓
14	ZZ/014	SUNDRIES 100		
15	ZZ/015	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS	550.00	280 ✓
16	ZZ/016	TO REMOVE & REFIX FUEL TANK	200.00	✓
17	ZZ/017	TO SUPPLY AND INSTALL(REAR)TINTED FILM	145.00	7 ✓
18	ZZ/018	REMOVE &REFIX AIRCON CONDENSER&RADIATOR TO FACILITATE REPAIR	220.00	X ←
19	ZZ/10	WHEEL ALIGNMENT	200.00	7 ←
TOTAL LABOUR CHARGES			10125.00	

Labour

10:

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	EXH PIPE ASSY R	608C/N 44200FJ110	R 684.00	X		
2	MUFFLER AY	(SUPP) 44300FJ040	R 576.00	X		
3	PNL SD OUT QTR RP5RH	NEED 909400005 51439FJ0429P	Rm 864.00			
4	FLOOR PAN R	CKD-XV 52129FJ0009P	R 540.00	X		
5	SKIRT COMPL R SD	52401FJ0209P	Sm 244.80	?		
6	PANEL COMPL-RADIATOR UP	53029FJ0109P	R 54.00	X		
7	STAY HOOD COMPL	53029FJ0209P	R 72.00	X		
8	PANEL COMPLETE-RADIATOR UPPER RH	53029FJ0309P	Sm 100.80	?		
9	PANEL COMPL-RADIATOR UP LH	53029FJ0409P	Sm 64.80	?		
10	PANEL COMPLETE-RADIATOR SIDE,RIGHT	53029FJ0509P	R 64.80	X		
11	PANEL COMPL-RADIATOR SIDE LH	53029FJ0609P	Sm 64.80	?		
12	FRAME COMPL-RADIATOR LWR PANEL	53029FJ0709P	Sm 68.40	?		
13	HOOD COMPLETE-FRONT	57229FJ0009P	R 540.00	X		
14	BUMPER FACE REAR XV	57704FJ041	Rm / CM 594.00			
15	BUMPER FACE F XUV	57704FJ070	CM 414.00			
16	ENR ABSORB FOAM XU	57705FJ010	Sm 79.20	X		
17	BRKT CORNER F RH	57707FJ001	Sm 43.20	X		
18	BRKT FLH BUMP CORN	57707FJ011	Sm 43.20	?		
19	BRKT RRH BUMP CORN	57707FJ080	Sm 28.80	?		
20	BRKT RLH BUMP CORN	57707FJ090	Sm 28.80	?		
21	BRKT BUMP FRH	57707FJ141	Sm 7.20	?		
22	BRKT SD F XUV LH	57707FJ151	Sm 7.20	?		
23	BRKT RRH BUMP	57707FJ160	Sm 14.40	?		
24	BRKT RLH BUMP	57707FJ170	Sm 14.40	?		
25	BRKT BUMP R LWR	57707FJ201	Sm 14.40	?		

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SPB6222E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
26	BEAM COMPL R EU	57711FJ0239P	R	187.20	X	
27	BACK BEAM COMPL-F	57711FJ0519P	R	259.20	X	
28	COVER-REAR BUMPER	57731FG010I6	Sn	14.40	X	
29	COVER FOG F XUV LH	57731FJ430	Sn	65.60	X	
30	COVER HOOK F	57731FJ460	Sn	4.70	X	
31	PANEL COMPL R GAT	60809FJ0509P	R	756.00	X	
32	GLASS ASSY R G	63019FJ040	Sn	1020.70	X	
33	LAT & ACT AY RG	63032FG111	Sn	176.40	X	
34	STRIKER R/G	63264AG100	R	21.60	X	
35	WEATHER STRIP-REAR GATE	63516FJ000	Sn	85.00	X	
36	GLASS-REAR QUARTER,RH	65209FJ000	Sn	504.00	X	
37	DAM RUBBER	65245FJ000	Sn	10.80	X	
38	DAM RUBBER R WIND	65245SC000	Sn	21.60	X	
39	SEAL R QTR WIND	65277FJ000	Sn	4.70	X	
40	LAMP ASSY HEAD EHL <i>LT</i>	84001FJ630	<i>ngcm</i>	853.20	X	
41	REFLEX AY RH	84281FG000	Sn	21.60	X	
42	REFLEX ASSY LH	84281FG010	Sn	21.60	X	
43	FOG DRL ASSY F	CBU-1.6 84503FJ000	Sn	425.00	X	
44	LENS & BODY COMPL	84912FJ361	Sn	355.40	X	
45	LENS & BODY COMPL (NEED CORD-84981FJ150)	84912FJ370	Sn	355.40	X	
46	LENS & BODY-FOG LIGHT,REAR	84913FG420	Sn	102.00	X	
47	GARNISH ASSY-REAR GATE,B	91111FJ190WU	Sn	238.00	X	
48	GRILLE F BASE PT	91122FJ060	Sn	180.00	X	
49	GRILLE F MLD RING6KA	91122FJ070	Sn	223.20	X	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319295

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
50	GRILLE F MLD WING6KA	91122FJ090	147.60			
51	BRKT-GRILLE FOR 1.6XV (DIFF TO 2.0XV)	91165FJ000	28.80			
52	SEAL	91171FJ010	19.80			
53	ORNAMENT F SIX	93013FJ040	67.10			
54	LETTER MARK-REAR	93079FJ060	68.00			
55	LETTER MARK-REAR	93079FJ100	40.80			
56	TRIM PNL R SKIRT	94026FJ000VH	90.00			
SUB TOTAL			11596.60	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)			2319.32	0.00	0.00	0.00
GRAND TOTAL			9277.28	0.00	0.00	0.00
OVERALL TOTAL			9277.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFB6222E

TOTAL LABOUR CHARGES	10125.00
TOTAL SPARE PARTS CHARGES	9277.28
GRAND TOTAL	19402.28 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Not Authored
1.B.1
Presurvey B4 party

12 days

add 1 days. ←

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

FINALIZED : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0653/2018
DATE : 27-FEB-2018

ERGO INSURANCE PTE LTD
5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
S(038985)
TEL : 6829 9199/200
FAX : 6829 9248/49
MOTOR CLAIM DEPT

OWNER'S NAME : KOH WENG CHEONG, JEFFREY
ADDRESS : APT BLK 255 KIM KEAT AVENUE
#08-144
S(310255)
TELEPHONE NO : 96640316

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100507011-00000
VEHICLE NO : SFB6222E
MODEL CODE : GP3FKDC
MODEL/YEAR : XV 1.6L-S AWD CVT
ENGINE NO : FB16Y483993
CHASSIS NO : JF1GP3KC5HG201994
MILEAGE : 12014 KM
DATE IN : 27/02/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SAYEDINAH ALI**
ACCIDENT DATE : 26/02/2018

Print Date : 07/08/2018
Print Time : 13:46:51

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM ERGO LOC:PIE TOWARS CHANGI AIRPORT BEFORE EXIT TO BKE DATE:26/02/2018 TIME:1715H		
3	ZZ/002	REMOVE/REPLACE FRT BUMPER,HOOD,FRT RH FENDER, FRT PANEL	2240.00	2240.00
4	ZZ/003	RESPRAY FRT BUMPER,HOOD,FRT RH FENDER,FRT PANEL	1680.00	1260.00
5	ZZ/004	REMOVE/REPLACE RR BUMPER,RR PANEL,RR RH FENDER	1680.00	840.00
6	ZZ/005	RESPRAY RR BUMPER,RR PANEL,RR RH FENDER	1260.00	840.00
7	ZZ/006	DISMANTLE&REFIX UNDERCARRIAGE(REAR)TO FACILITATE REPAIR	900.00	900.00
8	ZZ/007	REMOVE & REFLX EXHAUST	150.00	150.00
9	ZZ/008	TRANSFER(RR TAILGATE)MECHANISM	150.00	.00
10	ZZ/009	TO CONDUCT WATER SEPAGE TEST	100.00	50.00
11	ZZ/011	REMOVE & INSTALL(REAR)WINDSCREEN	300.00	.00
12	ZZ/012	TO CONDUCT (REAR)LIGHTING TEST	50.00	30.00
13	ZZ/013	TO SUPPLY AND INSTALL REVERSE SENSOR-2EYES	300.00	300.00
14	ZZ/014	SUNDRIES 100		
15	ZZ/015	REMOVE&REFIX CARPET,SEATS TO FACILITATE REPAIRS	550.00	280.00
16	ZZ/016	TO REMOVE & REFLX FUEL TANK	200.00	200.00
17	ZZ/017	TO SUPPLY AND INSTALL(REAR)TINTED FILM	145.00	.00
18	ZZ/018	REMOVE &REFIX AIRCON CONDENSER&RADIATOR TO FACILITATE REPAIR	220.00	.00
19	ZZ/021	REMOVE/REPLACE REAR RH QUARTER GLASS (SUPP)	180.00	180.00
20	ZZ/022	SUPPLY & INSTALL RH QUARTER GLASS TINTED FILM (SUPP)	145.00	145.00
21	ZZ/10	WHEEL ALIGNMENT	200.00	200.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
		TOTAL LABOUR CHARGES	10450.00	7615.00

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	EXH PIPE ASSY R	608C/N 44200FJ110	684.00			X
2	MUFFLER AY	(SUPP) 44300FJ040	576.00			X
3	PNL SD OUT QTR RP5RH	NEED 909400005 51439FJ0429P	864.00			OK
4	FLOOR PAN R	CKD-XV 52129FJ0009P	540.00			X
5	SKIRT COMPL R 5D	52401FJ0209P	244.80			X
6	PANEL COMPL-RADIATOR UPP	53029FJ0109P	54.00			X
7	STAY HOOD COMPL	53029FJ0209P	72.00			X
8	PANEL COMPLETE-RADIATOR UPPER RH	53029FJ0309P	100.80			X
9	PANEL COMPL-RADIATOR UPP LH	53029FJ0409P	64.80			X
10	PANEL COMPLETE-RADIATOR SIDE,RIGHT	53029FJ0509P	64.80			X
11	PANEL COMPL-RADIATOR SIDE LH	53029FJ0609P	64.80			X
12	FRAME COMPL-RADIATOR LWR PANEL	53029FJ0709P	68.40			X
13	HOOD COMPLETE-FRONT	57229FJ0009P	540.00			X
14	BUMPER FACE REAR XV	57704FJ041	594.00			OK
15	BUMPER FACE F XUV	57704FJ070	414.00			OK
16	ENR ABSORB FOAM XU	57705FJ010	79.20			X
17	BRKT CORNER F RH	57707FJ001	43.20			X
18	BRKT FLH BUMP CORN	57707FJ011	43.20			X
19	BRKT RRH BUMP CORN	57707FJ080	28.80			X
20	BRKT RLH BUMP CORN	57707FJ090	28.80			X
21	BRKT BUMP FRH	57707FJ141	7.20			X
22	BRKT SD F XUV LH	57707FJ151	7.20			X
23	BRKT RRH BUMP	57707FJ160	14.40			X
24	BRKT RLH BUMP	57707FJ170	14.40			X
25	BRKT BUMP R LWR	57707FJ201	14.40			X

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
26 BEAM COMPL R EU	57711FJ0239P	187.20			X
27 BACK BEAM COMPL-F	57711FJ0519P	259.20			X
28 COVER-REAR BUMPER	57731FG010I6	14.40			X
29 CVR RRH BUMP (SUPP)	57731FJ080	28.80			X
30 COVER FOG F XUV LH	57731FJ430	65.60			X
31 COVER HOOK F	57731FJ460	4.70			X
32 MUDGUARD-REAR RH	59122FJ001	64.80			<i>CM</i> OK
33 MUDGUARD-REAR RH	59122FJ001	64.80			X
34 PANEL COMPL R GAT	60809FJ0509P	756.00			X
35 GLASS ASSY R G	63019FJ040	1020.70			X
36 LAT & ACT AY RG	63032FG111	176.40			X
37 STRIKER R/G	63264AG100	21.60			X
38 WEATHER STRIP-REAR GATE	63516FJ000	85.00			X
39 GLASS-REAR QUARTER,RH	65209FJ000	504.00			<i>Me</i> OK
40 GLASS-REAR QUARTER,RH	65209FJ000	504.00			X
41 DAM RUBBER	65245FJ000	10.80			<i>Me</i> OK
42 DAM RUBBER	65245FJ000	10.80			X
43 DAM RUBBER R WIND	65245SC000	21.60			X
44 SEAL R QTR WIND	65277FJ000	4.70			<i>Me</i> OK
45 SEAL R QTR WIND	65277FJ000	4.70			X
46 GRILL AIR VENT	72651FG000	39.60			X
47 GRILL AIR VENTLTN	72651FG001	39.60			OK
48 LAMP ASSY HEAD EHL	84001FJ630	853.20			OK
49 REFLEX AY RH	84281FG000	21.60			X

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFB6222E

DAMAGED PARTS & PRICES

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
50 RELFLEX ASSY LH	84281FG010	21.60			X
51 FOG DRL ASSY F	CBU-1.6 84503FJ000	425.00			X
52 LENS & BODY COMPL	84912FJ361	355.40			X
53 LENS & BODY COMPL (NEED CORD-84981FJ150)	84912FJ370	355.40			X
54 LENS & BODY-FOG LIGHT,REAR	84913FG420	102.00			X
55 CLIP LAMP SD	909150032	2.20			X
56 GROMMET	909220011	2.20			X
57 GROMMET	909220013	0.90			X
58 GARNISH ASSY-REAR GATE,B	91111FJ190WU	238.00			X
59 GRILLE F BASE PT	91122FJ060	180.00			X
60 GRILLE F MLD RING6KA	91122FJ070	223.20			X
61 GRILLE F MLD WING6KA	91122FJ090	147.60			X
62 BRKT-GRILLE FOR 1.6XV (DIFF TO 2.0XV)	91165FJ000	28.80			X
63 SEAL	91171FJ010	19.80			X
64 ORNAMENT F SIX	93013FJ040	67.10			X
65 LETTER MARK-REAR	93079FJ060	68.00			X
66 LETTER MARK-REAR	93079FJ100	40.80			X
67 TRIM PNL R SKIRT	94026FJ000VH	90.00			X
68 SCREW GROMMET	96056FA010	3.20			X
SUB TOTAL		3349.10	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		669.82	0.00	0.00	0.00
GRAND TOTAL		2679.28	0.00	0.00	0.00
OVERALL TOTAL		2679.28			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SFB6222E

NETT ITEM	3349.10
LESS 20 %	-669.82
NETT AMOUNT	2679.28

LIST ITEM	0.00
LESS 50 %	0.00
LIST AMOUNT	0.00

SPECIAL NETT AMOUNT	0.00
---------------------	------

S/LIST ITEM	0.00
LESS 30 %	0.00
S/LIST AMOUNT	0.00

TOTAL LABOUR CHARGES	7615.00
TOTAL SPARE PARTS CHARGES	2679.28

TOTAL CHARGES	10294.28
ADD 7 % GST	720.60

GRAND TOTAL	11014.88
-------------	----------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ERGO INSURANCE PTE LTD		Ref : CS/EGI18004182/Kqd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985		Date : 18-10-2018	
		Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJU 7534B	Veh. Inspected	SFB 6222E
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800395	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model	SUBARU XV (A)	c.c	1600
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JF1GP3KC5HG201994	Colour	METALLIC DARK GREY
Odometer	12002	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R17	YOKOHAMA	8 mm
L/H Front Tyre	225/55 R17	YOKOHAMA	8 mm
R/H Rear Tyre	225/55 R17	YOKOHAMA	8 mm
L/H Rear Tyre	225/55 R17	YOKOHAMA	8 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	26/02/2018	Inspection Date	06/03/2018
Survey held at	MOTOR IMAGE ENTERPRISES PTE LTD 19 TOA PAYOH LORONG 8 SINGAPORE 319255		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 6222E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	EXH PIPE ASSY R (N)	TO REPAIR SEE LABOUR	684.00	-
1	MUFFLER AY (N)	TO REPAIR SEE LABOUR	576.00	-
1	PNL SD OUT QTR RP5RH (N)	BUCKLED	864.00	864.00
1	FLOOR PAN R (N)	TO REPAIR SEE LABOUR	540.00	-
1	SKIRT COMPL R 5D (N)	SERVICEABLE	244.80	-
1	PANEL COMPL-RADIATOR UPP (N)	TO REPAIR SEE LABOUR	54.00	-
1	STAY HOOD COMPL (N)	TO REPAIR SEE LABOUR	72.00	-
1	PANEL COMPLETE-RADIATOR UPPER RH (N)	SERVICEABLE	100.80	-
1	PANEL COMPL-RADIATOR UPP LH (N)	SERVICEABLE	64.80	-
1	PANEL COMPLETE-RADIATOR SIDE, RIGHT (N)	TO REPAIR SEE LABOUR	64.80	-
1	PANEL COMPL-RADIATOR SIDE LH (N)	SERVICEABLE	64.80	-
1	FRAME COMPL-RADIATOR LWR PANEL (N)	SERVICEABLE	68.40	-
1	HOOD COMPLETE-FRONT (N)	TO REPAIR SEE LABOUR	540.00	-
1	BUMPER FACE REAR XV (N)	BENT / CRACKED	594.00	594.00
1	BUMPER FACE F XUV (N)	CRACKED	414.00	414.00
1	ENR ABSORB FOAM XU (N)	SERVICEABLE	79.20	-
1	BRKT CORNER F RH (N)	SERVICEABLE	43.20	-
1	BRKT FLH BUMP CORN (N)	SERVICEABLE	43.20	-
1	BRKT RRH BUMP CORN (N)	SERVICEABLE	28.80	-
1	BRKT RLH BUMP CORN (N)	SERVICEABLE	28.80	-
1	BRKT BUMP FRH (N)	SERVICEABLE	7.20	-
1	BRKT SD F XUV LH (N)	SERVICEABLE	7.20	-
1	BRKT RRH PUMP (N)	SERVICEABLE	14.40	-
1	BRKT RLH BUMP (N)	SERVICEABLE	14.40	-
1	BRKT PUMP R LWR (N)	SERVICEABLE	14.40	-
1	BEAM COMPL R EU (N)	TO REPAIR SEE LABOUR	187.20	-

Report Ref No. CS/EGI18004182/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BACK BEAM COMPL-F (N)	TO REPAIR SEE LABOUR	259.20	-
1	COVER-REAR BUMPER (N)	SERVICEABLE	14.40	-
1	COVER FOG F XUV LH (N)	SERVICEABLE	65.60	-
1	COVER HOOK F (N)	SERVICEABLE	4.70	-
1	PANEL COMPL R GAT (N)	TO REPAIR SEE LABOUR	756.00	-
1	GLASS ASSY R G (N)	SERVICEABLE	1,020.70	-
1	LAT & ACT AY RG (N)	SERVICEABLE	176.40	-
1	STRIKER R/G (N)	TO REPAIR SEE LABOUR	21.60	-
1	WEATHER STRIP-REAR GATE (N)	SERVICEABLE	85.00	-
1	GLASS-REAR QUARTER, RH (N)	NECESSARY	504.00	504.00
1	DAM RUBBER (N)	NECESSARY	10.80	10.80
1	DAM RUBBER R WIND (N)	NOT NECESSARY	21.60	-
1	SEAL R QTR WIND (N)	NECESSARY	4.70	4.70
1	LAMP ASSY HEAD EHL LH (N)	MTG CRACKED	853.20	853.20
1	REFLEX AY RH (N)	SERVICEABLE	21.60	-
1	RELFLX ASSY LH (N)	SERVICEABLE	21.60	-
1	FOG DRL ASSY F (N)	SERVICEABLE	425.00	-
1	LENS & BODY COMPL (N)	SERVICEABLE	355.40	-
1	LENS & BODY COMPL (N)	SERVICEABLE	355.40	-
1	LENS & BODY-FOG LIGHT, REAR (N)	SERVICEABLE	102.00	-
1	GARNISH ASSY-REAR GATE, B (N)	SERVICEABLE	238.00	-
1	GRILLE F BASE PT (N)	SERVICEABLE	180.00	-
1	GRILLE F MLD RING6KA (N)	SERVICEABLE	223.20	-
1	GRILLE F MLD WING6KA (N)	SERVICEABLE	147.60	-
1	BRKT-GRILLE (N)	SERVICEABLE	28.80	-
1	SEAL (N)	SERVICEABLE	19.80	-
1	ORNAMENT F SIX (N)	NOT NECESSARY	67.10	-
1	LETTER MARK-REAR (N)	NOT NECESSARY	68.00	-
1	LETTER MARK-REAR (N)	NOT NECESSARY	40.80	-
1	TRIM PNL R SKIRT (N)	SERVICEABLE	90.00	-
1	REAR RH MUDGUARD (N) (ADDITIONAL)	CRACKED	64.80	64.80

Report Ref No. CS/EGI18004182/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GRILLE AIR VENT ASSEMBLY (N) (ADDITIONAL)	DENTED	39.60	39.60
	LESS 20% DISCOUNT		-2,340.20	-669.82
			9,360.80	2,679.28
	<u>SPECIAL NETT ITEMS</u>			
1	REVERSE SENSOR - 2EYES (SN)	DENTED	300.00	300.00
			300.00	300.00
	<u>LABOUR</u>			
	REMOVE / REPLACE FRT BUMPER, HOOD, FRT RH FENDER, FRT PANEL. INCLUSIVE OF THE REPAIR OF EXH PIPE ASSY R, MUFFLER AY, FLOOR PAN R, PANEL COMPL-RADIATOR UPP, STAY HOOD COMPL, PANEL COMPLETE-RADIATOR SIDE, RIGHT, HOOD COMPLETE-FRONT, BEAM COMPL R EU, BACK BEAM COMPL-F, PANEL COMPL R GAT AND STRIKER R/G.		2,240.00	2,240.00
	RESPRAY FRT BUMPER, HOOD, FRT RH FENDER, FRT PANEL.		1,680.00	1,260.00
	REMOVE / REPLACE RR BUMPER, RR PANEL, RR RH FENDER.		1,680.00	840.00
	RESPRAY RR BUMPER, RR PANEL, RR RH FENDER.		1,260.00	840.00
	DISMANTLE & REFIX UNDERCARRIAGE (REAR) TO FACILITATE REPAIR.		900.00	900.00
	REMOVE & REFIX EXHAUST.		150.00	150.00
	TRANSFER (RR TAILGATE) MECHANISM.	NOT NECESSARY	150.00	-
	TO CONDUCT WATER SEEPAGE TEST.		100.00	50.00
	REMOVE & INSTALL (REAR) WINDSCREEN.	NOT NECESSARY	300.00	-
	TO CONDUCT (REAR) LIGHTING TEST.		50.00	30.00
	REMOVE & REFIX CARPET, SEATS TO FACILITATE REPAIRS.		550.00	280.00
	TO REMOVE & REFIX FUEL TANK.		200.00	200.00
	TO SUPPLY AND INSTALL (REAR) TINTED FILM.	NOT NECESSARY	145.00	-
	REMOVE & REFIX AIRCON CONDENSER & RADIATOR TO FACILITATE REPAIR.	NOT NECESSARY	220.00	-
	WHEEL ALIGNMENT.		200.00	200.00
	REMOVE / REPLACE REAR RH QUARTER GLASS. (ADDITIONAL)		180.00	180.00

Report Ref No. CS/EG18004182/Kqd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY & INSTALL RH QUARTER GLASS TINTED FILM. (ADDITIONAL)		145.00	145.00
			10,150.00	7,315.00
GRAND TOTAL			19,810.80	10,294.28
RECOMMENDED COST OF REPAIRS				10,294.28

Report Ref No. CS/EG118004182/Kqd3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.