

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541
Tel : 82990599 Fax : 64816131
Email : lhcar@hotmail.sg

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541

VEHICLE NO. SLS4207C
CHASSIS NO. ZYX102066428
MAKE. : TOYOTA C-HR
YEAR. : 2017

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

ESTIMATE COST OF REPAIR

1	Front fender n/s	<i>Pr</i> \$819.30	\$ 819.30 ✓
1	Front fender emblem n/s	<i>Pr</i> \$57.80	\$ 57.80 ✓
1	Front fender lower shield n/s	<i>Pr</i> \$272.60	\$ 272.60 X
6	Front fender lower shield clip n/s	<i>Pr</i> \$12.90	\$ 77.40 X
3	Front fender rear protector clip n/s	<i>Pr</i> \$12.90	\$ 38.70 1
1	Front wheelarch garnish n/s	<i>Pr</i> \$173.00	\$ 173.00 2
8	Front wheelarch garnish clip n/s	<i>Pr</i> \$12.90	\$ 103.20 ✓
1	Front bumper retainer n/s	<i>Pr</i> \$116.30	\$ 116.30 X

TOTAL : \$ 1,658.30

-25% \$ 414.58

\$ 1,243.73

LABOUR

To renew & align above mentioned damaged parts	\$ 450.00 <i>2501</i>
To putty and spray paint	\$ 450.00 <i>2201</i>
To check wirings and focus headlamp	\$ 150.00 <i>151</i>
To carry out antirust treatment on affected panels	\$ 100.00 <i>301</i>
To apply underseal on the affected areas	<i>Pr</i> \$ 80.00 X

GRAND TOTAL : \$ 2,473.73

Not Authorised

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey 84 parts

Kennerly
0: 62563561

2 days

LIAN HER MOTORS

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541
Tel : 82990599 Fax : 64816131
Email : lhcar@hotmail.sg

H.L. CAR RENTAL PTE LTD

BLK 5038 ANG MO KIO IND. PARK 2 #01-405
SINGAPORE 569541

VEHICLE NO. SLS4207C
CHASSIS NO. ZYX102066428
MAKE. : TOYOTA C-HR
YEAR. : 2017

QTY	Description	Unit Price	Amount
-----	-------------	------------	--------

ESTIMATE COST OF REPAIR (SUPPLEMENTARY)

1	LH FRONT DOOR SIDE MIRROR <i>P?</i>	\$1,650.00	\$ 1,650.00
---	-------------------------------------	------------	-------------

TOTAL : \$ 1,650.00
-25% \$ 412.50
\$ 1,237.50

LABOUR

To putty and spray paint	\$ 150.00
To carry out antirust treatment on affected panels	\$ 100.00

GRAND TOTAL : \$ 1,487.50