

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeilkkauto.com | fax: 6741-4108

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Friday, 9 March 2018 5:22 PM

To: Shu Pei (LKKAuto) <shupeilkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Shu Pei,

Attach picture where the Ngee Ann Tower "B" STOP lane is.

This scenario is just like entering a single lane roundabout .

Audi was entering single lane roundabout which was driving toward the left side of the Maserati, in other word the Maserati has the right way so the left car has to give way to the right that why there is a STOP line between Tower B and Taka mall.

Base on the attach 2nd picture clearly show that the Audi was driving toward the Maserati instead of giving way or what the Audi driver reported.

If base on the Audi driver's report it should the Maserati hitting again the Audi's rim instead.

Moreover this is Audi RS6 with 560HP is a very fast car.

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Thursday, 8 March, 2018 7:13 PM

To: 'Shu Pei (LKKAuto)'

Cc: Admin A

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Thank you Shu Pei,

In fact there is a STOP sign/ line between Tower B driving and taxi stand lobby. The stop sign is to prevent accident from cars turning into taxi stand lobby.

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Thursday, 8 March, 2018 4:36 PM

To: Sam Tan

Cc: Admin A

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Dear Sam,

Please refer to the enclosed.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Thursday, 8 March 2018 3:38 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Thank you Veron,

I need to know is the liability clear for my client to claim again the 3rd party ?

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Thursday, 8 March, 2018 3:15 PM

To: CS A Team; Admin A; Sam Tan

Cc: SUR

Subject: FW: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Dear Bevan,

Please assist

CC4/ASM18004189/T1mb3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Thursday, 8 March 2018 2:48 PM

To: SUR <sur@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Taufikh ,

Who is the OIC for this case ?

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Wednesday, 7 March, 2018 5:14 PM

To: 'SUR'; 'Taufikh (LKK Auto)'

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Taufikh,

Attach pictures of the leaking power steering .

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Wednesday, 7 March, 2018 4:28 PM

To: 'SUR'; 'Taufikh (LKK Auto)'

Subject: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Tauffikh,

Attach pictures & accident report from the Maserati owner.

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

Bevan Lim (LKK Auto)

To: Sam Tan
Cc: Vic (LKKAuto)
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

WITHOUT PREJUDICE

Dear Sam,

Your client reported that our insured cut into his lane and collided with your client vehicle.

Our insured Driver reported she was moving straight and when you client turn into her lane and collision happen.

Based on both party it a conflicting version and both parties are unable to provide any evidence to support their statement.

We have instruction from our principal without admission of liability to settle your client's claim at 50%.

Kindly revert acceptance.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."


Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Sam Tan [mailto:samtan@hongseh.com.sg]
Sent: Tuesday, 27 March 2018 10:45 AM
To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>
Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Bevan,

Any news ?

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Bevan Lim (LKK Auto) [<mailto:bevanlim@lkkauto.com>]
Sent: Wednesday, 21 March, 2018 6:09 PM
To: Sam Tan
Cc: Vic (LKKAuto)
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11;45 hour at Shopping Tower of Ngee Ann City

WITHOUT PREJUDICE

Dear Sam,

We have managed to contacted our insured today and she strongly disputed the claim.

We seek further instruction from our principal and revert soonest.

Thank you

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]
Sent: Wednesday, 21 March 2018 4:32 PM

To: Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11;45 hour at Shopping Tower of Ngee Ann City

Hi Bevan,

Please advise .

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Tuesday, 20 March, 2018 3:44 PM

To: 'Bevan Lim (LKK Auto)'

Cc: 'Vic (LKKAuto)'; 'Admin A'

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11;45 hour at Shopping Tower of Ngee Ann City

Hi Bevan,

Any update ?

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Monday, 12 March, 2018 2:06 PM
To: 'Bevan Lim (LKK Auto)'
Cc: Vic (LKKAuto); Admin A
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Thank you Bevan,

The car is seating in the workshop, please let me as soon as possible .

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Bevan Lim (LKK Auto) [<mailto:bevanlim@lkkauto.com>]
Sent: Monday, 12 March, 2018 2:03 PM
To: Sam Tan
Cc: Vic (LKKAuto); Admin A
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

WITHOUT PREJUDICE

Hi Sam,

I refer to your email below and content noted.

Currently we are unable to contact Our insured as she is away for oversea and will be back only next week. In the meanwhile we are also seeking for further instruction from our principal.

We will revert back soonest once we have any reply from our principal.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Bevan Lim | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: BevanLim@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Friday, 9 March 2018 6:10 PM

To: Shu Pei (LKKAuto); Bevan Lim (LKK Auto)

Cc: Admin A

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Guys ,

Kindly let me as soon as possible car is seating in the workshop .

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Friday, 9 March, 2018 5:57 PM

To: Sam Tan; Bevan Lim (LKK Auto)

Cc: Admin A

Subject: FW: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Dear Sam,

Thank you for your email.

Our respective case handler will look into the matter and revert to you in due course.

Dear Bevan,

For your information and necessary action please.

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeilkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Friday, 9 March 2018 5:22 PM

To: Shu Pei (LKKAuto) <shupeilkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Shu Pei,

Attach picture where the Ngee Ann Tower "B" STOP lane is.

This scenario is just like entering a single lane roundabout .

Audi was entering single lane roundabout which was driving toward the left side of the Maserati, in other word the Maserati has the right way so the left car has to give way to the right that why there is a STOP line between Tower B and Taka mall.

Base on the attach 2nd picture clearly show that the Audi was driving toward the Maserati instead of giving way or what the Audi driver reported.

If base on the Audi driver's report it should the Maserati hitting again the Audi's rim instead.

Moreover this is Audi RS6 with 560HP is a very fast car.

Best regards.

Sam Tan

Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg

From: Sam Tan

Sent: Thursday, 8 March, 2018 7:13 PM

To: 'Shu Pei (LKKAuto)'

Cc: Admin A

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Thank you Shu Pei,

In fact there is a STOP sign/ line between Tower B driving and taxi stand lobby. The stop sign is to prevent accident from cars turning into taxi stand lobby.

Best regards,
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]

Sent: Thursday, 8 March, 2018 4:36 PM

To: Sam Tan

Cc: Admin A

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Dear Sam,

Please refer to the enclosed.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Thursday, 8 March 2018 3:38 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Thank you Veron,

I need to know is the liability clear for my client to claim again the 3rd party ?

Best regards,
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Thursday, 8 March, 2018 3:15 PM

To: CS A Team; Admin A; Sam Tan

Cc: SUR

Subject: FW: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Dear Bevan,

Please assist

CC4/ASM18004189/T1mb3

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sam Tan [<mailto:samtan@hongseh.com.sg>]

Sent: Thursday, 8 March 2018 2:48 PM

To: SUR <sur@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11:45 hour at Shopping Tower of Ngee Ann City

Hi Taufikh ,

Who is the OIC for this case ?

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Wednesday, 7 March, 2018 5:14 PM
To: 'SUR'; 'Taufikh (LKK Auto)'
Subject: RE: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11;45 hour at Shopping Tower of Ngee Ann City

Hi Taufikh,

Attach pictures of the leaking power steering .

Best regards.
Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707
Tel: +65 6266 1555 Fax: +65 6265 9595
DID: +65 6316 5916
HP: +65 96302180
Email: samtan@hongseh.com.sg

From: Sam Tan
Sent: Wednesday, 7 March, 2018 4:28 PM
To: 'SUR'; 'Taufikh (LKK Auto)'
Subject: Accident between reg SKB4008L and SKL9923J on 21st Feb 2018 at 11;45 hour at Shopping Tower of Ngee Ann City

Hi Tauffikh,

Attach pictures & accident report from the Maserati owner.

Best regards.

Sam Tan
Service Advisor



Hong Seh Motors Pte Ltd

10 Fourth Lok Yang Road Singapore 629707

Tel: +65 6266 1555 Fax: +65 6265 9595

DID: +65 6316 5916

HP: +65 96302180

Email: samtan@hongseh.com.sg



<Submit wp Report> S8M009BK

Type

🔔 Question

Message

Hi, we were informed by third party repairer that their client had withdrawn the claim and they have closed file. In view of this, we will proceed to close this outstanding claim file and submit our survey report to your good-office. Thank you. Hsiao Tong - 20 Aug 2019

Reply



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

22 MARCH 2018

GOH AH HENG
47 RIDOUT ROAD
SINGAPORE 248445

Dear Sir/Madam,

OUR REF : CC4/ASM18004189/T1mb3
YOUR REF : SKL 9923J
ACCIDENT INVOLVING SKL 9923J AND SKB 4008L ALONG/AT ENTRANCE TO
NGEE ANN CITY ON 21.02.2018

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s Hong Seh Motors Pte Ltd, acting on behalf of the owner of SKB 4008L against your motor insurance policy.

Based on the accident report and accident scenario and pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant. Unless proven otherwise.

You are aware that your No-Claim Discount (NCD – if applicable) will be withheld for the time being pending for final allocation of liability in settlement by our principal.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter.

Your full co-operation in the handling of the claim is required and kindly submit the following to bevanlim@lkkauto.com within 7 days from the date of this letter **if not provided at AXA's reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6749 4274 or email us at bevanlim@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

Bevan Lim
Case Handler
DID: 6749 4274
FAX: 6741 4108
Email: bevanlim@lkkauto.com

c.c. AXA Insurance Pte Ltd (AXA)
(Motor Claims Dept)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM18004189/T1pb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: CYNTHIA LOH		Date : 23-08-2019	
		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 9923J	Veh. Inspected	SKB 4008L
Policy No.	CN865198	Coverage (\$)	0.00
Claim No.	S8M009BK	Excess (\$)	0.00
Assign From	CYNTHIA LOH	Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model	MASERATI GRANTURISMO 4.2	c.c	4244
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	ZAMGH45C000058269	Colour	WHITE
Odometer	76599	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/40 R19	PIRELLI	6 mm
L/H Front Tyre	245/40 R19	PIRELLI	6 mm
R/H Rear Tyre	245/40 R19	PIRELLI	6 mm
L/H Rear Tyre	245/40 R19	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	21/02/2018	Inspection Date	06/03/2018
Survey held at	HONG SEH MOTORS PTE LTD 10 FOURTH LOK YANG ROAD JURONG TOWN SINGAPORE 628631		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKB 4008L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	COMPLETE FRONT BUMPER MGT (CONSISTENT)	DEFORMED	6,500.00	6,500.00
13	SCREW (CONSISTENT)	NECESSARY	214.50	214.50
4	RIVET (CONSISTENT)	NECESSARY	19.40	19.40
4	SCREW FOR FRT GRILLE (CONSISTENT)	NECESSARY	24.80	24.80
4	SCREW (CONSISTENT)	NECESSARY	16.00	16.00
4	WASHER FOR BRACKET ON HEAT (CONSISTENT)	NECESSARY	8.00	8.00
1	BUMPER UPPER SUPPORT PADDING (CONSISTENT)	* CHECK	539.20	-
1	BUMPER LOWER SUPPORT PADDING (CONSISTENT)	* CHECK	539.20	-
1	AIR CONVEYOR (CONSISTENT)	* CHECK	1,085.00	-
1	SIDE GRILL KIT (CONSISTENT)	BENT	502.70	502.70
1	FRONT LH SUSP ARM KIT (CONSISTENT)	* CHECK	2,820.00	-
1	LH FRONT HEADLIGHTS (CONSISTENT)	* CHECK	6,800.00	-
1	LH FOG LIGHT (CONSISTENT)	NOT NECESSARY	250.00	-
1	COMPLETE STEERING RACK (CONSISTENT)	* CHECK	7,268.00	-
2	STEERING RACK PIPE COPPER WASHER (CONSISTENT)	* CHECK	3.00	-
2	STEERING PIPE COPPER WASHER (CONSISTENT)	* CHECK	2.40	-
1	LH FRONT WHEELHOUSE (CONSISTENT)	NOT NECESSARY	150.00	-
1	LH FRONT DEFLECTOR (CONSISTENT)	TORN	120.00	120.00
11	SCREW (CONSISTENT)	NECESSARY	60.50	60.50
11	WASHER (CONSISTENT)	NECESSARY	28.05	28.05
1	FRONT BUMPER PARKING SENSOR (CONSISTENT)	* CHECK	480.00	-
2	PARKING SENSOR GASKET (CONSISTENT)	NECESSARY	70.00	70.00
2	BUMPER SIDE PARK SENSOR MOUNT (CONSISTENT)	NECESSARY	36.00	36.00
1	FRONT WHEEL RIM SILVER "19 (CONSISTENT)	CUT	2,600.00	2,600.00
1	245/40 ZR19 94Y PZERO (@ \$780.00 DISC 80%) (CONSISTENT)	* CHECK	780.00	-
5	WHEEL STUDS (CONSISTENT)	NECESSARY	125.00	125.00
1	TYRE VALVE (CONSISTENT)	NECESSARY	17.60	17.60
1	LH FENDER MGT (CONSISTENT)	BENT	6,000.00	6,000.00
3	LH AIR INTAKE (CONSISTENT)	NECESSARY	169.20	169.20
1	PININFARINA INSCRIPTION (CONSISTENT)	NECESSARY	28.00	28.00

Report Ref No. CC4/ASM18004189/T1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	LH KICK PLATE (CONSISTENT)	NECESSARY	169.00	169.00
1	REG PLATE (CONSISTENT)	NECESSARY	60.00	60.00
1	SYNTHETIC ATF 111G (2.5) (CONSISTENT)	* CHECK	55.00	-
1	LH HEADLIGHT SUPPORT BRACKET (CONSISTENT)	* CHECK	620.00	-
1	OVAL EMBLEM, MGS (FRT BUMPER) (CONSISTENT)	NECESSARY	62.00	62.00
1	LH SIDE LIGHT (CONSISTENT)	NECESSARY	30.55	30.55
1	FRONT BUMPER CROSS MEMBER (CONSISTENT)	TO REPAIR SEE LABOUR	5,250.00	-
1	LH SKIRT HOLDER BRACKET - MTG (CONSISTENT)	NECESSARY	192.75	192.75
8	NUT (CONSISTENT)	NECESSARY	8.80	8.80
11	SIDE SKIRT SCREW (CONSISTENT)	NECESSARY	181.50	181.50
1	LH BALL TIE ROD (CONSISTENT)	* CHECK	350.00	-
1	FRONT SUSPENSION SCREW (CONSISTENT)	* CHECK	121.50	-
2	NUT (CONSISTENT)	NECESSARY	24.00	24.00
2	WASHER (CONSISTENT)	NECESSARY	17.00	17.00
1	FRONT SUSPENSION BOLT (CONSISTENT)	* CHECK	218.00	-
1	LH BRACKET HEADLAMP WASHER GUN HOLDER (CONSISTENT)	NECESSARY	56.00	56.00
1	RH BRACKET HEADLAMP WASHER GUN HOLDER (CONSISTENT)	NECESSARY	56.00	56.00
1	WHEEL CAP BLACK (CONSISTENT)	NECESSARY	36.00	36.00
			44,764.65	17,433.35
LABOUR				
REMOVE, INSTALL & RENEW: FRONT BUMPER, FRONT GRILL, BOTH HEADLAMP WASHER SYSTEM PIPING, FRONT BUMPER AIR CONVEYOR, BOTH HEADLAMP, FENDER GRILLS, INDICATOR LAMP & ENGINE COMPARTMENT COVER TO FACILITATE REPAIRS. INCLUSIVE OF THE REPAIR OF FRONT BUMPER CROSS MEMBER.			5,800.00	4,200.00
RENEW LEFT HEADLAMP SUPPORT BRACKET INCLUDE CUT & WELD.			950.00	800.00
REMOVE & RENEW LEFT FRONT FENDER INCLUDE CUT & WELD INCLUDE REMOVE & REINSTALL LEFT SIDE SKIRT TO FACILITATE REPAIR.			3,000.00	2,800.00
RENEW FRONT LEFT RIM & TYRE INCLUDE BALANCE.			180.00	140.00

Report Ref No. CC4/ASM18004189/T1pb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & RENEW LEFT RIGHT SUSPENSION ARMS, WHEEL BEARING.		1,600.00	1,400.00
	REMOVE & RENEW POWER STEERING RACK & BLEED SYSTEM.		1,600.00	1,400.00
	RESET ALL SYSTEM WITH COMPUTER TESTER AND RESET HEADLIGHT AIMING.		950.00	950.00
	RESET ALL WHEEL ALIGNMENT.		750.00	750.00
	RESPRAY PREMIER & PAINT: FRONT BUMPER, LEFT FRONT FENDER. PARKING SENSOR.		3,500.00	3,000.00
			18,330.00	15,440.00
	GRAND TOTAL		63,094.65	32,873.35
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$21,525.30 NETT)			-

Report Ref No. CC4/ASM18004189/T1pb3s2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.