



Motor Claim Department  
Axa Insurance Pte Ltd  
8 Shenton Way, #27-01  
AXA Tower  
Singapore 069542

customer.service@axa.com.sg

02 March 2018

Dear Sir / Madam

**RE: Masarati Quattroporte Auto, Vehicle Reg No, SKB4008L , Chassis No, ZAMGH45C000058269.**

We are pleased to submit quotation for the repair of the above-mentioned vehicle:

<u>A) Labour Description</u>	<u>Part Cost</u>	<u>Labour Cost</u>
1 Remove, install & renew :- Front bumper, front grill, both headlamp washer system piping, front bumper air conveyor, both headlamp, fender grills, indicator lamp & engine compartment cover to facilitate repairs .	1400	\$ 5,800.00 4200
2 Renew left headlamp support bracket include cut & weld		\$ 950.00 800
3 Remove & renew left front fender include cut & weld include remove & reinstall left side skirt to facilitate repair.		\$ 3,000.00 2800.
4 Renew front left rim & tyre Include balance.		\$ 180.00 140
5 Remove & renew left right suspension arms, wheel bearing .		\$ 1,600.00 plus photo.
6 Remove & renew power steering rack & bleed system.		\$ 1,600.00 plus photo.
7 Reset all system with computer tester and reset headlight aiming.		\$ 950.00 ✓
8 Reset all wheel alignment .		\$ 750.00 ✓
9 Respray premier & paint: Front bumper, left front fender, parking sensor .	1400	\$ 3,500.00 3000

<u>B) Parts</u>	<u>Qty</u>	<u>Total Price (\$\$)</u>
1 Complete Front Bumper MGT	1	\$ 6,500.00 del ✓
2 Screw	13	\$ 214.50 not ✓
3 RIVET	4	\$ 19.40 not ✓

4 Screw For Frt Grille	4	\$	24.80	rec ✓
5 Screw	4	\$	16.00	rec ✓
6 Washer for Bracket on Heat	4	\$	8.00	rec ✓
7 Bumper Upper Support Padding	1	\$	539.20	?
8 Bumper Lower Support Padding	1	\$	539.20	?
9 Air Conveyor	1	\$	1,085.00	?
10 Side Grill Kit	1	\$	502.70	bt ✓
11 Front LH Susp Arm Kit	1	\$	2,820.00	?
12 LH Front Headlights	1	\$	6,800.00	?
13 LH Fog Light	1	\$	250.00	X
14 Complete Steering Rack	1	\$	7,268.00	?
15 Steering Rack Pipe copper Washer.	2	\$	3.00	?
16 Steering Pipe Copper Washer	2	\$	2.40	?
17 Lh Front Wheelhouse	1	\$	150.00	X
18 L.H Front Deflector	1	\$	120.00	th ✓
19 Screw	11	\$	60.50	rec ✓
20 Washer	11	\$	28.05	rec ✓
21 Front Bumper Parking Sensor	1	\$	480.00	?
22 Parking Sensor Gasket	2	\$	70.00	rec ✓
23 Bumper Side Park. Sensor Mount	2	\$	36.00	rec ✓
24 Front Wheel Rim Silver 19"	1	\$	2,600.00	cut ✓
25 245/40 ZR19 94Y PZERO	1	\$	780.00	? go/o.
26 Wheel Studs	5	\$	125.00	rec ✓
27 Tyre Valve	1	\$	17.60	rec ✓
28 LH Fender MGT	1	\$	6,000.00	bt ✓
29 L.H. Air Intake	3	\$	169.20	rec ✓
30 Pininfarina Inscription	1	\$	28.00	rec ✓
31 LH Kick Plate	1	\$	169.00	rec ✓
32 Reg Plate	1	\$	60.00	rec ✓
33 Synthetic Atf 111G	2.5	\$	55.00	?
34 LH Headlight Support Bracket	1	\$	620.00	?
35 Oval Emblem, Mgs (Frt Bumper	1	\$	62.00	rec ✓
36 LH & RH Side Light	1	\$	30.55	rec ✓
37 Front Bumper Cross Member	1	\$	5,250.00	Rx
38 Lh Exhaust Bracket -Mgt skint holder brackets	1	\$	192.75	rec ✓
39 NUT	8	\$	8.80	rec ✓
40 Side Skirt Screw	11	\$	181.50	rec ✓
41 LH Ball Tie Rod	1	\$	350.00	?
42 Front Suspension Screw	1	\$	121.50	?
43 NUT	2	\$	24.00	rec ✓
44 Washer	2	\$	17.00	rec ✓
45 Front Suspension Bolt	1	\$	218.00	?
46 LH Bracket head lamp washer gun holder	1	\$	56.00	rec ✓
47 RH Bracket head lamp washer gun holder	1	\$	56.00	rec ✓
48 Wheel Cap Black	1	\$	36.00	rec ✓
<b>TOTAL:</b>		\$	<b>44,764.65</b>	\$ <b>18,330.00</b>

Front bumper under tray car ✓  
 Front bumper under tray screws rec ✓  
 Front bumper under tray clip rec ✓

wheel bearing ?  
 ABS sensor ?

Total Labour : \$ 18,330.00  
Total Parts : \$ 44,764.65  
: \$ 63,094.65  
Plus 7% GST : \$ 4,416.63  
Grand Total : \$ 67,511.28

Should this repair job require any additional parts, we will inform you and bill you accordingly.  
Please confirm your acceptance of this quotation by sending us a return fax with your  
signature and company stamp on it.

Yours sincerely,

I agree and accept the above quotation.

  
\_\_\_\_\_  
Workshop Department

\_\_\_\_\_  
Signature & Company stamp

Tanpin 97495749  
WP  
6/3/18 @ 1630.  
Resurvey new parts.  
Resurvey before paint  
10 days.  
su@ulcamp.com