



FINAL REPORT

Estimate No. : **b1 45933**
Date Estimated : **14/02/2018**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

REPAIR FOR -
Chong Heong Wee (Zhong Xiongwei)
Apt Blk 62 Lorong 4 Toa Payoh
#21-109

- ACCOUNT - 509
Sompo Insurance Singapore Pte Ltd
50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623

Singapore 310062

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SGN9239M	CM75562	30/11/2006	523iA	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachments include knocking out dents caused by the accident			850.00		850.00
To spray paint front bumper			934.00		934.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.			150.00		150.00
Sundries.			80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER LH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER RH SIDE BKT	18.15	1.00		18.15
# FRT BUMPER LH FLAP COVER LEVER	11.65	1.00		11.65
# FRT BUMPER RH FLAP COVER LEVER	11.65	1.00		11.65
FRT BUMPER (PDC)	1,149.80	1.00		1,149.80

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,209.40
Total Labour & Parts :	3,223.40
Deduction for Excess :	
Total Repair Costs less Excess:	3,223.40
GST @7%:	225.64
Grand Total :	3,449.04