

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721
Tel: 64515752 (2 Lines) . Fax: 64514658
Reg No. 201629438M

02/03/2018

Owner: CLNG SERVICES

ESTIMATE TO REPAIR TOYOTA WISH - SLR563E

1pc	rear tailgate
1pc	rear tailgate "TOTOTA" logo
1pc	rear tailgate "VALVE MATIC" emble
1pc	rear tailgate inner rubber
1pc	rear bumper
2pcs	rear bumper side retainer 1 @\$123.05
2pcs	rear bumper side retainer 2 @\$132.10
1pc	rear end panel
2pcs	rear end panel bracket @\$141.40
1pc	rear end panel sensor

less 25%

1set reverse sensor

remove & refix rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

Not authorized
1.2.1
Phanny Bepaim
2 days

<i>ru</i>	\$ 1,415.50	<i>X</i>
<i>nn</i>	\$ 51.10	<i>X</i>
<i>nn</i>	\$ 53.90	<i>X</i>
<i>sn</i>	\$ 375.45	<i>X</i>
<i>nn</i>	\$ 975.00	<i>✓</i>
<i>old</i>	\$ 246.10	<i>✓</i>
	\$ 264.20	<i>?</i>
<i>ru</i>	\$ 581.45	<i>X</i>
<i>.</i>	\$ 282.80	<i>?</i>
<i>sn</i>	\$ 380.00	<i>X</i>
	\$ 4,625.50	
	\$ 1,156.38	
	<u>\$ 3,469.13</u>	

s.nett \$ 280.00 *?*

<i>nn</i>	\$ 160.00	<i>X</i>
<i>nn</i>	\$ 80.00	<i>X</i>
	\$ 80.00	<i>15/</i>
<i>nn</i>	\$ 80.00	<i>X</i>
	\$ 850.00	<i>3601</i>
	\$ 950.00	<i>300</i>
	<u>\$ 5,949.13</u>	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: