

15/02/18

INS. CASE OWNER:

Joel

CC3 / EQ1180 04199

KLP33SV

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

ASSIGNMENT

02/03/18

Date / Time:

02/03/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SW 3940C

Claim No.:

DM18H000582-JG

Name of Insured:

NG RUI QI STEPHANEE

Policy No.:

DMPHQ17-001351

Insured Tel No.:

HP: 9841 2492

Make / Model:

CHEVROLET AVEO -1.4 SDR T255CM

Excess Sec II :SS

D.O.A: 02/03/18

Place of Accident:

KPE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: ROY HO GUAN RONG

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.: 9169 1192

(V/L: YES / NO)

Insured Liability:

% Final ? Yes / No

SAC 2753L



INSRS:

WSP: C046 (Long)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SAC 2753L - C046 (Long) / 005744/RL6352 001 2/03/18
 - NS/INC11025973/HEN DOA 15/12/17
 SW 3940C - C046 (Long) / 005744/RL6352 001 2/03/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

24/03/18 y 29/3/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

27/03/18 (HT)

29/3/18 @ 12.30pm Called OI, Mr Roy. HP line busy.
 @ 12.45pm OI Mr Roy called back. Confirm
 rear-endel tp. Insure tp claim. Agreed
 to settle & andre NCB issue.

17/4/18

File pass to Mei Kwan to close

RECEIVED 17 APR 2018

PRELIMINARY ADVICE

Date/Time: 02/03/18

Sent By:

Shirley Huen

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with: Jim

Email

Call

Final Liability:

SS

%

(Agreed / Assessed) BOLA S/N No.: 27

Repair Cost:

SS

2782.00

Loss of Rental (LOR):

SS

294.75

(3 days)

x \$98.25

Loss of Use (LOU):

SS

-

(\$ - x - days)

Loss of Income (LOI):

SS

150.00

(\$50 x 3 days)

LOR only

LOU only

LOR + LOU

LOR + LOU

[Tick only one]

GIA/LTA Search

SS

749

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

3234.20

Global Sum SS: 3230.00

FINAL PAYMENT

Date/Time:

Confirm with: Jim

Email

Call

Payee 1:

SS

3230.00

Name 1:

ComfortDelgro Engineering Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

31 Dec 2010

SA C27502 Page 100

File M Car M Cops Bus Van Lorry 0 Print Motor

Track Tagging

Hyundai South 1991
Blk Ins 0 Sid N/A
971105 - Facs Ins 0 Sid N/A

KMHETKIRMAA 80325X

6

0

0

0

215 / 60K16

SS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI
TOYO / YOKO

Maxxi

Front Rear

FS SS FS SS FS SS FS SS FS SS FS SS

2/3/18 2/3/18

CDGE (Loyang)

Rear

EQ
4s.

L/S \$2600 CRed (\$3397.74/57%).




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
EQ INSURANCE COMPANY LTD		Ref : CC3/EQI18004199/K1ps3	
5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110		Date : 05-03-2018	
		Code : EQI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJW 3940C	Veh. Inspected	SHC 2753L
Policy No.	DMPPHQ17-001351	Coverage (\$)	0.00
Claim No.	DM18HO00582-JG	Excess (\$)	0.00
Assign From		Assign Date	05/03/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/03/2018	Inspection Date	02/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO: 305121453

CUSTOMER

REGN NO: SHC2753L

MILEAGE

COMFORT TRANSPORTATION PTE LTD

MAKE: HYUNDAI

FUEL

IS 7010045

CUSTOMER NO: 383 SIN MING DRIVE

E.....1/2.....F

ADDRESS Singapore SINGAPORE 575717

MODEL SONATA 02.03.2018 10:50

65508755

YR OF MANU 31.12.2010

TARGET DATE

(R) (O)

(P)

CHASSIS CODE RMHET41VMAA803254

COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 02.03.2018

NATURE: 3P 02.03.18

NO	LABOR CODE	DESCRIPTION
----	------------	-------------

CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Receipt Slip

Exit Pass

No.: SHC2753L

JU EQ LKK

Vehicle No.: SHC2753L

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

REPAIR ESTIMATE*

VEHICLE NO : SHC 2753L

Jumani

DATE 2/3/2018 14:57

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid			\$ 1,349.50	
	Boot Lid Rubber X			\$ 110.90	
	Boot Lid Lock Upper X			\$ 132.10	
	Boot Lid Lock Lower X			\$ 30.30	
	Boot Lid Sonata Plate			\$ 43.60	
	Boot Lid Hyundai Plate			\$ 24.20	
	Boot Lid 'H' Emblem			\$ 26.10	
	Boot Lid CRDI Plate			\$ 22.70	
	Boot Lid Lamp (LH/RH) X		\$ 230.20	\$ 460.40	
	Rear Bumper			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip			\$ 22.00	
	Rear Bumper Sponge			\$ 137.40	
	Rear Bumper Under Cover X			\$ 185.80	
	Rear Bumper Protector (LH/RH) X repair		\$ 38.00	\$ 76.00	
	Tail Lamp (LH/RH) X		\$ 344.00	\$ 688.00	
	Rear Panel X repair			\$ 391.80	
	Rear Panel Garnish X			\$ 95.80	
	SUB TOTAL			\$ 4,858.30	
	LESS 20%			\$ 971.66	
	DISCOUNTED TOTAL			\$ 3,886.64	
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00	Nett
	Rear No. Plate X			\$ 25.00	Nett
	Rear Bumper Reverse Sensor X			\$ 135.70	Nett
	Rear Bumper Advertisement Logo			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
				\$ 440.70	
	Labour Charge				
	Panel Beating			\$ 850.00	400
	Spray Painting Charge			\$ 600.00	500
	Wiring Charge			\$ 50.00	X
	Tuff Kote			\$ 50.00	20
	Remove/Refix Reverse Sensor			\$ 120.00	X
	TOTAL LABOUR			\$ 1,670.00	
	ESTIMATE TOTAL			\$ 5,997.34	
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL : (065) 62563561. FAX : (065) 62564315

Your ref: TBA
Our ref: CC3/EQI18004199/K1ps3

Date: 05.03.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

SHC 2753L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 02.03.2018 at the premises of M/s ComfortDelGro Engineering Pte Ltd (Loyang) and have the following to report:-

Workshop Estimate Amount	: S\$	5,997.34
Revised Estimate Amount	: S\$	2,893.20
"Check" Items Amount	: S\$	496.56
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3.0 days

Remarks :

Yours faithfully,

KALVIN ANG
Licensed Appraiser

Our Job Ref No : 305121453
Date : 05/03/18

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax :
Attn : KALVIN
Vehicle Reg No. : SHC2753L Date of Accident : 02/03/18

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: EQ --- SJW3940C
###
2. The finalized amount shall be:
 - (a) Spare Parts after List discount
 - (b) Labour Charges ###
 - Total for Part-By-Part Repair Cost
 - (c.) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20% \$2,600.00
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 3 working days
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance.

We confirm the estimates and
finalized amount

Signature :
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature :
Name : Kalvin
Date : 6/3/18

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2753L

Jumani

DATE 2/3/2018 14:57

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber			\$ 110.90
	Boot Lid Lock Upper			\$ 132.10
	Boot Lid Lock Lower			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH)		\$ 230.20	\$ 460.40
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover			\$ 185.80
	Rear Bumper Protector (LH/RH)		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH)		\$ 344.00	\$ 688.00
	Rear Panel			\$ 391.80
	Rear Panel Garnish			\$ 95.80
	SUB TOTAL			\$ 4,858.30
	LESS 20%			\$ 971.66
	DISCOUNTED TOTAL			\$ 3,886.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00
	Rear No. Plate			\$ 25.00
	Rear Bumper Reverse Sensor			\$ 135.70
	Rear Bumper Advertisement Logo			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00
	Labour Charge			
	Panel Beating			\$ 850.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,670.00
	ESTIMATE TOTAL			\$ 5,997.34

Kelvin 11/11/14
2/3/18 1536 hrs
3 Rys
45
After Repair photo

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices subject to confirmation
- Third party is on a "without prejudice" basis
- No illegal modifications allowed
- Supplementary materials to be resurveyed and
- Insurance claim to be submitted from the Company

Acknowledged: _____
Signature: _____
Date: _____

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Shirley Hiew (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 26 March 2018 4:42 PM
To: Shirley Hiew (LKK Auto)
Cc: Admin A; Zaini (LKK Auto); Hsiao Tong (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SJW3940C (OI : EQI - DM18HO00582-JG) AND SHC2753L (TP : LKK REF - CC3/EQI18004199/K1ps3) on 02/03/2018
Attachments: SJW3940C.PDF

Dear Shirley

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

 A Member of Citystate

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, March 21, 2018 1:17 PM
To: Janet Tan; Hsiao Tong (LKKAuto)
Cc: eqiprs@eqinsurance.com.sg; Joel Goh; Admin A; Zaini (LKK Auto)
Subject: FW: Direct Settlement - Accident Involving SJW3940C (OI : EQI - TBA) AND SHC2753L (TP : LKK REF - CC3/EQI18004199/K1ps3) on 02/03/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shirley Hiew (LKK Auto)

Sent: Monday, 5 March 2018 7:34 PM

To: Bazlin Ahmad <bazlin.ahmad@eqinsurance.com.sg>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; Zaini (LKK Auto) <Zaini@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJW3940C (OI : EQI - TBA) AND SHC2753L (TP : LKK REF - CC3/EQI18004199/K1ps3) on 02/03/2018

WITHOUT PREJUDICE

Dear Lynn,

We refer to the above matter.

We have inspected TP vehicle SHC 2753L at M/s ComfortDelGro Engineering Pte Ltd - Loyang.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 16 April 2018 1:55 PM
To: 'Jim Wong See Pah'
Subject: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQ118004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Your ref: **T 0318/ SHC2753L/ JW (st)**
Our ref: CC3/EQ118004199/K1pa3

Without Prejudice

Dear Sir/Mdm,

ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018

We refer to the above matter.

We propose settlement at a global sum of **\$3,230.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Jim Wong See Pah <jimwong@cdge.com.sg>
Sent: Monday, 16 April 2018 2:21 PM
To: Hsiao Tong (LKKAuto)
Subject: Re: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQI18004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Dear Ms Chew

Please process settlement in sum \$ 3230.00 for resolving our property damage claim amicably.

Thank you.

Best Regards

Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

From: "Hsiao Tong (LKKAuto)" <chewht@lkkauto.com>
To: Jim Wong See Pah <jimwong@cdge.com.sg>
Date: 16/04/2018 01:55 PM
Subject: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQI18004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Your ref: **T 0318/ SHC2753L/ JW (st)**
Our ref: CC3/EQI18004199/K1pa3

Without Prejudice

Dear Sir/Mdm,

ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018

We refer to the above matter.

We propose settlement at a global sum of **\$3,230.00(all-in).**

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.




Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 16 April 2018 5:15 PM
To: 'Jim Wong See Pah'
Subject: RE: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQI18004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Without Prejudice

Hi Mr Jim,

Thank you for your acceptance.

We will proceed to close file.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jim Wong See Pah [mailto:jimwong@cdge.com.sg]

Sent: Monday, 16 April 2018 2:21 PM

To: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>

Subject: Re: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQI18004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Dear Ms Chew

Please process settlement in sum \$ 3230.00 for resolving our property damage claim amicably.

Thank you.

Best Regards

Jim Wong

Claims Department / ComfortDelgro Engineering Pte Ltd

Off: 62148374 / Fax: 62141843

From: "Hsiao Tong (LKKAUTO)" <chewht@lkkauto.com>
To: Jim Wong See Pah <jimwong@cde.com.sg>
Date: 16/04/2018 01:55 PM
Subject: Your ref: T 0318/ SHC2753L/ JW (st) *Our ref: CC3/EQ118004199/K1pa3 [ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018]

Your ref: **T 0318/ SHC2753L/ JW (st)**
Our ref: CC3/EQ118004199/K1pa3

Without Prejudice

Dear Sir/Mdm,

ACCIDENT INVOLVING SJW 3940C(EQ) & SHC 2753L ON 02/03/2018

We refer to the above matter.

We propose settlement at a global sum of **\$3,230.00(all-in)**.

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This message and any attachments may contain confidential, privileged or proprietary information. If you are not the intended recipient, kindly notify us and delete this message and its attachments immediately, and please be advised that using, copying, distributing or disclosing any contents therein is not allowed. Statements pertaining to any matter outside our business are not to be taken as endorsed by ComfortDelGro Corporation Limited or its related companies. The comments/proposals provided are for discussion purposes only and are subject to approvals. Nothing herein shall constitute a binding agreement between the parties. Neither party shall be bound in any way to any term or condition except as agreed in a written agreement signed by the duly authorised representatives of both parties.

ComfortDelGro - a Green Office certified by the Singapore Environment Council - is committed to preserving the environment. We encourage you to print this only if necessary.

ComfortDelGro Engineering Pte Ltd [Registration No. 199506048W]



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s EQ INSURANCE COMPANY LTD

Date: 23/04/2018

THIRD PARTY DIRECT SETTLEMENT

Vehicle No.	SJW 3940C (Insd Veh)	Your Ref. No. : DM18HO00582-JG
	SHC 2753L (TP Veh)	Our Ref. No. : CC3/EQI18004199/K1pa3s2
Date of Accident	2/3/2018	

Liability	100%	
Final Repair Cost	: \$ 2,782.00	(W/GST)
Loss of Income	: \$ 150.00	3 days
Rental (If any)	: \$ 294.75	3 days
Others:	: \$ 7.49	
	: \$	
	3,234.24	
Final Settlement Sum	: \$ 3,230.00	(GLOBAL SUM)
Remarks	:	

Payment Instruction: Payee's Breakdown

1)	COMFORTDELGRO ENGINEERING PTE LTD	: \$ 3,230.00
		: \$

NUR SHAQILAH

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC3/EQ18004199/K1pa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 23-04-2018



Code : EQ1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJW 3940C	Veh. Inspected	SHC 2753L
Policy No.	DMPPHQ17-001351	Coverage (\$)	0.00
Claim No.	DM18HO00582-JG	Excess (\$)	0.00
Assign From		Assign Date	02/03/2018

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI SONATA	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	KMHET41VMAA803254	Colour	BLUE
Odometer	971105	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	MAXXIS	7 mm
L/H Front Tyre	215/60R16	MAXXIS	7 mm
R/H Rear Tyre	215/60R16	MAXXIS	7 mm
L/H Rear Tyre	215/60R16	MAXXIS	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	02/03/2018	Inspection Date	02/03/2018
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 2753L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOT LID	DENTED	1,349.50	1,349.50
1	BOOT LID RUBBER	SERVICEABLE	110.90	-
1	BOOT LID LOCK UPPER	SERVICEABLE	132.10	-
1	BOOT LID LOCK LOWER	SERVICEABLE	30.30	-
1	BOOT LID SONATA PLATE	NECESSARY	43.60	43.60
1	BOOT LID HYUNDAI PLATE	NECESSARY	24.20	24.20
1	BOOT LID 'H' EMBLEM	NECESSARY	26.10	26.10
1	BOOT LID CRDI PLATE	NECESSARY	22.70	22.70
2	BOOT LID LAMP (LH/RH) @ \$230.20	SERVICEABLE	460.40	-
1	REAR BUMPER	DEFORMED	578.40	578.40
1	REAR BUMPER REINFORCEMENT	CRACKED	483.30	483.30
10	REAR BUMPER CLIP	NECESSARY	22.00	22.00
1	REAR BUMPER SPONGE	SERVICEABLE	137.40	-
1	REAR BUMPER UNDER COVER	SERVICEABLE	185.80	-
2	REAR BUMPER PROTECTOR (LH/RH) @ \$38.00	TO REPAIR SEE LABOUR	76.00	-
2	TAIL LAMP (LH/RH) @ \$344.00	SERVICEABLE	688.00	-
1	REAR PANEL	TO REPAIR SEE LABOUR	391.80	-
1	REAR PANEL GARNISH	SERVICEABLE	95.80	-
	LESS 20% DISCOUNT		-971.66	-509.96
			3,886.64	2,039.84
SPECIAL NETT ITEMS				
1	BOOT LID COMFORT LOGO & TEL NO. STICKER (SN)	NECESSARY	30.00	30.00
1	REAR NO. PLATE (SN)	SERVICEABLE	25.00	-
1	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	REAR BUMPER ADVERTISEMENT LOGO (SN)	NECESSARY	50.00	50.00
2	REAR FENDER ADVERTISEMENT LOGO (LH/RH) @ \$100.00 (SN)	NECESSARY	200.00	200.00
			440.70	280.00

Report Ref No. CC3/EQ18004199/K1pa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR BUMPER PROTECTOR (LH/RH) AND REAR PANEL.		850.00	400.00
	SPRAY PAINTING.		600.00	540.00
	WIRING CHARGE.	NOT NECESSARY	50.00	-
	TUFF KOTE.		50.00	20.00
	REMOVE / REFIX REVERSE SENSOR.	NOT NECESSARY	120.00	-
			1,670.00	960.00
	GRAND TOTAL		5,997.34	3,279.84
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,600.00

Report Ref No. CC3/EQ18004199/K1pa3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.