

REPAIR ESTIMATE*

VEHICLE NO : SHC 2753L

Jumani

DATE 2/3/2018 14:57

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 1,349.50
	Boot Lid Rubber X			\$ 110.90
	Boot Lid Lock Upper X			\$ 132.10
	Boot Lid Lock Lower X			\$ 30.30
	Boot Lid Sonata Plate			\$ 43.60
	Boot Lid Hyundai Plate			\$ 24.20
	Boot Lid 'H' Emblem			\$ 26.10
	Boot Lid CRDI Plate			\$ 22.70
	Boot Lid Lamp (LH/RH) X		\$ 230.20	\$ 460.40
	Rear Bumper			\$ 578.40
	Rear Bumper Reinforcement ?			\$ 483.30
	Rear Bumper Clip			\$ 22.00
	Rear Bumper Sponge			\$ 137.40
	Rear Bumper Under Cover X			\$ 185.80
	Rear Bumper Protector (LH/RH) X repair		\$ 38.00	\$ 76.00
	Tail Lamp (LH/RH) X		\$ 344.00	\$ 688.00
	Rear Panel X repair			\$ 391.80
	Rear Panel Garnish X			\$ 95.80
	SUB TOTAL			\$ 4,858.30
	LESS 20%			\$ 971.66
	DISCOUNTED TOTAL			\$ 3,886.64
	Boot Lid Comfort Logo & Tel No. Sticker			\$ 30.00 Nett
	Rear No. Plate X			\$ 25.00 Nett
	Rear Bumper Reverse Sensor X			\$ 135.70 Nett
	Rear Bumper Advertisement Logo			\$ 50.00 Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00 Nett
				\$ 440.70
	Labour Charge			
	Panel Beating			\$ 850.00 400
	Spray Painting Charge			\$ 600.00 540
	Wiring Charge			\$ 50.00 X
	Tuff Kote			\$ 50.00 20
	Remove/Refix Reverse Sensor			\$ 120.00 X
				\$ 1,670.00
	TOTAL LABOUR			\$ 5,997.34
	ESTIMATE TOTAL			
	Acknowledged by:			
	Signature:			
	Date:			

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.