



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



Thatcham escribe

Reg. No: 52983356E GST Reg. No. 20-0405911-H

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18004200/Gvbn2			
73 BRAS BASAH ROAD			
#05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			
		Date: 16-03-2018	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SBX 57L	<b>Veh. Inspected</b>	SHC 4338P
<b>Policy No.</b>	5096367499	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/0984416-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>		<b>Assign Date</b>	02/03/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	TOYOTA PRIUS	<b>c.c</b>	1798
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2013
<b>Chassis No.</b>	JTDKN36U305713418	<b>Colour</b>	MAROON
<b>Odometer</b>	452369	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	FALKEN	6 mm
<b>L/H Front Tyre</b>	195/65 R15	FALKEN	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	FALKEN	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	FALKEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
<b>Accident Date</b>	01/03/2018	<b>Inspection Date</b>	02/03/2018
<b>Survey held at</b>	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	