

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5944H -**AAD1802-179***Not Authorised*
Recovery B4 paint 83887.18

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5944H - JASMINE

VF1ABL15AUC281463

RENAULT

LATITUDE

15.02.2018

AXA

PART			LIST		
1	1	BUMPER COVER FRT	\$	Reclaim 1,259.42	✓
2	1	BUMPER SPOILER FRT	\$	SL 181.75	X
3	1	BUMPER FOG LAMP GRILLE RH	\$	SL 207.22	X
4	1	BUMPER RETAINER FRT RH	\$	Dis 151.41	✓
5	1	BUMPER RETAINER FRT RH	\$	SL 151.41	X
6	1	BUMPER SUPPORT FRT RH	\$	SL 123.88	X
7	1	BUMPER BEAM FRT	\$	R 914.08	X
8	1	RADAIOR GRILLE	\$	SL 1,707.78	X
9	1	RADAIOR GRILLE BADGE 'RENAULT'	\$	SL 225.36	X
10	1	RADAIOR GRILLE FRAME	\$	SL 1,353.75	X
11	1	FRAME FULL SUPPORT PANEL	\$	SL 615.90	X
12	1	FRAME FULL SUPPORT BRACKET	\$	R 89.79	X
13	1	BONNET	\$	R 1,941.63	X
14	1	HEADLALMP RH	\$	Reclaim 1,184.43	✓
15	1	HEADLAMP PANEL FRT RH	\$	R 152.15	X
16	1	FENDER PANEL FRT RH	\$	Re 783.83	✓
17	1	FENDER INSULATOR RH	\$	SL 130.84	} X
18	1	WHEEL HOUSING PANEL FRT RH	\$	R 4,682.09	
19	1	WHEELARCH FRT RH	\$	SL 278.84	
20	1	LOWER ARM FRT RH	\$	SL 685.76	
21	1	KUNCKLE ARM FRT RH	\$	SL 846.98	
22	1	ABSORBER FRT RH	\$	SL 360.54	
23	1	DOOR MIRROR RH	\$	SL 1,483.40	
24	1	DOOR MIRROR GLASS RH	\$	SL 148.20	
25	1	DOOR MIRROR BACK COVER RH	\$	SL 218.46	
26	1	DOOR PANEL FRT RH	\$	R 2,844.66	
27	1	DOOR HINGE UPPER RH	\$	R 274.50	
28	1	DOOR HINGE LOWER RH	\$	R 300.55	

TOTAL	\$	23,298.61
10%	\$	2,329.86
	\$	20,968.75

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD
AAD1802-179

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB5944H -

1	1SET	FRONT BUMPER CLIP	\$	nn	66.00	✓
2	1SET	WHEELARCH CLIP RH	\$	nn	66.00	
3	1	TOW COVER FRT	\$	sn	14.50	
4	1	CAP HUB RH FRT	\$	sn	35.00	
5	1	RIM RH FRT	\$	sn	385.00	
6	1	TYRE RH FRT	\$	sn	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP RH	\$	nn	9.80	
8	1SET	BUMEPR RETAINER FRT CLIP RH	\$	nn	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
10	1	DOOR STICKER "Classic"	\$	nn	30.00	

TOTAL	\$	1,028.80
TOTAL PARTS	\$	21,997.55

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,800.00 *4000*

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

Putty and spray painting of the affected portion.

\$ 3,000.00 *4400*

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

Towing Fees

\$ nn 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To rust-proofing of the affected areas.

\$ 170.00 *300*

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ nn 170.00 X

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ nn 380.00 X

final checking and testing and notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

TOTAL \$ 7,200.00
Over All Total \$ 29,197.55

(PARTS BY PARTS) Repair Days

10 Days

2 days

Acknowledged by Repairer

Signature:

Date: