



FALCON-AIR

YEO LING LING  
BLK 13 TECK WHYE LANE  
SINGAPORE 680013

Attention : Motor Claim Department  
Contact : 91767313

# FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D  
GST REG. NO.: 19-9501140-D

Estimate : ES003127

Date : 01/03/2018  
Vehicle Num. : SJH3602H  
Make/Model : NISSAN LATIO  
Chassis/Eng#: JN1FAAC11Z0001636  
Accident Date : 23/02/2018  
Claim No. :  
Reference : TP TMIS VS EQ  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                       |   |                           |  |                     |
|-----------------------|---|---------------------------|--|---------------------|
| 1.                    | 1 | NETT ITEMS :              |  |                     |
| 2.                    | 1 | LH REAR FENDER            |  | 1,004.70 <i>due</i> |
| 3.                    | 1 | TAILLAMP                  |  | 279.00 <i>one</i>   |
| 4.                    | 1 | REAR BUMPER               |  | 532.40 <i>de</i>    |
|                       |   | REAR BUMPER SIDE RETAINER |  | 33.20 <i>new</i>    |
| Nett Total S\$ :      |   |                           |  | 1,849.30            |
| 10.00% Discount S\$ : |   |                           |  | 184.93              |
|                       |   |                           |  | 1,664.37            |

|                                                         |                   |
|---------------------------------------------------------|-------------------|
| LABOUR :                                                |                   |
| TO RUST PROOF ON ACCIDENT DAMAGED PARTS                 | 150.00 <i>60</i>  |
| TO REMOVE/REFIX CUSHION SEAT, CARPET, GARNISH, WIRING   | 150.00 <i>80</i>  |
| SPRAY PAINTING ON ACCIDENT DAMAGED AREAS                | 900.00 <i>700</i> |
| TO CUT OUT REWELD LH REAR FENDER, REPAIR REAR END PANEL |                   |
| INNER PANEL INCLUDES KNOCKING & REPLACEMENT OF PARTS    | 700.00 <i>600</i> |
| Labour Total S\$ :                                      | 1,900.00          |

E. & O.E.

Total S\$ : 3,564.37

for FALCON AIR AUTO SERVICES PTE LTD



*Tanjin 97495719*  
*2/3/18*  
*up*

*humpsum*  
*Recovery after repair*  
*6 days*  
*sure@humpsum.com*

**FALCON-AIR AUTO SERVICES PTE LTD**  
(a subsidiary of Falcon-Air Holdings Pte Ltd)

## LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary (s) must be provided and is subject to final approval from the insurance Company

Acknowledged by Repairer

Signature:

Date:

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg